

CNC

MELDAS C6/C64/C64T

PARAMETER MANUAL



MELDAS and MELSEC are registered trademarks of Mitsubishi Electric Corporation.
Microsoft and Windows are a registered trademark of Microsoft Corporation in the United States and/or other countries.
Other brands and product names throughout this manual are trademarks or registered trademarks of their respective holders.

Introduction

This manual is a guide of the parameters used with the CNC MELDAS C6/C64/C64T. This manual is written on the assumption that all machine parameters of the MELDAS C6/C64/C64T are provided. However, the CNC may not necessarily be provided with all of the options. When the system is used, therefore, reference should be made to the Specifications Manual issued by the machine maker.

Points to be observed when reading this manual

- (1) This manual contains general descriptions as seen from the standpoint of NC (numerical control) and thus refer to the Instruction Manual issued by the machine maker for descriptions of individual machine tools.
The Instruction Manual issued by the machine maker takes precedence over this manual when any mention of "restrictions", "usable states" or such details are mentioned.
- (2) As much information as possible on special procedures has been included in this manual, and it may be considered that any procedures not mentioned cannot be undertaken.
- (3) Also refer to the following manuals.
 - MELDAS C6/C64/C64T Instruction Manual..... BNP-B2259
 - MELDAS C6/C64/C64T Programming Manual
(Machining center/Transfer machine system)..... BNP-B2260
 - MELDAS C6/C64/C64T Programming Manual (Lathe system) BNP-B2264
 - MELDAS AC Servo MDS-B-Vx Series Servo Parameter Manual..... BNP-A2993
 - MELDAS AC Servo MDS-C1 Series Specification Manual..... BNP-C3000

CAUTION

-  For items described as "Restrictions" or "Usable State" in this manual, the Instruction Manual issued by the machine maker takes precedence over this manual.
-  Items that are not described must be interpreted as "not possible".
-  This manual is written on the assumption that all option functions are added. Refer to the Specifications Manual issued by the machine maker before starting use.
-  Refer to the manuals issued by the machine manufacturer for each machine tool explanation.
-  Some screens and functions may differ or may not be usable depending on the NC system version.

Precautions for Safety

Always read the Specifications Manual issued by the machine maker, this manual, related manuals and attached documents before installation, operation, programming, maintenance or inspection to ensure correct use. Understand this numerical controller, safety items and cautions before using the unit.

This manual ranks the safety precautions into "DANGER", "WARNING" and "CAUTION".



When the user may be subject to imminent fatalities or major injuries if handling is mistaken.



When the user may be subject to fatalities or major injuries if handling is mistaken.



When the user may be subject to injuries or when physical damage may occur if handling is mistaken.

Note that even items ranked as "**CAUTION**", may lead to major results depending on the situation.

In any case, important information that must always be observed is described.

DANGER

Not applicable in this manual.

WARNING

Not applicable in this manual.

CAUTION

1. Items related to product and manual

-  For items described as "Restrictions" or "Usable State" in this manual, the Instruction Manual issued by the machine maker takes precedence over this manual.
-  Items that are not described must be interpreted as "not possible".
-  This manual is written on the assumption that all option functions are added. Refer to the Specifications Manual issued by the machine maker before starting use.
-  Refer to the manuals issued by the machine manufacturer for each machine tool explanation.
-  Some screens and functions may differ or may not be usable depending on the NC system version.

CAUTION

2. Items related to servo/spindle parameters

-  To change the control mode to the High-gain amp (MDS-B-V14/V24) mode after replacement of the Standard amp (MDS-B-V1/V2), it is need to change the parameters and to adjust the servo parameters to fit to the High-gain amp.
-  Mode change between the Standard amp mode and the High-gain amp mode is actually performed when the power (200V) is turned ON. Thus, when changing some parameters unique to each amp, an alarm "7F" occurs and requests to turn the power ON again.
Note that the alarm "7F" may occur when the amp is mounted on the machine for the first time.
When the alarm "7F" occurs, turn the power ON again.
The alarm "7F" may not occur at second turning ON or later unless the above-mentioned parameters are changed.
-  With MDS-C1 series, only the serial encoder is applied as the motor end detector. Thus, OHE/OHA type detector cannot be used as the motor end detector.
-  Do not make remarkable adjustments or changes of the parameters as the operation may became unstable.

3. Items related to the other parameters

-  When setting the parameter (#6449/bit6, 7) not to check the overheat, the control unit and the communication terminal may not be controlled because of overheat. In such case, axis runaway may cause a machine breakage, an accident resulting in injury or death, or device breakage.
To prevent the serious results, ordinarily set the parameters so that the overheat check is valid.

CONTENTS

1. Parameter Screens	1
2. Machining Parameters	3
2.1 Workpiece Coordinate Offset	3
2.2 Process Parameters	4
2.3 Control Parameters	6
2.4 Axis Parameters	7
2.5 Barrier Data	8
3. I/O Parameters	9
3.1 Base Parameters	9
3.2 I/O Device Parameters	10
4. Setup Parameters	14
5. Base Specifications Parameters	15
6. Axis Specifications Parameters	66
6.1 Axis Specifications Parameters	66
6.2 Zero Point Return Parameters	73
6.3 Absolute Position Parameters	75
6.4 Axis Specifications Parameters 2	77
7. Servo Parameters	80
7.1 MDS-B-SVJ2	82
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)	108
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)	136
7.4 Supplement	166
7.4.1 D/A Output Specifications	166
7.4.2 Electronic Gears	172
7.4.3 Lost Motion Compensation	173
8. Spindle Parameters	174
8.1 Spindle Base Specifications Parameters	174
8.2 MDS-B-SPJ2	181
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH	201
8.4 MDS-C1-SPM	234
8.5 Supplement	266
8.5.1 D/A Output Specifications	266
9. Machine Error Compensation	269
9.1 Function Outline	269
9.2 Setting Compensation Data	273
9.3 Example in Using a Linear Axis as the Base Axis	275
9.4 Example in Using a Rotation Axis as the Base Axis	277
10. PLC Constants	278
10.1 PLC Timer	278
10.2 PLC Counter	278
10.3 PLC Constants	279
10.4 PLC Bit Selection	280
11. Macro List	283
12. Position Switch	284
12.1 Outline of Function	284
12.2 Canceling the Position Switch	286
13. Indexing Axis Parameters	287
14. Indexing Axis Position Switch	289
14.1 Outline of Function	289
15. Indexing Axis Commands	290
16. Auxiliary Axis Parameters	291

1. Parameter Screens

1. Parameter Screens

The parameter input setting units are as follow.

Input unit "#1003 iunit"	Linear axis "#1017 rot"=0		Rotary axis "#1017 rot"=1
	Machine constant:mm "#1040 M_inch"=0	Machine constant:inch "#1040 M_inch"=1	
B	0.001 mm	0.0001 inch	0.001°
C	0.0001 mm	0.00001 inch	0.0001°

(1) User parameters

The following menus can be selected when the key

TOOL PARAM

 is pressed.

Menu	Details	Reference Section
WORK	The WORK OFFSET screen will open.	2.1 Workpiece Coordinate Offset
PROCESS	The PROCESS PARAM screen will open.	2.2 Process Parameters
		2.3 Control Parameters
		2.4 Axis Parameters
		2.5 Barrier Data
I/O PARAM	The I/O PARAM screen will open.	3.1 Base Parameters
		3.2 I/O Device Parameters
SETUP	The screen to set the setup parameters will open.	4. Setup Parameters

1. Parameter Screens

(2) Setup Parameters

The following menus can be selected when SETUP is selected. (Refer to the section "4. Setup Parameters" for details.

Menu	Details	Reference Section
BASE	The BASE SPEC. PARAM screen will open.	5. Base Specifications Parameters
AXIS SPEC	The AXIS SPEC PARAM screen will open.	6. Axis Specifications Parameters
SERVO	The SERVO PARAM screen will open.	7. Servo Parameters
SPINDLE	The SPINDLE BASE SPEC. PARAM screen will open.	8. Spindle Parameters
MC-ERR	The MC-ERR. CMP. screen will open.	9. Machine Error Compensation
PLC	The PLC DATA screen will open.	10. PLC Constants
MACRO	The MACRO FILE screen will open.	11. Macro List
PSW	The POSITION SWITCH screen will open.	12. Position Switch
IDX-PRM	The INDEXING AXIS PARAMETERS screen will open.	13. Indexing Axis Parameters
IDX-PSW	The INDEXING AXIS POSITION SWITCH screen will open.	14. Indexing Axis Position Switch
IDX-CMD	The INDEXING AXIS COMMANDS screen will open.	15. Indexing Axis Commands

(3) The following menus can be selected when the key ALARM
DIAGN is pressed.

Menu	Details	Reference Section
AUX-PRM	The AUX-PARA screen will open.	16. Auxiliary Axis Parameter

2. Machining Parameters
2.1 Workpiece Coordinate Offset

2. Machining Parameters

2.1 Workpiece Coordinate Offset

#	Parameter	Explanation	Setting range (unit)
54	G54 offset	Set the workpiece coordinate system and external workpiece coordinate offset values from G54 to G59. The workpiece coordinate system offset data can be set as an absolute value or incremental value. <div style="text-align: center;"> </div>	±99999.999 (mm)
55	G55 offset		
56	G56 offset		
57	G57 offset		
58	G58 offset		
59	G59 offset		
60	EXT offset		

2. Machining Parameters
2.2 Process Parameters

2.2 Process Parameters

<WRK COUNT> (No. of workpieces machined)

#	Item	Contents	Setting range (unit)
8001	WRK COUNT M	Set the M code that counts the No. of workpiece repeated machining. The No. will not be counted when set to 0.	0 to 99
8002	WRK COUNT	The current machining No. is displayed. Set the initial value.	0 to 999999
8003	WRK LIMIT	Set the maximum No. of workpieces machined. A signal is output to PLC when the No. of machining times is counted to this limit.	0 to 999999

<AUTO TLM> (Automatic tool length measurement)

#	Item	Contents	Setting range (unit)
8004	SPEED	Set the feedrate during automatic tool length measurement.	1 to 1000000 (mm/min)
8005	ZONE r	Set the distance between the measurement position and deceleration start point.	0 to 99999.999 (mm)
8006	ZONE d	Set the tolerable zone of the measurement position. If the sensor signal turns on in front of d before the measurement position, or if the signal does not turn on after d is passed, an alarm will occur.	0 to 99999.999 (mm)

<AUTO CORNER OVR> (Automatic corner override)

#	Item	Contents	Setting range (unit)
8007	OVERRIDE	Set the override value for automatic corner override.	0 to 100 (%)
8008	MAX ANGLE	Set the max. corner opening angle where deceleration should start automatically. If the angle is larger than this value, deceleration will not start.	0 to 180 (degrees)
8009	DSC. ZONE	Set the position where deceleration starts at the corner. Designate at which length point before the corner deceleration should start.	0 to 99999.999 (mm)

<T-TIP OFFSET> (Wear data input)

#	Item	Contents	Setting range (unit)
8010	ABS. MAX. (For L system only)	Set the max. value when inputting the tool wear compensation amount. A value exceeding this setting value cannot be set.	0 to 99.999 (mm)
8011	INC. MAX. (For L system only)	Set the max. value for when inputting the tool wear offset amount in the addition mode.	0 to 99.999 (mm)


2. Machining Parameters

2.2 Process Parameters

<FIXED C.> (Fixed cycle)

#	Item	Contents	Setting range (unit)
8012	G73 n (For M system only)	Set the return amount for G73 (step cycle).	0 to 99999.999 (mm)
8013	G83 n	Set the return amount for G83 (deep hole drilling cycle).	0 to 99999.999 (mm)
8014	CDZ-VALE (For L system only)	Set the screw cut up amount for G76, 78 (thread cutting cycle).	0 to 127 (0.1 lead)
8015	CDZ-ANGLE (For L system only)	Set the screw cut up angle for G76, 78 (thread cutting cycle).	0 to 89 (degrees)
8016	G71 MINIMUM (For L system only)	Set the minimum cut amount for the final cutting in G71, 72 (rough cutting cycle). If the final cutting amount is smaller than this value, the final cut will not be performed.	0 to 99.999 (mm)
8017	DELTA-D (For L system only)	Set the change amount to the command cut amount D for G71, 72 (rough cutting cycle). Each cut amount will be the value obtained by adding or subtracting this value from command D, and thus, the amount can be changed each cut.	0 to 99.999 (mm)
8018	G84/G74 return (For M system only)	Set up return length m at a G84/G74 pecking tap cycle. (Note) Set 0 to specify a usual tap cycle.	0 to 99.999 (mm)

<PRECISION> (High precision control)

#	Item	Contents	Setting range (unit)
8019	R COMP	Set up a compensation factor for reducing a control error in the reduction of a corner roundness and arch radius. Indicates a maximum control error (mm) in parentheses. The larger the setup value, the smaller the theoretical error will be. However, since the speed at the corner goes down, the cycle time is extended.	0 to 99 (%)
8020	DCC ANGLE	Set up the minimum value of an angle (external angle) that should be assumed to be a corner. When an inter-block angle (external angle) in high-precision mode is larger than the set value, it is determined as a corner and the speed goes down to sharpen the edge.  <p>If the set value is smaller than θ, the speed goes down to optimize the corner.</p> <p>(Note) If "0" is set, it will be handled as 5 degrees. The standard setting value is "0".</p>	0 to 30 (degrees) 0: The angle will be 5 degrees.

2. Machining Parameters
2.3 Control Parameters

2.3 Control Parameters

#	Item	Contents	Setting range (unit)
8101	MACRO SINGLE	Select the control of the blocks where the user macro command continues. 0: Do not stop while macro block continues. 1: Stop every block during signal block operation.	0/1
8102	COLL. ALM OFF	Select the interference (bite) control to the workpiece from the tool diameter during cutter compensation and nose R offset. 0: An alarm is output and operation stops when an interference is judged. 1: Changes the path to avoid interference.	0/1
8103	COLL. CHK OFF	Select the interference (bite) control to the work from the tool diameter during cutter compensation and nose R offset. 0: Performs interference check 1: Does not perform interference check	0/1
8105	EDIT LOCK B	Select the edit lock for program Nos. 8000 to 9999. 0: Program can be edited. 1: Editing of above program is prohibited.	0/1
8106	G46 NO REV-ERR (For L system only)	Select the control for the compensation direction reversal in G46 (nose R offset). 0: An alarm is output and operation stops when the compensation direction is reversed (G41 → G42, G42 → G41). 1: An alarm does not occur when the compensation direction is reversed, and the current compensation direction is maintained.	0/1
8107	R COMPENSATION	0: In arc cutting mode, the machine moves to the inside because of a delay in servo response to a command, making the arc smaller than the command value. 1: In arc cutting mode, the machine compensates the movement to the inside because of a delay in servo response to a command	0/1
8108	R COMP Select	Specify whether to perform arc radius error correction over all axes or axis by axis. 0: Perform correction over all axes. 1: Perform correction over axis by axis. (Note) This parameter is effective only when "#8107 R COMPENSATION" is 1.	0/1
8109	HOST LINK	Not used.	0

2. Machining Parameters
2.4 Axis Parameters

2.4 Axis Parameters

#	Item	Contents	Setting range (unit)
8201	AX. RELEASE	Select the function to remove the control axis from the control target. 0: Control as normal 1: Remove from control target	0/1
8202	OT-CHECK OFF	Select the stored stroke limit function set in #8204 and #8205. 0: Stored stroke limit valid 1: Stored stroke limit invalid	0/1
8203	OT-CHECK-CANCEL	When the simple absolute position method ("#2049 type" is 9) is selected, the stored stroke limits I, II (or IIB) and IB will be invalid until the first reference point return is executed after the power is turned on. 0: Stored stroke limit II valid (according to #8202) 1: Stored stroke limit II invalid (Note) This setting (#8203) affects all the stored stroke limits.	0/1
8204	OT-CHECK-N	Set the coordinates of the (–) direction in the moveable range of the stored stroke limit II or the lower limit coordinates of the prohibited range of stored stroke limit IIB. If the sign and value are the same as #8205 (other than "0"), the stored stroke limit II (or IIB) will be invalid. If the stored stroke limit IIB function is selected, the prohibited range will be between two points even when #8204 and #8205 are set in reverse. When II is selected, the entire range will be prohibited.	–99999.999 to +99999.999 (mm)
8205	OT-CHECK-P	Set the coordinates of the (+) direction in the moveable range of the stored stroke limit II or the upper limit coordinates of the prohibited range of stored stroke limit IIB.	–99999.999 to +99999.999 (mm)
8206	TOOL CHG. P	Set the coordinates of the tool change position for G30. n (tool change position return). Set with coordinates in the basic machine coordinate system.	–99999.999 to +99999.999 (mm)
8207	G76/87 IGNR (For M system only)	Select the shift operation at G76 (fine boring) and G87 (back boring). 0: Shift effective 1: No shift	0/1

2. Machining Parameters
2.5 Barrier Data

#	Item	Contents	Setting range (unit)
8208	G76/87 (–) (For M system only)	Specify the shift direction at G76 and G87. 0: Shift to (+) direction 1: Shift to (–) direction	0/1
8209	G60 SHIFT (For M system only)	Set the last positioning direction and distance for a G60 (uni-directional positioning) command.	–99999.999 to +99999.999 (mm)
8210	OT INSIDE	The stored stroke limit function set in #8204 and #8205 prevents the machine from moving to the inside or outside of the specified range. 0: Inhibits outside area. (select stored stroke limit II.) 1: Inhibits inside area. (select stored stroke limit II B.)	0/1

2.5 Barrier Data

#	Item	Contents	Setting range (unit)
8300	P0 (For L system only)	Set the reference X-coordinates of the chuck and the tail stock barrier. Set the center coordinate (Radius value) of workpiece by the basic machine coordinate system.	–99999.999 to +99999.999 (mm)
8301	P1	Set the area of the chuck and tail stock barrier. (Radius value) Set the coordinate value from the center of workpiece for X-axis. Set the coordinate value by basic machine coordinate system for Z-axis.	–99999.999 to +99999.999 (mm)
8302	P2		
8303	P3		
8304	P4		
8305	P5		
8306	P6 (For L system only)		

3. I/O Parameters
3.1 Base Parameters

3. I/O Parameters

3.1 Base Parameters

<I/O>	#	<PORT No.>	#	<DEV. No.> <DEV. NAME>
		Specify the board No. to which the serial input/output device is connected to each application.		Set the input/output device No. for each application. The device Nos. are 0 to 4 and correspond to the input/output device parameters. The device name set in the input/output device parameter is also displayed for identification.
DATA IN	9001	Specify the port for inputting the data such as machine program and parameters.	9002	Specify the No. of the device that inputs the data.
DATA OUT	9003	Specify the port for outputting the data such as machine program and parameters.	9004	Specify the No. of the device that outputs the data.
TAPE MODE	9005	Specify the input port for running with the tape mode.	9006	Specify the No. of the device to be run with the tape mode.
MACRO PRINT	9007	Specify the output port for the user macro DPRINT command.	9008	Specify the No. of the device for the DPRINT command.
PLC IN/OUT	9009	Specify the port for inputting/outputting various data with PLC.	9010	Specify the No. of the device for the PLC input/output.
REMOTE PROG IN	9011	Not used.	9012	Not used.

3. I/O Parameters
3.2 I/O Device Parameters

3.2 I/O Device Parameters

Parameters for up to five types of input/output devices can be set in DEV <0> to <4>.

(Note) The parameters are set for each device.

9101 ~	Set the same settings for device 0.
9201 ~	Set the same settings for device 1.
9301 ~	Set the same settings for device 2.
9401 ~	Set the same settings for device 3.
9501 ~	Set the same settings for device 4.

#	Item	Contents	Setting range (unit)
9101 9201 9301 9401 9501	DEVICE NAME 0 DEVICE NAME 1 DEVICE NAME 2 DEVICE NAME 3 DEVICE NAME 4	Set the device name corresponding to the device No. Set a simple name for quick identification.	Use alphabet characters, numerals and symbols to set a name within 3 characters.
9102 9202 9302 9402 9502	BAUD RATE	Set the serial communication speed.	1: 9600 (bps) 2: 4800 3: 2400 4: 1200 5: 600 6: 300 7: 150
9103 9203 9303 9403 9503	STOP BIT	Set the stop bit length used in the start-stop system.	1: 1 (bit) 2: 1.5 3: 2
9104 9204 9304 9404 9504	PARITY CHECK	Specify whether to add the parity check bit to the data during communication.	0: Parity bit not added 1: Parity bit added
9105 9205 9305 9405 9505	EVEN PARITY	Specify the odd or even parity when it is added to the data.	0: Odd parity 1: Even parity
9106 9206 9306 9406 9506	CHR. LENGTH	Set the length of the data bit.	0: 5 (bit) 1: 6 2: 7 3: 8

3. I/O Parameters
3.2 I/O Device Parameters

#	Item	Contents	Setting range (unit)
9107 9207 9307 9407 9507	TERMINATOR TYPE	The code to terminate data reading can be selected.	0 and 3: EOR 1 and 2: EOB or EOR
9108 9208 9308 9408 9508	HAND SHAKE	Specify the transmission control method. The method will be no procedure if a value except 1 to 3 is set.	1: RTS/CTS method (This method can be used only for SIO2.) 2: No procedure (No handshaking) 3: DC code method
9109 9209 9309 9409 9509	DC CODE PARITY	Specify the DC code when the DC code method is selected.	0: No parity to DC code (DC3 = 13H) 1: DC code with parity (DC3 = 93H)
9111 9211 9311 9411 9511	DC2/DC4 OUTPUT	Specify the DC code handling when outputting data to the output device.	DC2 / DC4 0: None / None 1: Yes / None 2: None / Yes 3: Yes / Yes
9112 9212 9312 9412 9512	CR OUTPUT	Specify whether to insert the <CR> code just before the EOB (L/F) code during output.	0: Do not add 1: Add
9113 9213 9313 9413 9513	EIA Output	In data output mode, select the ISO or EIA code for data output. In data input mode, the ISO and EIA codes are identified automatically.	0: ISO code output 1: EIA code output
9114 9214 9314 9414 9514	FEED CHR.	Specify the length of the tape feed to be output at the start and end of the data during tape output.	0 to 999 (characters)
9115 9215 9315 9415 9515	PARITY V	Specify whether to check the parity of the No. of characters in block during data input. The No. of characters is factory-set so that the check is valid at all times.	0: Do not perform parity V check 1: Perform parity V check

3. I/O Parameters
3.2 I/O Device Parameters

#	Item	Contents	Setting range (unit)
9116 9216 9316 9416 9516	TIME-OUT (s)	Set the time out time to detect an interruption in communication. The time out is not checked when 0 is set, so the waiting time will be infinite. The screens cannot be changed during the waiting time. Set this time to 10 as the standard.	0 to 30 (s)
9117 9217 9317 9417 9517	DR OFF	Specify whether to check the DR data at the data input/output.	0: DR valid 1: DR invalid
9118 9218 9318 9418 9518	DATA ASC II	0: Output in ISO/EIA code (Depends on whether #9113, #9213, #9313, #9413, or #9513 EIA output parameter is set up) 1: Output in ASC II code	0/1
9119 9219 9319 9419 9519	INPUT FORM	Specify the mode for input (collation). 0: Standard input (Data from the very first EOB is handled as significant information.) 1: EOBs following the first EOB of the input data are skipped until data other than EOB is input.	0/1
9121 9221 9321 9421 9521	EIA CODE [When outputting with the EIA codes, special ISO codes not included in EIA can be output with alternate codes. For each special code, designate a code (as a hexadecimal) that is not duplicated with existing EIA codes. (Continued on the next page.)	0 to FF (hexadecimal)
9122 9222 9322 9422 9522]		
9123 9223 9323 9423 9523	#		
9124 9224 9324 9424 9524	*		

3. I/O Parameters
3.2 I/O Device Parameters


#	Item	Contents	Setting range (unit)
9125 9225 9325 9425 9525	=	(Continued from the previous page.)	
9126 9226 9326 9426 9526	:		
9127 9227 9327 9427 9527	\$		
9128 9228 9328 9428 9528	!		

4. Setup Parameters

Pressing the menu key displays the OPEN SETUP PARAM screen.

The system's basic parameters are normally hidden as setup parameters to prevent mistaken operations and to simplify the display.

The setup parameters can be displayed and set by making a declaration to open the setup parameters on this screen.



- 1) Select the setup parameter.

Key-in in # (), and then press .

The basic specification parameter screen appears and the normally hidden setup parameter menu will display.

The required menu can be selected to display and set the setup parameters.

- 2) Cancel the setup parameter selection.

Key-in in # (), and then press .

The setup parameter menu will disappear.

(Note) The setup parameters are not displayed when the power is turned on.

Refer to "5. Base Specifications Parameters" and following for details on the setup parameters. Be sure to turn off the power supply after selecting the setup parameter.

5. Base Specifications Parameters

5. Base Specifications Parameters

After setting up the parameter (PR) listed in the table, turn off the NC power. To validate the parameter, turn on the power again.

#	Items		Details	Setting range (unit)								
1001 (PR)	SYS_ON	Part system validation setup	Specify the presence of the PLC axes and the 1st to 7th part systems with 1 or 0.	0: Not used 1: Used								
1002 (PR)	axisno	Number of axes	Set No. of axes in each part system and the No. of PLC axes. Set so that the total of the NC axes and PLC axes is less than the maximum number of controllable axes.	0 to 14								
1003 (PR)	iunit	Input setup unit	Specify the input setting value for each part system and the PLC axis. The parameter units will follow this specification.	B: 1 μm C: 0.1 μm								
1013	axname	Axis name	Specify each axis' name address with an alphabetic character. Use the characters X, Y, Z, U, V, W, A, B or C. Do not specify the same address in one part system. The same address can be specified as the other part system. The PLC address does not need to be set. (The axis name is displayed as 1 and 2.)	Axis addresses such as X, Y, Z, U, V, W, A, B, and C								
1014	incax	Increment command axis name	When specifying the program movement rate's absolute or incremental method with an address, specify the incremental command axis name address with an alphabetic character. The address that can be used is the same as "#1013 axname". Specify an address that is different from that #1013. Setting is not required if absolute/incremental command with addresses is not performed ("#1076 AbsInc" = 0).									
1015 (PR)	cunit	Command unit	Specify the minimum unit of the program movement amount. cunit Movement amount for movement command 1 10: 0.001 mm (1 μm) 100: 0.01 mm (10 μm) 1000: 0.1 mm (100 μm) 10000: 1.0 mm If there is a decimal point in the movement command, the decimal point position will be handled as 1mm regardless of this setting.	<table border="1" style="margin-left: auto; margin-right: auto;"> <tbody> <tr> <td style="text-align: center;">10</td> <td style="text-align: center;">1 μm</td> </tr> <tr> <td style="text-align: center;">100</td> <td style="text-align: center;">10 μm</td> </tr> <tr> <td style="text-align: center;">1000</td> <td style="text-align: center;">100 μm</td> </tr> <tr> <td style="text-align: center;">10000</td> <td style="text-align: center;">1 mm</td> </tr> </tbody> </table>	10	1 μm	100	10 μm	1000	100 μm	10000	1 mm
10	1 μm											
100	10 μm											
1000	100 μm											
10000	1 mm											
1016 (PR)	iout	Inch output	Specify whether the machine system (ball screw pitch, position detection unit) is an inch unit system or metric unit system.	0: Metric unit system 1: Inch unit system								

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)
1017 (PR)	rot Rotational axis	Specify whether the axis is a rotary axis or linear axis. For the rotary axis, the position display will be 360 degrees, and the axis will return to 0 degrees. If the position display is to be continuously displayed even with the rotary axis, set the axis as a linear axis	0: Linear axis 1: Rotary axis
1018 (PR)	ccw Motor CCW	Specify the direction of the motor rotation to the command direction. 0: Rotates clockwise (looking from motor shaft) with the forward rotation command. 1: Rotates counterclockwise (looking from motor shaft) with the forward rotation command.	0: Rotates clockwise 1: Rotates counterclockwise
1019 (PR)	dia Diameter specification axis	Specify whether the program movement amount is to be commanded with the diameter dimension or as movement amount. When the movement amount is commanded with the diameter dimensions, 5mm will be moved when the command is a movement distance of 10mm. The movement amount per pulse will also be halved during manual pulse feed. Among parameters concerning length, the tool length, the wear compensation amount and the workpiece coordinate offset are displayed in diameter value when diameter is specified, but other parameters are always displayed in radius value.	0: Command with movement amount 1: Command with diameter dimension
1020 (PR)	sp_ax Spindle Interpolation	Specify 1 when the NC control axis is used as the spindle.	0: The NC control axis is used as the servo axis. 1: The NC control axis is used as the spindle.

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)
1025	I_plane Initial plane selection	Specify the plane to be selected when the power is turned on or reset. When 0 is specified, 1 is assumed (X-Y plane).	1: X-Y plane (G17 command state) 2: Z-X plane (G18 command state) 3: Y-Z plane (G19 command state)
1026 1027 1028	base_I Base axis I base_J Base axis J base_K Base axis K	Specify the basic axis address that composes the plane. Specify the axis address set in "#1013 axname". Set the axis name even when there is no need to configure a plane, such as the case of 2-axis specifications. Normally, when X, Y and Z are specified respectively for base_I,_J,_K, the following relation will be established: G17: X-Y G18: Z-X G19: Y-Z Specify the desired address to set an axis address other than the above.	Control axis addresses such as X, Y, and Z
1029	aux_I Flat axis I	If there is an axis parallel to "#1026 base_I", specify that axis address.	Control axis addresses such as X, Y, and Z
1030	aux_J Flat axis J	If there is an axis parallel to "#1027 base_J", specify that axis address.	Control axis addresses such as X, Y, and Z
1031	aux_K Flat axis K	If there is an axis parallel to "#1028 base_K", specify that axis address.	Control axis addresses such as X, Y, and Z

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)																											
1037	cmdtyp Command type	<p>Specify the program G code series and compensation type.</p> <table border="1" style="width: 100%; border-collapse: collapse; margin-bottom: 10px;"> <thead> <tr> <th style="width: 10%;">cmdtyp</th> <th style="width: 40%;">G code series</th> <th style="width: 50%;">Compensation type</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">1</td> <td>System 1 (for M)</td> <td>Type A (one compensation amount for one compensation number)</td> </tr> <tr> <td style="text-align: center;">2</td> <td>System 2 (for M)</td> <td>Type B (shape and wear amounts for one compensation number)</td> </tr> <tr> <td style="text-align: center;">3</td> <td>System 2 (for L)</td> <td>Type C (two kinds of compensation amount of shape and wear per compensation No.)</td> </tr> <tr> <td style="text-align: center;">4</td> <td>System 3 (for L)</td> <td>Same as above</td> </tr> <tr> <td style="text-align: center;">5</td> <td>System 4 (for special L)</td> <td>Same as above</td> </tr> <tr> <td style="text-align: center;">6</td> <td>System 5 (for special L)</td> <td>Same as above</td> </tr> <tr> <td style="text-align: center;">7</td> <td>System 6 (for special L)</td> <td>Same as above</td> </tr> <tr> <td style="text-align: center;">8</td> <td>System 7 (for special L)</td> <td>Same as above</td> </tr> </tbody> </table> <p>There are some items in the specifications that can be used or cannot be used according to the value set in this parameter. The file structure may also change depending on the compensation data type. Thus, after changing this parameter, initialize the system with "#1060 SETUP".</p> <pre style="font-family: monospace; margin-left: 20px;"> # (1060) DATA (1) () <input style="border: 1px solid black; padding: 2px 10px;" type="text" value="INPUT"/> ↓ "BASE PARA SET? (Y/N)" : N <input style="border: 1px solid black; padding: 2px 10px;" type="text" value="INPUT"/> ↓ "FORMAT? (Y/N)" : Y <input style="border: 1px solid black; padding: 2px 10px;" type="text" value="INPUT"/> ↓ "SETUP COMPLETE" </pre> <p>(Note) The machining program is cleared with the above operations. Back up necessary machining programs in an external memory before initializing.</p>	cmdtyp	G code series	Compensation type	1	System 1 (for M)	Type A (one compensation amount for one compensation number)	2	System 2 (for M)	Type B (shape and wear amounts for one compensation number)	3	System 2 (for L)	Type C (two kinds of compensation amount of shape and wear per compensation No.)	4	System 3 (for L)	Same as above	5	System 4 (for special L)	Same as above	6	System 5 (for special L)	Same as above	7	System 6 (for special L)	Same as above	8	System 7 (for special L)	Same as above	1 to 8
cmdtyp	G code series	Compensation type																												
1	System 1 (for M)	Type A (one compensation amount for one compensation number)																												
2	System 2 (for M)	Type B (shape and wear amounts for one compensation number)																												
3	System 2 (for L)	Type C (two kinds of compensation amount of shape and wear per compensation No.)																												
4	System 3 (for L)	Same as above																												
5	System 4 (for special L)	Same as above																												
6	System 5 (for special L)	Same as above																												
7	System 6 (for special L)	Same as above																												
8	System 7 (for special L)	Same as above																												
1038	plcsel Ladder selection	Specify the PLC type.	0 to 2																											

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)
1039	spinno Number of spindles	Specify the existence of a spindle. 0: No spindle 4: Four spindles 1: One spindle 5: Five spindles 2: Two spindles 6: Six spindles 3: Three spindles 7: Seven spindles	0 to 7
1040 (PR)	M_inch Constant input (inch)	Specify the parameter unit system for the position and length.	0: Metric system 1: Inch system
1041 (PR)	I_inch Initial state (inch)	Specify the unit system for the program movement amount when the power is turned on or reset and for position display.	0: Metric system 1: Inch system
1042 (PR)	pcinch PLC axis command (inch)	Specify the unit system for the commands to the PLC axis.	0: Metric system 1: Inch system
1043	lang Select language displayed	Specify the display language. 0 : Japanese display 1 : English display 21: Polish display (Note) If no character package is available for a specified language, the screen is displayed in English.	0/1/21
1044 (PR)	auxno MR-J2-CT connections	Specify the number of MR-J2-CT axes connected. As for C6/C64 system, up to 5 axes of MR-J2-CT can be connected, thus, the setting range is 0 to 5.	0 to 7

(Note) Selection of inch and metric unit


When set value of "#1041 I_inch" is changed, the unit of length is changed after reset.

Among parameters concerning length, following items are not changed automatically, therefore change the set values to agree with the new unit system when the unit system is changed.

Tool compensation amount (Tool length compensation amount, tool wear compensation amount and tool tip compensation amount)			
Workpiece coordinate offset			
Machining parameter	#8004 SPEED	#8013 G83n	#8052 PULL UP
	#8005 ZONE r	#8016 G71 MINIMUM	#8053 G73U
	#8006 ZONE d	#8017 G71 DELTA-D	#8054 W
	#8009 DSC. ZONE	#8018 G84/G74n	#8056 G74 RETRACT
	#8010 ABS. MAX.	#8027 Toler-1	#8057 G76 LAST-D
	#8011 INC. MAX.	#8028 Toler-2	
	#8012 G73n	#8051 G71 THICK	
Axis parameter	#8204 OT-CHECK-N		
	#8205 OT-CHECK-P		
	#8206 TOOL CHG.P		
	#8209 G60 Shift		
Barrier data	#8300 – #8306		
Basic specification parameter	#1084 RadErr		

#8004 SPEED is 10 inches/min. unit for the inch system.

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)
1060	SETUP Activate setup processing	<p>Execute the functions required for initializing the system.</p> <p style="text-align: center;">1: Execute one-touch setup</p> <div style="text-align: center;">  <pre> graph TD Start["# (1060) Data(1)()"] --> Input1[INPUT] Input1 --> Display1["BASE PARA. SET? (Y/N) is displayed."] Display1 --> InitParam["To initialize the parameters."] Display1 --> RetainParam["To retain the current parameters."] InitParam --> InputY1[Y] InputY1 --> InputBox1[INPUT] RetainParam --> InputN1[N] InputN1 --> InputBox2[INPUT] Note1["The parameters are initialized according to the setting values in #1001 to #1043."] Display2["FORMAT? (Y/N) is displayed."] InitFile["To initialize the machining program file and tool offset file."] RetainFile["To retain the current machining program file and tool offset file."] InputY2[Y] --> InputBox3[INPUT] InputN2[N] --> InputBox4[INPUT] Note2["The above files are initialized and the standard canned cycle program is input."] Display3["SETUP COMPLETE" is displayed."] </pre> </div> <p>(Note) Most setup parameters will be initialized with one-touch setup, so confirm the data before executing. This parameter will automatically be set to 0 when the power is turned on.</p>	1
1061 (PR)	intabs Manual ABS updating	<p>Defines whether to update the absolute value data during automatic handle interrupt. This parameter is valid only when "#1145 I_abs" is set to 1.</p>	<p>0: Does not update (shift coordinates by the amount of the interruption)</p> <p>1: Updates (same coordinates as when interrupt did not occur will be applied.)</p>

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)															
1062	T_cmp Tool offset function	Specify whether the tool length offset and wear compensation is valid during T command execution. <table border="1" style="margin: 10px auto; width: 80%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: center;">Setting value</th> <th style="text-align: center;">Tool length offset</th> <th style="text-align: center;">Wear compensation</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">0</td> <td style="text-align: center;">Valid</td> <td style="text-align: center;">Valid</td> </tr> <tr> <td style="text-align: center;">1</td> <td style="text-align: center;">Valid</td> <td style="text-align: center;">Invalid</td> </tr> <tr> <td style="text-align: center;">2</td> <td style="text-align: center;">Invalid</td> <td style="text-align: center;">Valid</td> </tr> <tr> <td style="text-align: center;">3</td> <td style="text-align: center;">Invalid</td> <td style="text-align: center;">Invalid</td> </tr> </tbody> </table>	Setting value	Tool length offset	Wear compensation	0	Valid	Valid	1	Valid	Invalid	2	Invalid	Valid	3	Invalid	Invalid	0 to 3
Setting value	Tool length offset	Wear compensation																
0	Valid	Valid																
1	Valid	Invalid																
2	Invalid	Valid																
3	Invalid	Invalid																
1063	mandog Manual dog-type	The initial return to the reference point is performed with dog-type return after the power is turned on, and the coordinate system is established. Specify the manual reference point return method after the coordinate system is established with this parameter. (This setting is not required when using absolute position detection.)	0: High speed return 1: Dog-type															
1064 (PR)	svof Error correction	Specify whether to correct the error when the servo is off.	0: Does not correct the error 1: Corrects the error															
1065	JOG_H JOG response type	Set up an improved JOG response type. 0: Conventional specification The system is started and stopped by signals via ladder without reference to external input signals. 1: Type 1 The system is started up and stopped by external signals. 2: Type 2 The system is started up and stopped by performing the AND operation for external signals and signals via ladder. 3: Type 3 The system is started up when signals via ladder rise. It is stopped when external signals and signals via ladder fall. 4: Type 4 Reference point return mode: The system is started up and stopped by signals via ladder without reference to external input signals (conventional specification). Non-reference point return mode: The system is started up and stopped by performing AND for external signals and signals via ladder (type 2).	0 to 4															

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)
1066	JOG_HP Select JOG activation (+) device	Specify the number of the device that inputs +JOG activation signals. The device type is specified by "#1071 JOG_D". The effective range of set values vary depending on the device type. A value outside of the effective range is invalid if specified. (Note) The setting range of this parameter has been expanded on the software Ver.D0 and later.	X: 0000 to 03FF (hexadecimal) M: 0000 to 8191 (decimal)
1067	JOG_HN Select JOG activation (-) device	Specify the number of the device that inputs -JOG activation signals. The device type is specified by "#1071 JOG_D". The effective range of set values vary depending on the device type. A value outside of the effective range is invalid if specified. (Note) The setting range of this parameter has been expanded on the software Ver.D0 and later.	X: 0000 to 03FF (hexadecimal) M: 0000 to 8191 (decimal)
1068 (PR)	slavno Slave axis number	Specify the axis number of a slave axis to be synchronized. The axis number is an NC number excluding the spindle and PLC axis. Two or more slave axes cannot be set up for one master axis. This parameter "slavno" cannot be set up for a slave axis. A multiple part system cannot be set up so that the relation between the master and slave axes extends over a part system.	0: No slave axis 1 to 6: First to sixth axes
1069 (PR)	no_dsp Axis with no counter display	Set up an axis that displays no counter. This option is valid on the counter display screen (e.g. POSITION screen).	0: Displays the counter 1: Does not display the counter.
1070	axoff Axis removal	Define an axis that enables axis removal control.	0: Disables axis removal. 1: Enables axis removal
1071 (PR)	JOG_D ±JOG activation signal device name	Specify the number of the device that inputs ±JOG activation signals. 0 : X device 1 or 2: M device Set the JOG_HP (#1066) and JOG_HN (#1067) parameters according to this device specification parameter. (Note) The setting range of #1066 and #1067 parameters has been expanded on the software Ver.D0 and later.	0 to 2

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)
1073	I_Absm Initial absolute value	Specify the absolute value/incremental value mode for when the power is turned on or reset.	0: Incremental value command mode 1: Absolute value command mode
1074	I_Sync Initial synchronous feed	Specify the feedrate specification mode for when the power is turned on or reset. 0: Asynchronous feed (feed per minute) 1: Synchronous feed (feed per rotation)	0: Asynchronous feed 1: Synchronous feed
1075	I_G00 Initial G00	Specify the linear command mode for when the power is turned on or reset. 0: Linear interpolation (G01 command state) 1: Positioning (G00 command state)	0: Linear interpolation 1: Positioning
1076	AbsInc (For L system only) ABS/INC address	The absolute value/incremental commands can be issued by using the absolute value address and incremental value address for the same axis. 0: Absolute/incremental with G command 1: Absolute/incremental with address code (The "#1013 axname" address will be the absolute value command, and "#1014 incax" address will be the incremental value command)	0: Absolute/incremental with G command 1: Absolute/incremental with address code
1077	radius Incremental command for diameter specification axis	Specify if the diameter specification axis' ("#1019 dia" is set to 1) incremental value command uses the diameter value or radius value	0: Diameter value 1: Radius value
1078	Decpt2 Decimal point type 2	Specify the unit of position commands that do not have a decimal point. 0: The min. input command unit is used (follows "#1015 cunit") 1: 1mm (or 1inch) unit is used	0: The min. input command unit is used 1: 1mm (or 1inch) unit is used
1079	F1digit Validate F1 digit	Specify whether to execute the F command with a 1-digit code command or with a direct numerical command. 0: Direct numerical command (command feedrate during feed per minute or rotation) 1: 1-digit code command (feedrate specified with "#1185 spd_F1" to "#1189 F5")	0: Direct numerical command 1: 1-digit code command

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)	
1080	Dril_Z (For M system only)	Specify boring axis	Specify a fixed-cycle boring axis. 0: Uses an axis perpendicular to the selected plane as the boring axis. 1: Uses the Z axis as the boring axis regardless of the selected plane.	0/1
1081	Gmac_P	Give priority to G code parameter	Specify the G code priority relationship during the macro call with the G command. 0: G code used in system is priority 1: Registered G code for call out is priority	0/1
1082	Geomet (For L system only)	Geometric	Specify the validity of the geometric function. As the designated address code is used exclusively for geometric, if "A" or "C" is used for the axis address or 2nd miscellaneous command code, "A" that is the axis address may be handled as the geometric's angle specification. Take special care to the setting of the axis name, etc., when using this function.	0: Invalid 1: Valid
1084	RadErr	Arc error	Specify the tolerable error range when a deviation occurs in the end point and center coordinate in the circular command.	0 to 1.000 (mm)
1085	G00Drm	G00 dry run	Specify whether to apply dry run (feed with manual setting speed instead of command feedrate) to the G00 command. 0: Does not apply to G00 (moves at rapid traverse feedrate) 1: Applies to G00 (moves at manual set feedrate)	0/1
1086	G0Intp	G00 non-interpolation	Specify the G00 movement path type 0: Moves linearly toward the end point (interpolation type) 1: Moves to the end point of each axis at the rapid traverse feedrate for each axis (non-interpolation)	0/1
1087	G96_G0	Constant surface speed control by rapid traverse feed command	Specify how to handle the cycle speed for the G00 command when using the constant surface speed control function. 0: Calculates the cycle speed constantly even during G00 movement. 1: Calculates the cycle speed at the block end point in the G00 command.	0/1

5. Base Specifications Parameters

#	Items		Details	Setting range (unit)
1088	G30SL	Disable G30 soft limit	Specify how to handle the soft limit during G30 (2nd reference point return) movement. 0: Soft limit valid during G30 movement 1: Soft limit invalid during G30 movement	0/1
1089	Cut_RT	Short cut for rotary axis	Specify how to handle the short cut control for the rotary axis ("#1017 rot" is set to 1). 0: No short cut (move toward end point) 1: Uses short cut (when using the absolute value command, move in the direction where the movement amount will be 180 degrees or less)	0: No short cut 1: Use short cut
1090	Lin_RT	Linear rotary axis	Specify how to handle a command for the rotary axis that exceeds 360 degrees. 0: For absolute value commands that exceed 360 degrees, the value will be converted into a remainder of 360 degrees and the axis will move. Example: If the command is 420 degrees, the applied value will be 60 degrees. 1: For absolute value commands that exceed 360 degrees, the axis will move in the same manner as a linear axis. Example: If the command is 420 degrees, the axis will pass the 360 degree position and will move to the 60 degree position.	0/1
1091	Mpoint	Ignore middle point	Specify how to handle the middle point during G28 and G30 reference point return. 0: Moves to the reference point after passing the middle point designated in the program. 1: Ignores the middle point designated in the program and move straight to the reference point.	0/1
1092	Tchg_A	Replace tools for additional axis	Specify the movement of the additional axis during tool change position return. 0: The additional axis does not move with the tool change position return command. 1: After returning the standard axis with the tool change position return command, the additional axis also returns to the tool change position.	0/1
1093	Wmvfin	Waiting method between part systems	Specify the method for waiting between part systems. When the movement command is found in the wait command ! block: 0: Waits before executing movement command 1: Waits after executing movement command	0/1
1094	TI_SBK (for L system only)	Select life count for single block	Select whether to count the data units to be used for a single block when using the tool life management II function (lathe system). 0: Does not count the data units. 1: Count the data units.	0/1

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)
1095	T0tfof TF output	Select how to handle TF for T00 command. 0: TF is output. 1: TF is not output	0/1
1096	T_Ltyp (For L system only) Tool life management type	Specify the tool life management type.	1: Life management type I 2: Life management type II
1097	T1digit Tool wear compensation number 1-digit command	Specify the No. of digits in the tool wear compensation No. in the T command. 0: The 2 high-order digits are the tool No., and the 2 low-order digits are the wear compensation No. 1: The 3 high-order digits are the tool No., and the 1 low-order digit is the wear compensation No. This parameter will be fixed to 0 when tool life management II is selected.	0/1
1098	Tlno. Tool length offset number	Specify the No. of digits in the tool length offset No. in the T command. 0: The 2 or 3 high-order digits are the tool No. The 2 or 1 low-order digits are the tool length offset and wear compensation Nos. 1: The 2 or 3 high-order digits are the tool No. and tool length offset Nos. The 2 or 1 low-order digits are the wear compensation No.	0/1
1099	Treset Cancel tool wear compensation amount	Specify how to handle tool compensation vector when resetting system. 0: Clears the tool length and wear compensation vectors when resetting. 1: Saves the tool length and wear compensation vectors when resetting. When the values are cleared, the compensation will not be applied, so the axis will move the compensation amount in the next compensation operation. When the values are saved, the compensation will be applied, so the axis will shift the differential amount of the compensation amount in the next compensation operation.	0: Clears 1: Saves

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)
1100	Tmove Tool wear compensation	Specify the period to perform tool length offset and wear compensation. 0: Compensate when T command is executed. 1: Superimpose and compensate with the movement command in the block where the T command is located. If there is no movement command in the same block, compensation will be executed after the movement command is superimposed in the next movement command block. 2: Compensate when the T command is executed. 1: Superimpose and compensate a tool length offset with the movement command in the same block. If there is no movement command in the same block, compensation will be executed after the movement command is superimposed in the next movement command block.	0 to 2
1101	Tabsmv Tool wear compensation method	Specify the type of movement command when "#1100 Tmove" is set to 1. 0: Compensate regardless of the movement command type. 1: Compensate only at the movement command in the absolute value command.	0: Compensate regardless of the command type. 1: Compensate only with the absolute value command.
1102	tIm (For L system only) Manual tool length measuring system	Specify the measurement method for manual tool measurement I. 0: Align tool with basic position 1: Input measurement results	0: Basic position method 1: Measured value input method
1103	T_life Validate life management	Select the usage of the tool life management function.	0: Do not use. 1: Perform tool life management control.
1104	T_Com2 Tool command method 2	Select the command method for when "#1103 T_Life" is set to 1. 0: Handle the program tool command as the group No. 1: Handle the program tool command as the tool No.	0/1

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)
1105	T_Sel2 Tool selection method 2	Select the tool selection method for when "#1103 T_Life" is set to 1. 0: Select in order of registered No. from the tools used in the same group. 1: Select the tool with the longest remaining life from tools used in the same group and the unused tools.	0/1
1106	Tcount (For L system only)	Life management count	Specify the function when address N is omitted when inputting data (G10 L3 command) for tool life management function II. 0: Time specified input 1: No. of times specified input
1107	TlIfsc (For L system only)	Split life management display screen	Set up the number of groups to be displayed on the tool life management II (lathe system) screen. 0: Displayed group count 1 1: Displayed group count 2 2: Displayed group count 4
1108	TirectM (For L system only)	Life management re-count M code	Set up the M code for tool life management II (lathe system) re-count. 0 to 99
1109 (PR)	subs_M	Validate alternate M code	Select the user macro interrupt with the substitute M code. 0: Alternate M code invalid 1: Alternate M code valid
1110	M96_M	M96 alternate M code	Specify an M code to replace M96 when "#1109 subs_M" is set to 1.
1111	M97_M	M97 alternate M code	Specify an M code to replace M97 when "#1109 subs_M" is set to 1.
1112 (PR)	S_TRG	Validate status trigger system	Specify the validity conditions for the user macro interrupt signal. 0: Valid when interrupt signal (UIT) turns off to on. 1: Valid when interrupt signal (UIT) is ON. 0: Valid when interrupt signal (UIT) turns off to on. 1: Valid when interrupt signal (UIT) is ON.
1113 (PR)	INT_2	Validate interrupt method type 2	Specify the movement after user macro interrupt signal (UIT) input. 0: Execute interrupt program without waiting for block being executed to end. 1: Execute interrupt program after completing block being executed.

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)
1114	mcrint Macro argument initialization	Select whether to clear statements other than specified arguments by macro call. Also, select whether to clear local variables by power-on and resetting. 0: Delete non-specified arguments by macro call. 1: Retain non-specified arguments by macro call. 2: Retain non-specified arguments by macro call and clear local variables by power-on and resetting.	0/1/2
1115	thwait Waiting for thread cutting	Set the queue number during screw thread cutting when the chamfering is not valid.	0 to 99 (Approx. 4 ms.) Standard set value: 4
1116	G30SLM Invalidate soft limit (manual operation)	Enable this function when disabling the soft limit check function from the second to the fourth reference point return by manual operation.	0: Enable soft limit function. 1: Disable soft limit function.
1117	H_sens Handle response switch	Switch the handle response mode when feeding the handle. 0: Standard handle response 1: High-speed handle response	0/1
1118	mirr_A (For L system only) Select how to set up the length of tools on facing turret (double-turret mirror image)	Select one of the following two methods. 0: Set up the current length of tools on facing turret. 1: Set up a value, assuming that the tools on facing turret is in the same direction as that of those on the base turret.	0/1
1119	Tmiron (For L system only) Select the double-turret mirror image with T command	Select whether to validate the double-turret mirror image with the T command.	0: Invalid 1: Valid
1120 (PR)	TofVal Change macro variable	Specify whether to change the macro variable (tool offset) numbers for shape compensation and wear compensation. 0: Do not change. (Conventional specifications) 1: Change the shape and wear compensation variable numbers each for X, Z, and R.	0/1

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)
1121	edlk_c	Edit lock C	Specify whether to prohibit editing of program Nos. 9000 to 9999. 0: Editing possible 1: Editing prohibited
1122 (PR)	pglk_c	Program display lock	The display and search of program Nos. 9000 to 9999 can be prohibited. Specify whether to prohibit display and search. 0: Display and search is possible 1: Program details are not displayed 2: Program details are not displayed, and operation search is prohibited. The program details will not be displayed, but the program No. and sequence No. will display in the prohibited state.
1123	origin	Origin zero inhibition	Select whether to use the origin zero function. 0: Use 1: Do not use
1124	ofsfix	Fix tool wear compensation number	Specify whether to automatically increment the offset No. by 1 with the input or to display the No. as it is in the setting on the tool offset screen. 0: Increment the # No. by 1 when the input key is pressed. (Same as general parameters) 1: # No. does not change even if input key is pressed. When making settings in sequence, 0 is handier. When changing and setting repeatedly while adjusting one offset value, 1 is handier
1125	real_f	Actual feedrate display	Specify the feedrate display on the monitor screen. 0: Command speed 1: Real movement feedrate
1126	PB_G90		Not used. 0
1127	DPRINT	DPRINT alignment	Specify the alignment for printing out with the DPRINT function. 0: No alignment, data is printed with left justification. 1: Align the minimum digit and output.

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)	
1133	ofsmem	Select how to set up tool wear compensation screen	Select the number stored by previous setup when selecting the tool wear compensation screen. 0: Does not display the number when selecting the screen. 1: Displays the stored number when selecting the screen.	0/1
1134	LCDneg	LCD reverse display	Specify 1 to reverse the display on the 10.4-type monochrome LCD.	0: Normal display 1: Reverse display
1135	unt_nm	Unit name	Set up a unit name. Set up the unit name with 4 or less characters consisting of both alphabets and numbers. If 0 is set up, the unit name is not displayed.	4 or less characters consisting of both alphabets and numbers
1138	Pnosel		Not used.	0
1139	edtype	Edit type selection	Set up an edit type. 0: Screen edit type (M50 or equivalent operation) 1: Screen edit type (The screen of EDIT or MDI is changed automatically according to the selected operation mode.) 2: Word edit type (The screen of EDIT or MDI is changed automatically according to the selected operation mode.)	0/1/2
1140	Mn100	M code number	First number of M code that corresponds to setup number from 100 to 199.	0 to 99999999
1141	Mn200	M code number	First number of M code that corresponds to setup number from 200 to 299.	0 to 99999999
1142	Mn300	M code number	First number of M code that corresponds to setup number from 300 to 399.	0 to 99999999
1143	Mn400	M code number	First number of M code that corresponds to setup number from 400 to 499.	0 to 99999999
1144	mdlkof	MDI setup lock	Select whether to enable MDI setup in non-MDI mode.	0: Disable MDI setup 1: Enable MDI setup

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)																
1145	I_abs Manual ABS parameter	Specify how to handle the absolute position data during automatic handle interrupt. 0: Absolute position data is renewed if manual ABS switch is on. Data is not renewed if switch is off. 1: Follows the intabs state when "#1061 intabs" is valid.	0/1																
1146	Sclamp Spindle rotation clamp function	Specify how to handle the spindle rotation clamp function with the G92S command. 0: G92S command is handled as a clamp command only in the G96 state (during constant surface speed control). G92S will be handled as normal S command in G97 state (constant surface speed OFF). 1: The S command in the same block as G92 is constantly handled as a clamp command.	0/1																
1147	smin_V Minimum spindle rotation speed clamp type	Specify the type of spindle min. rotation speed clamp value. 0: Rotation speed setting 1: Output voltage coefficient setting Set the "#3023 smini" parameter according to this type setting.	0: Rotation speed setting 1: Output voltage coefficient setting																
1148	I_G611 Initial high precision	Specify the default mode after power-on or resetting. 0: G64 (cutting mode) 1: G61.1 (high precision control mode)	0/1																
1149	cireft Arc deceleration speed change	Specify whether to enable deceleration at the arc entrance or exit. 0: Disable 1: Enable	0/1																
1150	F1dc0 G00 feed forward filter	This parameter is used to filter acceleration changes at the start of rapid acceleration/deceleration. Specify the filters in bit units. <div style="text-align: center;"> <table style="border-collapse: collapse; margin: 0 auto;"> <tr> <td style="padding: 0 5px;">7</td><td style="padding: 0 5px;">6</td><td style="padding: 0 5px;">5</td><td style="padding: 0 5px;">4</td><td style="padding: 0 5px;">3</td><td style="padding: 0 5px;">2</td><td style="padding: 0 5px;">1</td><td style="padding: 0 5px;">0</td> </tr> <tr> <td style="border: 1px solid black; width: 20px; height: 15px;"></td> <td style="border: 1px solid black; width: 20px; height: 15px;"></td> <td style="border: 1px solid black; width: 20px; height: 15px;"></td> <td style="border: 1px solid black; width: 20px; height: 15px;"></td> <td style="border: 1px solid black; width: 20px; height: 15px;"></td> <td style="border: 1px solid black; width: 20px; height: 15px;"></td> <td style="border: 1px solid black; width: 20px; height: 15px;"></td> <td style="border: 1px solid black; width: 20px; height: 15px;"></td> </tr> </table> <div style="margin-left: 100px;"> </div> </div> 0: Common 1: Independent	7	6	5	4	3	2	1	0									bit1: 7.1 (ms) bit2: 14.2 (ms) bit3: 28.4 (ms) bit4: 56.8 (ms) If bit 1 to bit 4 are all 0 or two or more bits of bit 1 to bit 4 are 1, 3.5 ms is set up.
7	6	5	4	3	2	1	0												
1151	rstint Reset initial	Specify whether to initialize various modals by resetting. 0: Does not initialize. 1: Initializes.	0/1																

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)
1152	I_G20 Initial command unit	Specify whether the default mode after power-on or resetting, inch command or metric command mode. 0: Metric command (G21 command state) 1: Inch command (G20 command state) Valid when reset input is made. Related parameter: Bit 6 "Select setting and display unit" of #1226	0/1
1154 (PR)	pdoor Door interlock II (for each part system)	Specify whether to control door interlock II independently for each of the two part systems. When door interlock II is controlled for each part system of the two part systems, part system 1 is connected to SERVO1 of the base I/O unit and part system 2 is connected to SERVO2 of the base I/O unit. <div style="text-align: center;"> <p>C6/C64 unit</p> <pre> graph LR subgraph C6_C64_unit [C6/C64 unit] SERVO1[SERVO1] SERVO2[SERVO2] end SERVO1 --- AMP1_1[AMP] AMP1_1 --- AMP1_2[AMP] AMP1_2 --- AMP1_3[AMP] SERVO2 --- AMP2_1[AMP] AMP2_1 --- AMP2_2[AMP] AMP2_2 --- AMP2_3[AMP] AMP1_3 --- PS1[Part system 1] AMP2_3 --- PS2[Part system 2] </pre> </div> When the auxiliary axis (MR-J2-CT) is used, connect it to the SERVO2 side (after the spindle). This validates door interlock II of part system 2. 0: Do not use door interlock II independently for each part system. 1: Use door interlock II independently for each part system. When 0 is specified for this parameter, "Signal input device 1 for door interlock II (#1155 DOOR_m)" and "Device number 2 for door interlock II signal input (#1156 DOOR_s) are valid. When 1 is specified, "Signal input device 1 for door interlock II: for each part system (#1511 DOORPm)" and "Signal input device 2 for door interlock II: for each part system (#1512 DOORPs)."	0/1

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)	
1155	DOOR_m	Signal input device 1 for door interlock II	Set up a fixed device number (X??) for door interlock II signal input. A device number from X001 to X3FF can be set up. Device number 000 is invalid. Set up device number 100 when using no fixed device number for door interlock II signal input. (Note) The setting range of this parameter has been expanded on the software Ver.D0 and later. Related parameter: "#1154 pdoor" Door interlock II (for each part system)	000 to 3FF (hexadecimal)
1156	DOOR_s	Device number 2 for door interlock II signal input	Set up a fixed device number (X??) for door interlock II signal input. (Set up the same value as that of #1155.) (Note) The setting range of this parameter has been expanded on the software Ver.D0 and later. Related parameter: "#1154 pdoor" Door interlock II (for each part system)	000 to 3FF (hexadecimal)
1157	F0atrn	F0 automatic running	Not used.	
1158	F0atno	F0 automatic running program	Not used.	
1166	fixpro	Fixed cycle editing	Select whether to use the edit, program list, and data input/output functions for the fixed cycle or general program. 0: Editing, etc., of general program will be possible. 1: Editing, etc., of fixed cycle will be possible.	0/1
1167	e2rom		Not used.	
1168	test	Simulation test	Specify the test mode for the control unit. The test mode does not use reference point return, and tests with a hypothetical reference point return completed state. This is limited to test operation of the control unit itself, and must not be used when connected to the machine.	0: Normal operation mode 1: Test mode

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)																																																																																									
1169	system name Part system name	Set the name of each part system. This must be set when using the multiple part system. This name is displayed on the screen only when the part systems must be identified. Use a max. of four alphabetic characters or numerals.	A max. of four alphabetic characters or numerals.																																																																																									
1170	M2name Second miscellaneous code	Set this address code when using the 2nd miscellaneous command. Set an address with A, B and C that is not used with "#1013 axname" or "#1014 incax".	A, B, C																																																																																									
1171	taprov Tap retract override	Set the tap retract override value for the synchronous tap.	1 to 100 (%)																																																																																									
1172	tapovr Tap retract override	Set the override value when leaving the tap end point in the synchronous tap cycle. The setting range is 1 to 999, and the unit is %. When a value less than 100 is set, it will be judged as 100%.	1 to 999 (%)																																																																																									
1173	dwlskp G04 skip condition	Specify the skip signal for ending the G04 (dwell) command. <table border="1" style="margin: 10px auto;"> <thead> <tr> <th rowspan="2">Setting</th> <th colspan="4">Skip signals</th> </tr> <tr> <th>SKIP3</th> <th>SKIP2</th> <th>SKIP1</th> <th>SKIP0</th> </tr> </thead> <tbody> <tr><td>0</td><td>×</td><td>×</td><td>×</td><td>×</td></tr> <tr><td>1</td><td>×</td><td>×</td><td>×</td><td>○</td></tr> <tr><td>2</td><td>×</td><td>×</td><td>○</td><td>×</td></tr> <tr><td>3</td><td>×</td><td>×</td><td>○</td><td>○</td></tr> <tr><td>4</td><td>×</td><td>○</td><td>×</td><td>×</td></tr> <tr><td>5</td><td>×</td><td>○</td><td>×</td><td>○</td></tr> <tr><td>6</td><td>×</td><td>○</td><td>○</td><td>×</td></tr> <tr><td>7</td><td>×</td><td>○</td><td>○</td><td>○</td></tr> <tr><td>8</td><td>○</td><td>×</td><td>×</td><td>×</td></tr> <tr><td>9</td><td>○</td><td>×</td><td>×</td><td>○</td></tr> <tr><td>10</td><td>○</td><td>×</td><td>○</td><td>×</td></tr> <tr><td>11</td><td>○</td><td>×</td><td>○</td><td>○</td></tr> <tr><td>12</td><td>○</td><td>○</td><td>×</td><td>×</td></tr> <tr><td>13</td><td>○</td><td>○</td><td>×</td><td>○</td></tr> <tr><td>14</td><td>○</td><td>○</td><td>○</td><td>×</td></tr> <tr><td>15</td><td>○</td><td>○</td><td>○</td><td>○</td></tr> </tbody> </table> <p>Skip when ○ signal is input.</p>	Setting	Skip signals				SKIP3	SKIP2	SKIP1	SKIP0	0	×	×	×	×	1	×	×	×	○	2	×	×	○	×	3	×	×	○	○	4	×	○	×	×	5	×	○	×	○	6	×	○	○	×	7	×	○	○	○	8	○	×	×	×	9	○	×	×	○	10	○	×	○	×	11	○	×	○	○	12	○	○	×	×	13	○	○	×	○	14	○	○	○	×	15	○	○	○	○	0 to 15
Setting	Skip signals																																																																																											
	SKIP3	SKIP2	SKIP1	SKIP0																																																																																								
0	×	×	×	×																																																																																								
1	×	×	×	○																																																																																								
2	×	×	○	×																																																																																								
3	×	×	○	○																																																																																								
4	×	○	×	×																																																																																								
5	×	○	×	○																																																																																								
6	×	○	○	×																																																																																								
7	×	○	○	○																																																																																								
8	○	×	×	×																																																																																								
9	○	×	×	○																																																																																								
10	○	×	○	×																																																																																								
11	○	×	○	○																																																																																								
12	○	○	×	×																																																																																								
13	○	○	×	○																																																																																								
14	○	○	○	×																																																																																								
15	○	○	○	○																																																																																								
1174	skip_F G31 skip speed	Specify the feedrate when there is no F command in the program at G31 (skip) command.	1 to 999999 (mm/min)																																																																																									

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)																																																																																									
		<p>Specify the skip signal in the G31.1 to G31.3 (multi-step skip) command, and the feedrate when there is no F command in the program.</p> <table border="1" style="margin-left: auto; margin-right: auto; border-collapse: collapse;"> <thead> <tr> <th rowspan="2">Setting</th> <th colspan="4">Skip signals</th> </tr> <tr> <th>SKIP3</th> <th>SKIP2</th> <th>SKIP1</th> <th>SKIP0</th> </tr> </thead> <tbody> <tr><td>0</td><td>x</td><td>x</td><td>x</td><td>x</td></tr> <tr><td>1</td><td>x</td><td>x</td><td>x</td><td>○</td></tr> <tr><td>2</td><td>x</td><td>x</td><td>○</td><td>x</td></tr> <tr><td>3</td><td>x</td><td>x</td><td>○</td><td>○</td></tr> <tr><td>4</td><td>x</td><td>○</td><td>x</td><td>x</td></tr> <tr><td>5</td><td>x</td><td>○</td><td>x</td><td>○</td></tr> <tr><td>6</td><td>x</td><td>○</td><td>○</td><td>x</td></tr> <tr><td>7</td><td>x</td><td>○</td><td>○</td><td>○</td></tr> <tr><td>8</td><td>○</td><td>x</td><td>x</td><td>x</td></tr> <tr><td>9</td><td>○</td><td>x</td><td>x</td><td>○</td></tr> <tr><td>10</td><td>○</td><td>x</td><td>○</td><td>x</td></tr> <tr><td>11</td><td>○</td><td>x</td><td>○</td><td>○</td></tr> <tr><td>12</td><td>○</td><td>○</td><td>x</td><td>x</td></tr> <tr><td>13</td><td>○</td><td>○</td><td>x</td><td>○</td></tr> <tr><td>14</td><td>○</td><td>○</td><td>○</td><td>x</td></tr> <tr><td>15</td><td>○</td><td>○</td><td>○</td><td>○</td></tr> </tbody> </table>	Setting	Skip signals				SKIP3	SKIP2	SKIP1	SKIP0	0	x	x	x	x	1	x	x	x	○	2	x	x	○	x	3	x	x	○	○	4	x	○	x	x	5	x	○	x	○	6	x	○	○	x	7	x	○	○	○	8	○	x	x	x	9	○	x	x	○	10	○	x	○	x	11	○	x	○	○	12	○	○	x	x	13	○	○	x	○	14	○	○	○	x	15	○	○	○	○	<p>Skip condition: 0 to 15</p> <p>Skip federate: 1 to 999999 (mm/min)</p>
Setting	Skip signals																																																																																											
	SKIP3	SKIP2	SKIP1	SKIP0																																																																																								
0	x	x	x	x																																																																																								
1	x	x	x	○																																																																																								
2	x	x	○	x																																																																																								
3	x	x	○	○																																																																																								
4	x	○	x	x																																																																																								
5	x	○	x	○																																																																																								
6	x	○	○	x																																																																																								
7	x	○	○	○																																																																																								
8	○	x	x	x																																																																																								
9	○	x	x	○																																																																																								
10	○	x	○	x																																																																																								
11	○	x	○	○																																																																																								
12	○	○	x	x																																																																																								
13	○	○	x	○																																																																																								
14	○	○	○	x																																																																																								
15	○	○	○	○																																																																																								
1175	skip1	G31.1 skip condition																																																																																										
		Skip when ○ signal is input. Skip signal specified at G31.1																																																																																										
1176	1f	G31.1 skip speed																																																																																										
		Skip feedrate at G31.1																																																																																										
1177	2	G31.2 skip condition																																																																																										
		Skip signal specified at G31.2																																																																																										
1178	2f	G31.2 skip speed																																																																																										
		Skip feedrate at G31.2																																																																																										
1179	3	G31.3 skip condition																																																																																										
		Skip signal specified at G31.3																																																																																										
1180	3f	G31.3 skip speed																																																																																										
		Skip feedrate at G31.3																																																																																										

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)	
1181	G96_ax	Constant surface speed control	Specify the axis to be targeted for constant surface speed control. 0: Program specification will be invalidated, and the axis will always be fixed to the 1st axis. 1: 1st axis specification 2: 2nd axis specification 3: 3rd axis specification 4: 4th axis specification The program specification will be the priority for all settings other than 0.	0 to 4
1182	thr_F	Thread cutting speed	Set the screw cut up speed when not using chamfering in the thread cutting cycle. 0: Cutting feed clamp feedrate 1 to 60000 mm/min: Set feedrate	0 to 60000 (mm/min)
1183	clmp_M	M code for clamp	Set the M code for C-axis clamp in the hole opening cycle.	0 to 99999999
1184	clmp_D	Dwelling time after outputting M code for unclamp	Set the dwell time after outputting the M code for C-axis unclamp in the hole opening cycle.	0.000 to 99999.999 (s)
1185	spd_F1	F1 digit feedrate	Specify the feedrate for the F command in the F1-digit command ("#1079 F1 digit" is set to 1). Feedrate when F1 is issued (mm/min)	1 to 1000000 (mm/min)
1186	F2	F2	Feedrate when F2 is issued (mm/min)	
1187	F3	F3	Feedrate when F3 is issued (mm/min)	
1188	F4	F4	Feedrate when F4 is issued (mm/min)	
1189	F5	F5	Feedrate when F5 is issued (mm/min)	
1190 (PR)	s_xcnt (For L system only)	Validate inclined-axis control	0: Disable inclined-axis control 1: Enable inclined-axis control	0/1
1191 (PR)	s_angl (For L system only)	Inclination angle	Specify the inclination angle α of the oblique coordinate X' axis from the orthogonal coordinate system's X axis.	-80.000 to 80.000 (degree)
1192 (PR)	s_zrmv (For L system only)	Compensation at reference point return	Specify whether to perform compensation for the base axis corresponding to the inclined axis at reference point return. 0: Performs compensation. 1: Does not perform compensation.	0/1

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)	
1193	inpos	Validate in-position check	Specify the deceleration confirmation method for the positioning command. 0: Command deceleration check (Positioning is completed when the deceleration is completed with the acceleration/deceleration speed issued from the control unit.) 1: In-position check (Positioning is completed by detecting that the servo amplifier has reached within a set distance from the end point. The set distance is set in "#2224 SV024".)	0: Command deceleration check 1: In-position check
1194	H_acc0	Time constant 0 for handle feed	Specify the time constant for the manual handle feed. 0: Use time constant for G01 1: Time constant 0 (step)	0/1
1195 1196 1197 1198	Mmac Smac Tmac M2mac	Macro call for: M command S command T command Second miscellaneous code	Specify the user macro M, S or T command macro call out. Macro call out with M command Macro call out with S command Macro call out with T command Macro call out with 2nd miscellaneous command	0: Invalid 1: Valid
1199 (PR)	Sselect	Select initial spindle control	Select the initial condition of spindle control after power is turned on. 0: 1st spindle control mode (G43.1) 1: 2nd spindle control mode (G44.1)	0: G43.1 1: G44.1
1200 (PR)	G0_acc	Validate acceleration and deceleration with inclination angle constant G0	Set up acceleration and deceleration types when a rapid traverse command is issued 0: Acceleration and deceleration (conventional) with time constant 1: Acceleration and deceleration with inclination angle constant	0/1
1201 (PR)	G1_acc	Validate acceleration and deceleration with inclination constant G1	Set up acceleration and deceleration types when a linear interpolation command is issued. 0: Acceleration and deceleration (conventional) with time constant 1: Acceleration and deceleration with inclination angle constant	0/1
1202	mirofs (For L system only)	Distance between facing turrets	Set up the distance between tools (noses) (between turrets).	0 to 99999.999 (mm)

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)	
1203	TmirS1 (For L system only)	Select turrets for double-turret mirror image with T command	Set up turrets for double-turret mirror image with the T command that corresponds to tool numbers 1 to 32.	0 to FFFFFFFF
1204	TmirS2 (For L system only)	Select turrets for double-turret mirror image with T command	Set up turrets for double-turret mirror image with the T command that corresponds to tool numbers 33 to 64.	0 to FFFFFFFF
1205	G0bdcc	Acceleration and deceleration before G0 interpolation	0: G00 acceleration and deceleration are selected as those after interpolation regardless of high-accuracy mode. 1: G00 acceleration and deceleration are selected as those before interpolation.	0/1
1206	G1bF	Maximum speed	Set up a cutting feedrate when selecting acceleration and deceleration before interpolation.	1 to 1000000 (mm/min)
1207	G1btL	Time constant	Set up a cutting feed time constant when selecting acceleration and deceleration before interpolation.	1 to 5000 (ms)
1208	RCK	Arc radius error compensation factor	An arc radius error compensation amount can be increased and decreased from -60.0 to 20.0%.	-60.0 to +20.0 (%)
1209	cirdcc	Arc deceleration speed	Specify the deceleration speed at the arc entrance or exit.	1 to 1000000 (mm/min)

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)																																																																
1210	RstGmd: Modal G code reset	<p>Specify whether to initialize each G code group modal and the H and D codes when the system is reset. Specify the initialization items in bit correspondence. 0: Initialize. 1: Do not initialize.</p> <p>M system</p> <table border="1" style="width: 100%; border-collapse: collapse; margin-bottom: 10px;"> <tr><td style="width: 5%;">0</td><td>Group 1 Move G modal</td></tr> <tr><td>1</td><td>Group 2 Flat selection modal</td></tr> <tr><td>2</td><td>Group 3 Absolute/increment command modal</td></tr> <tr><td>3</td><td></td></tr> <tr><td>4</td><td>Group 5 Feed G modal</td></tr> <tr><td>5</td><td>Group 6 Inch/metric modal</td></tr> <tr><td>6</td><td>Group 7 Radius compensation modal</td></tr> <tr><td>7</td><td>Group 8 Length compensation modal</td></tr> <tr><td>8</td><td></td></tr> <tr><td>9</td><td>Group 10 Fixed cycle return command modal</td></tr> <tr><td>A</td><td></td></tr> <tr><td>B</td><td>Group 12 Workpiece coordinate system modal</td></tr> <tr><td>C</td><td>Group 13 Cut modal</td></tr> <tr><td>D</td><td></td></tr> <tr><td>E</td><td></td></tr> <tr><td>F</td><td></td></tr> </table> <table border="1" style="width: 100%; border-collapse: collapse; margin-bottom: 10px;"> <tr><td style="width: 5%;">10</td><td>Group 17 Constant surface speed control command modal</td></tr> <tr><td>11</td><td></td></tr> <tr><td>12</td><td>Group 19 G command mirror modal</td></tr> <tr><td>13</td><td>Group 20 Spindle 2 control modal</td></tr> <tr><td>14</td><td></td></tr> <tr><td>15</td><td></td></tr> <tr><td>16</td><td></td></tr> <tr><td>17</td><td></td></tr> <tr><td>18</td><td>H, D codes</td></tr> <tr><td>19</td><td></td></tr> <tr><td>1A</td><td></td></tr> <tr><td>1B</td><td></td></tr> <tr><td>1C</td><td></td></tr> <tr><td>1D</td><td></td></tr> <tr><td>1E</td><td></td></tr> <tr><td>1F</td><td></td></tr> </table> <p>The H code indicates the tool length offset number, and the D code indicates the tool radius compensation number.</p> <p>When bit 18 is set to on, the H and D codes and group 8 G modal area retained.</p> <p>When bit 7 is set to on, the H code and group 8 G modal are retained.</p>	0	Group 1 Move G modal	1	Group 2 Flat selection modal	2	Group 3 Absolute/increment command modal	3		4	Group 5 Feed G modal	5	Group 6 Inch/metric modal	6	Group 7 Radius compensation modal	7	Group 8 Length compensation modal	8		9	Group 10 Fixed cycle return command modal	A		B	Group 12 Workpiece coordinate system modal	C	Group 13 Cut modal	D		E		F		10	Group 17 Constant surface speed control command modal	11		12	Group 19 G command mirror modal	13	Group 20 Spindle 2 control modal	14		15		16		17		18	H, D codes	19		1A		1B		1C		1D		1E		1F		Specify a hexadecimal number.
0	Group 1 Move G modal																																																																		
1	Group 2 Flat selection modal																																																																		
2	Group 3 Absolute/increment command modal																																																																		
3																																																																			
4	Group 5 Feed G modal																																																																		
5	Group 6 Inch/metric modal																																																																		
6	Group 7 Radius compensation modal																																																																		
7	Group 8 Length compensation modal																																																																		
8																																																																			
9	Group 10 Fixed cycle return command modal																																																																		
A																																																																			
B	Group 12 Workpiece coordinate system modal																																																																		
C	Group 13 Cut modal																																																																		
D																																																																			
E																																																																			
F																																																																			
10	Group 17 Constant surface speed control command modal																																																																		
11																																																																			
12	Group 19 G command mirror modal																																																																		
13	Group 20 Spindle 2 control modal																																																																		
14																																																																			
15																																																																			
16																																																																			
17																																																																			
18	H, D codes																																																																		
19																																																																			
1A																																																																			
1B																																																																			
1C																																																																			
1D																																																																			
1E																																																																			
1F																																																																			

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)																																																																
1210	RstGmo Modal G code reset	<p>L system</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr><td style="text-align: center;">0</td><td>Group 1 Move G modal</td></tr> <tr><td style="text-align: center;">1</td><td>Group 2 Flat selection modal</td></tr> <tr><td style="text-align: center;">2</td><td>Group 3 Absolute/increment command modal</td></tr> <tr><td style="text-align: center;">3</td><td>Group 4 Barrier check modal</td></tr> <tr><td style="text-align: center;">4</td><td>Group 5 Feed G modal</td></tr> <tr><td style="text-align: center;">5</td><td>Group 6 Inch/metric modal</td></tr> <tr><td style="text-align: center;">6</td><td>Group 7 Nose radius compensation modal</td></tr> <tr><td style="text-align: center;">7</td><td></td></tr> <tr><td style="text-align: center;">8</td><td></td></tr> <tr><td style="text-align: center;">9</td><td>Group 10 Fixed cycle return command modal</td></tr> <tr><td style="text-align: center;">A</td><td></td></tr> <tr><td style="text-align: center;">B</td><td>Group 12 Workpiece coordinate system modal</td></tr> <tr><td style="text-align: center;">C</td><td>Group 13 Cut modal</td></tr> <tr><td style="text-align: center;">D</td><td></td></tr> <tr><td style="text-align: center;">E</td><td></td></tr> <tr><td style="text-align: center;">F</td><td></td></tr> </table> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr><td style="text-align: center;">10</td><td>Group 17 Constant surface speed control command modal</td></tr> <tr><td style="text-align: center;">11</td><td>Group 18 Balance cut</td></tr> <tr><td style="text-align: center;">12</td><td></td></tr> <tr><td style="text-align: center;">13</td><td>Group 20 Spindle 2 control modal</td></tr> <tr><td style="text-align: center;">14</td><td>Group 15 Double-turret mirror image</td></tr> <tr><td style="text-align: center;">15</td><td></td></tr> <tr><td style="text-align: center;">16</td><td></td></tr> <tr><td style="text-align: center;">17</td><td></td></tr> <tr><td style="text-align: center;">18</td><td></td></tr> <tr><td style="text-align: center;">19</td><td></td></tr> <tr><td style="text-align: center;">1A</td><td></td></tr> <tr><td style="text-align: center;">1B</td><td></td></tr> <tr><td style="text-align: center;">1C</td><td></td></tr> <tr><td style="text-align: center;">1D</td><td></td></tr> <tr><td style="text-align: center;">1E</td><td></td></tr> <tr><td style="text-align: center;">1F</td><td></td></tr> </table>	0	Group 1 Move G modal	1	Group 2 Flat selection modal	2	Group 3 Absolute/increment command modal	3	Group 4 Barrier check modal	4	Group 5 Feed G modal	5	Group 6 Inch/metric modal	6	Group 7 Nose radius compensation modal	7		8		9	Group 10 Fixed cycle return command modal	A		B	Group 12 Workpiece coordinate system modal	C	Group 13 Cut modal	D		E		F		10	Group 17 Constant surface speed control command modal	11	Group 18 Balance cut	12		13	Group 20 Spindle 2 control modal	14	Group 15 Double-turret mirror image	15		16		17		18		19		1A		1B		1C		1D		1E		1F		Specify a hexadecimal number.
0	Group 1 Move G modal																																																																		
1	Group 2 Flat selection modal																																																																		
2	Group 3 Absolute/increment command modal																																																																		
3	Group 4 Barrier check modal																																																																		
4	Group 5 Feed G modal																																																																		
5	Group 6 Inch/metric modal																																																																		
6	Group 7 Nose radius compensation modal																																																																		
7																																																																			
8																																																																			
9	Group 10 Fixed cycle return command modal																																																																		
A																																																																			
B	Group 12 Workpiece coordinate system modal																																																																		
C	Group 13 Cut modal																																																																		
D																																																																			
E																																																																			
F																																																																			
10	Group 17 Constant surface speed control command modal																																																																		
11	Group 18 Balance cut																																																																		
12																																																																			
13	Group 20 Spindle 2 control modal																																																																		
14	Group 15 Double-turret mirror image																																																																		
15																																																																			
16																																																																			
17																																																																			
18																																																																			
19																																																																			
1A																																																																			
1B																																																																			
1C																																																																			
1D																																																																			
1E																																																																			
1F																																																																			
1211	FHtyp Feed hold stop type	<p>Specify the type of the external signal used for feed hold.</p> <p>0: Disable the external signal. 1: Enable the external signal (contact A) 2: Enable the external signal (contact B)</p>	0 to 2																																																																
1212	FHno Feed hold external signal device	<p>Specify the number (X??) of the device used to input the feed hold signal.</p> <p>(Note) The setting range of this parameter has been expanded on the software Ver.D0 and later.</p>	000 to 3FF (hexadecimal)																																																																
1216	extdcc External deceleration level	Use an upper limit value at the feedrate indicated when validating external deceleration signals.	1 to 1000000 (mm/min)																																																																
1217	aux01	Not used.																																																																	

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)	
1218	aux02 (bit3)	Parameter input/output format	Specify a parameter input/output format. 0: Type I 1: Type II	0/1
	aux02 (bit4)	Tool number selection	Specify the R register that contains the tool number used for automatic calculation when measuring the coordinate offset of an external work piece. 0: Conforms to "#1130 set_t". 1: Uses the tool number indicated by user PLC	0/1
	aux02 (bit5)	Parameter I/O II spindle specification address	Specify the spindle specification address of parameter I/O type II. 0: C 1: T This parameter also applies to the spindle specification address for input and collation. (Note) This parameter is valid only for parameter I/O type II ("#1218 aux02/bit 3" is 1).	0/1
	aux02 (bit6)	Set No. valid when program input	Specify which program No. is selected when inputting operation using "#1 MAIN PROGRAM" in Data I/O screen. 0: The No. in the input data is valid. 1: The No. set in the data setting area is valid.	0/1
	aux02 (bit7)	Input by program overwrite	When inputting the machining program in the "Data input" screen, select one of the following options when the input program has already been registered: 0: Outputs error message "E65 PROG. No. DUPLI" 1: Input by overwrite	0/1
1219	aux03 (bit1)	Stop high-speed PC monitoring function	Set 1 to disable the function that stops the system when the high-speed processing time is extended. Disable the monitoring function only as a temporary measure.	0/1
	aux03 (bit2)	Improve skip coordinate accuracy	0: Skip accuracy (conventional specification) 1: Changes skip accuracy (correct a position in skip coordinates when entering skip signals).	0/1
	aux03 (bit3)		Reserved for the system.	0

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)
aux03 (bit7)	Time constant setting changeover for software acceleration/deceleration	<p>0: Accelerating time is $G0tL(G1tL)$. If the time is set to the software acceleration/deceleration 2nd step time constant (#2005 $G0t1$) under such condition as the acceleration/deceleration before $G00$ interpolation and the software acceleration/deceleration are used one together, the inclination at software acceleration/deceleration will be steeper. Thus, the acceleration for $G28/G30$ will be larger than that for $G00$.</p> <div style="text-align: center;"> <p>The figure contains two vertically aligned graphs sharing a common time axis (t). The top graph is labeled 'Speed' on the y-axis. It shows a curve that starts at the origin, rises to a peak, and then falls back to zero. A dashed line represents a linear rise to the peak. Horizontal arrows indicate time intervals: $G0tL - G0t1$ for the linear portion, $G0t1$ for the curved portion, and $G0tL$ for the total time to reach the peak. The bottom graph is labeled 'Acceleration' on the y-axis. It shows a trapezoidal profile. The acceleration rises linearly to a constant value, stays constant for a duration, and then falls linearly to zero. Horizontal arrows indicate time intervals: $G0t1$ for the initial linear rise, $G0t1$ for the final linear fall, and $G0tL - 2 \times G0t1$ for the constant acceleration phase.</p> </div> <p>1. Total accelerating time is "$G0L$". 2. The time for curve part is "$G0t1$". 3. The time for linear part is obtained by "$G0tL - (2 \times G0t1)$".</p> <p>(Continued on the next page)</p>	0/1

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)	
		<p>(Continued from the previous page)</p> <p>1: Accelerating time is obtained by $G0tL+G0t1$ ($G1tL+G1t1$). When the acceleration/deceleration before G00 interpolation and the software acceleration/deceleration are used one together, if the same time is set to S-curve filter time (#1131 F1dcc) and the software acceleration/deceleration 2nd step time constant (#2005 G0t1), the G00 acceleration can be obtained equals as G28/G30.</p> <p>1. Total accelerating time is obtained by "$G0tL+G0t1$". 2. The time for curve part is "$G0t1$". 3. The time for linear part is obtained by "$G0tL-G0t1$".</p> <p>(Note) This parameter is valid on the software Ver.C3 and later.</p>		
1220	aux04 (bit 0) (For L system only)	Tool life check timing selection	<p>Specify the life check standard applicable when the use count is incremented in tool life management II.</p> <p>0: Determines that the tool life is over when the incremented use count exceeds the life count. (Use count > life count)</p> <p>1: Determines that the tool life is over when the incremented use count has reached the life count. (Use count \geq life count)</p>	0/1 (Default: 0)

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)
1220	aux04 (bit1) Validity of space code in comment	Validate or invalidate the space code described in the comment statements in the machining program in edit operation with the custom display. 0: Invalidate the space code in the comment statements of the machining program. 1: Validate the space code in the comment statements of the machining program.	0/1 (Default: 0)
1221	aux05	Not used.	
1222	aux06 (bit0)	Not used.	0
	aux06 (bit1)	Not used.	0
	aux06 (bit3) Enable/disable setup parameter lock	Specify whether to enable the setup parameter lock function. 0: Disable 1: Enable	0/1
	aux06 (bit7)	Not used.	0
1223	aux07 (bit0)	Not used.	0
	aux07 (bit1)	Not used.	0
	aux07 (bit2)	Not used.	0
	aux07 (bit3)	Not used.	0
	aux07 (bit4)	Not used.	0
	aux07 (bit5)	Not used.	0
	aux07 (bit6) Cancel synchronous tap (,S) retract	0: Retains a spindle rotation speed (, S) when performing synchronous tap retract. 1: Cancels a spindle rotation speed (, S) by retract with G80.	0/1
	aux07 (bit7) Synchronous tap method	Specify a synchronous tap method. 0: Synchronous tap (multi-step acceleration and deceleration and rapid return) 1: Conventional type synchronous tap	0/1
1224	aux08	Unusable. Set 0 for this option.	
1225	aux09 (bit7) Enable/disable spindle rotation clamp	Specify whether to enable spindle rotation clamp by the spindle rotation clamp command (G92S, Q) instead of the spindle rotation command (R3210) specified by the user ladder. 0: Enable 1: Disable	0/1

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)	
1226	aux10 (bit0)	Tool compensation data for external workpiece coordinate offset measurement	Select the tool offset data to be used for external workpiece coordinate offset measurement. 0: Tool length data and nose wear data 1: Tool length data	0/1
	aux10 (bit1)	Optional block skip type	Specify whether to enable optional block skipping in the middle of a block. 0: Enable block skipping only at the beginning of a block. 1: Enable block skipping at the beginning of the block and in the middle of a block.	0/1
	aux10 (bit2)	Single block stop timing	Specify the time at which the single block signal is activated. 0: When the signal goes on while automatic operation is starting, the block stops after it is finished. 1: When the signal is on at the end of the block, the block stops.	0/1
	aux10 (bit3)		Not used.	0
	aux10 (bit4)	S command during constant surface speed	Specify whether to output a strobe signal when the S command is issued in constant surface speed mode. 0: Output no strobe signal in constant surface speed mode. 1: Output strobe signals in constant surface speed mode.	0/1
	aux10 (bit5)	Dog/OT signal arbitrary assignment valid	Specify whether to enable the arbitrary allocation parameter for the origin dog and H/W OT. 0: Disable arbitrary allocation. (Fixed devices are valid.) Note that when the backup module for powerfailure is mounted, all dog signals allocation will be disabled, however, OT signals will be allocated to the fixed devices. 1: Enable arbitrary allocation. (Devices specified by #2073 to #2075 parameters)	0/1

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)	
1226	aux10 (bit6)	Setup and display unit	Specify the unit to be used as the setup/display unit or handle feed unit, the command unit or internal unit. 0: Internal unit 1: Unit specified by command (Note 1) This parameter is valid only in initial millimeter mode (0 is set in "#1041 I_inch"). The internal unit is always used in initial inch mode (1 is set in "#1041 I_inch"). (Note 2) This parameter is validated immediately after it is set. (Note 3) If addition setting is performed for tool and workpiece offset data with the command unit being inch and internal unit being mm, an error may be generated. Related parameter: #1152 I_G20 (Initial command unit)	0/1
	aux10 (bit7)	Shorten JOG stop time	Specify whether to shorten the JOG stop time. 0: Do not shorten the JOG stop time. (Same as before) 1: Shorten the JOG stop time.	0/1
1227	aux11 (bit0)	Select PLC signal or spindle feedrate attained	Set up this option when disabling the cutting start interlock by spindle feedrate attained. 0: Cutting start interlock by PLC signal 1: Cutting start interlock by spindle feedrate attained	0/1
	aux11 (bit1)	Select H or D code	Set up this option to validate the data that is set up on the tool life management screen when issuing the H99 or D99 command. 0: The H and D codes validate the data that is set up on the management setup screen. 1: Validates the data that is set up on the management setup screen when issuing the H99 or D99 command.	0/1

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)	
1227	aux11 (bit2)	Measures against tool setter chattering	Select a condition where a relieving operation completes after measurement with tools. 0: Sensor signals have stopped for 500 ms or longer. 1: 100 μ s or longer has passed after sensor signals stopped.	0/1
	aux11 (bit3)	Absolute coordinate switching (nose R)	Select whether to display a nose position or coordinate value with the absolute coordinate counter. 0: Displays the nose position. 1: Displays the position specified by program command.	0/1
	aux11 (bit4)	Program address check	Specify whether to simply check the program address when the machining program is executed. 0: Does not check the program address. 1: Checks the program address.	0/1
	aux11 (bit5)	Spindle rotation speed clamp	Specify whether to clamp the rotation speed in constant surface speed mode when the spindle rotation clamp command is issued. 0: Clamps the rotation regardless of the constant surface speed mode. 1: Clamps the rotation only in constant surface speed mode.	0/1
	aux11 (bit6)		Not used.	0
	aux11 (bit7)	Switch the range of tool life data to be input	Set up the range of tool life data to be input or compared. 0: Inputs or compares all of the data output. 1: Inputs or compares part of the data output 1) Tool life management I data to be input or compared tool number (D), lifetime (E), life count (F), and auxiliary data (B). 2) Tool life management II data to be input or compared Group number (G), method (M), life (E/F), tool number (D), and compensation number (H)	0/1

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)	
1228	aux12 (bit0)	Switch coordinate value screen	Set up this option to switch the coordinate value screen. 0: 80-character screen 1: 40-character screen	0/1
	aux12 (bit1)	Switch offset and parameter screen	Set up this option to switch the offset and parameter screen to the parameter screen. 0: Displays the offset and parameter screen. 1: Displays the parameter screen.	0/1
	aux12 (bit2)	Switch data protection in data transmission mode	Set up the range of data protection in data transmission mode. 0: Protects both send and receive data. 1: Protects receive data only.	0/1
	aux12 (bit3)	Nose R specification	Select whether to specify the nose R compensation by shape or wear number. 0: Specifies the nose R compensation by shape number. 1: Specifies the nose R compensation by wear number.	0/1
	aux12 (bit4)	Select operation error or stop code	Specify both block cutting start interlock and cutting start interlock as the operation error or stop code. 0: Operation error 1: Stop code	0/1
	aux12 (bit5)	Select constant surface speed coordinates	Select constant surface speed coordinates. 0: Workpiece coordinate value 1: Absolute coordinate value	0/1
	aux12 (bit6)	Switch relative values displayed	0: Includes coordinate preset amounts in relative values (absolute values). 1: Does not coordinate preset amounts in relative values (absolute values).	0/1
	aux12 (bit7)	Protection with manual value command	Set up this option to protect a manual value command. 0: Does not protect the manual value command (same as before). 1: Protects the manual value command.	0/1
1229	set01 (bit0)	Subprogram interrupt	0: Specifies the user macro interrupt of macro type. 1: Specifies the user macro interrupt of sub-program type.	0/1
	set01 (bit1)	Accurate thread cutting E	0: Address E specifies the number of threads per inch for inch screw cutting. 1: Address E specifies precise reading for inch screw cutting.	0/1

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)	
1229	set01 (bit2)	Radius compensation type B (For M system only)	<p>0: When the start-up and cancel commands are operated during radius compensation, their blocks are not handled by intersection operation processing; they are handled as offset vectors in the direction vertical to that of the commands.</p> <p>1: When the start-up and cancel commands are operated during radius compensation, the intersection operation processing of the command block and the next block is executed.</p>	0/1
		Nose R compensation type B (For L system only)	<p>0: When the start-up and cancel commands are operated during nose R, their blocks are not handled by intersection operation processing; they are handled as offset vectors in the direction vertical to that of the commands.</p> <p>1: When the start-up and cancel commands are operated during nose R, the intersection operation processing of the command block and the next block is executed.</p>	0/1
	set01 (bit3)	Initial constant surface speed	<p>0: The initial state after power-on is a constant surface speed control cancel mode.</p> <p>1: The initial state after power-on is a constant surface speed control mode.</p>	0/1
	set01 (bit4)	Synchronous tap	<p>0: Handles the tap cycles as the tap cycles with a floating tap chuck.</p> <p>1: Handles the tap cycles as the tap cycles without a floating tap chuck.</p>	0/1
	set01 (bit5)	Start point alarm	<p>Select an operation when the operation start point cannot be found while moving the next block of G117.</p> <p>0: Enables an auxiliary function after the block has been moved.</p> <p>1: Outputs a program error (P33) when the operation start point is not found.</p>	0/1
	set01 (bit6)	Grid display selection	<p>Select a grid type to be displayed on the servo monitor screen during dog type reference point return.</p> <p>0: Selects the distance between dog ON and reference point (including a grid mask amount).</p> <p>1: Selects a value given by reducing a grid mask amount from the distance between dog ON and reference point.</p>	0/1
1230	set02	Not used.		
1231	set03	Not used.		
1232	set04	Not used.		
1233	set05	Not used.		

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)
1234	set06		Not used.
1235	set07		Not used.
1236	set08 (bit0)	Manual rotation axis feedrate unit	Select the unit of manual rotation axis feedrate. 0: Fixed to [°/min] 1: Same speed as before
1237 (PR)	set09 (bit0)	External workpiece offset	Set up this function to use the external workpiece coordinates by shifting them to the Z axis. 0: Does not reverse the sign of external workpiece offsets (Z shift) (same as before). 1: Reverses the sign of external workpiece offsets (Z shift). (Note) When the sign of external workpiece offsets (Z shift) has been reversed, do not measure those external workpiece offsets. However, the external workpiece offsets can be measured by tool pre-setter.
1238 (PR)	set10		Not used.
1239 (PR)	set11 (bit0)	Coil switching method	0: Via PLC. (YD3F) 1: NC internal processing. (YD3F is invalid.) (Note) As for C6/C64/C64T, always set "1" when using MDS-B-SP and later. However, if the system structure needs the mechanical gears for spindles, set "0".
1240 (PR)	set12 (bit0)	Handle input pulse	Select the handle input pulse. 0: MELDAS standard handle pulse 1: Handle 400 pulse
	set12 (bit1)	Megatorque motor handle feed magnification	Select the magnification of megatorque motor handle 1 pulse. 0: Double the handle 1 pulse magnification specified by the handle feed magnification signal (Y780, Y781, Y782). 1: Use the handle 1 pulse magnification specified by the handle feed magnification signal (Y780, Y781, Y782) as is.

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)	
1265 (PR)	ext01 (bit0)	Command format	Select the command format. 0: Conventional format	0
1266 (PR)	ext02		Not used.	
1267 (PR)	ext03 (bit0)	G code type	Select the G code type. This parameter is valid when 1 is set in "#1265 ext01 bit 0 (command format)".	0/1
1268 (PR)	ext04		Not used.	
1269 (PR)	ext05		Not used.	
1270 (PR)	ext06		Not used.	
1271 (PR)	ext07 (bit0)	Mirror image operation	Select the type of mirror image operation. Not applied to this CNC. 0: Type 1 <ul style="list-style-type: none"> The program mirror image, external mirror image, and parameter mirror image are exclusive to each other. An increment command moves the image to the position indicated by the move amount with the sign inverted. 1: Type 2 <ul style="list-style-type: none"> Mirror image operation is enabled when the program mirror image (G51.1) command is issued or when the external signal or parameter is ON. An increment command moves the image to the position determined by applying the mirror image to the absolute program coordinates. 	0/1 (Default: 0)
	ext07 (bit1)	Address specifying fixed-cycle repetition count (For M system only)	Specify the address that specifies the fixed-cycle repetition count. Not applied to this CNC. 0: Address L only 1: Addresses K and L If addresses K and L are specified simultaneously, the data at address K is used for operation.	0/1 (Default: 0)
	ext07 (bit2)	F-command unit	Specify the unit to be used if a thread cutting read command contains on decimal point. Not applied to this CNC. 0: Type 1 (conventional specifications) F1 → 1 mm/rev, 1 inch/rev 1: Type 2 F1 → 0.01 mm/rev, 0.0001 inch/rev	0/1 (Default: 0)

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)
1271 (PR)	ext07 (bit3) G-code group for unidirectional positioning (for M system only)	Specify the G-code group for unidirectional positioning. Not applied to this CNC. 0: Unmodal G code (group 00) 1: Modal G code (group 01) Related parameter: "#8209 G60 SHIFT"(Set the last positioning direction and distance for each axis applicable when the unidirectional positioning command is issued.)	0/1
	ext07 (bit4) Operation by independent G40 command	Specify the mode of canceling tool radius compensation vector by the independent G40 command. Not applied to this CNC. 0: Type 1 (conventional specifications) The independent G40 command cancels the tool radius compensation vector. 1: Type 2 The tool radius compensation vector is not canceled by the independent G40 command but is canceled by the next move command for the tool radius compensation plane.	0/1 (Default: 0)
	ext07 (bit5) Cut start position (For L system only)	Specify the position from where cutting begins in a composite-type fixed cycle for lathe. 0: Conventional specifications The cut start position is determined by the final shaping program. 1: Extended specifications The cut start position is determined from the cycle start point.	0/1 (Default: 0)
	ext07 (bit6) Nose R compensation (For L system only)	Specify whether to apply nose R compensation to shapes in a rough cutting cycle. 0: Conventional specifications If nose R compensation is enabled for the final shaping program, the shape obtained after applying nose R compensation to the final shaping program is used as the rough cutting shape. 1: Extended specifications The shape made by the final shaping program, without nose R compensation, is used as the rough cutting shape.	0/1 (Default: 0)

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)	
1271 (PR)	ext07 (bit7)	Cut amount (For L system only)	Specify the operation to be performed when the program-specified cut amount exceeds the cut amount of the final shaping program. 0: Conventional specifications A program error occurs if the program-specified cut amount exceeds the cut amount of the final shaping program. 1: Extended specifications Rough cutting is performed by one cut if the program-specified cut amount exceeds the cut amount of the final shaping program.	0/1 (Default: 0)
1272 (PR)	ext08 (bit1)	M function synchronous tap cycle	Specify whether to enable the M function synchronous tap cycle. 0: Disable 1: Enable	0/1
1273 (PR)	ext09		Not used.	
1274 (PR)	ext10		Not used.	
1275 (PR)	ext11		Not used.	
1276 (PR)	ext12		Not used.	
1277 (PR)	ext13 (bit0)	Tool life management II count type 2	Specify how and when the mount or use count is incremented in tool life management II. 0: Type 1 The count is incremented when the spindle is used for cutting. 1: Type 2 The count is incremented for the tool used or mounted for one program. The increment is enabled by resetting.	0/1 (Default: 0)
1278 (PR)	ext14		Not used.	
1279 (PR)	ext15		Not used.	
1280 (PR)	ext16		Not used.	
1281 (PR)	ext17		Not used.	
1282 (PR)	ext18		Not used.	
1283 (PR)	ext19		Not used.	
1284 (PR)	ext20		Not used.	
1285 (PR)	ext21		Not used.	

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)
1286 (PR)	ext22	Not used.	
1287 (PR)	ext23 (bit0)	Workpiece coordinate display Select the mode of displaying the workpiece coordinate counter. 0: Does not update the display immediately after workpiece coordinate data is changed. 1: Updates the display immediately after workpiece coordinate data is changed.	0/1
	ext23 (bit4)	Relative coordinate display (M system) 0: Displays the actual position including tool length compensation. 1: Displays the machining position in terms of a program command excluding tool length compensation. (L system) 0: Displays the actual position including tool shape compensation. 1: Displays the machining position in terms of a program command excluding tool shape compensation.	0/1
	ext23 (bit5)	Relative coordinate display (M system) 0: Displays the actual position including tool radius compensation. 1: Displays the machining position in terms of a program command excluding tool radius compensation. (L system) 0: Displays the actual position including nose R compensation. 1: Displays the machining position in terms of a program command excluding nose R compensation.	0/1
	ext23 (bit6)	Absolute coordinate display (M system) 0: Displays the actual position including tool length compensation. 1: Displays the machining position in terms of a program command excluding tool length compensation. (L system) 0: Displays the actual position including tool shape compensation. 1: Displays the machining position in terms of a program command excluding tool shape compensation.	0/1

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)	
	ext23 (bit7)	Absolute coordinate display	(M system) 0: Displays the actual position including tool radius compensation. 1: Displays the machining position in terms of a program command excluding tool radius compensation. (L system) 0: Displays the actual position including nose R compensation. 1: Displays the machining position in terms of a program command excluding nose R compensation.	0/1
1288 (PR)	ext24		Not used.	
1289 (PR)	ext25		Not used.	
1290 (PR)	ext26		Not used.	
1291 (PR)	ext27		Not used.	
1292 (PR)	ext28		Not used.	
1293 (PR)	ext29		Not used.	
1294 (PR)	ext30		Not used.	
1295 (PR)	ext31		Not used.	
1296 (PR)	ext32		Not used.	
1297 (PR)	ext33		Not used.	
1298 (PR)	ext34		Not used.	
1299 (PR)	ext35		Not used.	
1300 (PR)	ext36 (bit7)	Spindle synchronization command method	Select the command method for spindle synchronous control. 0: Spindle synchronous control II (Controlled by PLC I/F) 1: Spindle synchronous control I (Controlled by G code)	0/1

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)
1301	nrfchk Origin neighboring check method	Select the high-speed check method of the origin neighboring signal. 0: Does not check positions near the origin at high speeds. (Conventional specifications) 1: Checks positions near the origin at high speeds using command machine positions. 2: Checks positions near the origin at high speeds using detector feedback positions.	0 to 2
1501	polyax (For L system only) Rotational tool axis number	Specify the number of the rotational tool axis (servo axis) used for polygonal machining (G51.1). Specify 0 when polygonal machining is not performed. A value exceeding the base specification parameter "#1002 axisno" cannot be specified. This parameter is valid when the G code system is 6 or 7 (7 or 8 is set in base specification parameter "#1037 cmdtyp").	0 to controlled axis number
1505	ckref2 Second reference point return check	Specify the trigger for a check at the specified position in manual second reference point return mode. 0: Completion of spindle orientation 1: Generation of second reference point return interlock signal	0/1
1510	DOOR_H Shorten door interlock II axis stop time	Specify whether to shorten the time during which the axis is stopped when the door is opened. 0: Uses the conventional axis stop time. 1: Shortens the axis stop time. (Note) When the door interlock II signal is input via a ladder, the conventional axis stop time is used.	0/1
1511	DOORPm Signal input device 1 for door interlock II: for each part system	Specify the fixed device number (X??) for door interlock II signal input for each part system. A device number from X001 to X3FF can be specified. Device number 000 is invalid. Specify device number 100 when using no fixed device number for door interlock II signal input. (Note) The setting range of this parameter has been expanded on the software Ver.D0 and later. Related parameter: #1154 pdoor (Door interlock II for each part system)	000 to 3FF (hexadecimal)
1512	DOORPs Signal input device 2 for door interlock II: for each part system	Specify the fixed device number (X??) for door interlock II signal input for each part system. (Specify the same value as that of #1155.) (Note) The setting range of this parameter has been expanded on the software Ver.D0 and later. Related parameter: #1154 pdoor (Door interlock II for each part system)	000 to 3FF (hexadecimal)

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)
1801	Hacc_c	Arc radius clam acceleration	-99999999 to +99999999
1802	Macc_c	Acceleration check at middle speed	-99999999 to +99999999
1803	Lacc_c	Acceleration check at low speed	-99999999 to +99999999
1811	Hcof_A	X-axis high acceleration coefficient β	-99999999 to +99999999
1812	Hcof_B	X-axis high acceleration coefficient α	-99999999 to +99999999
1813	Mcof_A	X-axis middle acceleration coefficient β	-99999999 to +99999999
1814	Mcof_B	X-axis middle acceleration coefficient α	-99999999 to +99999999
1815	Lcof_A	X-axis low acceleration coefficient β	-99999999 to +99999999
1816	Lcof_B	X-axis low acceleration coefficient α	-99999999 to +99999999
1817	mag_C	X-axis change magnification θ [%] Set 0 when no compensation or change is executed.	-99999999 to +99999999
1821	Hcof_A	Y-axis high acceleration coefficient β	-99999999 to +99999999
1812	Hcof_B	Y-axis high acceleration coefficient α	-99999999 to +99999999
1813	Mcof_A	Y-axis middle acceleration coefficient β	-99999999 to +99999999
1814	Mcof_B	Y-axis middle acceleration coefficient α	-99999999 to +99999999
1815	Lcof_A	Y-axis low acceleration coefficient β	-99999999 to +99999999
1816	Lcof_B	Y-axis low acceleration coefficient α	-99999999 to +99999999
1817	mag_C	Y-axis change magnification θ [%] Set 0 when no compensation or change is executed.	-99999999 to +99999999

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)
1901 (PR)	station addr	Set up a station address number (the NC is the n-th slave station).	1 to 7
1902 (PR)	Din size	Set up the size of the data to be transferred from the PC to the NC (from the master station to the slave station) in bytes (8 points).	0 to 32 (bytes (8 bits))
1903 (PR)	Dout size	Set up the size of the data to be transferred from the NC to the PC (from the slave station to the master station) in bytes (8 points).	0 to 32 (bytes (8 bits))
1904 (PR)	data length	Set up the data length of a character.	0 to 2 : 7 bits 3 : 8 bits
1905 (PR)	baud rate	Set up a data transfer rate. The transfer rate differs according to operation clock rates.	Clock: 6/10 MHz 0: 38400 / 57600 1: 19200 / 28800 2: 9600 / 14400 3: 4800 / 7200 4: 2400 / 3600 5: 1200 / 1800 6: 600 / 900 (bps)
1906 (PR)	stop bit	Set up the stop bit length.	0 and 1: 1 bit 2 and 3: 2 bits
1907 (PR)	parity check	Select whether to make a parity check.	0: Invalid 1: Valid
1908 (PR)	even parity	Select the odd or even parity bit. If no parity check is specified, this parameter is ignored.	0: Odd parity 1: Even parity
1909 (PR)	Tout (ini)	(ini) specifies a time-out from when the connection check sequence finishes to when the first usual sequence (input) finishes.	0 to 999 (0.1 s)
1910 (PR)	(run)	(run) specifies a time-out from when the NC (slave station) outputs usual sequence data to when the next usual sequence data is input. If the time-out is exceeded, an emergency stop occurs and the system waits for the preparation sequence to start. If the set value is 0, no time-out occurs or no communication stop can be detected.	
1911 (PR)	clock select	Select an operation cycle.	0: 6 MHz 1: 10 MHz
1926 (PR)	IP address	Set NC's IP address.	Set these according to connection environment's network regulations.
1927 (PR)	Subnet mask	Set sub-net mask.	
1928 (PR)	Gateway address	Designate gateway IP address.	

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)
1929 (PR)	Port number	Set the HMI connection port No. (Set the default value 64758 unless particularly required.)	0 to 65535
1930 (PR)	Speed 10M/auto	Set the communication rate. 0: Fixed to "10Mbyte" 1: Recognized whether "10Mbyte" or "100Mbyte" automatically and set.	0/1
1931 (PR)	IP address(2)	Set NC's IP address. Set for the card mounted on the 2nd channel when 2-channel connection is used on the Ethernet communication. (Note1)	Set these according to connection environment's network regulations.
1932 (PR)	Subnet mask(2)	Set sub-net mask. Set for the card mounted on the 2nd channel when 2-channel connection is used on the Ethernet communication. (Note1)	
1933 (PR)	Port number(2)	Set the HMI connection port No. (Set the default value 64758 unless particularly required.) Set for the card mounted on the 2nd channel when 2-channel connection is used on the Ethernet communication. (Note1)	0 to 65535
1934 (PR)	Speed(2) 10M/auto	Set the communication rate. 0: Fixed to "10Mbyte" 1: Recognized "10Mbyte" or "100Mbyte" automatically and set. Set for the card mounted on the 2nd channel when 2-channel connection is used on the Ethernet communication. (Note1)	0/1

(Note1) When two Ethernet cards are mounted, make sure not to use IP address on the same network IDs.

The cards are regarded as "same network IDs" when the area masked (validated) by "Subnet mask" parameter is the same as another.

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)
21025	SmpDelay	Set up a sampling time after an alarm occurs.	0 to 3000 (ms)
21028	ed_mess	Set up an edit type. 0: Displays messages with state. 1: Displays operation message equivalent to M50.	0/1
21029	NCname	Use this to display the NC unit name on the CE terminal screen.	8 or less alphanumeric characters
21030	AlmHold (h)	Set the time to delete sampling data automatically after an alarm occurs. If 0 is set, the alarm will not be deleted automatically.	0 to 9999 (h)
21031	UnitMax	Set the number of connected control units when setting and displaying several NC control units with one terminal using the multiple NC common display function. Up to 15 NC control units can be connected. The default value is "0", so if the setting is not changed, it will be interpreted that 1 control unit is connected. (The setting values "0" and "1" are handled in the same manner.)	0 to 15 (Default value: 0)
21032	UnitNum	Set the control unit's station No. when setting and displaying several NC control units with one terminal using the multiple NC common display function. "0" is the first station No. and "14" is the last station No. Make sure that the stations are not set in duplicate.	0 to 14 (Default value: 0)
21033	KeyCtrlLmt	Acquisition of the key operation rights are limited. 0: The key operation rights can be acquired from another display unit on all screens. 1: The key operation rights cannot be acquired while the Program screen is opened. 2: The key operation rights cannot be acquired from another display unit on any screen.	0 to 2
21034	ReMonDisp	The remote monitor tool displays are limited. 0: The remote monitor tool displays are not limited. 1: Display information is not sent to the remote monitor tool. (Note) Avoid setting from the remote monitor tool. The display will not appear as soon as this parameter is set.	0 to 1
21049	SPname	Designate the spindle No. selected for the G43.1 modal in each part system. 0: 1st spindle 4: 4th spindle 1: 1st spindle 5: 5th spindle 2: 2nd spindle 6: 6th spindle 3: 3rd spindle 7: 7th spindle	0 to 7

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)	
21101	add01 (bit0)	PLC axis rapid traverse mode acceleration/deceleration type	Select the PLC axis rapid traverse mode acceleration/deceleration type. (This is compatible from software version C0 and higher.) 0: Select constant time constant acceleration/deceleration 1: Select constant inclination acceleration/deceleration (Note) This parameter cannot be used when the peripheral axes (MC1K I/F) is used.	0/1
	add01 (bit1)	PLC axis cutting feed mode acceleration/deceleration type /Peripheral axis (MC1K I/F) acceleration/deceleration type	Select the PLC axis cutting feed mode acceleration/deceleration type. (This is compatible from software version C0 and higher.) 0: Select constant time constant acceleration/deceleration 1: Select constant inclination acceleration/deceleration (Note) Select the peripheral axis (MC1K I/F) acceleration/deceleration type when the peripheral axes are used. (This is compatible from software version C0 and higher.)	0/1
	add01 (bit2)	Circular command block overlap valid	Validates the block overlap at the circular command. (This is compatible from software version C1 and higher.) 0: Invalid 1: Valid	0/1
	add01 (bit3)	G31 automatic acceleration/deceleration	Validates dry run, override and automatic acceleration/deceleration for the G31 (skip) command. (This is compatible from software version C1 and higher.) 0: Invalid 1: Valid	0/1
	add01 (bit4)		Reserved for system.	0
	add01 (bit5)		Reserved for system.	0

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)	
21102	add02 (bit0)	Servo parameter 100-point compliance	0: The number of servo parameters is set to 64 points. 1: The number of servo parameters is set to 100 points when using the 100-point servo parameter compliant amplifier. (This is compatible from software version C1 and higher.)	0/1
	add02 (bit1)	External search time-out valid	0: Time-out check of the external search command (DDBS) is not performed. 1: Time-out is performed approx. 3 seconds after the external search command (DDBS) is issued. (This is compatible from software version C2 and higher.)	0/1
	add02 (bit2)	RIO communication interruption alarm invalid	0: The alarm "RIO communication interrupted" will occur if the remote I/O unit is not mounted. 1: Any alarm will not occur even if the remote I/O unit is not mounted. Set "1" if the remote I/O unit is not used though CC-Link, MELSECNET/10, etc. is used. (This is compatible from software version C3 and higher.)	0/1
21103	add03 (bit0)		Reserved for system.	0
	add03 (bit1)	Amp S/W automatic download valid (only C64T)	Specify whether to perform or not the automatic download of the amp software when the power is turned ON. 0: Disables download 1: Enables download (This is compatible from software version C4 and higher.)	0/1 (Standard:0)
21104	add04 (bit0)	Sampling mode selection	Select the sampling mode. (This is compatible from software version D0 and higher.) 0: Cycle monitor mode 1: NC alarm diagnosis mode When NC power is turned ON, cycle monitor mode is selected.	0/1

5. Base Specifications Parameters

#	Items	Details	Setting range (unit)
21105	add05	Not used.	0
21106	add06		
21107	add07		
21108	add08		
21109	add09		
21110	add10		
21111	add11		
21112	add12		
21113	add13		
21114	add14		
21115	add15		
21116	add16		
21117	add17		
21118	add18		
21119	add19		
21120	add20		
21121	add21		
21122	add22		
21123	add23		
21124	add24		

6. Axis Specifications Parameters
6.1 Axis Specifications Parameters


6. Axis Specifications Parameters

6.1 Axis Specifications Parameters



After setting up the parameter (PR) listed in the table, turn off the NC power. To validate the parameter, turn on the power again.

#	Items		Details	Setting range (unit)																																
2001	rapid	Rapid traverse feedrate	Set up the rapid traverse feedrate for each axis. The maximum value to be set differs with mechanical systems.	1 to 1000000 (mm/min)																																
2002	clamp	Cutting feedrate for clamp function	Define the maximum cutting feedrate for each axis. Even if the feedrate in G01 exceeds this value, the clamp will be applied at this feedrate.	1 to 1000000 (mm/min)																																
2003 (PR)	smgst	Acceleration and deceleration modes	<p>Specify acceleration and deceleration control modes.</p> <table style="margin-left: 20px; border-collapse: collapse;"> <tr> <td style="text-align: center;">F</td><td style="text-align: center;">E</td><td style="text-align: center;">D</td><td style="text-align: center;">C</td><td style="text-align: center;">B</td><td style="text-align: center;">A</td><td style="text-align: center;">9</td><td style="text-align: center;">8</td><td style="text-align: center;">7</td><td style="text-align: center;">6</td><td style="text-align: center;">5</td><td style="text-align: center;">4</td><td style="text-align: center;">3</td><td style="text-align: center;">2</td><td style="text-align: center;">1</td><td style="text-align: center;">0</td> </tr> <tr> <td style="border: 1px solid black; width: 20px; height: 20px;"></td><td style="border: 1px solid black; width: 20px; height: 20px;"></td> </tr> </table> <p>(Note) Set 0 in null bits.</p> <p>Rapid traverse feed acceleration and deceleration types</p> <ul style="list-style-type: none"> LR: Linear acceleration/deceleration R1: Primary delay R3: Exponential acceleration and linear deceleration <p>(Note) Designate “F” with bits 0 to 3 for rapid traverse with acceleration/deceleration by software. Note that the acceleration/deceleration by software will not applied on such case as follows;</p> <ol style="list-style-type: none"> (1) When the parameters are set as “#1205 G0bdcc” = “1” (acc/dec before G00 is valid) and “#1086 G0Intp” = “0” (G00 non-interpolation invalid), the acceleration/deceleration before interpolation will be applied to the following operation. <ol style="list-style-type: none"> (a) Travel by G00 command (b) Travel from G28/G30 command start point to the intermediate point (c) Travel from G29 command reference to the intermediate point <p>(Continued on the next page)</p>	F	E	D	C	B	A	9	8	7	6	5	4	3	2	1	0																	Specify the modes in hexadecimal notation.
F	E	D	C	B	A	9	8	7	6	5	4	3	2	1	0																					




6. Axis Specifications Parameters
6.1 Axis Specifications Parameters

#	Items	Details	Setting range (unit)																				
		<p>(Continued from the previous page)</p> <p>Cutting feed acceleration and deceleration types LC: Linear acceleration/deceleration C1: Primary delay C3: Exponential acceleration and linear deceleration</p> <p>(Note) Designate "F" with bits 4 to 7 for cutting feed with acceleration/deceleration by software. Note that the acceleration/deceleration by software will not applied on such case as follows;</p> <p>(1) AS for G01/G02/G03 command during G61.1 modal, s-curve acceleration/ deceleration before interpolation is applied to.</p> <p>(2) Linear acceleration/deceleration is applied to the cutting feed during synchronous tapping.</p> <p><Combination of acceleration and deceleration patterns></p>  <p>R1 > R3 when both R1 and R3 contain 1.</p> <p><Stroke end stop types></p> <table border="1" data-bbox="598 1473 1077 1646"> <thead> <tr> <th>Type</th> <th>OT2</th> <th>OT3</th> </tr> </thead> <tbody> <tr> <td>Linear deceleration</td> <td>0</td> <td>0</td> </tr> <tr> <td>Position loop step stop</td> <td>1</td> <td>0</td> </tr> <tr> <td>Speed loop step stop</td> <td>0</td> <td>1</td> </tr> <tr> <td>Position loop step stop</td> <td>1</td> <td>1</td> </tr> </tbody> </table> <table border="1" data-bbox="598 1668 1061 1736"> <tr> <td rowspan="2">OT1</td> <td>0</td> <td>Deceleration by G0t1</td> </tr> <tr> <td>1</td> <td>Deceleration by 2 × G0t1</td> </tr> </table> <p>(Continued on the next page)</p>	Type	OT2	OT3	Linear deceleration	0	0	Position loop step stop	1	0	Speed loop step stop	0	1	Position loop step stop	1	1	OT1	0	Deceleration by G0t1	1	Deceleration by 2 × G0t1	
Type	OT2	OT3																					
Linear deceleration	0	0																					
Position loop step stop	1	0																					
Speed loop step stop	0	1																					
Position loop step stop	1	1																					
OT1	0	Deceleration by G0t1																					
	1	Deceleration by 2 × G0t1																					





6. Axis Specifications Parameters
6.1 Axis Specifications Parameters

#	Items	Details	Setting range (unit)
		<p>(Continued from the previous page)</p>  <p>OT1 is valid under the following conditions (valid for dog type reference point return): Stop type: Linear deceleration Acceleration mode: Exponential Deceleration mode: Linear</p>	
2004	G0tL G0 time constant (linear)	<p>Set up a linear control time constant for rapid traverse acceleration and deceleration. The time constant is validated when LR (rapid traverse feed with linear acceleration or deceleration) or F (acceleration or deceleration by software) is selected in acceleration or deceleration mode "#2003 smgst."</p> 	1 to 4000 (ms)

6. Axis Specifications Parameters
6.1 Axis Specifications Parameters

#	Items	Details	Setting range (unit)
2005	<p>G01</p> <p>G0 time constant (primary delay)</p> <p>Second-step time constant for acceleration and deceleration by software</p>	<p>Set up a primary-delay time constant for rapid traverse acceleration and deceleration. The time constant is validated when R1 (rapid traverse feed with primary delay) or R3 (exponential acceleration and linear deceleration) is selected in acceleration or deceleration mode "#2003 smgst."</p> <p>When acceleration or deceleration by software is selected, the second-step time constant is used.</p> <p align="center"><Rapid traverse feed with primary delay></p>  <p align="center"><Rapid traverse feed with exponential acceleration and linear deceleration></p>  <p align="center"><Acceleration/deceleration by software></p> 	1 to 5000 (ms)
2006	G02	Not used.	0

6. Axis Specifications Parameters
6.1 Axis Specifications Parameters

#	Items	Details	Setting range (unit)
2007	G1tL	<p>G1 time constant (linear)</p> <p>Set up a linear control time constant for cutting acceleration and deceleration.</p> <p>The time constant is validated when LC (cutting feed with linear acceleration and deceleration) or F (acceleration and deceleration by software) is selected in acceleration or deceleration mode "#2003 smgst."</p> 	1 to 4000 (ms)
2008	G1t1	<p>G1 time constant (primary delay)</p> <p>Set up the primary delay time constant for cutting acceleration and deceleration.</p> <p>The time constant is validated when C1 (cutting feed with the primary delay) or C3 (cutting feed with exponential acceleration and linear deceleration) is selected in acceleration or deceleration mode "#2003 smgst."</p> <p>When acceleration or deceleration by software is selected, the second stage time constant is used.</p> <p>Second-step time constant for acceleration and deceleration by software</p> <p><Cutting feed with primary delay></p>  <p><Cutting feed with exponential acceleration and linear deceleration></p>  <p><Acceleration/deceleration by software></p> 	1 to 5000 (ms)
2009	G1t2	Not used.	

6. Axis Specifications Parameters
6.1 Axis Specifications Parameters

#	Items	Details	Setting range (unit)	
2010	fwd_g	Feed forward gain	Set up a feed forward gain for pre-interpolation acceleration and deceleration. The larger the set value, the smaller the theoretical control error will be. However, if a mechanical vibration occurs, the set value must be reduced.	0 to 100 (%)
2011	G0back	G0 backlash	Set up the backlash compensation amount when the direction is reversed with the movement command in rapid traverse feed mode or in manual mode.	-9999 to 9999 (command unit / 2)
2012	G1back	G1 backlash	Set up the backlash compensation amount when the direction is reversed with the movement command in cutting mode.	-9999 to 9999 (command unit / 2)
2013 2014	OT - OT +	Soft limit I - Soft limit I +	Set up a soft limit area with reference to the zero point of the basic mechanical coordinates. For the movable area of stored stroke limit 1, set the coordinate in the negative direction in #2013 and the coordinate in the positive direction in #2014. To narrow the available range in actual use, use the parameters #8204 OT- and #8205 OT+. (Note) When the same value (other than 0) is set in #2013 and #2014, this function is disabled.	±99999.999 (mm)
2015	t1m1-	Negative direction sensor of tool setter or TLM standard length	Set up a sensor position in the negative direction when using the tool setter. When the TLM is used, set up the distance of a tool replacement point (reference point) for measuring the tool length from the zero point to the measurement reference point (surface).	±99999.999 (mm)
2016	t1m1+	Positive direction sensor of tool setter	Set up the sensor position in the positive direction when using the tool setter.	±99999.999 (mm)


6. Axis Specifications Parameters
6.1 Axis Specifications Parameters

#	Items	Details	Setting range (unit)	
2017	tap_g	Axis servo gain	Set the position loop gain in the synchronous tap cycle. The setting range is 0.25 to 200.00rad/s, in 0.25 increment units. The standard setting is 10.	0.25 to 200.00 (rad/s)
2018	no_srv	Operation with no servo control	Set when performing test operation without connecting the drive amplifier and motor. 0: Specify normal operation. 1: Operation is possible even if units are not connected as the drive system alarm will be ignored. This is for test operation during start up and is not used normally. If 1 is set during normal operation, errors will not be detected even if they occur.	0/1
2019	revnum	Retract steps	Set up the steps required for retracting to the reference point for each axis. 0: Does not execute retracting to the reference point. 1 to 4: Sets up the steps required for retracting to the reference point.	0 to 4
2020	o_chkp	Spindle orientation completion check during second reference point return	Set up the distance from the second reference point to the position for checking that the spindle orientation has completed during second reference point return. If the set value is 0, the above check is omitted.	0 to 99999.999 (mm)
2021	out_f	Maximum speed outside soft limit range	Set up the maximum speed outside the soft limit range.	0 to 1000000
2022	G30SLX	Validate soft limit (automatic and manual)	Set up this function to disable a soft limit check during the second to the fourth reference points return in both automatic and manual operation modes. 0: Enables soft limit check. 1: Disables soft limit check.	0/1
2023	ozfmin	Set up ATC speed lower limit	Set up the minimum speed outside the soft limit range during the second to the fourth reference points return in both automatic and manual operation modes.	0 to 1000000
2024	synerr	Allowable error	Set up the following for the master axis: the maximum synchronization error that is allowed to check for synchronization errors. When 0 is set up, the error check is not carried out.	0 to 99999.999 (mm)



6. Axis Specifications Parameters
6.2 Zero Point Return Parameters

6.2 Zero Point Return Parameters

After setting up the parameter (PR) listed in the table, turn off the NC power. To validate the parameter, turn on the power again.

#	Items	Details	Setting range (unit)
2025	G28rap G28 rapid traverse feedrate	Set up a rapid traverse feedrate for dog type reference point return command.	1 to 1000000 (mm/min)
2026	G28crp G28 approach speed	Set up the speed of approach to the reference point in the reference point return command. This speed is attained after the system stops with deceleration by dog detection. (Note) The G28 approach speed unit is 10°/min only when using the spindle/C-axis with the Z-phase type encoder for the reference point return type ("#1226 aux10" bit3 = 1). Note that this unit is applied to both micrometric and sub-micrometric specifications.	1 to 60000 (mm/min)
2027	G28sft Reference point shift distance	Set up the distance from the electrical zero-point detection position to the actual machine reference point during reference point return.	0 to 65535 (μm)
2028	grmask Grid mask amount	Set up a distance where the grid point is ignored when near-point dog OFF signals are close to that grid point during reference point return.  The grid mask is valid by one grid.	0 to 65535 (μm) Even for the specifications in sub-micrometric system, set up the value in units of μm.
2029	grspc Grid interval	Set up a detector grid interval. Generally, set up the value equal to the ball screw pitch. However, if the detector grid interval is not equal to the screw pitch when measured with a linear scale, set up the detector grid interval. To reduce the grid interval, use its divisors. To use 0.001 mm as minimum setup units, set up the negative value. Example) Setup value 1 → 1.000 mm (°) -1 → 0.001 mm (°) Even when the specifications in sub-micrometrics are used, 0.001 mm is specified for the minimum setup units.	-32767 to 999 (mm)

6. Axis Specifications Parameters
6.2 Zero Point Return Parameters

#	Items	Details	Setting range (unit)
2030 (PR)	dir (-) Reference point direction (-)	<p>Set which side of the near-point dog the reference point is at during reference point return.</p> <p><For dog type reference point return></p> <p>Direction in which zero point is established as viewed from the near-point dog</p> 	0: Positive direction 1: Negative direction
2031	noref Axis without reference point	Specify the axis that does not have a reference point. Before automatic operation starts, reference point return is not required.	0: Normal controlled axis 1: Axis without reference point
2032	nochk Whether reference point return is completed is checked	The absolute and incremental commands can be executed even if dog type (or Z phase pulse system) reference point return is not completed. Specify whether to check that the reference point return is completed.	0: Checks reference point return completion. 1: Does not check reference point return completion.
2037 2038 2039 2040	G53ofs #2_rfp #3_rfp #4_rfp Reference point #1 to #4	<p>Set up the position of the first, second, third, and fourth reference points from the zero point of the basic mechanical coordinates.</p> 	±999999.999 (mm)

6. Axis Specifications Parameters
6.3 Absolute Position Parameters

6.3 Absolute Position Parameters

#	Items	Details	Setting range (unit)
2049 (PR)	type Absolute position detection method	Specify the absolute position zero point alignment method. 0: Not absolute position detection 1: Stopper method (push onto mechanical stopper) 2: Marked point alignment method (align with marked point) 3: Dog-type (align with dog and proximity switch) 9: Simple absolute position detection (Not absolute position detection, but the position when the power is turned off is registered.) Automatic initial setting is valid only when the stopper method is selected.	0 to 9
2050	absdir Base point of Z direction	Set the direction of the grid point just before the marked point (of the detector) when using marked point alignment method.	0: Positive direction 1: Negative direction
2051	check Check	Set the tolerable range for the movement amount (deviation amount) when the power is turned off. 0: Not checked 1 to 99999.999mm: If the difference of the position when the power is turned off and turned on again is larger than this value, an alarm will be output.	0 to 99999.999 (mm)
2052	absg28 Width compared by G28	Specify the position comparison when executing G28 or G30. The comparison results set the tolerable range. 0: No comparison 1 to 65535 (0.5 μm units): If the results of the comparison of the value read in from the detector and the position in the control unit exceed this set value, an alarm will be output, and the machine will stop. The standard value is 100.	0 to 65535 (0.5 μm)
2053	absm02 Width compared by M02	Specify the position comparison when executing M02 or M30. The comparison results set the tolerable range. 0: Not compared 1 to 65535 (0.5 μm units): If the results of the comparison of the value read in from the detector and the position in the control unit exceed this set value, an alarm will be output, and the machine will stop. The standard value is 100.	0 to 65535 (μm)

6. Axis Specifications Parameters
6.3 Absolute Position Parameters

#	Items	Details	Setting range (unit)
2054	clpush Current limit (%)	Set up the current limit value for the initial setting when detecting an absolute position with a dog-less system. The setup value is the ratio of the current limit value to the rated value.	0 to 100 (%)
2055	pushf Push speed	Set the feedrate for the automatic initial setting during stopper method.	1 to 999 (mm/min)
2056	aproch Approach	Set the approach distance for the automatic initial setting in the stopper method. Approach distance: After pushing onto the machine stopper once, the tool returns this distance, and then pushes again. When set to 0, the reference point coordinates set in "#2037 G53ofs" will be used as the approach start position.	0 to 999.999 (mm)
2057	nrefp Near zero point +	Set the width where the near-reference-point signal is output. (Positive direction width) When set to 0, the width is equivalent to the grid width setting.	0 to 32.767 (mm)
2058	nrefn Near zero point -	Set the width where the near-reference-point signal is output. (Negative direction width) When set to 0, the width is equivalent to the grid width setting.	0 to 32.767 (mm)
2059	zerbas Select zero point parameter and reference point	Specify the position to be the zero point coordinate during absolute position initial setting. 0: Machine stopper position in machine stopper method. Marked point in marked point alignment method. 1: On the grid point just before machine stopper in machine stopper. On the grid point just before the marked point in marked point alignment method.	0/1

6. Axis Specifications Parameters
6.4 Axis Specifications Parameters 2

6.4 Axis Specifications Parameters 2

#	Items	Details	Setting range (unit)
2061	OT_1B- Soft limit IB-	Set up the coordinates of the lower limit of the inhibited area of stored stroke limit IB. Specify a value in the basic machine coordinates system. If the same value (other than 0) with the same sign as that of "#2062 OT_1B-" is specified, the stored stroke limit IB function is disabled.	±99999.999 (mm)
2062	OT_1B+ Soft limit IB+	Set up the coordinates of the upper limit of the inhibited area of stored stroke limit IB. Specify a value in the basic machine coordinates system.	±99999.999 (mm)
2063	OT_1B type Soft limit IB type	Select OT_1B or OT_1C in which OT_1B+/- is used in stored stroke limit I. 0: Soft limit IB valid 1: Soft limit IB and IC invalid 2: Soft limit IC valid	0/1/2
2068	G0fwdg G00 feed forward gain	Specify the feed forward gain applicable to acceleration/deceleration before G00 interpolation. The greater the set value, the shorter the positioning time during in-position checking. If machine vibration occurs, decrease the set value.	0 to 200 (%)
2069	Rcoeff Axis arc radius error correction efficient	The amount of arc radius error correction can be increased or decreased between -100% to +100% for each axis.	-100.0 to +100.0 (%)
2070 (PR)	div_RT Rotational axis division count	Specify the number of divisions of one turn of the rotational axis for purpose of control. (Example) When 36 is set, one turn is supposed to be 36.000. (Note) When 0 is set, the normal rotational axis (360.000 degrees for one turn) is assumed. * If this parameter is changed when the absolute position detection specification is used, absolute position data is lost. Initialization must be performed again.	0 to 999

6. Axis Specifications Parameters
6.4 Axis Specifications Parameters 2

#	Items	Details	Setting range (unit)
2073	zrn_dog Origin dog Random assignment device	<p>When it is desired to assign the origin dog signal to a position other than the fixed device, specify the input device in this parameter.</p> <p>(Note1) This parameter is valid when 1 is set in #1226 aux10 bit 5.</p> <p>(Note2) When this parameter is valid, do not set the same device number. If the same device number exists, an emergency stop occurs. Note that the device number is not checked for an axis to which a signal that ignores the fixed signal is input.</p> <p>(Note3) The setting range of this parameter has been expanded on the software Ver.D0 and later.</p>	000 to 3FF (HEX)
2074	H/W_OT+ H/W OT+ Random assignment device	<p>When it is desired to assign the OT (+) g signal to a position other than the fixed device, specify the input device in this parameter.</p> <p>(Note1) This parameter is valid when 1 is set in #1226 aux10 bit 5.</p> <p>(Note2) When this parameter is valid, do not set the same device number. If the same device number exists, an emergency stop occurs. Note that the device number is not checked for an axis to which a signal that ignores the fixed signal is input.</p> <p>(Note3) The setting range of this parameter has been expanded on the software Ver.D0 and later.</p>	000 to 3FF (HEX)
2075	H/W_OT- H/W OT- Random assignment device	<p>When it is desired to assign the OT (-) g signal to a position other than the fixed device, specify the input device in this parameter.</p> <p>(Note1) This parameter is valid when 1 is set in #1226 aux10 bit 5.</p> <p>(Note2) When this parameter is valid, do not set the same device number. If the same device number exists, an emergency stop occurs. Note that the device number is not checked for an axis to which a signal that ignores the fixed signal is input.</p> <p>(Note3) The setting range of this parameter has been expanded on the software Ver.D0 and later.</p>	000 to 3FF (HEX)
2076	index_x Index table indexing axis	<p>Specify the index table indexing axis.</p> <p>0: Normal axis 1: Index table indexing axis</p> <p>(Note) This parameter is valid only for the NC axis. The parameter is invalid if specified for the PLC axis.</p>	0/1

6. Axis Specifications Parameters
6.4 Axis Specifications Parameters 2

#	Items	Details	Setting range (unit)
22011	bscmp- Offset compensation position	Specify the coordinates on the machine basic coordinates where the compensation is carried out by the offset amount.	±99999.999
22012	bscmp+ Max. compensation position	Specify the coordinates on the machine basic coordinates where the compensation is carried out by the max. offset amount.	±99999.999

(Note) The positional relation of either #22011 and #22012 can be on the minus side.

7. Servo Parameters

7. Servo Parameters

The parameters can be changed from any screen.

The valid servo parameters will differ according to the motor type. The setting values and meanings may also differ. Follow the correspondence table given below, and set the correct parameters.

Refer to each Instruction Manual or the following manuals for details on each motor.

MELDAS AC Servo/ Spindle MDS-A Series MDS-B Series Specification ManualBNP-B3759

MELDAS AC Servo MDS-B-SVJ2 Series Specification and Instruction ManualBNP-B3937

MELDAS AC Servo/ Spindle MDS-C1 Series Specification ManualBNP-C3000

Parameter		Corresponding model		
		MDS-B-SVJ2	MDS-C1-Vx (High-gain) (MDS-B-Vx4)	MDS-C1-Vx (Standard) (MDS-B-Vx)
SV001	Motor side gear ratio	○	○	○
SV002	Machine side gear ratio	○	○	○
SV003	Position loop gain 1	○	○	○
SV004	Position loop gain 2	○	○	○
SV005	Speed loop gain 1	○	○	○
SV006	Speed loop gain 2	—	○	○
SV007	Speed loop delay compensation	—	○	○
SV008	Speed loop lead compensation	○	○	○
SV009	Current loop q axis lead compensation	○	○	○
SV010	Current loop d axis lead compensation	○	○	○
SV011	Current loop q axis gain	○	○	○
SV012	Current loop d axis gain	○	○	○
SV013	Current limit value	○	○	○
SV014	Current limit value in special control	○	○	○
SV015	Acceleration rate feed forward gain	○	○	○
SV016	Lost motion compensation 1	○	○	○
SV017	Servo specification selection	○	○	○
SV018	Ball screw pitch	○	○	○
SV019	Position detector resolution	○	○	○
SV020	Speed detector resolution	○	○	○
SV021	Overload detection time constant	○	○	○
SV022	Overload detection level	○	○	○
SV023	Excessive error detection width during servo ON	○	○	○
SV024	In-position detection width	○	○	○
SV025	Motor/Detector type	○	○	○
SV026	Excessive error detection width during servo OFF	○	○	○
SV027	Servo function selection 1	○	○	○
SV028	Linear motor magnetic pole shift length	—	—	—
SV029	Speed at the change of speed loop gain	—	○	○
SV030	Voltage dead time compensation	-/○	○/○	○/○
SV031	Overshooting compensation 1	○	○	○
SV032	Torque offset	○	○	○

7. Servo Parameters

Parameter		Corresponding model		
		MDS-B-SVJ2	MDS-C1-Vx (High-gain) (MDS-B-Vx4)	MDS-C1-Vx (Standard) (MDS-B-Vx)
SV033	Servo function selection 2	○	○	○
SV034	Servo function selection 3	○	○	○
SV035	Servo function selection 4	○	○	○
SV036	Regenerative resistor type	○	○	○
SV037	Load inertia scale	○	○	○
SV038	Notch filter frequency 1	—	○	○
SV039	Lost motion compensation timing	—	○	○
SV040	Non-sensitive band in feed forward control	—/○	○/○	○/○
SV041	Lost motion compensation 2	○	○	○
SV042	Overshooting compensation 2	○	○	○
SV043	Disturbance observer filter frequency	○	○	○
SV044	Disturbance observer gain	○	○	○
SV045	Frictional torque	—/○	○/○	○/○
SV046	Notch filter frequency 2	—	○	—
SV047	Inductive voltage compensation gain	○	○	○
SV048	Vertical axis drop prevention time	○	○	○
SV049	Position loop gain 1 in spindle synchronous control	○	○	○
SV050	Position loop gain 2 in spindle synchronous control	○	○	○
SV051	Dual feedback control time constant	—	○	○
SV052	Dual feedback control non-sensitive band	—	○	○
SV053	Excessive error detection width in special control	○	○	○
SV054	Overrun detection width in closed loop control	—/—	○/○	○/○
SV055	Max. gate off delay time after emergency stop	—	○	○
SV056	Deceleration time constant at emergency stop	○	○	○
SV057	SHG control gain	○	○	○
SV058	SHG control gain in spindle synchronous control	○	○	○
SV059	Collision detection torque estimating gain	○	○	○
SV060	Collision detection level	○	○	○
SV061	D/A output channel 1 data No.	○	○	○
SV062	D/A output channel 2 data No.	○	○	○
SV063	D/A output channel 1 output scale	○	○	○
SV064	D/A output channel 2 output scale	○	○	○
SV065	Tool end compensation spring constant	—	○	—

7. Servo Parameters

7.1 MDS-B-SVJ2

7.1 MDS-B-SVJ2

(1) Details for servo parameters

For parameters marked with a (PR) in the table, turn the NC power OFF after setting. After the power is turned ON again, the parameter is validated.

CAUTION In the explanation on bits, set all bits not used, including blank bits, to "0".
--

No.	Items	Details	Setting range
2201 (PR)	SV001 PC1	Motor side gear ratio	1 to 32767
2202 (PR)	SV002 PC2	Machine side gear ratio	1 to 32767
2203	SV003 PGN1	Position loop gain 1	1 to 200 (rad/s)
2204	SV004 PGN2	Position loop gain 2	0 to 999 (rad/s)
2205	SV005 VGN1	Speed loop gain	1 to 999
2206		Not used. Set to "0".	0
2207		Not used. Set to "0".	0
2208	SV008 VIA	Speed loop lead compensation	1 to 9999
2209	SV009 IQA	Current loop q axis lead compensation	1 to 20480
2210	SV010 IDA	Current loop d axis lead compensation	1 to 20480
2211	SV011 IQG	Current loop q axis gain	1 to 2560
2212	SV012 IDG	Current loop d axis gain	1 to 2560

7. Servo Parameters
7.1 MDS-B-SVJ2

No.	Items	Details	Setting range	
2213	SV013 ILMT	Current limit value	Set the normal current (torque) limit value. (Limit values for both + and - direction.) When the value is "500" (a standard setting), the maximum torque is determined by the specification of the motor.	0 to 500 (Stall [rated] current %)
2214	SV014 ILMTsp	Current limit value in special control	Set the current (torque) limit value in a special control (initial absolute position setting, stopper control, etc). (Limit values for both of the + and - directions.) Set to "500" when not using.	0 to 500 (Stall [rated] current %)
2215	SV015 FFC	Acceleration rate feed forward gain	When a relative error in the synchronous control is large, apply this parameter to the axis that is delaying. The standard setting value is "0". For the SHG control, set to "100". To adjust a relative error in acceleration/ deceleration, increase the value by 50 to 100 at a time.	0 to 999 (%)
2216	SV016 LMC1	Lost motion compensation 1	Set this when the protrusion (that occurs due to the non-sensitive band by friction, torsion, backlash, etc) at quadrant change is too large. This compensates the torque at quadrant change. This is valid only when the lost motion compensation (SV027 (SSF1/lmc)) is selected.	
		Type 1: When SV027 (SSF1)/ bit9, 8 (lmc)=01 Set the compensation amount based on the motor torque before the quadrant change. The standard setting is "100". Setting to "0" means the compensation amount is zero. Normally, use Type 2.	-1 to 200 (%)	
		Type 2: When SV027 (SSF1)/ bit9, 8 (lmc)=10 Set the compensation amount based on the stall (rated) current of the motor. The standard setting is double of the friction torque. Setting to "0" means the compensation amount is zero.	-1 to 100 (Stall [rated] current %)	
		When you wish different compensation amount depending on the direction When SV041 (LMC2) is "0", compensate with the value of SV016 (LMC1) in both of the + and -directions. If you wish to change the compensation amount depending on the command direction, set this and SV041 (LMC2). (SV016: + direction, SV041: - direction. However, the directions may be opposite depending on other settings.) When "-1" is set, the compensation won't be performed in the direction of the command.		

7. Servo Parameters
7.1 MDS-B-SVJ2

No.	Items	Details	Setting range																																																																																																				
2217 (PR)	SV017 SPEC	Servo specification selection	<table border="1" style="width:100%; text-align:center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td colspan="8"> </td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td>abs</td><td></td><td>vdir</td><td></td><td>mc</td><td></td><td></td><td>dmk</td> </tr> </table> <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>bit</th> <th></th> <th>Meaning when "0" is set</th> <th>Meaning when "1" is set</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>dmk</td> <td>Deceleration control stop (SVJ2 standard)</td> <td>Dynamic brake stop</td> </tr> <tr> <td>1</td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td></td> <td></td> <td></td> </tr> <tr> <td>3</td> <td>mc</td> <td>Contactor control output invalid</td> <td>Contactor control output valid</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td>vdir</td> <td>HA053N to HA33N motor Detector installation position standard (A, C)</td> <td>HA053N to HA33N motor Detector installation position 90 degrees (B, D)</td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td>abs</td> <td>Incremental control</td> <td>Absolute position control</td> </tr> <tr> <td>8</td> <td></td> <td></td> <td></td> </tr> <tr> <td>9</td> <td></td> <td></td> <td></td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> <td></td> </tr> <tr> <td>D</td> <td></td> <td></td> <td></td> </tr> <tr> <td>E</td> <td></td> <td></td> <td></td> </tr> <tr> <td>F</td> <td></td> <td></td> <td></td> </tr> </tbody> </table> <p>(Note) Set to "0" for bits with no particular description.</p>	F	E	D	C	B	A	9	8									7	6	5	4	3	2	1	0	abs		vdir		mc			dmk	bit		Meaning when "0" is set	Meaning when "1" is set	0	dmk	Deceleration control stop (SVJ2 standard)	Dynamic brake stop	1				2				3	mc	Contactor control output invalid	Contactor control output valid	4				5	vdir	HA053N to HA33N motor Detector installation position standard (A, C)	HA053N to HA33N motor Detector installation position 90 degrees (B, D)	6				7	abs	Incremental control	Absolute position control	8				9				A				B				C				D				E				F			
F	E	D	C	B	A	9	8																																																																																																
7	6	5	4	3	2	1	0																																																																																																
abs		vdir		mc			dmk																																																																																																
bit		Meaning when "0" is set	Meaning when "1" is set																																																																																																				
0	dmk	Deceleration control stop (SVJ2 standard)	Dynamic brake stop																																																																																																				
1																																																																																																							
2																																																																																																							
3	mc	Contactor control output invalid	Contactor control output valid																																																																																																				
4																																																																																																							
5	vdir	HA053N to HA33N motor Detector installation position standard (A, C)	HA053N to HA33N motor Detector installation position 90 degrees (B, D)																																																																																																				
6																																																																																																							
7	abs	Incremental control	Absolute position control																																																																																																				
8																																																																																																							
9																																																																																																							
A																																																																																																							
B																																																																																																							
C																																																																																																							
D																																																																																																							
E																																																																																																							
F																																																																																																							
2218 (PR)	SV018 PIT	Ball screw pitch	Set the ball screw pitch. Set to "360" for the rotary axis. 1 to 32767 (mm/rev)																																																																																																				
2219 (PR)	SV019 RNG1	Position detector resolution	For both parameters, set the number of pulses per one revolution of the motor detector. 8 to 100 (kp/rev)																																																																																																				
2220 (PR)	SV020 RNG2	Speed detector resolution	<table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th rowspan="2">Motor model name</th> <th colspan="2">Setting value</th> </tr> <tr> <th>SV019</th> <th>SV020</th> </tr> </thead> <tbody> <tr> <td>HC*-E42/A42/A47, HC*R-E42/A42/A47 HA*N-E42/A42</td> <td>100</td> <td>100</td> </tr> <tr> <td>HC*-E33/A33, HC*R-E33/A33 HA*N-E33/A33</td> <td>25</td> <td>25</td> </tr> <tr> <td>HC-SF, HC-RF</td> <td>16</td> <td>16</td> </tr> <tr> <td>HA-FF, HC-MF</td> <td>8</td> <td>8</td> </tr> </tbody> </table>	Motor model name	Setting value		SV019	SV020	HC*-E42/A42/A47, HC*R-E42/A42/A47 HA*N-E42/A42	100	100	HC*-E33/A33, HC*R-E33/A33 HA*N-E33/A33	25	25	HC-SF, HC-RF	16	16	HA-FF, HC-MF	8	8																																																																																			
Motor model name	Setting value																																																																																																						
	SV019	SV020																																																																																																					
HC*-E42/A42/A47, HC*R-E42/A42/A47 HA*N-E42/A42	100	100																																																																																																					
HC*-E33/A33, HC*R-E33/A33 HA*N-E33/A33	25	25																																																																																																					
HC-SF, HC-RF	16	16																																																																																																					
HA-FF, HC-MF	8	8																																																																																																					

7. Servo Parameters
7.1 MDS-B-SVJ2

No.	Items	Details	Setting range
2221	SV021 OLT	Overload detection time constant	1 to 300 (s)
2222	SV022 OLL	Overload detection level	50 to 180 (Stall [rated] current %)
2223	SV023 OD1	Excessive error detection width during servo ON	0 to 32767 (mm)
2224	SV024 INP	In-position detection width	0 to 32767 (μm)

7. Servo Parameters
7.1 MDS-B-SVJ2

No.	Items	Details	Setting range																																																																																																																																																																																																																																																																																																																																																																													
2225 (PR)	SV025 MTYP Motor/ Detector type	<table border="1" style="width:100%; text-align:center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td colspan="4">pen</td><td colspan="4">ent</td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td colspan="8">mtyp</td> </tr> </table>	F	E	D	C	B	A	9	8	pen				ent				7	6	5	4	3	2	1	0	mtyp																																																																																																																																																																																																																																																																																																																																																					
F	E	D	C	B	A	9	8																																																																																																																																																																																																																																																																																																																																																																									
pen				ent																																																																																																																																																																																																																																																																																																																																																																												
7	6	5	4	3	2	1	0																																																																																																																																																																																																																																																																																																																																																																									
mtyp																																																																																																																																																																																																																																																																																																																																																																																
		<table border="1" style="width:100%;"> <thead> <tr> <th data-bbox="560 557 683 591">bit</th> <th colspan="10" data-bbox="691 557 1445 591">Explanation</th> </tr> </thead> <tbody> <tr> <td data-bbox="560 602 683 636">0</td> <td colspan="10" data-bbox="691 602 1445 636">Set the motor type.</td> </tr> <tr> <td data-bbox="560 647 683 680">1</td> <td data-bbox="691 647 778 680">Set- ting</td> <td data-bbox="786 647 874 680">0x</td> <td data-bbox="882 647 922 680">1x</td> <td data-bbox="930 647 970 680">2x</td> <td data-bbox="978 647 1018 680">3x</td> <td data-bbox="1026 647 1066 680">4x</td> <td data-bbox="1074 647 1114 680">5x</td> <td data-bbox="1121 647 1161 680">6x</td> <td data-bbox="1169 647 1209 680">7x</td> <td data-bbox="1217 647 1257 680">8x</td> <td data-bbox="1265 647 1445 680"></td> </tr> <tr> <td data-bbox="560 692 683 725">2</td> <td data-bbox="691 692 778 725">x0</td> <td data-bbox="786 692 874 725">HA40N</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td data-bbox="1169 692 1257 725">HA-FF43</td> <td data-bbox="1265 692 1445 725">HA43N</td> <td></td> </tr> <tr> <td data-bbox="560 736 683 770">3</td> <td data-bbox="691 736 778 770">x1</td> <td data-bbox="786 736 874 770">HA80N</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td data-bbox="1169 736 1257 770">HA-FF63</td> <td data-bbox="1265 736 1445 770">HA83N</td> <td></td> </tr> <tr> <td data-bbox="560 781 683 815">4</td> <td data-bbox="691 781 778 815">x2</td> <td data-bbox="786 781 874 815">HA100N</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td data-bbox="1265 781 1445 815">HA103N</td> <td></td> </tr> <tr> <td data-bbox="560 826 683 860">5</td> <td data-bbox="691 826 778 860">x3</td> <td data-bbox="786 826 874 860">HA200N</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="560 871 683 904">6</td> <td data-bbox="691 871 778 904">x4</td> <td></td> </tr> <tr> <td data-bbox="560 916 683 949">7</td> <td data-bbox="691 916 778 949">x5</td> <td></td> </tr> <tr> <td></td> <td data-bbox="691 960 778 994">x6</td> <td></td> </tr> <tr> <td></td> <td data-bbox="691 1005 778 1039">x7</td> <td></td> </tr> <tr> <td></td> <td data-bbox="691 1050 778 1084">x8</td> <td></td> </tr> <tr> <td></td> <td data-bbox="691 1095 778 1128">x9</td> <td></td> </tr> <tr> <td></td> <td data-bbox="691 1140 778 1173">xA</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td data-bbox="1265 1140 1445 1173">HA93N</td> <td></td> </tr> <tr> <td></td> <td data-bbox="691 1184 778 1218">xB</td> <td></td> </tr> <tr> <td></td> <td data-bbox="691 1229 778 1263">xC</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td data-bbox="1169 1229 1257 1263">HA-FF053</td> <td data-bbox="1265 1229 1445 1263">HA053N</td> <td></td> </tr> <tr> <td></td> <td data-bbox="691 1274 778 1308">xD</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td data-bbox="1169 1274 1257 1308">HA-FF13</td> <td data-bbox="1265 1274 1445 1308">HA13N</td> <td></td> </tr> <tr> <td></td> <td data-bbox="691 1319 778 1352">xE</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td data-bbox="1169 1319 1257 1352">HA-FF23</td> <td data-bbox="1265 1319 1445 1352">HA23N</td> <td></td> </tr> <tr> <td></td> <td data-bbox="691 1364 778 1397">xF</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td data-bbox="1169 1364 1257 1397">HA-FF33</td> <td data-bbox="1265 1364 1445 1397">HA33N</td> <td></td> </tr> <tr> <td colspan="2"></td> <td data-bbox="691 1408 1445 1957"> <table border="1" style="width:100%;"> <thead> <tr> <th data-bbox="699 1420 778 1453">Set- ting</th> <th data-bbox="786 1420 874 1453">9x</th> <th data-bbox="882 1420 922 1453">Ax</th> <th data-bbox="930 1420 970 1453">Bx</th> <th data-bbox="978 1420 1018 1453">Cx</th> <th data-bbox="1026 1420 1066 1453">Dx</th> <th data-bbox="1074 1420 1114 1453">Ex</th> <th data-bbox="1121 1420 1161 1453">Fx</th> </tr> </thead> <tbody> <tr> <td data-bbox="699 1453 778 1487">x0</td> <td data-bbox="786 1453 874 1487">HC-MF43</td> <td></td> <td data-bbox="930 1453 1018 1487">HC52 or HC-SF52</td> <td data-bbox="1026 1453 1114 1487">HC53 or HC-SF53</td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1498 778 1532">x1</td> <td data-bbox="786 1498 874 1532">HC-MF73</td> <td></td> <td data-bbox="930 1498 1018 1532">HC102 or HC-SF102</td> <td data-bbox="1026 1498 1114 1532">HC103 or HC-SF103</td> <td></td> <td data-bbox="1169 1498 1257 1532">HC103R or HC-RF103</td> <td></td> </tr> <tr> <td data-bbox="699 1543 778 1576">x2</td> <td></td> <td></td> <td data-bbox="930 1543 1018 1576">HC152 or HC-SF152</td> <td data-bbox="1026 1543 1114 1576">HC153 or HC-SF153</td> <td></td> <td data-bbox="1169 1543 1257 1576">HC153R or HC-RF153</td> <td></td> </tr> <tr> <td data-bbox="699 1588 778 1621">x3</td> <td></td> <td></td> <td data-bbox="930 1588 1018 1621">HC202 or HC-SF202</td> <td data-bbox="1026 1588 1114 1621">HC203 or HC-SF203</td> <td></td> <td data-bbox="1169 1588 1257 1621">HC203R or HC-RF203</td> <td></td> </tr> <tr> <td data-bbox="699 1632 778 1666">x4</td> <td></td> <td></td> <td data-bbox="930 1632 1018 1666">HC352 or HC-SF352</td> <td data-bbox="1026 1632 1114 1666">HC-SF353</td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1677 778 1711">x5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1722 778 1756">x6</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1767 778 1800">x7</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1812 778 1845">x8</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1856 778 1890">x9</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1901 778 1935">xA</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1946 778 1980">xB</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1991 778 2024">xC</td> <td data-bbox="786 1991 874 2024">HC-MF053</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 2036 778 2069">xD</td> <td data-bbox="786 2036 874 2069">HC-MF13</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 2080 778 2114">xE</td> <td data-bbox="786 2080 874 2114">HC-MF23</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 2125 778 2159">xF</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table> </td> <td></td> </tr> </tbody> </table>	bit	Explanation										0	Set the motor type.										1	Set- ting	0x	1x	2x	3x	4x	5x	6x	7x	8x		2	x0	HA40N							HA-FF43	HA43N		3	x1	HA80N							HA-FF63	HA83N		4	x2	HA100N								HA103N		5	x3	HA200N										6	x4											7	x5												x6												x7												x8												x9												xA									HA93N			xB												xC								HA-FF053	HA053N			xD								HA-FF13	HA13N			xE								HA-FF23	HA23N			xF								HA-FF33	HA33N				<table border="1" style="width:100%;"> <thead> <tr> <th data-bbox="699 1420 778 1453">Set- ting</th> <th data-bbox="786 1420 874 1453">9x</th> <th data-bbox="882 1420 922 1453">Ax</th> <th data-bbox="930 1420 970 1453">Bx</th> <th data-bbox="978 1420 1018 1453">Cx</th> <th data-bbox="1026 1420 1066 1453">Dx</th> <th data-bbox="1074 1420 1114 1453">Ex</th> <th data-bbox="1121 1420 1161 1453">Fx</th> </tr> </thead> <tbody> <tr> <td data-bbox="699 1453 778 1487">x0</td> <td data-bbox="786 1453 874 1487">HC-MF43</td> <td></td> <td data-bbox="930 1453 1018 1487">HC52 or HC-SF52</td> <td data-bbox="1026 1453 1114 1487">HC53 or HC-SF53</td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1498 778 1532">x1</td> <td data-bbox="786 1498 874 1532">HC-MF73</td> <td></td> <td data-bbox="930 1498 1018 1532">HC102 or HC-SF102</td> <td data-bbox="1026 1498 1114 1532">HC103 or HC-SF103</td> <td></td> <td data-bbox="1169 1498 1257 1532">HC103R or HC-RF103</td> <td></td> </tr> <tr> <td data-bbox="699 1543 778 1576">x2</td> <td></td> <td></td> <td data-bbox="930 1543 1018 1576">HC152 or HC-SF152</td> <td data-bbox="1026 1543 1114 1576">HC153 or HC-SF153</td> <td></td> <td data-bbox="1169 1543 1257 1576">HC153R or HC-RF153</td> <td></td> </tr> <tr> <td data-bbox="699 1588 778 1621">x3</td> <td></td> <td></td> <td data-bbox="930 1588 1018 1621">HC202 or HC-SF202</td> <td data-bbox="1026 1588 1114 1621">HC203 or HC-SF203</td> <td></td> <td data-bbox="1169 1588 1257 1621">HC203R or HC-RF203</td> <td></td> </tr> <tr> <td data-bbox="699 1632 778 1666">x4</td> <td></td> <td></td> <td data-bbox="930 1632 1018 1666">HC352 or HC-SF352</td> <td data-bbox="1026 1632 1114 1666">HC-SF353</td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1677 778 1711">x5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1722 778 1756">x6</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1767 778 1800">x7</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1812 778 1845">x8</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1856 778 1890">x9</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1901 778 1935">xA</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1946 778 1980">xB</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1991 778 2024">xC</td> <td data-bbox="786 1991 874 2024">HC-MF053</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 2036 778 2069">xD</td> <td data-bbox="786 2036 874 2069">HC-MF13</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 2080 778 2114">xE</td> <td data-bbox="786 2080 874 2114">HC-MF23</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 2125 778 2159">xF</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Set- ting	9x	Ax	Bx	Cx	Dx	Ex	Fx	x0	HC-MF43		HC52 or HC-SF52	HC53 or HC-SF53				x1	HC-MF73		HC102 or HC-SF102	HC103 or HC-SF103		HC103R or HC-RF103		x2			HC152 or HC-SF152	HC153 or HC-SF153		HC153R or HC-RF153		x3			HC202 or HC-SF202	HC203 or HC-SF203		HC203R or HC-RF203		x4			HC352 or HC-SF352	HC-SF353				x5								x6								x7								x8								x9								xA								xB								xC	HC-MF053							xD	HC-MF13							xE	HC-MF23							xF								
bit	Explanation																																																																																																																																																																																																																																																																																																																																																																															
0	Set the motor type.																																																																																																																																																																																																																																																																																																																																																																															
1	Set- ting	0x	1x	2x	3x	4x	5x	6x	7x	8x																																																																																																																																																																																																																																																																																																																																																																						
2	x0	HA40N							HA-FF43	HA43N																																																																																																																																																																																																																																																																																																																																																																						
3	x1	HA80N							HA-FF63	HA83N																																																																																																																																																																																																																																																																																																																																																																						
4	x2	HA100N								HA103N																																																																																																																																																																																																																																																																																																																																																																						
5	x3	HA200N																																																																																																																																																																																																																																																																																																																																																																														
6	x4																																																																																																																																																																																																																																																																																																																																																																															
7	x5																																																																																																																																																																																																																																																																																																																																																																															
	x6																																																																																																																																																																																																																																																																																																																																																																															
	x7																																																																																																																																																																																																																																																																																																																																																																															
	x8																																																																																																																																																																																																																																																																																																																																																																															
	x9																																																																																																																																																																																																																																																																																																																																																																															
	xA									HA93N																																																																																																																																																																																																																																																																																																																																																																						
	xB																																																																																																																																																																																																																																																																																																																																																																															
	xC								HA-FF053	HA053N																																																																																																																																																																																																																																																																																																																																																																						
	xD								HA-FF13	HA13N																																																																																																																																																																																																																																																																																																																																																																						
	xE								HA-FF23	HA23N																																																																																																																																																																																																																																																																																																																																																																						
	xF								HA-FF33	HA33N																																																																																																																																																																																																																																																																																																																																																																						
		<table border="1" style="width:100%;"> <thead> <tr> <th data-bbox="699 1420 778 1453">Set- ting</th> <th data-bbox="786 1420 874 1453">9x</th> <th data-bbox="882 1420 922 1453">Ax</th> <th data-bbox="930 1420 970 1453">Bx</th> <th data-bbox="978 1420 1018 1453">Cx</th> <th data-bbox="1026 1420 1066 1453">Dx</th> <th data-bbox="1074 1420 1114 1453">Ex</th> <th data-bbox="1121 1420 1161 1453">Fx</th> </tr> </thead> <tbody> <tr> <td data-bbox="699 1453 778 1487">x0</td> <td data-bbox="786 1453 874 1487">HC-MF43</td> <td></td> <td data-bbox="930 1453 1018 1487">HC52 or HC-SF52</td> <td data-bbox="1026 1453 1114 1487">HC53 or HC-SF53</td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1498 778 1532">x1</td> <td data-bbox="786 1498 874 1532">HC-MF73</td> <td></td> <td data-bbox="930 1498 1018 1532">HC102 or HC-SF102</td> <td data-bbox="1026 1498 1114 1532">HC103 or HC-SF103</td> <td></td> <td data-bbox="1169 1498 1257 1532">HC103R or HC-RF103</td> <td></td> </tr> <tr> <td data-bbox="699 1543 778 1576">x2</td> <td></td> <td></td> <td data-bbox="930 1543 1018 1576">HC152 or HC-SF152</td> <td data-bbox="1026 1543 1114 1576">HC153 or HC-SF153</td> <td></td> <td data-bbox="1169 1543 1257 1576">HC153R or HC-RF153</td> <td></td> </tr> <tr> <td data-bbox="699 1588 778 1621">x3</td> <td></td> <td></td> <td data-bbox="930 1588 1018 1621">HC202 or HC-SF202</td> <td data-bbox="1026 1588 1114 1621">HC203 or HC-SF203</td> <td></td> <td data-bbox="1169 1588 1257 1621">HC203R or HC-RF203</td> <td></td> </tr> <tr> <td data-bbox="699 1632 778 1666">x4</td> <td></td> <td></td> <td data-bbox="930 1632 1018 1666">HC352 or HC-SF352</td> <td data-bbox="1026 1632 1114 1666">HC-SF353</td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1677 778 1711">x5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1722 778 1756">x6</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1767 778 1800">x7</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1812 778 1845">x8</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1856 778 1890">x9</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1901 778 1935">xA</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1946 778 1980">xB</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 1991 778 2024">xC</td> <td data-bbox="786 1991 874 2024">HC-MF053</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 2036 778 2069">xD</td> <td data-bbox="786 2036 874 2069">HC-MF13</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 2080 778 2114">xE</td> <td data-bbox="786 2080 874 2114">HC-MF23</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td data-bbox="699 2125 778 2159">xF</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Set- ting	9x	Ax	Bx	Cx	Dx	Ex	Fx	x0	HC-MF43		HC52 or HC-SF52	HC53 or HC-SF53				x1	HC-MF73		HC102 or HC-SF102	HC103 or HC-SF103		HC103R or HC-RF103		x2			HC152 or HC-SF152	HC153 or HC-SF153		HC153R or HC-RF153		x3			HC202 or HC-SF202	HC203 or HC-SF203		HC203R or HC-RF203		x4			HC352 or HC-SF352	HC-SF353				x5								x6								x7								x8								x9								xA								xB								xC	HC-MF053							xD	HC-MF13							xE	HC-MF23							xF																																																																																																																																																																																																																																													
Set- ting	9x	Ax	Bx	Cx	Dx	Ex	Fx																																																																																																																																																																																																																																																																																																																																																																									
x0	HC-MF43		HC52 or HC-SF52	HC53 or HC-SF53																																																																																																																																																																																																																																																																																																																																																																												
x1	HC-MF73		HC102 or HC-SF102	HC103 or HC-SF103		HC103R or HC-RF103																																																																																																																																																																																																																																																																																																																																																																										
x2			HC152 or HC-SF152	HC153 or HC-SF153		HC153R or HC-RF153																																																																																																																																																																																																																																																																																																																																																																										
x3			HC202 or HC-SF202	HC203 or HC-SF203		HC203R or HC-RF203																																																																																																																																																																																																																																																																																																																																																																										
x4			HC352 or HC-SF352	HC-SF353																																																																																																																																																																																																																																																																																																																																																																												
x5																																																																																																																																																																																																																																																																																																																																																																																
x6																																																																																																																																																																																																																																																																																																																																																																																
x7																																																																																																																																																																																																																																																																																																																																																																																
x8																																																																																																																																																																																																																																																																																																																																																																																
x9																																																																																																																																																																																																																																																																																																																																																																																
xA																																																																																																																																																																																																																																																																																																																																																																																
xB																																																																																																																																																																																																																																																																																																																																																																																
xC	HC-MF053																																																																																																																																																																																																																																																																																																																																																																															
xD	HC-MF13																																																																																																																																																																																																																																																																																																																																																																															
xE	HC-MF23																																																																																																																																																																																																																																																																																																																																																																															
xF																																																																																																																																																																																																																																																																																																																																																																																

(To be continued to the next page)

7. Servo Parameters
7.1 MDS-B-SVJ2

No.	Items	Details	Setting range																																																																																											
		(Continued from the previous page) <table border="1" data-bbox="571 398 1449 689"> <thead> <tr> <th colspan="2">bit</th> <th>Explanation</th> </tr> </thead> <tbody> <tr> <td>8</td> <td rowspan="4">ent</td> <td rowspan="4">Set the speed detector type. Set to "2".</td> </tr> <tr> <td>9</td> </tr> <tr> <td>A</td> </tr> <tr> <td>B</td> </tr> <tr> <td>C</td> <td rowspan="4">pen</td> <td rowspan="4">Set the position detector type. Set to "2".</td> </tr> <tr> <td>D</td> </tr> <tr> <td>E</td> </tr> <tr> <td>F</td> </tr> </tbody> </table>	bit		Explanation	8	ent	Set the speed detector type. Set to "2".	9	A	B	C	pen	Set the position detector type. Set to "2".	D	E	F																																																																													
bit		Explanation																																																																																												
8	ent	Set the speed detector type. Set to "2".																																																																																												
9																																																																																														
A																																																																																														
B																																																																																														
C	pen	Set the position detector type. Set to "2".																																																																																												
D																																																																																														
E																																																																																														
F																																																																																														
2226	SV026 OD2	Excessive error detection width during servo OFF Set the excessive error detection width when servo ON. For the standard setting, refer to the explanation of SV023 (OD1). When "0" is set, the excessive error detection will not be performed.	0 to 32767 (mm)																																																																																											
2227	SV027 SSF1	Servo function selection 1 <table border="1" data-bbox="580 896 1439 1039"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td>aflt</td><td>zrn2</td><td></td><td></td><td>ovs</td><td></td><td>lmc</td><td></td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td></td><td></td><td>vfct</td><td></td><td></td><td></td><td></td><td>zup</td> </tr> </table> <table border="1" data-bbox="571 1088 1449 2033"> <thead> <tr> <th>bit</th> <th></th> <th>Meaning when "0" is set</th> <th>Meaning when "1" is set</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>zup</td> <td>Vertical axis lift-up control stop</td> <td>Vertical axis lift-up control start</td> </tr> <tr> <td>1</td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td></td> <td></td> <td></td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td rowspan="2">vfct</td> <td rowspan="2">Set the jitter compensation No. of compensation pulses with a binary. 00: Jitter compensation invalid 01: Jitter compensation 1 pulse 10: Jitter compensation 2 pulses 11: Jitter compensation 3 pulses</td> <td rowspan="2"></td> </tr> <tr> <td>5</td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> <td></td> </tr> <tr> <td>8</td> <td rowspan="2">lmc</td> <td rowspan="2">Set the compensation amount with SV016 (LMC1) and SV041 (LMC2). 00: Lost motion compensation stop 01: Lost motion compensation type 1 10: Lost motion compensation type 2 11: Setting prohibited</td> <td rowspan="2"></td> </tr> <tr> <td>9</td> </tr> <tr> <td>A</td> <td rowspan="2">ovs</td> <td rowspan="2">Set the compensation amount with SV031 (OVS1) and SV042 (OVS2). 00: Overshooting compensation stop 01: Overshooting compensation type 1 10: Overshooting compensation type 2 11: Setting prohibited</td> <td rowspan="2"></td> </tr> <tr> <td>B</td> </tr> <tr> <td>C</td> <td></td> <td></td> <td></td> </tr> <tr> <td>D</td> <td></td> <td></td> <td></td> </tr> <tr> <td>E</td> <td>zrn2</td> <td>Set to "1".</td> <td></td> </tr> <tr> <td>F</td> <td>aflt</td> <td>Adoptive filter stops</td> <td>Adoptive filter starts</td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8	aflt	zrn2			ovs		lmc		7	6	5	4	3	2	1	0			vfct					zup	bit		Meaning when "0" is set	Meaning when "1" is set	0	zup	Vertical axis lift-up control stop	Vertical axis lift-up control start	1				2				3				4	vfct	Set the jitter compensation No. of compensation pulses with a binary. 00: Jitter compensation invalid 01: Jitter compensation 1 pulse 10: Jitter compensation 2 pulses 11: Jitter compensation 3 pulses		5	6				7				8	lmc	Set the compensation amount with SV016 (LMC1) and SV041 (LMC2). 00: Lost motion compensation stop 01: Lost motion compensation type 1 10: Lost motion compensation type 2 11: Setting prohibited		9	A	ovs	Set the compensation amount with SV031 (OVS1) and SV042 (OVS2). 00: Overshooting compensation stop 01: Overshooting compensation type 1 10: Overshooting compensation type 2 11: Setting prohibited		B	C				D				E	zrn2	Set to "1".		F	aflt	Adoptive filter stops	Adoptive filter starts	(Note) Set to "0" for bits with no particular description.
F	E	D	C	B	A	9	8																																																																																							
aflt	zrn2			ovs		lmc																																																																																								
7	6	5	4	3	2	1	0																																																																																							
		vfct					zup																																																																																							
bit		Meaning when "0" is set	Meaning when "1" is set																																																																																											
0	zup	Vertical axis lift-up control stop	Vertical axis lift-up control start																																																																																											
1																																																																																														
2																																																																																														
3																																																																																														
4	vfct	Set the jitter compensation No. of compensation pulses with a binary. 00: Jitter compensation invalid 01: Jitter compensation 1 pulse 10: Jitter compensation 2 pulses 11: Jitter compensation 3 pulses																																																																																												
5																																																																																														
6																																																																																														
7																																																																																														
8	lmc	Set the compensation amount with SV016 (LMC1) and SV041 (LMC2). 00: Lost motion compensation stop 01: Lost motion compensation type 1 10: Lost motion compensation type 2 11: Setting prohibited																																																																																												
9																																																																																														
A	ovs	Set the compensation amount with SV031 (OVS1) and SV042 (OVS2). 00: Overshooting compensation stop 01: Overshooting compensation type 1 10: Overshooting compensation type 2 11: Setting prohibited																																																																																												
B																																																																																														
C																																																																																														
D																																																																																														
E	zrn2	Set to "1".																																																																																												
F	aflt	Adoptive filter stops	Adoptive filter starts																																																																																											

7. Servo Parameters
7.1 MDS-B-SVJ2

No.	Items	Details	Setting range	
2228	SV028		Not used. Set to "0".	0
2229	SV029		Not used. Set to "0".	0
2230	SV030 IVC	Voltage dead time compensation	When 100% is set, the voltage equivalent to the logical non-energized time will be compensated. Adjust in increments of 10% from the default value 100%. If increased too much, vibration or vibration noise may be generated. When not using, set to "0".	0 to 200 (%)
2231	SV031 OVS1	Overshooting compensation 1	<p>Set this if overshooting occurs during positioning. This compensates the motor torque during positioning. This is valid only when the overshooting compensation SV027 (SSF1/ovs) is selected.</p> <p>Type 1: When SV027 (SSF1)/ bit11, 10 (ovs)=01 Set the compensation amount based on the motor's stall (rated) current. Increase by 1% and determine the amount that overshooting doesn't occur. In Type 1, compensation during the feed forward control during circular cutting won't be performed.</p> <p>Type 2: When SV027 (SSF1)/ bit11, 10 (ovs)=10 Use this if you perform the overshooting compensation during the feed forward control during circular cutting. The setting method is the same in Type 1.</p> <p>When you wish different compensation amount depending on the direction When SV042 (OVS2) is "0", compensate with the value of SV031 (OVS1) in both of the + and -directions. If you wish to change the compensation amount depending on the command direction, set this and SV042 (OVS2). (SV031: + direction, SV042: - direction. However, the directions may be opposite depending on other settings.) When "-1" is set, the compensation won't be performed in the direction of the command.</p>	-1 to 100 (Stall [rated] current %)
2232	SV032 TOF	Torque offset	Set the unbalance torque of vertical axis and inclined axis.	-100 to 100 (Stall [rated] current %)

7. Servo Parameters
7.1 MDS-B-SVJ2

No.	Items	Details	Setting range																																				
2234	SV034 SSF3	Servo function selection 3	<table border="1"> <tr> <td align="center">F</td> <td align="center">E</td> <td align="center">D</td> <td align="center">C</td> <td align="center">B</td> <td align="center">A</td> <td align="center">9</td> <td align="center">8</td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td align="center">7</td> <td align="center">6</td> <td align="center">5</td> <td align="center">4</td> <td align="center">3</td> <td align="center">2</td> <td align="center">1</td> <td align="center">0</td> </tr> <tr> <td align="center">daf2</td> <td align="center">daf1</td> <td align="center">dac2</td> <td align="center">dac1</td> <td align="center" colspan="4">mon</td> </tr> </table>	F	E	D	C	B	A	9	8									7	6	5	4	3	2	1	0	daf2	daf1	dac2	dac1	mon							
			F	E	D	C	B	A	9	8																													
			7	6	5	4	3	2	1	0																													
			daf2	daf1	dac2	dac1	mon																																
			<table border="1"> <thead> <tr> <th>bit</th> <th>Meaning when "0" is set</th> <th>Meaning when "1" is set</th> </tr> </thead> <tbody> <tr> <td align="center">0</td> <td colspan="2">NC servo monitor MAX current display data changeover</td> </tr> <tr> <td align="center">1</td> <td align="center">Set- ting</td> <td align="center">MAX current 1</td> </tr> <tr> <td align="center">2</td> <td align="center">0</td> <td align="center">MAX current 2</td> </tr> <tr> <td align="center">3</td> <td align="center">1</td> <td align="center">MAX current 1</td> </tr> <tr> <td></td> <td align="center">2</td> <td align="center">MAX current 2</td> </tr> <tr> <td></td> <td align="center">3</td> <td align="center">-</td> </tr> <tr> <td></td> <td align="center">4</td> <td align="center">Adaptive filter operation gain (%)</td> </tr> <tr> <td></td> <td align="center">5</td> <td align="center">Regenerative operation frequency monitor (The number of times/sec)</td> </tr> <tr> <td></td> <td align="center">6</td> <td align="center">MAX current FB value for one second (%)</td> </tr> <tr> <td></td> <td align="center">7</td> <td align="center">MAX disturbance torque for two seconds (%)</td> </tr> <tr> <td></td> <td align="center">8 to F</td> <td align="center">Setting prohibited</td> </tr> </tbody> </table>	bit	Meaning when "0" is set	Meaning when "1" is set	0	NC servo monitor MAX current display data changeover		1	Set- ting	MAX current 1	2	0	MAX current 2	3	1	MAX current 1		2	MAX current 2		3	-		4	Adaptive filter operation gain (%)		5	Regenerative operation frequency monitor (The number of times/sec)		6	MAX current FB value for one second (%)		7	MAX disturbance torque for two seconds (%)		8 to F	Setting prohibited
			bit	Meaning when "0" is set	Meaning when "1" is set																																		
			0	NC servo monitor MAX current display data changeover																																			
			1	Set- ting	MAX current 1																																		
			2	0	MAX current 2																																		
3	1	MAX current 1																																					
	2	MAX current 2																																					
	3	-																																					
	4	Adaptive filter operation gain (%)																																					
	5	Regenerative operation frequency monitor (The number of times/sec)																																					
	6	MAX current FB value for one second (%)																																					
	7	MAX disturbance torque for two seconds (%)																																					
	8 to F	Setting prohibited																																					
4	dac1	D/A output ch.1 overflow setting	D/A output ch.1 clamp setting																																				
5	dac2	D/A output ch.2 overflow setting	D/A output ch.2 clamp setting																																				
6	daf1	D/A output ch.1 no filter	D/A output ch.1 filter setting																																				
7	daf2	D/A output ch.2 no filter	D/A output ch.2 filter setting																																				
8																																							
9																																							
A																																							
B																																							
C																																							
D																																							
E																																							
F																																							

(Note) Set to "0" for bits with no particular description.

7. Servo Parameters
7.1 MDS-B-SVJ2

No.	Items	Details	Setting range																																																																																						
2235	SV035 SSF4 Servo function selection 4	<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:12.5%; text-align:center;">F</td> <td style="width:12.5%; text-align:center;">E</td> <td style="width:12.5%; text-align:center;">D</td> <td style="width:12.5%; text-align:center;">C</td> <td style="width:12.5%; text-align:center;">B</td> <td style="width:12.5%; text-align:center;">A</td> <td style="width:12.5%; text-align:center;">9</td> <td style="width:12.5%; text-align:center;">8</td> </tr> <tr> <td style="text-align:center;">cl2n</td> <td colspan="3" style="text-align:center;">clG1</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align:center;">7</td> <td style="text-align:center;">6</td> <td style="text-align:center;">5</td> <td style="text-align:center;">4</td> <td style="text-align:center;">3</td> <td style="text-align:center;">2</td> <td style="text-align:center;">1</td> <td style="text-align:center;">0</td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </table> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th style="width:10%;">bit</th> <th style="width:55%;">Meaning when "0" is set</th> <th style="width:35%;">Meaning when "1" is set</th> </tr> </thead> <tbody> <tr><td>0</td><td></td><td></td></tr> <tr><td>1</td><td></td><td></td></tr> <tr><td>2</td><td></td><td></td></tr> <tr><td>3</td><td></td><td></td></tr> <tr><td>4</td><td></td><td></td></tr> <tr><td>5</td><td></td><td></td></tr> <tr><td>6</td><td></td><td></td></tr> <tr><td>7</td><td></td><td></td></tr> <tr><td>8</td><td></td><td></td></tr> <tr><td>9</td><td></td><td></td></tr> <tr><td>A</td><td></td><td></td></tr> <tr><td>B</td><td></td><td></td></tr> <tr> <td>C</td> <td colspan="2">Collision detection method 1</td> </tr> <tr> <td>D</td> <td colspan="2">Set the collision detection level during cutting feed (G1).</td> </tr> <tr> <td></td> <td colspan="2">The G1 collision detection level=SV060*clG1.</td> </tr> <tr> <td>E</td> <td colspan="2">When clG1=0, the collision detection method 1 during cutting feed won't function.</td> </tr> <tr> <td>F</td> <td>cl2n Collision detection method 2 valid</td> <td>Collision detection method 2 invalid</td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8	cl2n	clG1							7	6	5	4	3	2	1	0									bit	Meaning when "0" is set	Meaning when "1" is set	0			1			2			3			4			5			6			7			8			9			A			B			C	Collision detection method 1		D	Set the collision detection level during cutting feed (G1).			The G1 collision detection level=SV060*clG1.		E	When clG1=0, the collision detection method 1 during cutting feed won't function.		F	cl2n Collision detection method 2 valid	Collision detection method 2 invalid	
F	E	D	C	B	A	9	8																																																																																		
cl2n	clG1																																																																																								
7	6	5	4	3	2	1	0																																																																																		
bit	Meaning when "0" is set	Meaning when "1" is set																																																																																							
0																																																																																									
1																																																																																									
2																																																																																									
3																																																																																									
4																																																																																									
5																																																																																									
6																																																																																									
7																																																																																									
8																																																																																									
9																																																																																									
A																																																																																									
B																																																																																									
C	Collision detection method 1																																																																																								
D	Set the collision detection level during cutting feed (G1).																																																																																								
	The G1 collision detection level=SV060*clG1.																																																																																								
E	When clG1=0, the collision detection method 1 during cutting feed won't function.																																																																																								
F	cl2n Collision detection method 2 valid	Collision detection method 2 invalid																																																																																							
(Note) Set to "0" for bits with no particular description.																																																																																									

7. Servo Parameters
7.1 MDS-B-SVJ2

No.	Items	Details	Setting range																																																																																															
2236 (PR)	SV036 PTYP Regenerative resistor type	<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:12.5%; text-align:center;">F</td> <td style="width:12.5%; text-align:center;">E</td> <td style="width:12.5%; text-align:center;">D</td> <td style="width:12.5%; text-align:center;">C</td> <td style="width:12.5%; text-align:center;">B</td> <td style="width:12.5%; text-align:center;">A</td> <td style="width:12.5%; text-align:center;">9</td> <td style="width:12.5%; text-align:center;">8</td> </tr> <tr> <td colspan="4" style="text-align:center;">amp</td> <td colspan="4" style="text-align:center;">rtyp</td> </tr> <tr> <td style="text-align:center;">7</td> <td style="text-align:center;">6</td> <td style="text-align:center;">5</td> <td style="text-align:center;">4</td> <td style="text-align:center;">3</td> <td style="text-align:center;">2</td> <td style="text-align:center;">1</td> <td style="text-align:center;">0</td> </tr> <tr> <td colspan="4" style="text-align:center;">emgx</td> <td></td> <td></td> <td></td> <td></td> </tr> </table> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th style="width:10%;">bit</th> <th style="width:5%;"> </th> <th>Explanation</th> </tr> </thead> <tbody> <tr> <td>0</td> <td></td> <td rowspan="4">Always set to "0(0000)".</td> </tr> <tr> <td>1</td> <td></td> </tr> <tr> <td>2</td> <td></td> </tr> <tr> <td>3</td> <td></td> </tr> <tr> <td>4</td> <td rowspan="5">emgx</td> <td rowspan="5">Set the external emergency stop function. (Setting is prohibited for values with no description.)</td> </tr> <tr> <td>5</td> <td> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th style="width:15%;">Set-ting</th> <th>Explanation</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>External emergency stop invalid</td> </tr> <tr> <td>4</td> <td>External emergency stop valid</td> </tr> </tbody> </table> </td> </tr> <tr> <td>6</td> <td></td> </tr> <tr> <td>7</td> <td></td> </tr> <tr> <td>8</td> <td rowspan="7">rtyp</td> <td rowspan="7">Set the regenerative resistor type.</td> </tr> <tr> <td>9</td> <td> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th style="width:15%;">Set-ting</th> <th>Explanation</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>Drive unit standard built-in resistor (SVJ2-01 doesn't have a built-in resistor)</td> </tr> <tr> <td>1</td> <td>Setting prohibited</td> </tr> <tr> <td>2</td> <td>MR-RB032</td> </tr> <tr> <td>3</td> <td>MR-RB12 or GZG200W390HMK</td> </tr> <tr> <td>4</td> <td>MR-RB32 or GZG200W1200HMK: 3 units connected in parallel</td> </tr> <tr> <td>5</td> <td>MR-RB30 or GZG200W390HMK: 3 units connected in parallel</td> </tr> <tr> <td>6</td> <td>MR-RB50 or GZG300W390HMK: 3 units connected in parallel</td> </tr> <tr> <td>7 to F</td> <td>Setting prohibited</td> </tr> </tbody> </table> </td> </tr> <tr> <td>A</td> <td></td> </tr> <tr> <td>B</td> <td></td> </tr> <tr> <td>C</td> <td rowspan="4">amp</td> <td rowspan="4">Always set to "0(0000)".</td> </tr> <tr> <td>D</td> <td></td> </tr> <tr> <td>E</td> <td></td> </tr> <tr> <td>F</td> <td></td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8	amp				rtyp				7	6	5	4	3	2	1	0	emgx								bit		Explanation	0		Always set to "0(0000)".	1		2		3		4	emgx	Set the external emergency stop function. (Setting is prohibited for values with no description.)	5	<table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th style="width:15%;">Set-ting</th> <th>Explanation</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>External emergency stop invalid</td> </tr> <tr> <td>4</td> <td>External emergency stop valid</td> </tr> </tbody> </table>	Set-ting	Explanation	0	External emergency stop invalid	4	External emergency stop valid	6		7		8	rtyp	Set the regenerative resistor type.	9	<table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th style="width:15%;">Set-ting</th> <th>Explanation</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>Drive unit standard built-in resistor (SVJ2-01 doesn't have a built-in resistor)</td> </tr> <tr> <td>1</td> <td>Setting prohibited</td> </tr> <tr> <td>2</td> <td>MR-RB032</td> </tr> <tr> <td>3</td> <td>MR-RB12 or GZG200W390HMK</td> </tr> <tr> <td>4</td> <td>MR-RB32 or GZG200W1200HMK: 3 units connected in parallel</td> </tr> <tr> <td>5</td> <td>MR-RB30 or GZG200W390HMK: 3 units connected in parallel</td> </tr> <tr> <td>6</td> <td>MR-RB50 or GZG300W390HMK: 3 units connected in parallel</td> </tr> <tr> <td>7 to F</td> <td>Setting prohibited</td> </tr> </tbody> </table>	Set-ting	Explanation	0	Drive unit standard built-in resistor (SVJ2-01 doesn't have a built-in resistor)	1	Setting prohibited	2	MR-RB032	3	MR-RB12 or GZG200W390HMK	4	MR-RB32 or GZG200W1200HMK: 3 units connected in parallel	5	MR-RB30 or GZG200W390HMK: 3 units connected in parallel	6	MR-RB50 or GZG300W390HMK: 3 units connected in parallel	7 to F	Setting prohibited	A		B		C	amp	Always set to "0(0000)".	D		E		F		
F	E	D	C	B	A	9	8																																																																																											
amp				rtyp																																																																																														
7	6	5	4	3	2	1	0																																																																																											
emgx																																																																																																		
bit		Explanation																																																																																																
0		Always set to "0(0000)".																																																																																																
1																																																																																																		
2																																																																																																		
3																																																																																																		
4	emgx	Set the external emergency stop function. (Setting is prohibited for values with no description.)																																																																																																
5			<table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th style="width:15%;">Set-ting</th> <th>Explanation</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>External emergency stop invalid</td> </tr> <tr> <td>4</td> <td>External emergency stop valid</td> </tr> </tbody> </table>	Set-ting	Explanation	0	External emergency stop invalid	4	External emergency stop valid																																																																																									
Set-ting			Explanation																																																																																															
0			External emergency stop invalid																																																																																															
4			External emergency stop valid																																																																																															
6																																																																																																		
7																																																																																																		
8	rtyp	Set the regenerative resistor type.																																																																																																
9			<table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th style="width:15%;">Set-ting</th> <th>Explanation</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>Drive unit standard built-in resistor (SVJ2-01 doesn't have a built-in resistor)</td> </tr> <tr> <td>1</td> <td>Setting prohibited</td> </tr> <tr> <td>2</td> <td>MR-RB032</td> </tr> <tr> <td>3</td> <td>MR-RB12 or GZG200W390HMK</td> </tr> <tr> <td>4</td> <td>MR-RB32 or GZG200W1200HMK: 3 units connected in parallel</td> </tr> <tr> <td>5</td> <td>MR-RB30 or GZG200W390HMK: 3 units connected in parallel</td> </tr> <tr> <td>6</td> <td>MR-RB50 or GZG300W390HMK: 3 units connected in parallel</td> </tr> <tr> <td>7 to F</td> <td>Setting prohibited</td> </tr> </tbody> </table>	Set-ting	Explanation	0	Drive unit standard built-in resistor (SVJ2-01 doesn't have a built-in resistor)	1	Setting prohibited	2	MR-RB032	3	MR-RB12 or GZG200W390HMK	4	MR-RB32 or GZG200W1200HMK: 3 units connected in parallel	5	MR-RB30 or GZG200W390HMK: 3 units connected in parallel	6	MR-RB50 or GZG300W390HMK: 3 units connected in parallel	7 to F	Setting prohibited																																																																													
Set-ting			Explanation																																																																																															
0			Drive unit standard built-in resistor (SVJ2-01 doesn't have a built-in resistor)																																																																																															
1			Setting prohibited																																																																																															
2			MR-RB032																																																																																															
3			MR-RB12 or GZG200W390HMK																																																																																															
4	MR-RB32 or GZG200W1200HMK: 3 units connected in parallel																																																																																																	
5	MR-RB30 or GZG200W390HMK: 3 units connected in parallel																																																																																																	
6	MR-RB50 or GZG300W390HMK: 3 units connected in parallel																																																																																																	
7 to F	Setting prohibited																																																																																																	
A																																																																																																		
B																																																																																																		
C	amp	Always set to "0(0000)".																																																																																																
D																																																																																																		
E																																																																																																		
F																																																																																																		

7. Servo Parameters
7.1 MDS-B-SVJ2

No.	Items	Details	Setting range
2237	SV037 JL	Load inertia scale Set "the motor inertia + motor axis conversion load inertia" in respect to the motor inertia. $SV037 (JL) = \frac{Jl+Jm}{Jm} *100$ Jm: Motor inertia Jl: Motor axis conversion load inertia	0 to 5000 (%)
2238	SV038 FHZ1	Notch filter frequency 1 Set the vibration frequency to suppress if machine vibration occurs. (Valid at 72 or more) When not using, set to "0".	0 to 3000 (Hz)
2239	SV039 LMCD	Lost motion compensation timing Set this when the lost motion compensation timing does not match. Adjust by increasing the value by 10 at a time.	0 to 2000 (ms)
2240	SV040 LMCT	Non-sensitive band in feed forward control Set the non-sensitive band of the lost motion compensation and overshooting compensation during the feed forward control. When "0" is set, the actual value that will be set is 2μm. Adjust by increasing by 1μm.	0 to 100 (μm)
2241	SV041 LMC2	Lost motion compensation 2 Set this with SV016 (LMC1) only when you wish to set the lost motion compensation amount to be different depending on the command directions. Set to "0" as a standard.	-1 to 200 (Stall [rated] current %)
2242	SV042 OVS2	Overshooting compensation 2 Set this with SV031 (OVS1) only when you wish to set the overshooting compensation amount to be different depending on the command directions. Set to "0" as a standard.	-1 to 100 (Stall [rated] current %)
2243	SV043 OBS1	Disturbance observer filter frequency Set the disturbance observer filter band. The standard setting is "300". Lower the setting by 50 at a time if vibration occurs. To use the disturbance observer, also set SV037 (JL) and SV044 (OBS2). When not using, set to "0".	0 to 1000 (rad/s)
2244	SV044 OBS2	Disturbance observer gain Set the disturbance observer gain. The standard setting is "100" to "300". To use the disturbance observer, also set SV037 (JL) and SV043 (OBS1). When not using, set to "0".	0 to 1000 (%)
2245	SV045 TRUB	Frictional torque Set the frictional torque when using the collision detection function.	0 to 100 (Stall [rated] current %)
2246	SV046	Not used. Set to "0".	0
2247	SV047 EC	Inductive voltage compensation gain Set the inductive voltage compensation gain. Set to "100" as a standard. If the current FB peak exceeds the current command peak, lower the gain.	0 to 200 (%)
2248	SV048 EMGrT	Vertical axis drop prevention time Input a length of time to prevent the vertical axis from dropping by delaying Ready OFF until the brake works when the emergency stop occurs. Increase the setting by 100ms at a time and set the value where the axis does not drop.	0 to 2000 (ms)

7. Servo Parameters
7.1 MDS-B-SVJ2

No.	Items	Details	Setting range	
2249	SV049 PGN1sp	Position loop gain 1 in spindle synchronous control	Set the position loop gain during the spindle synchronous control (synchronous tapping, synchronous control with spindle/C axis). Set the same value as the value of the spindle parameter, position loop gain in synchronous control. When performing the SHG control, set this with SV050 (PGN2sp) and SV058 (SHGCsp).	1 to 200 (rad/s)
2250	PGN2sp	Position loop gain 2 in spindle synchronous control	Set this with SV049 (PGN1sp) and SV058 (SHGCsp) if you wish to perform the SHG control in the spindle synchronous control (synchronous tapping, synchronous control with spindle/C axis). When not performing the SHG control, set to "0".	0 to 999 (rad/s)
2251	SV051		Not used. Set to "0".	0
2252	SV052		Not used. Set to "0".	0
2253	SV053 OD3	Excessive error detection width in special control	Set the excessive error detection width when servo ON in a special control (initial absolute position setting, stopper control, etc.). If "0" is set, excessive error detection won't be performed when servo ON during a special control.	0 to 32767 (mm)
2254	SV054		Not used. Set to "0".	0
2255	SV055		Not used. Set to "0".	0
2256	SV056 EMGt	Deceleration time constant at emergency stop	Set the time constant used for the deceleration control at emergency stop. Set a length of time that takes from rapid traverse rate (rapid) to stopping. Normally, set the same value as the rapid traverse acceleration/deceleration time constant.	0 to 5000 (ms)
2257	SV057 SHGC	SHG control gain	When performing the SHG control, set this with S003 (PGN1) and SV004 (PGN2). When not performing the SHG control, set to "0".	0 to 999 (rad/s)
2258	SV058 SHGCsp	SHG control gain in spindle synchronous control	Set this with SV049 (PGN1sp) and SV050 (PGN2sp) if you wish to perform the SHG control in the spindle synchronous control (synchronous tapping, synchronous control with spindle/C axis). When not performing the SHG control, set to "0".	0 to 999 (rad/s)
2259	SV059 TCNV	Collision detection torque estimating gain	To use the collision detection function, set the torque estimating gain. In the case of MDS-B-SVJ2, the value is the same as the load inertia ratio that includes the motor inertia. (=SV037:JL) If acceleration/deceleration is performed after setting SV034.mon=3 and SV060=0, the load inertia ratio will be displayed on the NC monitor screen.	0 to 5000 (%)
2260	SV060 TLMT	Collision detection level	When using the collision detection function, set the collision detection level during the G0 feeding. If "0" is set, none of the collision detection function will work.	0 to 200 (Stall [rated] current %)

7. Servo Parameters
7.1 MDS-B-SVJ2

No.	Items		Details	Setting range
2261	SV061 DA1NO	D/A output channel 1 data No.	Input the data number you wish to output to D/A output channel.	0 to 102
2262	SV062 DA2NO	D/A output channel 2 data No.		
2263	SV063 DA1MPY	D/A output channel 1 output scale	When "0" is set, output is done with the standard output unit. Set other than "0" when you wish to change the unit. Set the scale with a 1/256 unit. When "256" is set, the output unit will be the same as the standard output unit.	-32768 to 32767 (Unit: 1/256)
2264	SV064 DA2MPY	D/A output channel 2 output scale		
2265	SV065		Not used. Set to "0".	0

7. Servo Parameters
7.1 MDS-B-SVJ2

(2) Initial setting value

(a) HC**/HC**R series

Motor		HC 52	HC 102*	HC 102	HC 152*	HC 152	HC 202*	HC 202	HC 352*
Drive unit capacity		06	07	10	10	20	10	20	20
SV001	PC1	-	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	33	33	33
SV004	PGN2	0	0	0	0	0	0	0	0
SV005	VGN1	50	80	50	80	50	115	80	130
SV006		0	0	0	0	0	0	0	0
SV007		0	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	8192	4096	8192	4096	8192	2048	4096	2048
SV010	IDA	8192	4096	8192	4096	8192	2048	4096	2048
SV011	IQG	512	256	384	256	384	256	384	256
SV012	IDG	512	256	384	256	384	256	384	256
SV013	ILMT	500	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150	150
SV023	OD1	-	-	-	-	-	-	-	-
SV024	INP	50	50	50	50	50	50	50	50
SV025	MTYP	22B0	22B1	22B1	22B2	22B2	22B3	22B3	22B4
SV026	OD2	-	-	-	-	-	-	-	-
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0	0
SV029		0	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0	0

7. Servo Parameters
7.1 MDS-B-SVJ2

Motor		HC 52	HC 102*	HC 102	HC 152*	HC 152	HC 202*	HC 202	HC 352*
Drive unit capacity		06	07	10	10	20	10	20	20
SV033	SSF2	0	0	0	0	0	0	0	0
SV034	SSF3	0	0	0	0	0	0	0	0
SV035	SSF4	0	0	0	0	0	0	0	0
SV036	PTYP	-	-	-	-	-	-	-	-
SV037	JL	0	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	0	0	0	0	0
SV041	LMC2	0	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0	0
SV046		0	0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100	100
SV048	EMGr	0	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0	0
SV051		0	0	0	0	0	0	0	0
SV052		0	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0	0
SV054		0	0	0	0	0	0	0	0
SV055		0	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0	0
SV065		0	0	0	0	0	0	0	0

7. Servo Parameters
7.1 MDS-B-SVJ2

Motor		HC 53	HC 103	HC 153	HC 203*	HC 103R	HC 153R	HC 203R
Drive unit capacity		06	10	20	20	10	10	20
SV001	PC1	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	33	33
SV004	PGN2	0	0	0	0	0	0	0
SV005	VGN1	80	80	80	100	10	10	10
SV006		0	0	0	0	0	0	0
SV007		0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	4096	4096	4096	2048	8192	8192	8192
SV010	IDA	4096	4096	4096	2048	8192	8192	8192
SV011	IQG	256	256	256	200	384	384	256
SV012	IDG	256	256	256	200	384	384	256
SV013	ILMT	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150
SV023	OD1	-	-	-	-	-	-	-
SV024	INP	50	50	50	50	50	50	50
SV025	MTYP	22C0	22C1	22C2	22C3	22E1	22E2	22E3
SV026	OD2	-	-	-	-	-	-	-
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0
SV029		0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0

7. Servo Parameters
7.1 MDS-B-SVJ2

Motor		HC 53	HC 103	HC 153	HC 203*	HC 103R	HC 153R	HC 203R
Drive unit capacity		06	10	20	20	10	10	20
SV033	SSF2	0	0	0	0	0	0	0
SV034	SSF3	0	0	0	0	0	0	0
SV035	SSF4	0	0	0	0	0	0	0
SV036	PTYP	-	-	-	-	-	-	-
SV037	JL	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	0	0	0	0
SV041	LMC2	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0
SV046		0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100
SV048	EMGrt	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0
SV051		0	0	0	0	0	0	0
SV052		0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0
SV054		0	0	0	0	0	0	0
SV055		0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0
SV065		0	0	0	0	0	0	0

7. Servo Parameters
7.1 MDS-B-SVJ2

(b) HA**N series

Motor		HA 40N	HA 80N	HA 100N	HA 200N*	HA 053N	HA 13N	HA 23N	HA 33N	HA 43N	HA 83N	HA 103N*
Drive unit capacity		06	10	20	20	01	01	03	03	06	10	20
SV001	PC1	-	-	-	-	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	33	33	33	33	33	33
SV004	PGN2	0	0	0	0	0	0	0	0	0	0	0
SV005	VGN1	90	150	150	220	35	35	35	35	120	150	180
SV006		0	0	0	0	0	0	0	0	0	0	0
SV007		0	0	0	0	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	2048	2048	2048	2048	2048	2048	2048	2048	2048	2048	2048
SV010	IDA	2048	2048	2048	2048	2048	2048	2048	2048	2048	2048	2048
SV011	IQG	512	512	512	200	256	256	256	256	512	512	512
SV012	IDG	512	512	512	200	256	256	256	256	512	512	512
SV013	ILMT	500	500	500	500	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150	150	150	150	150
SV023	OD1	-	-	-	-	-	-	-	-	-	-	-
SV024	INP	50	50	50	50	50	50	50	50	50	50	50
SV025	MTYP	2200	2201	2202	2203	228C	228D	228E	228F	2280	2281	2282
SV026	OD2	-	-	-	-	-	-	-	-	-	-	-
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0	0	0	0	0
SV029		0	0	0	0	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0	0	0	0	0

7. Servo Parameters
7.1 MDS-B-SVJ2

Motor		HA 40N	HA 80N	HA 100N	HA 200N*	HA 053N	HA 13N	HA 23N	HA 33N	HA 43N	HA 83N	HA 103N*
Drive unit capacity		06	10	20	20	01	01	03	03	06	10	20
SV033	SSF2	0	0	0	0	0	0	0	0	0	0	0
SV034	SSF3	0	0	0	0	0	0	0	0	0	0	0
SV035	SSF4	0	0	0	0	0	0	0	0	0	0	0
SV036	PTYP	-	-	-	-	-	-	-	-	-	-	-
SV037	JL	0	0	0	0	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	0	0	0	0	0	0	0	0
SV041	LMC2	0	0	0	0	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0	0	0	0	0
SV046		0	0	0	0	0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100	100	100	100	100
SV048	EMGr	0	0	0	0	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0	0	0	0	0
SV051		0	0	0	0	0	0	0	0	0	0	0
SV052		0	0	0	0	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0	0	0	0	0
SV054		0	0	0	0	0	0	0	0	0	0	0
SV055		0	0	0	0	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0	0	0	0	0
SV065		0	0	0	0	0	0	0	0	0	0	0

7. Servo Parameters
7.1 MDS-B-SVJ2

(c) HC-SF series

Motor		HC-SF 52	HC-SF 102	HC-SF 152	HC-SF 202	HC-SF 352	HC-SF 53	HC-SF 103	HC-SF 153	HC-SF 203	HC-SF 353
Drive unit capacity		06	07	10	10	20	06	07	10	10	20
SV001	PC1	-	-	-	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	33	33	33	33	33
SV004	PGN2	0	0	0	0	0	0	0	0	0	0
SV005	VGN1	80	80	80	120	130	90	90	130	180	180
SV006		0	0	0	0	0	0	0	0	0	0
SV007		0	0	0	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	8192	4096	4096	2048	2048	4096	4096	2048	2048	2048
SV010	IDA	8192	4096	4096	2048	2048	4096	4096	2048	2048	2048
SV011	IQG	500	300	300	300	250	250	250	200	200	200
SV012	IDG	500	300	300	300	250	250	250	200	200	200
SV013	ILMT	500	500	500	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-	-	-	-	-
SV019	RNG1	16	16	16	16	16	16	16	16	16	16
SV020	RNG2	16	16	16	16	16	16	16	16	16	16
SV021	OLT	60	60	60	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150	150	150	150
SV023	OD1	-	-	-	-	-	-	-	-	-	-
SV024	INP	50	50	50	50	50	50	50	50	50	50
SV025	MTYP	22B0	22B1	22B2	22B3	22B4	22C0	22C1	22C2	22C3	22C4
SV026	OD2	-	-	-	-	-	-	-	-	-	-
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0	0	0	0
SV029		0	0	0	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0	0	0	0

7. Servo Parameters
7.1 MDS-B-SVJ2

Motor		HC-SF 52	HC-SF 102	HC-SF 152	HC-SF 202	HC-SF 352	HC-SF 53	HC-SF 103	HC-SF 153	HC-SF 203	HC-SF 353
Drive unit capacity		06	07	10	10	20	06	07	10	10	20
SV033	SSF2	0	0	0	0	0	0	0	0	0	0
SV034	SSF3	0	0	0	0	0	0	0	0	0	0
SV035	SSF4	0	0	0	0	0	0	0	0	0	0
SV036	PTYP	-	-	-	-	-	-	-	-	-	-
SV037	JL	0	0	0	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	0	0	0	0	0	0	0
SV041	LMC2	0	0	0	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0	0	0	0
SV046		0	0	0	0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100	100	100	100
SV048	EMGrt	0	0	0	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0	0	0	0
SV051		0	0	0	0	0	0	0	0	0	0
SV052		0	0	0	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0	0	0	0
SV054		0	0	0	0	0	0	0	0	0	0
SV055		0	0	0	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0	0	0	0
SV065		0	0	0	0	0	0	0	0	0	0

7. Servo Parameters
7.1 MDS-B-SVJ2

(d) HC-RF/HA-FF series

Motor		HC-RF 103	HC-RF 153	HC-RF 203	HA-FF 053	HA-FF 13	HA-FF 23	HA-FF 33	HA-FF 43	HA-FF 63
Drive unit capacity		10	10	20	01	01	03	03	04	06
SV001	PC1	-	-	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	33	33	33	33
SV004	PGN2	0	0	0	0	0	0	0	0	0
SV005	VGN1	10	10	10	10	13	13	18	20	20
SV006		0	0	0	0	0	0	0	0	0
SV007		0	0	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	8192	8192	8192	8192	4096	4096	4096	4096	4096
SV010	IDA	8192	8192	8192	8192	4096	4096	4096	4096	4096
SV011	IQG	384	384	256	500	300	700	500	700	700
SV012	IDG	384	384	256	500	300	700	500	700	700
SV013	ILMT	500	500	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-	-	-	-
SV019	RNG1	16	16	16	8	8	8	8	8	8
SV020	RNG2	16	16	16	8	8	8	8	8	8
SV021	OLT	60	60	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150	150	150
SV023	OD1	-	-	-	-	-	-	-	-	-
SV024	INP	50	50	50	50	50	50	50	50	50
SV025	MTYP	22E1	22E2	22E3	227C	227D	227E	227F	2270	2271
SV026	OD2	-	-	-	-	-	-	-	-	-
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0	0	0
SV029		0	0	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0	0	0

7. Servo Parameters
7.1 MDS-B-SVJ2

Motor		HC-RF 103	HC-RF 153	HC-RF 203	HA-FF 053	HA-FF 13	HA-FF 23	HA-FF 33	HA-FF 43	HA-FF 63
Drive unit capacity		10	10	20	01	01	03	03	04	06
SV033	SSF2	0	0	0	0	0	0	0	0	0
SV034	SSF3	0	0	0	0	0	0	0	0	0
SV035	SSF4	0	0	0	0	0	0	0	0	0
SV036	PTYP	-	-	-	-	-	-	-	-	-
SV037	JL	0	0	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	0	0	0	0	0	0
SV041	LMC2	0	0	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0	0	0
SV046		0	0	0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100	100	100
SV048	EMGr	0	0	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0	0	0
SV051		0	0	0	0	0	0	0	0	0
SV052		0	0	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0	0	0
SV054		0	0	0	0	0	0	0	0	0
SV055		0	0	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0	0	0
SV065		0	0	0	0	0	0	0	0	0

7. Servo Parameters
7.1 MDS-B-SVJ2

(e) HC-MF series

Motor		HC-MF 053	HC-MF 13	HC-MF 23	HC-MF 43	HC-MF 73
Drive unit capacity		01	01	03	04	07
SV001	PC1	-	-	-	-	-
SV002	PC2	-	-	-	-	-
SV003	PGN1	33	33	33	33	33
SV004	PGN2	0	0	0	0	0
SV005	VGN1	6	6	6	6	8
SV006		0	0	0	0	0
SV007		0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364
SV009	IQA	4096	4096	4096	4096	4096
SV010	IDA	4096	4096	4096	4096	4096
SV011	IQG	200	300	400	300	300
SV012	IDG	200	300	400	300	300
SV013	ILMT	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500
SV015	FFC	0	0	0	0	0
SV016	LMC1	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-
SV019	RNG1	8	8	8	8	8
SV020	RNG2	8	8	8	8	8
SV021	OLT	60	60	60	60	60
SV022	OLL	150	150	150	150	150
SV023	OD1	-	-	-	-	-
SV024	INP	50	50	50	50	50
SV025	MTYP	229C	229D	229E	2290	2291
SV026	OD2	-	-	-	-	-
SV027	SSF1	4000	4000	4000	4000	4000
SV028		0	0	0	0	0
SV029		0	0	0	0	0
SV030	IVC	0	0	0	0	0
SV031	OVS1	0	0	0	0	0
SV032	TOF	0	0	0	0	0

7. Servo Parameters
7.1 MDS-B-SVJ2

Motor		HC-MF 053	HC-MF 13	HC-MF 23	HC-MF 43	HC-MF 73
Drive unit capacity		01	01	03	04	07
SV033	SSF2	0	0	0	0	0
SV034	SSF3	0	0	0	0	0
SV035	SSF4	0	0	0	0	0
SV036	PTYP	-	-	-	-	-
SV037	JL	0	0	0	0	0
SV038	FHz1	0	0	0	0	0
SV039	LMCD	0	0	0	0	0
SV040	LMCT	0	0	0	0	0
SV041	LMC2	0	0	0	0	0
SV042	OVS2	0	0	0	0	0
SV043	OBS1	0	0	0	0	0
SV044	OBS2	0	0	0	0	0
SV045	TRUB	0	0	0	0	0
SV046		0	0	0	0	0
SV047	EC	100	100	100	100	100
SV048	EMGr	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0
SV051		0	0	0	0	0
SV052		0	0	0	0	0
SV053	OD3	0	0	0	0	0
SV054		0	0	0	0	0
SV055		0	0	0	0	0
SV056	EMGt	0	0	0	0	0
SV057	SHGC	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0
SV059	TCNV	0	0	0	0	0
SV060	TLMT	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0
SV065		0	0	0	0	0

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)


7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

(1) Details for servo parameters

For parameters marked with a (PR) in the table, turn the NC power OFF after setting. After the power is turned ON again, the parameter is validated.

⚠ CAUTION
 ⚠ In the explanation on bits, set all bits not used, including blank bits, to "0".

No.	Items	Details	Setting range
2201 (PR)	SV001 PC1	Motor side gear ratio	1 to 32767
2202 (PR)	SV002 PC2	Machine side gear ratio	1 to 32767
2203	SV003 PGN1	Position loop gain 1	1 to 200 (In case of MDS-B-Vx4, 1 to 400) (rad/s)
2204	SV004 PGN2	Position loop gain 2	0 to 999 (rad/s)
2205	SV005 VGN1	Speed loop gain 1	1 to 999
2206	SV006 VGN2	Speed loop gain 2	-1000 to 1000



7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

No.	Items	Details	Setting range	
2207	SV007 VIL	Speed loop delay compensation	Set this when the limit cycle occurs in the full-closed loop, or overshooting occurs in positioning. Select the control method with SV027 (SSF1)/bit1, 0 (vcnt). Normally, use "Changeover type 2". When you set this parameter, make sure to set the torque offset (SV032 (TOF)). When not using, set to "0".	0 to 32767
			No changeover When SV027 (SSF1)/ bit1, 0 (vcnt)=00 The delay compensation control is always valid.	
			Changeover type 1 When SV027 (SSF1)/ bit1, 0 (vcnt)=01 The delay compensation control works when the command from the NC is "0". Overshooting that occurs during pulse feeding can be suppressed.	
			Changeover type 2 When SV027 (SSF1)/ bit1, 0 (vcnt)=10 The delay compensation control works when the command from the NC is "0" and the position droop is "0". Overshooting or the limit cycle that occurs during pulse feeding or positioning can be suppressed.	
2208	SV008 VIA	Speed loop lead compensation	Set the gain of the speed loop integration control. The standard setting is "1364". During the SHG control, the standard setting is "1900". Adjust the value by increasing/decreasing it by about 100 at a time. Raise this value to improve contour tracking precision in high-speed cutting. Lower this value when the position droop vibrates (10 to 20Hz).	1 to 9999
2209	SV009 IQA	Current loop q axis lead compensation	Set the gain of current loop. As this setting is determined by the motor's electrical characteristics, the setting is fixed for each type of motor. Set the standard values for all the parameters depending on each motor type.	1 to 20480
2210	SV010 IDA	Current loop d axis lead compensation		
2211	SV011 IQG	Current loop q axis gain		
2212	SV012 IDG	Current loop d axis gain		
2213	SV013 ILMT	Current limit value	Set the normal current (torque) limit value. (Limit values for both + and - direction.) When the value is "500" (a standard setting), the maximum torque is determined by the specification of the motor.	0 to 999 (Stall [rated] current %)
2214	SV014 ILMTsp	Current limit value in special control	Set the current (torque) limit value in a special control (initial absolute position setting, stopper control, etc). (Limit values for both of the + and - directions.) Set to "500" when not using.	0 to 999 (Stall [rated] current %)

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

No.	Items	Details	Setting range	
2215	SV015 FFC	Acceleration rate feed forward gain	When a relative error in the synchronous control is large, apply this parameter to the axis that is delaying. The standard setting value is "0". For the SHG control, set to "100". To adjust a relative error in acceleration/deceleration, increase the value by 50 to 100 at a time.	0 to 999(%)
2216	SV016 LMC1	Lost motion compensation 1	Set this when the protrusion (that occurs due to the non-sensitive band by friction, torsion, backlash, etc) at quadrant change is too large. This compensates the torque at quadrant change. This is valid only when the lost motion compensation (SV027 (SSF1/lmc)) is selected.	
			Type 1: When SV027 (SSF1)/ bit9, 8 (lmc)=01 Set the compensation amount based on the motor torque before the quadrant change. The standard setting is "100". Setting to "0" means the compensation amount is zero. Normally, use Type 2.	-1 to 200 (%)
			Type 2: When SV027 (SSF1)/ bit9, 8 (lmc)=10 Set the compensation amount based on the stall (rated) current of the motor. The standard setting is double of the friction torque. Setting to "0" means the compensation amount is zero.	-1 to 100 (Stall [rated] current %)
			When you wish different compensation amount depending on the direction When SV041 (LMC2) is "0", compensate with the value of SV016 (LMC1) in both of the + and -directions. If you wish to change the compensation amount depending on the command direction, set this and SV041 (LMC2). (SV016: + direction, SV041: - direction. However, the directions may be opposite depending on other settings.) When "-1" is set, the compensation won't be performed in the direction of the command.	

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

No.	Items	Details	Setting range																																															
2217 (PR)	SV017 SPEC	Servo specification selection	<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center;">F</td> <td style="text-align: center;">E</td> <td style="text-align: center;">D</td> <td style="text-align: center;">C</td> <td style="text-align: center;">B</td> <td style="text-align: center;">A</td> <td style="text-align: center;">9</td> <td style="text-align: center;">8</td> </tr> <tr> <td colspan="4" style="text-align: center; border: 1px solid black;">spm</td> <td style="text-align: center; border: 1px solid black;">drvall</td> <td style="text-align: center; border: 1px solid black;">drvup</td> <td style="text-align: center; border: 1px solid black;">mpt3</td> <td style="text-align: center; border: 1px solid black;">mp</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> <td style="text-align: center;">1</td> <td style="text-align: center;">0</td> </tr> <tr> <td style="text-align: center; border: 1px solid black;">abs</td> <td style="text-align: center; border: 1px solid black;"></td> <td style="text-align: center; border: 1px solid black;">vdir</td> <td style="text-align: center; border: 1px solid black;">fdir</td> <td style="text-align: center; border: 1px solid black;">vfb</td> <td style="text-align: center; border: 1px solid black;">seqh</td> <td style="text-align: center; border: 1px solid black;">dfbx</td> <td style="text-align: center; border: 1px solid black;">fdir2</td> </tr> </table>	F	E	D	C	B	A	9	8	spm				drvall	drvup	mpt3	mp	7	6	5	4	3	2	1	0	abs		vdir	fdir	vfb	seqh	dfbx	fdir2															
			F	E	D	C	B	A	9	8																																								
			spm				drvall	drvup	mpt3	mp																																								
			7	6	5	4	3	2	1	0																																								
			abs		vdir	fdir	vfb	seqh	dfbx	fdir2																																								
			<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: center;">bit</th> <th style="text-align: center;">Meaning when "0" is set</th> <th style="text-align: center;">Meaning when "1" is set</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">0</td> <td>fdir2 Speed feedback forward polarity</td> <td>Speed feedback reverse polarity</td> </tr> <tr> <td style="text-align: center;">1</td> <td>dfbx Dual feedback control stop</td> <td>Dual feedback control start</td> </tr> <tr> <td style="text-align: center;">2</td> <td>seqh READY/Servo ON time normal</td> <td>READY/Servo ON time high speed</td> </tr> <tr> <td style="text-align: center;">3</td> <td>vfb Speed feedback filter stop</td> <td>Speed feedback filter stop (2250Hz)</td> </tr> <tr> <td style="text-align: center;">4</td> <td>fdir Position feedback forward polarity</td> <td>Position feedback reverse polarity</td> </tr> <tr> <td style="text-align: center;">5</td> <td>vdir Standard setting</td> <td>HA motor (4 pole motor) Detector installation position 90 degrees (B, D)</td> </tr> <tr> <td style="text-align: center;">6</td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">7</td> <td>abs Incremental control</td> <td>Absolute position control</td> </tr> <tr> <td style="text-align: center;">8</td> <td>mp MP scale 360P (2mm pitch)</td> <td>MP scale 720P (1mm pitch)</td> </tr> <tr> <td style="text-align: center;">9</td> <td>mpt3 MP scale ABS detection type 1, 2</td> <td>MP scale ABS detection type 3</td> </tr> <tr> <td style="text-align: center;">A</td> <td>drvup Standard setting</td> <td>Possible to connect a drive unit whose capacity is 1 rank higher/lower than the standard one.</td> </tr> <tr> <td style="text-align: center;">B</td> <td>drvall Setting for normal use</td> <td>Possible to connect a drive unit with any capacity.</td> </tr> <tr> <td style="text-align: center;">C</td> <td rowspan="4" style="vertical-align: middle;">spm</td> <td>0 : Setting for normal use</td> </tr> <tr> <td style="text-align: center;">D</td> <td>1 : When using the S type drive unit (Only in the case of MDS-C1-Vx)</td> </tr> <tr> <td style="text-align: center;">E</td> <td rowspan="2">2 to F : Setting prohibited</td> </tr> <tr> <td style="text-align: center;">F</td> </tr> </tbody> </table>	bit	Meaning when "0" is set	Meaning when "1" is set	0	fdir2 Speed feedback forward polarity	Speed feedback reverse polarity	1	dfbx Dual feedback control stop	Dual feedback control start	2	seqh READY/Servo ON time normal	READY/Servo ON time high speed	3	vfb Speed feedback filter stop	Speed feedback filter stop (2250Hz)	4	fdir Position feedback forward polarity	Position feedback reverse polarity	5	vdir Standard setting	HA motor (4 pole motor) Detector installation position 90 degrees (B, D)	6			7	abs Incremental control	Absolute position control	8	mp MP scale 360P (2mm pitch)	MP scale 720P (1mm pitch)	9	mpt3 MP scale ABS detection type 1, 2	MP scale ABS detection type 3	A	drvup Standard setting	Possible to connect a drive unit whose capacity is 1 rank higher/lower than the standard one.	B	drvall Setting for normal use	Possible to connect a drive unit with any capacity.	C	spm	0 : Setting for normal use	D	1 : When using the S type drive unit (Only in the case of MDS-C1-Vx)	E	2 to F : Setting prohibited	F
			bit	Meaning when "0" is set	Meaning when "1" is set																																													
			0	fdir2 Speed feedback forward polarity	Speed feedback reverse polarity																																													
			1	dfbx Dual feedback control stop	Dual feedback control start																																													
			2	seqh READY/Servo ON time normal	READY/Servo ON time high speed																																													
3	vfb Speed feedback filter stop	Speed feedback filter stop (2250Hz)																																																
4	fdir Position feedback forward polarity	Position feedback reverse polarity																																																
5	vdir Standard setting	HA motor (4 pole motor) Detector installation position 90 degrees (B, D)																																																
6																																																		
7	abs Incremental control	Absolute position control																																																
8	mp MP scale 360P (2mm pitch)	MP scale 720P (1mm pitch)																																																
9	mpt3 MP scale ABS detection type 1, 2	MP scale ABS detection type 3																																																
A	drvup Standard setting	Possible to connect a drive unit whose capacity is 1 rank higher/lower than the standard one.																																																
B	drvall Setting for normal use	Possible to connect a drive unit with any capacity.																																																
C	spm	0 : Setting for normal use																																																
D		1 : When using the S type drive unit (Only in the case of MDS-C1-Vx)																																																
E		2 to F : Setting prohibited																																																
F																																																		
(Note 1) Set to "0" for bits with no particular description.																																																		
(Note 2) bit3 (vfb) is only for MDS-C1-Vx.																																																		

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

No.	Items	Details	Setting range																																							
2218 (PR)	SV018 PIT	Ball screw pitch	Set the ball screw pitch. Set to "360" for the rotary axis.	1 to 32767 (mm/rev)																																						
2219 (PR)	SV019 RNG1	Position detector resolution	In the case of the semi-closed loop control Set the same value as SV020 (RNG2). (Refer to the explanation of SV020.)	1 to 9999 (kp/rev)																																						
			In the case of the semi-closed loop control Set the same value as SV020 (RNG2). (Refer to the explanation of SV020.)	1 to 9999 (kp/pit)																																						
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 30%;">Detector model name</th> <th style="width: 30%;">Resolution</th> <th style="width: 40%;">SV019 setting</th> </tr> </thead> <tbody> <tr> <td>OHE25K-ET, OHA25K-ET</td> <td>100,000(p/rev)</td> <td>100</td> </tr> <tr> <td>OSE104-ET, OSA104-ET</td> <td>100,000(p/rev)</td> <td>100</td> </tr> <tr> <td>OSE105-ET, OSA105-ET</td> <td>1,000,000(p/rev)</td> <td>1000</td> </tr> <tr> <td>RCN723 (Heidenhain)</td> <td>8,000,000(p/rev)</td> <td>8000</td> </tr> <tr> <td>Relative position detection scale</td> <td>Refer to specification manual for each detector</td> <td>PIT/Resolution (μm)</td> </tr> <tr> <td>AT41 (Mitsutoyo)</td> <td>1 (μm/p)</td> <td>The same as SV018 (PIT)</td> </tr> <tr> <td>FME type, FLE type (Futaba)</td> <td>Refer to specification manual for each detector</td> <td>PIT/Resolution (μm)</td> </tr> <tr> <td>MP type (Mitsubishi Heavy Industries)</td> <td>Refer to specification manual for each detector</td> <td>PIT/Resolution (μm)</td> </tr> <tr> <td>AT342 (Mitsutoyo)</td> <td>0.5 (μm/p)</td> <td>Twice as big as SV018 (PIT)</td> </tr> <tr> <td>AT343 (Mitsutoyo)</td> <td>0.05 (μm/p)</td> <td>20 times as big as SV018 (PIT)</td> </tr> <tr> <td>LC191M (Heidenhain)</td> <td>Refer to specification manual for each detector</td> <td>PIT/Resolution (μm)</td> </tr> <tr> <td>LC491M (Heidenhain)</td> <td>Refer to specification manual for each detector</td> <td>PIT/Resolution (μm)</td> </tr> </tbody> </table>				Detector model name	Resolution	SV019 setting	OHE25K-ET, OHA25K-ET	100,000(p/rev)	100	OSE104-ET, OSA104-ET	100,000(p/rev)	100	OSE105-ET, OSA105-ET	1,000,000(p/rev)	1000	RCN723 (Heidenhain)	8,000,000(p/rev)	8000	Relative position detection scale	Refer to specification manual for each detector	PIT/Resolution (μm)	AT41 (Mitsutoyo)	1 (μm/p)	The same as SV018 (PIT)	FME type, FLE type (Futaba)	Refer to specification manual for each detector	PIT/Resolution (μm)	MP type (Mitsubishi Heavy Industries)	Refer to specification manual for each detector	PIT/Resolution (μm)	AT342 (Mitsutoyo)	0.5 (μm/p)	Twice as big as SV018 (PIT)	AT343 (Mitsutoyo)	0.05 (μm/p)	20 times as big as SV018 (PIT)	LC191M (Heidenhain)	Refer to specification manual for each detector	PIT/Resolution (μm)	LC491M (Heidenhain)	Refer to specification manual for each detector	PIT/Resolution (μm)
Detector model name	Resolution	SV019 setting																																								
OHE25K-ET, OHA25K-ET	100,000(p/rev)	100																																								
OSE104-ET, OSA104-ET	100,000(p/rev)	100																																								
OSE105-ET, OSA105-ET	1,000,000(p/rev)	1000																																								
RCN723 (Heidenhain)	8,000,000(p/rev)	8000																																								
Relative position detection scale	Refer to specification manual for each detector	PIT/Resolution (μm)																																								
AT41 (Mitsutoyo)	1 (μm/p)	The same as SV018 (PIT)																																								
FME type, FLE type (Futaba)	Refer to specification manual for each detector	PIT/Resolution (μm)																																								
MP type (Mitsubishi Heavy Industries)	Refer to specification manual for each detector	PIT/Resolution (μm)																																								
AT342 (Mitsutoyo)	0.5 (μm/p)	Twice as big as SV018 (PIT)																																								
AT343 (Mitsutoyo)	0.05 (μm/p)	20 times as big as SV018 (PIT)																																								
LC191M (Heidenhain)	Refer to specification manual for each detector	PIT/Resolution (μm)																																								
LC491M (Heidenhain)	Refer to specification manual for each detector	PIT/Resolution (μm)																																								
2220 (PR)	SV020 RNG2	Speed detector resolution	Set the number of pulses per one revolution of the motor end detector.	1 to 9999 (kp/rev)																																						
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 50%;">Detector model name</th> <th style="width: 50%;">SV020 setting</th> </tr> </thead> <tbody> <tr> <td>OSE104, OSA104</td> <td>100</td> </tr> <tr> <td>OSE105, OSA105</td> <td>1000</td> </tr> </tbody> </table>				Detector model name	SV020 setting	OSE104, OSA104	100	OSE105, OSA105	1000																																	
Detector model name	SV020 setting																																									
OSE104, OSA104	100																																									
OSE105, OSA105	1000																																									

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

No.	Items	Details	Setting range
2221	SV021 OLT	Overload detection time constant Set the detection time constant of Overload 1 (Alarm 50). Set to "60" as a standard. (For machine tool builder adjustment.)	1 to 999 (s)
2222	SV022 OLL	Overload detection level Set the current detection level of Overload 1 (Alarm 50) in respect to the stall (rated) current. Set to "150" as a standard. (For machine tool builder adjustment.)	110 to 500 (Stall [rated] current %)
2223	SV023 OD1	Excessive error detection width during servo ON Set the excessive error detection width when servo ON. <Standard setting value> $OD1=OD2= \frac{\text{Rapid traverse rate (mm/min)}}{60 \cdot PGN1} / 2 \text{ (mm)}$ When "0" is set, the excessive error detection will not be performed.	0 to 32767 (mm)
2224	SV024 INP	In-position detection width Set the in-position detection width. Set the accuracy required for the machine. The lower the setting is, the higher the positioning accuracy gets, however, the cycle time (setting time) becomes longer. The standard setting is "50".	0 to 32767 (μm)

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

No.	Items	Details	Setting range																																																																																																																																																								
2225 (PR)	SV025 MTYP	Motor /Detector type	<table border="1"> <tr> <td align="center">F</td> <td align="center">E</td> <td align="center">D</td> <td align="center">C</td> <td align="center">B</td> <td align="center">A</td> <td align="center">9</td> <td align="center">8</td> </tr> <tr> <td align="center" colspan="4">pen</td> <td align="center" colspan="4">ent</td> </tr> <tr> <td align="center">7</td> <td align="center">6</td> <td align="center">5</td> <td align="center">4</td> <td align="center">3</td> <td align="center">2</td> <td align="center">1</td> <td align="center">0</td> </tr> <tr> <td align="center" colspan="8">mtyp</td> </tr> </table>	F	E	D	C	B	A	9	8	pen				ent				7	6	5	4	3	2	1	0	mtyp																																																																																																																															
			F	E	D	C	B	A	9	8																																																																																																																																																	
			pen				ent																																																																																																																																																				
			7	6	5	4	3	2	1	0																																																																																																																																																	
			mtyp																																																																																																																																																								
			bit	Explanation																																																																																																																																																							
			0	Set the motor type.																																																																																																																																																							
			1	Set this along with SV017 (SPEC)/spm.																																																																																																																																																							
			2	1) When SV017/spm=0 (Normal drive unit)																																																																																																																																																							
			3																																																																																																																																																								
4	mtyp	<table border="1"> <thead> <tr> <th>Set- ting</th> <th>0x</th> <th>1x</th> <th>2x</th> <th>3x</th> <th>4x</th> <th>5x</th> <th>6x</th> <th>7x</th> </tr> </thead> <tbody> <tr><td>x0</td><td>HA40N</td><td></td><td>HA50L</td><td>HA53L</td><td></td><td></td><td></td><td></td></tr> <tr><td>x1</td><td>HA80N</td><td></td><td>HA100L</td><td>HA103L</td><td></td><td></td><td></td><td></td></tr> <tr><td>x2</td><td>HA100N</td><td></td><td>HA200L</td><td>HA203L</td><td></td><td></td><td></td><td></td></tr> <tr><td>x3</td><td>HA200N</td><td></td><td>HA300L</td><td>HA303L</td><td></td><td></td><td></td><td></td></tr> <tr><td>x4</td><td>HA300N</td><td></td><td>HA500L</td><td>HA503L</td><td></td><td></td><td></td><td></td></tr> <tr><td>x5</td><td>HA700N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x6</td><td>HA900N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x7</td><td></td><td></td><td>HA-LH11K2</td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x8</td><td></td><td></td><td>HA-LH15K2</td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x9</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xA</td><td></td><td></td><td>HA150L</td><td>HA153L</td><td></td><td></td><td></td><td></td></tr> <tr><td>xB</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xC</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xD</td><td></td><td></td><td>HA-LF15K2</td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xE</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xF</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </tbody> </table>	Set- ting	0x	1x	2x	3x	4x	5x	6x	7x	x0	HA40N		HA50L	HA53L					x1	HA80N		HA100L	HA103L					x2	HA100N		HA200L	HA203L					x3	HA200N		HA300L	HA303L					x4	HA300N		HA500L	HA503L					x5	HA700N								x6	HA900N								x7			HA-LH11K2						x8			HA-LH15K2						x9									xA			HA150L	HA153L					xB									xC									xD			HA-LF15K2						xE									xF								
Set- ting		0x	1x	2x	3x	4x	5x	6x	7x																																																																																																																																																		
x0		HA40N		HA50L	HA53L																																																																																																																																																						
x1		HA80N		HA100L	HA103L																																																																																																																																																						
x2		HA100N		HA200L	HA203L																																																																																																																																																						
x3		HA200N		HA300L	HA303L																																																																																																																																																						
x4		HA300N		HA500L	HA503L																																																																																																																																																						
x5		HA700N																																																																																																																																																									
x6		HA900N																																																																																																																																																									
x7				HA-LH11K2																																																																																																																																																							
x8				HA-LH15K2																																																																																																																																																							
x9																																																																																																																																																											
xA				HA150L	HA153L																																																																																																																																																						
xB																																																																																																																																																											
xC																																																																																																																																																											
xD				HA-LF15K2																																																																																																																																																							
xE																																																																																																																																																											
xF																																																																																																																																																											
5		<table border="1"> <thead> <tr> <th>Set- ting</th> <th>8x</th> <th>9x</th> <th>Ax</th> <th>Bx</th> <th>Cx</th> <th>Dx</th> <th>Ex</th> <th>Fx</th> </tr> </thead> <tbody> <tr><td>x0</td><td>HA43N</td><td></td><td></td><td>HC52</td><td>HC53</td><td></td><td></td><td></td></tr> <tr><td>x1</td><td>HA83N</td><td></td><td></td><td>HC102</td><td>HC103</td><td></td><td>HC103R</td><td></td></tr> <tr><td>x2</td><td>HA103N</td><td></td><td></td><td>HC152</td><td>HC153</td><td></td><td>HC153R</td><td></td></tr> <tr><td>x3</td><td>HA203N</td><td></td><td></td><td>HC202</td><td>HC203</td><td></td><td>HC203R</td><td></td></tr> <tr><td>x4</td><td>HA303N</td><td></td><td></td><td>HC352</td><td>HC353</td><td></td><td>HC353R</td><td></td></tr> <tr><td>x5</td><td>HA703N</td><td></td><td></td><td>HC452</td><td>HC453</td><td></td><td>HC503R</td><td></td></tr> <tr><td>x6</td><td></td><td></td><td></td><td>HC702</td><td>HC703</td><td></td><td></td><td></td></tr> <tr><td>x7</td><td></td><td></td><td></td><td>HC902</td><td></td><td></td><td></td><td></td></tr> <tr><td>x8</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x9</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xA</td><td>HA93N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xB</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xC</td><td>HA053N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xD</td><td>HA13N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xE</td><td>HA23N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xF</td><td>HA33N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </tbody> </table>	Set- ting	8x	9x	Ax	Bx	Cx	Dx	Ex	Fx	x0	HA43N			HC52	HC53				x1	HA83N			HC102	HC103		HC103R		x2	HA103N			HC152	HC153		HC153R		x3	HA203N			HC202	HC203		HC203R		x4	HA303N			HC352	HC353		HC353R		x5	HA703N			HC452	HC453		HC503R		x6				HC702	HC703				x7				HC902					x8									x9									xA	HA93N								xB									xC	HA053N								xD	HA13N								xE	HA23N								xF	HA33N							
Set- ting	8x	9x	Ax	Bx	Cx	Dx	Ex	Fx																																																																																																																																																			
x0	HA43N			HC52	HC53																																																																																																																																																						
x1	HA83N			HC102	HC103		HC103R																																																																																																																																																				
x2	HA103N			HC152	HC153		HC153R																																																																																																																																																				
x3	HA203N			HC202	HC203		HC203R																																																																																																																																																				
x4	HA303N			HC352	HC353		HC353R																																																																																																																																																				
x5	HA703N			HC452	HC453		HC503R																																																																																																																																																				
x6				HC702	HC703																																																																																																																																																						
x7				HC902																																																																																																																																																							
x8																																																																																																																																																											
x9																																																																																																																																																											
xA	HA93N																																																																																																																																																										
xB																																																																																																																																																											
xC	HA053N																																																																																																																																																										
xD	HA13N																																																																																																																																																										
xE	HA23N																																																																																																																																																										
xF	HA33N																																																																																																																																																										
6																																																																																																																																																											
7																																																																																																																																																											
		(Continued to the next page)																																																																																																																																																									

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

No.	Items	Details	Setting range																																																																																																																																																																											
(Continued from the previous page)																																																																																																																																																																														
		<table border="1"> <thead> <tr> <th data-bbox="564 389 644 421">bit</th> <th colspan="8" data-bbox="979 389 1123 421">Explanation</th> </tr> </thead> <tbody> <tr> <td colspan="9" data-bbox="676 421 1123 452">2) When SV017/spm=1 (S type drive unit)</td> </tr> <tr> <th data-bbox="676 452 772 497">Set- ting</th> <th data-bbox="772 452 836 497">8x</th> <th data-bbox="836 452 900 497">9x</th> <th data-bbox="900 452 963 497">Ax</th> <th data-bbox="963 452 1027 497">Bx</th> <th data-bbox="1027 452 1091 497">Cx</th> <th data-bbox="1091 452 1155 497">Dx</th> <th data-bbox="1155 452 1219 497">Ex</th> <th data-bbox="1219 452 1283 497">Fx</th> </tr> <tr><td>x0</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x1</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x2</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x3</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x4</td><td></td><td></td><td>HC353</td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x5</td><td></td><td>HC452</td><td>HC453</td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x6</td><td></td><td>HC702</td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x7</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x8</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x9</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xA</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xB</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xC</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xD</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xE</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xF</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </tbody> </table>	bit	Explanation								2) When SV017/spm=1 (S type drive unit)									Set- ting	8x	9x	Ax	Bx	Cx	Dx	Ex	Fx	x0									x1									x2									x3									x4			HC353						x5		HC452	HC453						x6		HC702							x7									x8									x9									xA									xB									xC									xD									xE									xF									
bit	Explanation																																																																																																																																																																													
2) When SV017/spm=1 (S type drive unit)																																																																																																																																																																														
Set- ting	8x	9x	Ax	Bx	Cx	Dx	Ex	Fx																																																																																																																																																																						
x0																																																																																																																																																																														
x1																																																																																																																																																																														
x2																																																																																																																																																																														
x3																																																																																																																																																																														
x4			HC353																																																																																																																																																																											
x5		HC452	HC453																																																																																																																																																																											
x6		HC702																																																																																																																																																																												
x7																																																																																																																																																																														
x8																																																																																																																																																																														
x9																																																																																																																																																																														
xA																																																																																																																																																																														
xB																																																																																																																																																																														
xC																																																																																																																																																																														
xD																																																																																																																																																																														
xE																																																																																																																																																																														
xF																																																																																																																																																																														
8		Set the detector type.																																																																																																																																																																												
9		Set the position detector type for “pen”, and the speed detector type for “ent”. In the case of the semi-closed loop control, set the same value for “pen” and “ent”.																																																																																																																																																																												
A	ent																																																																																																																																																																													
B																																																																																																																																																																														
C	pen																																																																																																																																																																													
D																																																																																																																																																																														
E																																																																																																																																																																														
F																																																																																																																																																																														
		<table border="1"> <thead> <tr> <th data-bbox="676 1249 772 1294">pen setting</th> <th data-bbox="772 1249 900 1294">ent setting</th> <th data-bbox="1043 1249 1299 1294">Detector model name</th> </tr> </thead> <tbody> <tr><td>0</td><td>0</td><td>OSE104</td></tr> <tr><td>1</td><td>1</td><td>OSA104</td></tr> <tr><td>2</td><td>2</td><td>OSE105, OSA105</td></tr> <tr><td>3</td><td>3</td><td></td></tr> <tr><td>4</td><td>Setting impossible</td><td>OHE25K-ET, OSE104-ET</td></tr> <tr><td>5</td><td>Setting impossible</td><td>OHA25K-ET, OSA104-ET</td></tr> <tr><td>6</td><td>Setting impossible</td><td>OSE105-ET, OSA105-ET, RCN723 (Heidenhain)</td></tr> <tr><td>7</td><td>Setting impossible</td><td></td></tr> <tr><td>8</td><td>Setting impossible</td><td>Relative position detection scale, MP type (Mitsubishi Heavy Industries)</td></tr> <tr><td>9</td><td>Setting impossible</td><td>AT41 (Mitsutoyo), FME type, FLE type (Futaba)</td></tr> <tr><td>A</td><td>Setting impossible</td><td>AT342,AT343 (Mitsutoyo), LC191M/491M (Heidenhain), MDS-B-HR</td></tr> <tr><td>B</td><td>Setting impossible</td><td></td></tr> <tr><td>C</td><td>C (Current synchronization)</td><td>The setting of the slave axis in the speed/current synchronization control. When the master axis is the semi-closed control.</td></tr> <tr><td>D</td><td>E (Current synchronization)</td><td>The setting of the slave axis in the speed/current synchronization control. When the master axis is the full-closed control. (Current synchronization control is only for MDS-C2-Vx.)</td></tr> <tr><td>E</td><td>Setting impossible</td><td></td></tr> <tr><td>F</td><td>Setting impossible</td><td></td></tr> </tbody> </table>	pen setting	ent setting	Detector model name	0	0	OSE104	1	1	OSA104	2	2	OSE105, OSA105	3	3		4	Setting impossible	OHE25K-ET, OSE104-ET	5	Setting impossible	OHA25K-ET, OSA104-ET	6	Setting impossible	OSE105-ET, OSA105-ET, RCN723 (Heidenhain)	7	Setting impossible		8	Setting impossible	Relative position detection scale, MP type (Mitsubishi Heavy Industries)	9	Setting impossible	AT41 (Mitsutoyo), FME type, FLE type (Futaba)	A	Setting impossible	AT342,AT343 (Mitsutoyo), LC191M/491M (Heidenhain), MDS-B-HR	B	Setting impossible		C	C (Current synchronization)	The setting of the slave axis in the speed/current synchronization control. When the master axis is the semi-closed control.	D	E (Current synchronization)	The setting of the slave axis in the speed/current synchronization control. When the master axis is the full-closed control. (Current synchronization control is only for MDS-C2-Vx.)	E	Setting impossible		F	Setting impossible																																																																																																																										
pen setting	ent setting	Detector model name																																																																																																																																																																												
0	0	OSE104																																																																																																																																																																												
1	1	OSA104																																																																																																																																																																												
2	2	OSE105, OSA105																																																																																																																																																																												
3	3																																																																																																																																																																													
4	Setting impossible	OHE25K-ET, OSE104-ET																																																																																																																																																																												
5	Setting impossible	OHA25K-ET, OSA104-ET																																																																																																																																																																												
6	Setting impossible	OSE105-ET, OSA105-ET, RCN723 (Heidenhain)																																																																																																																																																																												
7	Setting impossible																																																																																																																																																																													
8	Setting impossible	Relative position detection scale, MP type (Mitsubishi Heavy Industries)																																																																																																																																																																												
9	Setting impossible	AT41 (Mitsutoyo), FME type, FLE type (Futaba)																																																																																																																																																																												
A	Setting impossible	AT342,AT343 (Mitsutoyo), LC191M/491M (Heidenhain), MDS-B-HR																																																																																																																																																																												
B	Setting impossible																																																																																																																																																																													
C	C (Current synchronization)	The setting of the slave axis in the speed/current synchronization control. When the master axis is the semi-closed control.																																																																																																																																																																												
D	E (Current synchronization)	The setting of the slave axis in the speed/current synchronization control. When the master axis is the full-closed control. (Current synchronization control is only for MDS-C2-Vx.)																																																																																																																																																																												
E	Setting impossible																																																																																																																																																																													
F	Setting impossible																																																																																																																																																																													

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

No.	Items	Details	Setting range																																																																																			
2226	SV026 OD2	Excessive error detection width during servo OFF	0 to 32767 (mm)																																																																																			
2227	SV027 SSF1	Servo function selection 1	<table border="1" style="width: 100%; text-align: center;"> <tr> <td>F</td> <td>E</td> <td>D</td> <td>C</td> <td>B</td> <td>A</td> <td>9</td> <td>8</td> </tr> <tr> <td>aflt</td> <td>zrn2</td> <td>afse</td> <td></td> <td>ovs</td> <td></td> <td>lmc</td> <td></td> </tr> <tr> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> <td>1</td> <td>0</td> </tr> <tr> <td>omr</td> <td>zrn3</td> <td>vfct</td> <td></td> <td></td> <td>upc</td> <td></td> <td>vcnt</td> </tr> </table> <table border="1" style="width: 100%; text-align: center;"> <thead> <tr> <th>bit</th> <th>Meaning when "0" is set</th> <th>Meaning when "1" is set</th> </tr> </thead> <tbody> <tr> <td>0</td> <td colspan="2">Set the execution changeover type of the speed loop delay compensation.</td> </tr> <tr> <td>1</td> <td colspan="2">00: Delay compensation changeover invalid 01: Delay compensation changeover type 1 10: Delay compensation type 2 11: Setting prohibited</td> </tr> <tr> <td>2</td> <td>Start torque compensation invalid</td> <td>Start torque compensation valid</td> </tr> <tr> <td>3</td> <td colspan="2"></td> </tr> <tr> <td>4</td> <td colspan="2">Set the number of compensation pulses of the jitter compensation.</td> </tr> <tr> <td>5</td> <td colspan="2">00: Jitter compensation invalid 01: Jitter compensation 1 pulse 10: Jitter compensation 2 pulses 11: Jitter compensation 3 pulses</td> </tr> <tr> <td>6</td> <td colspan="2">zrn3 ABS scale: Set to "1" in using AT342, AT343, LC191M/491M.</td> </tr> <tr> <td>7</td> <td>Machine end compensation invalid</td> <td>Machine end compensation valid</td> </tr> <tr> <td>8</td> <td colspan="2">Set the compensation amount with SV016 (LMC1) and SV041 (LMC2).</td> </tr> <tr> <td>9</td> <td colspan="2">00: Lost motion compensation stop 01: Lost motion compensation type 1 10: Overshooting compensation type 2 11: Setting prohibited</td> </tr> <tr> <td>A</td> <td colspan="2">Set the compensation amount with SV031 (OVS1) and SV042 (OVS2).</td> </tr> <tr> <td>B</td> <td colspan="2">00: Overshooting compensation stop 01: Overshooting compensation type 1 10: Overshooting compensation type 2 11: Overshooting compensation type 3</td> </tr> <tr> <td>C</td> <td colspan="2">00: Adoptive filter sensitivity standard</td> </tr> <tr> <td>D</td> <td colspan="2">11: Adoptive filter sensitivity increase (Set 2bits at a time)</td> </tr> <tr> <td>E</td> <td colspan="2">zrn2 Set to "1".</td> </tr> <tr> <td>F</td> <td>Adoptive filter stop</td> <td>Adoptive filter start</td> </tr> </tbody> </table> <p>(Note) Set to "0" for bits with no particular description.</p>	F	E	D	C	B	A	9	8	aflt	zrn2	afse		ovs		lmc		7	6	5	4	3	2	1	0	omr	zrn3	vfct			upc		vcnt	bit	Meaning when "0" is set	Meaning when "1" is set	0	Set the execution changeover type of the speed loop delay compensation.		1	00: Delay compensation changeover invalid 01: Delay compensation changeover type 1 10: Delay compensation type 2 11: Setting prohibited		2	Start torque compensation invalid	Start torque compensation valid	3			4	Set the number of compensation pulses of the jitter compensation.		5	00: Jitter compensation invalid 01: Jitter compensation 1 pulse 10: Jitter compensation 2 pulses 11: Jitter compensation 3 pulses		6	zrn3 ABS scale: Set to "1" in using AT342, AT343, LC191M/491M.		7	Machine end compensation invalid	Machine end compensation valid	8	Set the compensation amount with SV016 (LMC1) and SV041 (LMC2).		9	00: Lost motion compensation stop 01: Lost motion compensation type 1 10: Overshooting compensation type 2 11: Setting prohibited		A	Set the compensation amount with SV031 (OVS1) and SV042 (OVS2).		B	00: Overshooting compensation stop 01: Overshooting compensation type 1 10: Overshooting compensation type 2 11: Overshooting compensation type 3		C	00: Adoptive filter sensitivity standard		D	11: Adoptive filter sensitivity increase (Set 2bits at a time)		E	zrn2 Set to "1".		F	Adoptive filter stop	Adoptive filter start
F	E	D	C	B	A	9	8																																																																															
aflt	zrn2	afse		ovs		lmc																																																																																
7	6	5	4	3	2	1	0																																																																															
omr	zrn3	vfct			upc		vcnt																																																																															
bit	Meaning when "0" is set	Meaning when "1" is set																																																																																				
0	Set the execution changeover type of the speed loop delay compensation.																																																																																					
1	00: Delay compensation changeover invalid 01: Delay compensation changeover type 1 10: Delay compensation type 2 11: Setting prohibited																																																																																					
2	Start torque compensation invalid	Start torque compensation valid																																																																																				
3																																																																																						
4	Set the number of compensation pulses of the jitter compensation.																																																																																					
5	00: Jitter compensation invalid 01: Jitter compensation 1 pulse 10: Jitter compensation 2 pulses 11: Jitter compensation 3 pulses																																																																																					
6	zrn3 ABS scale: Set to "1" in using AT342, AT343, LC191M/491M.																																																																																					
7	Machine end compensation invalid	Machine end compensation valid																																																																																				
8	Set the compensation amount with SV016 (LMC1) and SV041 (LMC2).																																																																																					
9	00: Lost motion compensation stop 01: Lost motion compensation type 1 10: Overshooting compensation type 2 11: Setting prohibited																																																																																					
A	Set the compensation amount with SV031 (OVS1) and SV042 (OVS2).																																																																																					
B	00: Overshooting compensation stop 01: Overshooting compensation type 1 10: Overshooting compensation type 2 11: Overshooting compensation type 3																																																																																					
C	00: Adoptive filter sensitivity standard																																																																																					
D	11: Adoptive filter sensitivity increase (Set 2bits at a time)																																																																																					
E	zrn2 Set to "1".																																																																																					
F	Adoptive filter stop	Adoptive filter start																																																																																				
2228	SV028	Not used. Set to "0".	0																																																																																			
2229	SV029	Speed at the change of speed loop gain	0 to 9999 (r/min)																																																																																			

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

No.	Items	Details	Setting range
2230	The higher order 8bits and lower order 8bits are used for different functions. "The setting value of SV030" = (lcx*256) + IVC		0 to 32767
	SV030 IVC (Low order)	Voltage dead time compensation When 100% is set, the voltage equivalent to the logical non-energized time will be compensated. When "0" is set, a 100% compensation will be performed. Adjust in increments of 10% from the default value 100%. If increased too much, vibration or vibration noise may be generated.	0 to 255 (%)
	SV030 lcx (High order)	Current bias 1 Set to "0" as a standard. Use this in combination with SV040 and the high order 8bits of SV045.	0 to 127
2231	SV031 OVS1	Overshooting compensation 1 Set this if overshooting occurs during positioning. This compensates the motor torque during positioning. This is valid only when the overshooting compensation SV027 (SSF1/ovs) is selected.	-1 to 100 (Stall [rated] current %)
		Type 1: When SV027 (SSF1)/ bitB, A (ovs)=01 Set the compensation amount based on the motor's stall current. This compensates overshooting that occurs during pulse feeding. Normally, use Type 2.	
		Type 2: When SV027 (SSF1)/ bitB, A (ovs)=10 Set the compensation amount based on the motor's stall current. Increase by 1% and determine the amount that overshooting doesn't occur. In Type 2, compensation during the feed forward control during circular cutting won't be performed.	
		Type 3: When SV027 (SSF1)/ bitB, A (ovs)=11 Use this to perform the overshooting compensation during circular cutting or the feed forward control. The setting method is the same in Type 2. When you wish different compensation amount depending on the direction When SV042 (OVS2) is "0", compensate with the value of SV031 (OVS1) in both of the + and -directions. If you wish to change the compensation amount depending on the command direction, set this and SV042 (OVS2). (SV031: + direction, SV042: - direction. However, the directions may be opposite depending on other settings.) When "-1" is set, the compensation won't be performed in the direction of the command.	
2232	SV032 TOF	Torque offset Set the unbalance torque of vertical axis and inclined axis.	-100 to 100 (Stall [rated] current %)

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

No.	Items	Details	Setting range																																
2233	SV033 SSF2	Servo function selection 2	<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 12.5%; text-align: center;">F</td> <td style="width: 12.5%; text-align: center;">E</td> <td style="width: 12.5%; text-align: center;">D</td> <td style="width: 12.5%; text-align: center;">C</td> <td style="width: 12.5%; text-align: center;">B</td> <td style="width: 12.5%; text-align: center;">A</td> <td style="width: 12.5%; text-align: center;">9</td> <td style="width: 12.5%; text-align: center;">8</td> </tr> <tr> <td colspan="6" style="text-align: center; border: 1px solid black;">dos</td> <td style="text-align: center; border: 1px solid black;">hvx</td> <td style="text-align: center; border: 1px solid black;">svx</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> <td style="text-align: center;">1</td> <td style="text-align: center;">0</td> </tr> <tr> <td colspan="3" style="text-align: center; border: 1px solid black;">nfd2</td> <td style="text-align: center; border: 1px solid black;">nf3</td> <td colspan="3" style="text-align: center; border: 1px solid black;">nfd1</td> <td style="text-align: center; border: 1px solid black;">zck</td> </tr> </table>	F	E	D	C	B	A	9	8	dos						hvx	svx	7	6	5	4	3	2	1	0	nfd2			nf3	nfd1			zck
			F	E	D	C	B	A	9	8																									
			dos						hvx	svx																									
			7	6	5	4	3	2	1	0																									
			nfd2			nf3	nfd1			zck																									
			0	zck	Z phase check valid (Alarm 42)	Z phase check invalid																													
			1	nfd1	Set the filter depth for Notch filter 1 (SV038).																														
			2		Value	000 001 010 011 100 101 110 111																													
			3		Depth (dB)	Infntly deep -18.1 -12.0 -8.5 -6.0 -4.1 -2.5 -1.2																													
					Deep←	→ Shallow																													
			4	nf3	Notch filter 3 stop	Notch filter 3 start (1125Hz)																													
			5	nfd2	Set the operation frequency of Notch filter 2 (SV046).																														
			6		Value	000 001 010 011 100 101 110 111																													
			7		Depth (dB)	Infntly deep -18.1 -12.0 -8.5 -6.0 -4.1 -2.5 -1.2																													
					Deep←	→ Shallow																													
8	svx	Set the performance mode of the servo control. (Only for MDS-C1-Vx)																																	
9	hvx	00: By current loop gain 01: MDS-B-Vx compatible mode selected 10: High gain mode selected 11: High gain mode selected																																	
A																																			
B																																			
C	Digital signal output selection																																		
D	dos	0 : MP scale absolute position detection, offset demand signal output																																	
E		1 : Specified speed signal output																																	
F		2 to F : Setting prohibited																																	
(Note) Set to "0" for bits with no particular description.																																			

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

No.	Items	Details	Setting range																																
2234	SV034 SSF3	Servo function selection 3	<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center;">F</td> <td style="text-align: center;">E</td> <td style="text-align: center;">D</td> <td style="text-align: center;">C</td> <td style="text-align: center;">B</td> <td style="text-align: center;">A</td> <td style="text-align: center;">9</td> <td style="text-align: center;">8</td> </tr> <tr> <td colspan="8" style="text-align: center; border: 1px solid black;">ovsn</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> <td style="text-align: center;">1</td> <td style="text-align: center;">0</td> </tr> <tr> <td style="border: 1px solid black;"></td> <td style="border: 1px solid black;">os2</td> <td style="border: 1px solid black;">zeg</td> <td style="border: 1px solid black;"></td> <td style="border: 1px solid black;"></td> <td style="border: 1px solid black;">mohn</td> <td style="border: 1px solid black;">has2</td> <td style="border: 1px solid black;">has1</td> </tr> </table>	F	E	D	C	B	A	9	8	ovsn								7	6	5	4	3	2	1	0		os2	zeg			mohn	has2	has1
			F	E	D	C	B	A	9	8																									
			ovsn																																
			7	6	5	4	3	2	1	0																									
				os2	zeg			mohn	has2	has1																									
			bit	Meaning when “0” is set	Meaning when “1” is set																														
			0	has1	Setting for normal use (Except for HC)	HAS control 1 valid (HC: High acceleration rate support)																													
			1	has2	Setting for normal use (Except for HC)	HAS control 2 valid (HC: Overshooting support)																													
			2	mohn	MDS-B-HR motor thermal valid	MDS-B-HR motor thermal ignored																													
			3																																
4																																			
5	zeg	Z phase normal edge detection (Setting for normal use)	Z phase reverse edge detection (Valid only when SV027/bit6=1)																																
6	os2	Setting for normal use	Overspeed detection level changeover																																
7																																			
8																																			
9																																			
A																																			
B																																			
C		Set the non-sensitive band of the overshooting compensation type 3 in increments of 2 μ m at a time.																																	
D		In the feed forward control, the non-sensitive band of the model position droop is set, and overshooting of the model is ignored. Set the same value as the standard SV040.																																	
E	ovsn																																		
F																																			
(Note) Set to “0” for bits with no particular description.																																			

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

No.	Items	Details	Setting range																																
2235	SV035 SSF4 Servo function selection 4	<table style="width: 100%; border-collapse: collapse; margin-bottom: 5px;"> <tr> <td style="width: 12.5%; text-align: center;">F</td> <td style="width: 12.5%; text-align: center;">E</td> <td style="width: 12.5%; text-align: center;">D</td> <td style="width: 12.5%; text-align: center;">C</td> <td style="width: 12.5%; text-align: center;">B</td> <td style="width: 12.5%; text-align: center;">A</td> <td style="width: 12.5%; text-align: center;">9</td> <td style="width: 12.5%; text-align: center;">8</td> </tr> <tr> <td style="border: 1px solid black; text-align: center;">clt</td> <td colspan="3" style="border: 1px solid black; text-align: center;">clG1</td> <td style="border: 1px solid black; text-align: center;">cl2n</td> <td style="border: 1px solid black; text-align: center;">clet</td> <td colspan="2" style="border: 1px solid black; text-align: center;">cltq</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> <td style="text-align: center;">1</td> <td style="text-align: center;">0</td> </tr> <tr> <td colspan="2" style="border: 1px solid black; text-align: center;">ckab</td> <td style="border: 1px solid black; text-align: center;">iup</td> <td colspan="5" style="border: 1px solid black; text-align: center;">tdt</td> </tr> </table>	F	E	D	C	B	A	9	8	clt	clG1			cl2n	clet	cltq		7	6	5	4	3	2	1	0	ckab		iup	tdt					
		F	E	D	C	B	A	9	8																										
		clt	clG1			cl2n	clet	cltq																											
		7	6	5	4	3	2	1	0																										
		ckab		iup	tdt																														
		bit	Meaning when “0” is set	Meaning when “1” is set																															
		0	Td creation time setting Set to “0”. (For machine tool builder adjustment)																																
		1																																	
		2		tdt																															
		3																																	
4																																			
5																																			
6	iup	Set to “1” when using any of motors from HC152 to HC702 and from HC153 to HC453.																																	
7	ckab	Setting for normal use	No signal 2 (Alarm 21) special detection																																
8	cltq	Set the retracting torque for collision detection in respect to the maximum torque of the motor.																																	
9		00: 100% 01: 90% 10: 80% (Standard) 11: 70%																																	
A	clet	Setting for normal use	The disturbance torque peak of the latest two seconds is displayed in MPOS of the servo monitor screen.																																
B	cl2n	Collision detection method 2 valid	Collision detection method 2 invalid																																
C	Collision detection method 1																																		
D	Set the collision detection level during cutting feed (G1).																																		
E	clG1	The G1 collision detection level=SV060*clG1. When clG1=0, the collision detection method 1 during cutting feed won't function.																																	
F	clt	Setting for normal use	The guide value of the SV059 setting value is displayed in MPOS of the servo monitor screen.																																
(Note) bit7 (ckab) is only for MDS-C1-Vx.																																			

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

No.	Items	Details	Setting range																																																																																																																																																		
2236 (PR)	SV036 PTYP	Power supply type	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center;">F</td> <td style="text-align: center;">E</td> <td style="text-align: center;">D</td> <td style="text-align: center;">C</td> <td style="text-align: center;">B</td> <td style="text-align: center;">A</td> <td style="text-align: center;">9</td> <td style="text-align: center;">8</td> </tr> <tr> <td colspan="4" style="text-align: center;">amp</td> <td colspan="4" style="text-align: center;">rtyp</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> <td style="text-align: center;">1</td> <td style="text-align: center;">0</td> </tr> <tr> <td colspan="8" style="text-align: center;">ptyp</td> </tr> </table>	F	E	D	C	B	A	9	8	amp				rtyp				7	6	5	4	3	2	1	0	ptyp																																																																																																																									
			F	E	D	C	B	A	9	8																																																																																																																																											
			amp				rtyp																																																																																																																																														
			7	6	5	4	3	2	1	0																																																																																																																																											
			ptyp																																																																																																																																																		
			0	ptyp	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: center;">bit</th> <th colspan="9" style="text-align: center;">Explanation</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">0</td> <td colspan="9" rowspan="3"> When the CN4 connector of the drive unit and the power supply are connected, setting below is necessary. To validate the external emergency stop function, add 40h. </td> </tr> <tr> <td style="text-align: center;">1</td> </tr> <tr> <td style="text-align: center;">2</td> </tr> <tr> <td style="text-align: center;">3</td> <td style="text-align: center;">Setting</td> <td style="text-align: center;">0x</td> <td style="text-align: center;">1x</td> <td style="text-align: center;">2x</td> <td style="text-align: center;">3x</td> <td style="text-align: center;">4x</td> <td style="text-align: center;">5x</td> <td style="text-align: center;">6x</td> <td style="text-align: center;">7x</td> <td style="text-align: center;">8x</td> </tr> <tr> <td style="text-align: center;">4</td> <td style="text-align: center;">x0</td> <td style="text-align: center;">Not used</td> <td></td> <td></td> <td style="text-align: center;">CV-300</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">5</td> <td style="text-align: center;">x1</td> <td></td> <td style="text-align: center;">CV-110</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td style="text-align: center;">CR-10</td> </tr> <tr> <td style="text-align: center;">6</td> <td style="text-align: center;">x2</td> <td></td> <td></td> <td style="text-align: center;">CV-220</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td style="text-align: center;">CR-15</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">x3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td style="text-align: center;">CR-22</td> </tr> <tr> <td></td> <td style="text-align: center;">x4</td> <td style="text-align: center;">CV-37</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td style="text-align: center;">CR-37</td> </tr> <tr> <td></td> <td style="text-align: center;">x5</td> <td></td> <td style="text-align: center;">CV-150</td> <td></td> <td></td> <td style="text-align: center;">CV-450</td> <td style="text-align: center;">CV-550</td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td style="text-align: center;">x6</td> <td style="text-align: center;">CV-55</td> <td></td> <td style="text-align: center;">CV-260</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td style="text-align: center;">CR-55</td> </tr> <tr> <td></td> <td style="text-align: center;">x7</td> <td></td> <td></td> <td></td> <td style="text-align: center;">CV-370</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td style="text-align: center;">x8</td> <td style="text-align: center;">CV-75</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td style="text-align: center;">CR-75</td> </tr> <tr> <td></td> <td style="text-align: center;">x9</td> <td></td> <td style="text-align: center;">CV-185</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td style="text-align: center;">CR-90</td> </tr> </tbody> </table>	bit	Explanation									0	When the CN4 connector of the drive unit and the power supply are connected, setting below is necessary. To validate the external emergency stop function, add 40h.									1	2	3	Setting	0x	1x	2x	3x	4x	5x	6x	7x	8x	4	x0	Not used			CV-300						5	x1		CV-110							CR-10	6	x2			CV-220						CR-15	7	x3									CR-22		x4	CV-37								CR-37		x5		CV-150			CV-450	CV-550					x6	CV-55		CV-260						CR-55		x7				CV-370							x8	CV-75								CR-75		x9		CV-185							CR-90	
			bit			Explanation																																																																																																																																															
			0			When the CN4 connector of the drive unit and the power supply are connected, setting below is necessary. To validate the external emergency stop function, add 40h.																																																																																																																																															
			1																																																																																																																																																		
			2																																																																																																																																																		
3	Setting	0x	1x			2x	3x	4x	5x	6x	7x	8x																																																																																																																																									
4	x0	Not used					CV-300																																																																																																																																														
5	x1		CV-110									CR-10																																																																																																																																									
6	x2					CV-220						CR-15																																																																																																																																									
7	x3											CR-22																																																																																																																																									
	x4	CV-37								CR-37																																																																																																																																											
	x5		CV-150			CV-450	CV-550																																																																																																																																														
	x6	CV-55		CV-260						CR-55																																																																																																																																											
	x7				CV-370																																																																																																																																																
	x8	CV-75								CR-75																																																																																																																																											
	x9		CV-185							CR-90																																																																																																																																											
8	rtyp	Set the regenerative resistor type when MDS-A-CR is used.	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: center;">Setting</th> <th style="text-align: center;">Regenerative resistor model name</th> <th style="text-align: center;">Resistance value</th> <th style="text-align: center;">Capacity</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">0</td> <td colspan="3">MDS-C1-CV (Setting when using power supply regeneration)</td> </tr> <tr> <td style="text-align: center;">1</td> <td>GZG200W260HMJ</td> <td style="text-align: center;">26Ω</td> <td style="text-align: center;">80W</td> </tr> <tr> <td style="text-align: center;">2</td> <td>GZG300W130HMJ×2</td> <td style="text-align: center;">26Ω</td> <td style="text-align: center;">150W</td> </tr> <tr> <td style="text-align: center;">3</td> <td>MR-RB30</td> <td style="text-align: center;">13Ω</td> <td style="text-align: center;">300W</td> </tr> <tr> <td style="text-align: center;">4</td> <td>MR-RB50</td> <td style="text-align: center;">13Ω</td> <td style="text-align: center;">500W</td> </tr> <tr> <td style="text-align: center;">5</td> <td>GZG200W200HMJ×3</td> <td style="text-align: center;">6.7Ω</td> <td style="text-align: center;">350W</td> </tr> <tr> <td style="text-align: center;">6</td> <td>GZG300W200HMJ×3</td> <td style="text-align: center;">6.7Ω</td> <td style="text-align: center;">500W</td> </tr> <tr> <td style="text-align: center;">7</td> <td>R-UNIT-1</td> <td style="text-align: center;">30Ω</td> <td style="text-align: center;">700W</td> </tr> <tr> <td style="text-align: center;">8</td> <td>R-UNIT-2</td> <td style="text-align: center;">15Ω</td> <td style="text-align: center;">700W</td> </tr> <tr> <td style="text-align: center;">9</td> <td>R-UNIT-3</td> <td style="text-align: center;">15Ω</td> <td style="text-align: center;">2100W</td> </tr> <tr> <td style="text-align: center;">A to F</td> <td colspan="3">No setting</td> </tr> </tbody> </table>	Setting	Regenerative resistor model name	Resistance value	Capacity	0	MDS-C1-CV (Setting when using power supply regeneration)			1	GZG200W260HMJ	26Ω	80W	2	GZG300W130HMJ×2	26Ω	150W	3	MR-RB30	13Ω	300W	4	MR-RB50	13Ω	500W	5	GZG200W200HMJ×3	6.7Ω	350W	6	GZG300W200HMJ×3	6.7Ω	500W	7	R-UNIT-1	30Ω	700W	8	R-UNIT-2	15Ω	700W	9	R-UNIT-3	15Ω	2100W	A to F	No setting																																																																																																				
Setting				Regenerative resistor model name	Resistance value	Capacity																																																																																																																																															
0				MDS-C1-CV (Setting when using power supply regeneration)																																																																																																																																																	
1				GZG200W260HMJ	26Ω	80W																																																																																																																																															
2				GZG300W130HMJ×2	26Ω	150W																																																																																																																																															
3				MR-RB30	13Ω	300W																																																																																																																																															
4				MR-RB50	13Ω	500W																																																																																																																																															
5				GZG200W200HMJ×3	6.7Ω	350W																																																																																																																																															
6				GZG300W200HMJ×3	6.7Ω	500W																																																																																																																																															
7				R-UNIT-1	30Ω	700W																																																																																																																																															
8	R-UNIT-2	15Ω	700W																																																																																																																																																		
9	R-UNIT-3	15Ω	2100W																																																																																																																																																		
A to F	No setting																																																																																																																																																				
A																																																																																																																																																					
B																																																																																																																																																					
C																																																																																																																																																					
D																																																																																																																																																					
E																																																																																																																																																					
F																																																																																																																																																					
C		amp																																																																																																																																																			
D																																																																																																																																																					
E																																																																																																																																																					
F																																																																																																																																																					

2237	SV037 JL	Load inertia scale	Set "the motor inertia + motor axis conversion load inertia" in respect to the motor inertia. $SV037 (JL) = \frac{Jl+Jm}{Jm} * 100$ Jm: Motor inertia Jl: Motor axis conversion load inertia	0 to 5000 (%)
------	-------------	--------------------	--	---------------

2238	SV038 FHz1	Notch filter frequency 1	Set the vibration frequency to suppress if machine vibration occurs. (Valid at 36 or more) When not using, set to "0".	0 to 9000 (Hz)
------	---------------	--------------------------	---	----------------

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

No.	Items	Details	Setting range	
2239	SV039 LMCD	Lost motion compensation timing	Set this when the lost motion compensation timing does not match. Adjust by increasing the value by 10 at a time.	0 to 2000 (ms)
2240	The higher order 8bits and lower order 8bits are used for different functions. "Setting value of SV040" = (lcy*256) + LMCT		0 to 32767	
	SV040 LMCT (Low order)	Lost motion compensation non-sensitive band	Set the non-sensitive band of the lost motion compensation in the feed forward control. When "0" is set, the actual value that is set is 2μm. Adjust by increasing by 1μm at a time.	0 to 100 (μm)
	SV040 lcy (High order)	Current bias 2	Normally, set to "40" if you use HC202 to HC902, HC203 to HC703. Use this in combination with SV030 and the high order 8bits of SV045.	0 to 127
2241	SV041 LMC2	Lost motion compensation 2	Set this with SV016 (LMC1) only when you wish to set the lost motion compensation amount to be different depending on the command directions. Set to "0" as a standard.	-1 to 200 (Stall [rated] current %)
2242	SV042 OVS2	Overshooting compensation 2	Set this with SV031 (OVS1) only when you wish to set the overshooting compensation amount to be different depending on the command directions. Set to "0" as a standard.	-1 to 100 (Stall [rated] current %)
2243	SV043 OBS1	Disturbance observer filter frequency	Set the disturbance observer filter band. Set to "100" as a standard. To use the disturbance observer, also set SV037 (JL) and SV044 (OBS2). When not using, set to "0".	0 to 1000 (rad/s)
2244	SV044 OBS2	Disturbance observer gain	Set the disturbance observer gain. The standard setting is "100" to "300". To use the disturbance observer, also set SV037 (JL) and SV043 (OBS1). When not using, set to "0".	0 to 500 (%)
2245	The higher order 8bits and lower order 8bits are used for different functions. "Setting value of SV045" = (lcy*256) + LMCT		0 to 32767	
	SV045 TRUB (Low order)	Frictional torque	When you use the collision detection function, set the frictional torque.	0 to 100 (Stall [rated] current %)
	SV045 lb1 (High order)	Current bias 3	Set to "0" as a standard. Use this in combination with SV030 and the high order 8bits of SV040.	0 to 127
2246	SV046 FH2	Notch filter frequency 2	Set the vibration frequency to suppress if machine vibration occurs. (Valid at 36 or more) When not using, set to "0".	0 to 9000 (Hz)
2247	SV047 EC	Inductive voltage compensation gain	Set the inductive voltage compensation gain. Set to "100" as a standard. If the current FB peak exceeds the current command peak, lower the gain.	0 to 200 (%)
2248	SV048 EMGr	Vertical axis drop prevention time	Input a length of time to prevent the vertical axis from dropping by delaying Ready OFF until the brake works when the emergency stop occurs. Increase the setting by 100ms at a time and set the value where the axis does not drop.	0 to 20000 (ms)

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

No.	Items	Details	Setting range	
2249	SV049 PGN1sp	Position loop gain 1 in spindle synchronous control	Set the position loop gain during the spindle synchronous control (synchronous tapping, synchronous control with spindle/C axis). Set the same value as the value of the spindle parameter, position loop gain in synchronous control. When performing the SHG control, set this with SV050 (PGN2sp) and SV058 (SHGCsp).	1 to 200 (rad/s)
2250	PGN2sp	Position loop gain 2 in spindle synchronous control	Set this with SV049 (PGN1sp) and SV058 (SHGCsp) if you wish to perform the SHG control in the spindle synchronous control (synchronous tapping, synchronous control with spindle/C axis). When not performing the SHG control, set to "0".	0 to 999 (rad/s)
2251	SV051 DFBT	Dual feed back control time constant	Set the control time constant in dual feed back. When "0" is set, the actual value that is set is 1ms. The higher the time constant is, the closer it gets to the semi-closed control, so the limit of the position loop gain is raised.	0 to 9999 (ms)
2252	SV052 DFBN	Dual feedback control non-sensitive band	Set the non-sensitive band in the dual feedback control. Set to "0" as a standard.	0 to 9999 (μ m)
2253	SV053 OD3	Excessive error detection width in special control	Set the excessive error detection width when servo ON in a special control (initial absolute position setting, stopper control, etc.). If "0" is set, excessive error detection won't be performed when servo ON during a special control.	0 to 32767 (mm)

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

No.	Items	Details	Setting range
2254	When SV035 (SSF4)/ bitF (ckab)=0		-1 to 32767 (mm)
	SV054 ORE	Overrun detection width in closed loop control Set the overrun detection width in the full-closed loop control. If the gap between the motor end detector and the linear scale (machine end detector) exceeds the value set by this parameter, it is judged to be overrun and Alarm 43 will be detected. When "-1" is set, the alarm detection won't be performed. When "0" is set, overrun is detected with a 2mm width.	
	When SV035 (SSF4)/ bitF (ckab)=1 (Note) This applies to only MDS-C1-Vx. The higher order 8bits and lower order 8bits are used for different functions. "Setting value of SV054" =(NSE*256)+ORE		0 to 32767
	SV054 ORE (Low order)	Overrun detection-width in closed loop control Set the overrun detection width in the full-closed loop control. If the gap between the motor end detector and the linear scale (machine end detector) exceeds the value set by this parameter, it is judged to be overrun and Alarm 43 will be detected. When "255" is set, the alarm detection won't be performed. When "0" is set, overrun is detected with a 2mm width.	0 to 255 (mm)
SV054 NSE (High order)	Special detection width for No signal 2 When SV035 (SSF4)/ bitF (ckab) =1, this setting is valid. Set the special detection width for No signal 2 (Alarm 21). When "0" is set, overrun is detected with a 15μm width.	0 to 127 (μm)	
2255	SV055 EMGx	Max. gate off delay time after emergency stop Set a length of time from the point when the emergency stop is input to the point when READY OFF is compulsorily executed. Normally, set the same value as the absolute value of SV056. In preventing the vertical axis from dropping, the gate off is delayed for the length of time set by SV048 if SV055's value is smaller than that of SV048.	0 to 20000 (ms)
2256	SV056 EMGt	Deceleration time constant at emergency stop In the vertical axis drop prevention time control, set the time constant used for the deceleration control at emergency stop. Set a length of time that takes from rapid traverse rate (rapid) to stopping. Normally, set the same value as the rapid traverse acceleration/deceleration time constant. When executing the synchronous operation, put the minus sign to the settings of both of the master axis and slave axis.	-20000 to 20000 (ms)
2257	SV057 SHGC	SHG control gain When performing the SHG control, set this with S003 (PGN1) and SV004 (PGN2). When not performing the SHG control, set to "0".	0 to 1200 (rad/s)

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

No.	Items	Details	Setting range	
2258	SV058 SHGCsp	SHG control gain in spindle synchronous control	Set this with SV049 (PGN1sp) and SV050 (PGN2sp) if you wish to perform the SHG control in the spindle synchronous control (synchronous tapping, synchronous control with spindle/C axis). When not performing the SHG control, set to "0".	0 to 1200 (rad/s)
2259	SV059 TCNV	Collision detection torque estimating gain	Set the torque estimating gain when using the collision detection function. After setting as SV035/bitF(ctl)=1 and performing acceleration/deceleration, set the value displayed in MPOS of the NC servo monitor screen. Set to "0" when not using the collision detection function.	-32768 to 32767
2260	SV060 TLMT	Collision detection level	When using the collision detection function, set the collision detection level during the G0 feeding. If "0" is set, none of the collision detection function will work.	0 to 999 (Stall [rated] current %)
2261	SV061 DA1NO	D/A output channel 1 data No.	Input the data number you wish to output to D/A output channel. In the case of MDS-C1-V2, set the axis on the side to which the data will not be output to "-1".	-1 to 127
2262	SV062 DA2NO	D/A output channel 2 data No.		
2263	SV063 DA1MPY	D/A output channel 1 output scale	Set the scale with a 1/256 unit. When "0" is set, output is done with the standard output unit.	-32768 to 32767 (Unit: 1/256)
2264	SV064 DA2MPY	D/A output channel 2 output scale		
2265	SV065 TLC	Tool end compensation spring constant	Set the spring constant of the tool end compensation. In the semi-closed loop control, the tool end compensation amount is calculated with the following equation. $\text{Compensation amount} = \frac{F (\text{mm/min})^2 * \text{SV065}}{R (\text{mm}) * 10^9} (\mu\text{m})$ F: Commanded speed R: Radius When not using, set to "0".	-32768 to 32767

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

(2) Initial setting value

(a) HC**/HC**R series

Motor		HC 52	HC 102	HC 152	HC 202	HC 352	HC 452		HC 702		HC 902
Drive unit capacity		05	10	20	20	35	45s	45	70s	70	90
SV001	PC1	-	-	-	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-	-	-	-
SV003	PGN1	47	47	47	47	47	47	47	47	47	47
SV004	PGN2	0	0	0	0	0	0	0	0	0	0
SV005	VGN1	200	200	200	200	200	200	200	200	200	200
SV006	VGN2	0	0	0	0	0	0	0	0	0	0
SV007	VIL	0	0	0	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	4096	4096	4096	4096	4096	4096	4096	4096	4096	4096
SV010	IDA	4096	4096	4096	4096	4096	4096	4096	4096	4096	4096
SV011	IQG	768	768	768	768	768	768	768	768	768	768
SV012	IDG	768	768	768	768	768	768	768	768	768	768
SV013	ILMT	500	500	500	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	1000	0000	1000	0000	0000
SV018	PIT	-	-	-	-	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150	150	150	150
SV023	OD1	6	6	6	6	6	6	6	6	6	6
SV024	INP	50	50	50	50	50	50	50	50	50	50
SV025	MTYP	xxB0	xxB1	xxB2	xxB3	xxB4	xx95	xxB5	xx96	xxB6	xxB7
SV026	OD2	6	6	6	6	6	6	6	6	6	6
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0	0	0	0
SV029	VCS	0	0	0	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0	0	0	0

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

Motor		HC 52	HC 102	HC 152	HC 202	HC 352	HC 452		HC 702		HC 902
Drive unit capacity		05	10	20	20	35	45s	45	70s	70	90
SV033	SSF2	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV034	SSF3	0003	0003	0003	0003	0003	0003	0003	0003	0003	0003
SV035	SSF4	0000	0000	0040	0040	0040	0040	0040	0040	0040	0000
SV036	PTYP	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV037	JL	0	0	0	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	10240	10240	10240	10240	10240	10240	10240
SV041	LMC2	0	0	0	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0	0	0	0
SV046	FHz2	0	0	0	0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100	100	100	100
SV048	EMGr	0	0	0	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0	0	0	0
SV051	DFBT	0	0	0	0	0	0	0	0	0	0
SV052	DFBN	0	0	0	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0	0	0	0
SV054	ORE	0	0	0	0	0	0	0	0	0	0
SV055	EMGx	0	0	0	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0	0	0	0
SV065	TLC	0	0	0	0	0	0	0	0	0	0

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

Motor		HC 53	HC 103	HC 153	HC 203	HC 353		HC 453		HC 703
Drive unit capacity		05	10	20	35	45s	45	70s	70	90
SV001	PC1	-	-	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-	-	-
SV003	PGN1	47	47	47	47	47	47	47	47	47
SV004	PGN2	0	0	0	0	0	0	0	0	0
SV005	VGN1	200	200	200	200	200	200	200	200	200
SV006	VGN2	0	0	0	0	0	0	0	0	0
SV007	VIL	0	0	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	4096	4096	4096	4096	4096	4096	4096	4096	4096
SV010	IDA	4096	4096	4096	4096	4096	4096	4096	4096	4096
SV011	IQG	768	768	768	768	768	768	768	768	768
SV012	IDG	768	768	768	768	768	768	768	768	768
SV013	ILMT	500	500	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	1000	0000	1000	0000	0000
SV018	PIT	-	-	-	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150	150	150
SV023	OD1	6	6	6	6	6	6	6	6	6
SV024	INP	50	50	50	50	50	50	50	50	50
SV025	MTYP	xxC0	xxC1	xxC2	xxC3	xxA4	xxC4	xxA5	xxC5	xxC6
SV026	OD2	6	6	6	6	6	6	6	6	6
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0	0	0
SV029	VCS	0	0	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0	0	0

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

Motor		HC 53	HC 103	HC 153	HC 203	HC 353		HC 453		HC 703
Drive unit capacity		05	10	20	35	45s	45	70s	70	90
SV033	SSF2	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV034	SSF3	0003	0003	0003	0003	0003	0003	0003	0003	0003
SV035	SSF4	0000	0000	0040	0040	0040	0040	0040	0040	0000
SV036	PTYP	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV037	JL	0	0	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	10240	10240	10240	10240	10240	10240
SV041	LMC2	0	0	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0	0	0
SV046	FHz2	0	0	0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100	100	100
SV048	EMGr	0	0	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0	0	0
SV051	DFBT	0	0	0	0	0	0	0	0	0
SV052	DFBN	0	0	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0	0	0
SV054	ORE	0	0	0	0	0	0	0	0	0
SV055	EMGx	0	0	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0	0	0
SV065	TLC	0	0	0	0	0	0	0	0	0

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

Motor		HC 103R	HC 153R	HC 203R	HC 353R
Drive unit capacity		10	10	20	35
SV001	PC1	-	-	-	-
SV002	PC2	-	-	-	-
SV003	PGN1	33	33	33	33
SV004	PGN2	0	0	0	0
SV005	VGN1	15	15	20	40
SV006	VGN2	0	0	0	0
SV007	VIL	0	0	0	0
SV008	VIA	1364	1364	1364	1364
SV009	IQA	4096	4096	4096	4096
SV010	IDA	4096	4096	4096	4096
SV011	IQG	256	256	256	256
SV012	IDG	512	512	512	512
SV013	ILMT	500	500	500	500
SV014	ILMTsp	500	500	500	500
SV015	FFC	0	0	0	0
SV016	LMC1	0	0	0	0
SV017	SPEC	0000	0000	0000	0000
SV018	PIT	-	-	-	-
SV019	RNG1	-	-	-	-
SV020	RNG2	-	-	-	-
SV021	OLT	60	60	60	60
SV022	OLL	150	150	150	150
SV023	OD1	6	6	6	6
SV024	INP	50	50	50	50
SV025	MTYP	xxE1	xxE2	xxE3	xxE4
SV026	OD2	6	6	6	6
SV027	SSF1	4000	4000	4000	4000
SV028		0	0	0	0
SV029	VCS	0	0	0	0
SV030	IVC	0	0	0	0
SV031	OVS1	0	0	0	0
SV032	TOF	0	0	0	0

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

Motor		HC 103R	HC 153R	HC 203R	HC 353R
Drive unit capacity		10	10	20	35
SV033	SSF2	0200	0200	0200	0200
SV034	SSF3	0000	0000	0000	0000
SV035	SSF4	0000	0000	0000	0000
SV036	PTYP	0000	0000	0000	0000
SV037	JL	0	0	0	0
SV038	FHz1	0	0	0	0
SV039	LMCD	0	0	0	0
SV040	LMCT	0	0	0	0
SV041	LMC2	0	0	0	0
SV042	OVS2	0	0	0	0
SV043	OBS1	0	0	0	0
SV044	OBS2	0	0	0	0
SV045	TRUB	0	0	0	0
SV046	FHz2	0	0	0	0
SV047	EC	100	100	100	100
SV048	EMGrt	0	0	0	0
SV049	PGN1sp	15	15	15	15
SV050	PGN2sp	0	0	0	0
SV051	DFBT	0	0	0	0
SV052	DFBN	0	0	0	0
SV053	OD3	0	0	0	0
SV054	ORE	0	0	0	0
SV055	EMGx	0	0	0	0
SV056	EMGt	0	0	0	0
SV057	SHGC	0	0	0	0
SV058	SHGCsp	0	0	0	0
SV059	TCNV	0	0	0	0
SV060	TLMT	0	0	0	0
SV061	DA1NO	0	0	0	0
SV062	DA2NO	0	0	0	0
SV063	DA1MPY	0	0	0	0
SV064	DA2MPY	0	0	0	0
SV065	TLC	0	0	0	0

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

(b) HA**N series

Motor		HA 40N	HA 80N	HA 100N	HA 200N	HA 300N	HA 700N	HA 900N
Drive unit capacity		05	10	20	35	45	70	90
SV001	PC1	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	25	25
SV004	PGN2	0	0	0	0	0	0	0
SV005	VGN1	150	150	150	150	150	250	250
SV006	VGN2	0	0	0	0	0	0	0
SV007	VIL	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	4096	4096	4096	4096	4096	4096	4096
SV010	IDA	4096	4096	4096	4096	4096	4096	4096
SV011	IQG	768	768	768	768	768	768	768
SV012	IDG	768	768	768	768	768	768	768
SV013	ILMT	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150
SV023	OD1	6	6	6	6	6	6	6
SV024	INP	50	50	50	50	50	50	50
SV025	MTYP	xx00	xx01	xx02	xx03	xx04	xx05	xx06
SV026	OD2	6	6	6	6	6	6	6
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0
SV029	VCS	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

Motor		HA 40N	HA 80N	HA 100N	HA 200N	HA 300N	HA 700N	HA 900N
Drive unit capacity		05	10	20	35	45	70	90
SV033	SSF2	0000	0000	0000	0000	0000	0000	0000
SV034	SSF3	0000	0000	0000	0000	0000	0000	0000
SV035	SSF4	0000	0000	0000	0000	0000	0000	0000
SV036	PTYP	0000	0000	0000	0000	0000	0000	0000
SV037	JL	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	0	0	0	0
SV041	LMC2	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0
SV046	FHz2	0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100
SV048	EMGrt	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0
SV051	DFBT	0	0	0	0	0	0	0
SV052	DFBN	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0
SV054	ORE	0	0	0	0	0	0	0
SV055	EMGx	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0
SV065	TLC	0	0	0	0	0	0	0

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

Motor		HA 43N	HA 83N	HA 93N	HA 103N	HA 203N	HA 303N	HA 703N	HA 053N	HA 13N	HA 23N	HA 33N
Drive unit capacity		05	10	20	35	45	70	90	01	01	03	03
SV001	PC1	-	-	-	-	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	33	25	33	33	33	33
SV004	PGN2	0	0	0	0	0	0	0	0	0	0	0
SV005	VGN1	150	150	150	150	150	150	250	70	70	100	100
SV006		0	0	0	0	0	0	0	0	0	0	0
SV007		0	0	0	0	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	4096	4096	4096	4096	4096	4096	4096	4096	4096	4096	4096
SV010	IDA	4096	4096	4096	4096	4096	4096	4096	4096	4096	4096	4096
SV011	IQG	768	768	768	768	768	768	768	768	768	768	768
SV012	IDG	768	768	768	768	768	768	768	768	768	768	768
SV013	ILMT	500	500	500	500	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150	150	150	150	150
SV023	OD1	6	6	6	6	6	6	6	6	6	6	6
SV024	INP	50	50	50	50	50	50	50	50	50	50	50
SV025	MTYP	xx80	xx81	xx8A	xx82	xx83	xx84	xx85	xx8C	xx8D	xx8E	xx8F
SV026	OD2	6	6	6	6	6	6	6	6	6	6	6
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0	0	0	0	0
SV029		0	0	0	0	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0	0	0	0	0

7. Servo Parameters
7.2 MDS-C1-Vx High-gain (MDS-B-Vx4 Compatible)

Motor		HA 43N	HA 83N	HA 93N	HA 103N	HA 203N	HA 303N	HA 703N	HA 053N	HA 13N	HA 23N	HA 33N
Drive unit capacity		05	10	20	35	45	70	90	01	01	03	03
SV033	SSF2	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV034	SSF3	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV035	SSF4	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV036	PTYP	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV037	JL	0	0	0	0	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	0	0	0	0	0	0	0	0
SV041	LMC2	0	0	0	0	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0	0	0	0	0
SV046	FHz2	0	0	0	0	0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100	100	100	100	100
SV048	EMGrt	0	0	0	0	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0	0	0	0	0
SV051	DFBT	0	0	0	0	0	0	0	0	0	0	0
SV052	DFBN	0	0	0	0	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0	0	0	0	0
SV054	ORE	0	0	0	0	0	0	0	0	0	0	0
SV055	EMGx	0	0	0	0	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0	0	0	0	0
SV065	TLC	0	0	0	0	0	0	0	0	0	0	0

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

(1) Details for servo parameters

For parameters marked with a (PR) in the table, turn the NC power OFF after setting. After the power is turned ON again, the parameter is validated.

⚠ CAUTION
 ⚠ In the explanation on bits, set all bits not used, including blank bits, to "0".

No.	Items	Details	Setting range
2201 (PR)	SV001 PC1	Motor side gear ratio	1 to 32767
2202 (PR)	SV002 PC2	Machine side gear ratio	1 to 32767
2203	SV003 PGN1	Position loop gain 1	1 to 200 (rad/s)
2204	SV004 PGN2	Position loop gain 2	0 to 999 (rad/s)
2205	SV005 VGN1	Speed loop gain 1	1 to 999
2206	SV006 VGN2	Speed loop gain 2	-1000 to 1000

VGN1
 VGN2
 0 VCS VLMT
 (Rated speed*1.2)

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

No.	Items	Details	Setting range	
2207	SV007 VIL	Speed loop delay compensation	Set this when the limit cycle occurs in the full-closed loop, or overshooting occurs in positioning. Select the control method with SV027 (SSF1)/bit1, 0 (vcnt). Normally, use "Changeover type 2". When you set this parameter, make sure to set the torque offset (SV032 (TOF)). When not using, set to "0".	0 to 32767
			No changeover When SV027 (SSF1)/ bit1, 0 (vcnt)=00 The delay compensation control is always valid.	
			Changeover type 1 When SV027 (SSF1)/ bit1, 0 (vcnt)=01 The delay compensation control works when the command from the NC is "0". Overshooting that occurs during pulse feeding can be suppressed.	
			Changeover type 2 When SV027 (SSF1)/ bit1, 0 (vcnt)=10 The delay compensation control works when the command from the NC is "0" and the position droop is "0". Overshooting or the limit cycle that occurs during pulse feeding or positioning can be suppressed.	
2208	SV008 VIA	Speed loop lead compensation	Set the gain of the speed loop integration control. The standard setting is "1364". During the SHG control, the standard setting is "1900". Adjust the value by increasing/decreasing it by about 100 at a time. Raise this value to improve contour tracking precision in high-speed cutting. Lower this value when the position droop vibrates (10 to 20Hz).	1 to 9999
2209	SV009 IQA	Current loop q axis lead compensation	Set the gain of current loop. As this setting is determined by the motor's electrical characteristics, the setting is fixed for each type of motor.	1 to 20480
2210	SV010 IDA	Current loop d axis lead compensation	Set the standard values for all the parameters depending on each motor type.	1 to 20480
2211	SV011 IQG	Current loop q axis gain		1 to 2560
2212	SV012 IDG	Current loop d axis gain		1 to 2560

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

No.	Items	Details	Setting range	
2213	SV013 ILMT	Current limit value	Set the normal current (torque) limit value. (Limit values for both + and - direction.) When the value is "500" (a standard setting), the maximum torque is determined by the specification of the motor.	0 to 999 (Stall [rated] current %)
2214	SV014 ILMTsp	Current limit value in special control	Set the current (torque) limit value in a special control (initial absolute position setting, stopper control, etc). (Limit values for both of the + and - directions.) Set to "500" when not using.	0 to 999 (Stall [rated] current %)
2215	SV015 FFC	Acceleration rate feed forward gain	When a relative error in the synchronous control is large, apply this parameter to the axis that is delaying. The standard setting value is "0". For the SHG control, set to "100". To adjust a relative error in acceleration/deceleration, increase the value by 50 to 100 at a time.	0 to 999 (%)
2216	SV016 LMC1	Lost motion compensation 1	Set this when the protrusion (that occurs due to the non-sensitive band by friction, torsion, backlash, etc) at quadrant change is too large. This compensates the torque at quadrant change. This is valid only when the lost motion compensation (SV027 (SSF1/lmc)) is selected.	
		Type 1: When SV027 (SSF1)/ bit9, 8 (lmc)=01 Set the compensation amount based on the motor torque before the quadrant change. The standard setting is "100". Setting to "0" means the compensation amount is zero. Normally, use Type 2.	-1 to 200 (%)	
		Type 2: When SV027 (SSF1)/ bit9, 8 (lmc)=10 Set the compensation amount based on the stall (rated) current of the motor. The standard setting is double of the friction torque. Setting to "0" means the compensation amount is zero.	-1 to 100 (Stall [rated] current %)	
		When you wish different compensation amount depending on the direction When SV041 (LMC2) is "0", compensate with the value of SV016 (LMC1) in both of the + and -directions. If you wish to change the compensation amount depending on the command direction, set this and SV041 (LMC2). (SV016: + direction, SV041: - direction. However, the directions may be opposite depending on other settings.) When "-1" is set, the compensation won't be performed in the direction of the command.		

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

No.	Items	Details	Setting range																																	
2217 (PR)	SV017 SPEC	Servo specification selection	<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center;">F</td> <td style="text-align: center;">E</td> <td style="text-align: center;">D</td> <td style="text-align: center;">C</td> <td style="text-align: center;">B</td> <td style="text-align: center;">A</td> <td style="text-align: center;">9</td> <td style="text-align: center;">8</td> </tr> <tr> <td style="border: 1px solid black; width: 30px; height: 15px;"></td> <td style="border: 1px solid black; width: 30px; height: 15px;"></td> <td style="border: 1px solid black; width: 30px; height: 15px;"></td> <td style="border: 1px solid black; width: 30px; height: 15px;"></td> <td style="border: 1px solid black; width: 30px; height: 15px;"></td> <td style="border: 1px solid black; width: 30px; height: 15px;"></td> <td style="border: 1px solid black; width: 30px; height: 15px; text-align: center;">mpt3</td> <td style="border: 1px solid black; width: 30px; height: 15px; text-align: center;">mp</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> <td style="text-align: center;">1</td> <td style="text-align: center;">0</td> </tr> <tr> <td style="border: 1px solid black; width: 30px; height: 15px; text-align: center;">abs</td> <td style="border: 1px solid black; width: 30px; height: 15px;"></td> <td style="border: 1px solid black; width: 30px; height: 15px; text-align: center;">vdir</td> <td style="border: 1px solid black; width: 30px; height: 15px; text-align: center;">fdir</td> <td style="border: 1px solid black; width: 30px; height: 15px; text-align: center;">spwv</td> <td style="border: 1px solid black; width: 30px; height: 15px; text-align: center;">seqh</td> <td style="border: 1px solid black; width: 30px; height: 15px; text-align: center;">dfbx</td> <td style="border: 1px solid black; width: 30px; height: 15px; text-align: center;">fdir2</td> </tr> </table>	F	E	D	C	B	A	9	8							mpt3	mp	7	6	5	4	3	2	1	0	abs		vdir	fdir	spwv	seqh	dfbx	fdir2	
			F	E	D	C	B	A	9	8																										
									mpt3	mp																										
			7	6	5	4	3	2	1	0																										
			abs		vdir	fdir	spwv	seqh	dfbx	fdir2																										
			bit	Meaning when "0" is set	Meaning when "1" is set																															
			0	fdir2	Speed feedback forward polarity	Speed feedback reverse polarity																														
			1	dfbx	Dual feedback control stop	Dual feedback control start																														
			2	seqh	READY/Servo ON time normal	READY/Servo ON time high speed																														
			3	spwv	Normal mode	High gain servo synchronous mode																														
			4	fdir	Position feedback forward polarity	Position feedback reverse polarity																														
			5	vdir	Standard setting	HA motor (4 pole motor) Detector installation position 90 degrees (B, D)																														
6																																				
7	abs	Incremental control	Absolute position control																																	
8	mp	MP scale 360P (2mm pitch)	MP scale 720P (1mm pitch)																																	
9	mpt3	MP scale ABS detection type 1, 2	MP scale ABS detection type 3																																	
A																																				
B																																				
C																																				
D																																				
E																																				
F																																				
(Note) Set to "0" for bits with no particular description.																																				
2218 (PR)	SV018 PIT	Ball screw pitch	Set the ball screw pitch. Set to "360" for the rotary axis. 1 to 32767 (mm/rev)																																	

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

No.	Items	Details	Setting range																											
2219 (PR)	SV019 RNG1	Position detector resolution	In the case of the semi-closed loop control Set the same value as SV020 (RNG2). (Refer to the explanation of SV020.)	1 to 9999 (kp/rev)																										
			In the case of the full-closed loop control Set the number of pulses per ball screw pitch.	1 to 9999 (kp/pit)																										
		<table border="1"> <thead> <tr> <th>Detector model name</th> <th>Resolution</th> <th>SV019 setting</th> </tr> </thead> <tbody> <tr> <td>OHE25K-ET, OHA25K-ET</td> <td>100,000(p/rev)</td> <td>100</td> </tr> <tr> <td>OSE104-ET, OSA104-ET</td> <td>100,000(p/rev)</td> <td>100</td> </tr> <tr> <td>OSE105-ET, OSA105-ET</td> <td>1,000,000(p/rev)</td> <td>1000</td> </tr> <tr> <td>Relative position detection scale</td> <td>Refer to specification manual for each detector</td> <td>PIT/Resolution (μm)</td> </tr> <tr> <td>AT41 (Mitsutoyo)</td> <td>1 (μm/p)</td> <td>The same as SV018 (PIT)</td> </tr> <tr> <td>FME type, FLE type (Futaba)</td> <td>Refer to specification manual for each detector</td> <td>PIT/Resolution (μm)</td> </tr> <tr> <td>MP type (Mitsubishi Heavy Industries)</td> <td>Refer to specification manual for each detector</td> <td>PIT/Resolution (μm)</td> </tr> <tr> <td>AT342 (Mitsutoyo)</td> <td>0.5 (μm/p)</td> <td>Twice as big as SV018 (PIT)</td> </tr> </tbody> </table>	Detector model name	Resolution	SV019 setting	OHE25K-ET, OHA25K-ET	100,000(p/rev)	100	OSE104-ET, OSA104-ET	100,000(p/rev)	100	OSE105-ET, OSA105-ET	1,000,000(p/rev)	1000	Relative position detection scale	Refer to specification manual for each detector	PIT/Resolution (μm)	AT41 (Mitsutoyo)	1 (μm/p)	The same as SV018 (PIT)	FME type, FLE type (Futaba)	Refer to specification manual for each detector	PIT/Resolution (μm)	MP type (Mitsubishi Heavy Industries)	Refer to specification manual for each detector	PIT/Resolution (μm)	AT342 (Mitsutoyo)	0.5 (μm/p)	Twice as big as SV018 (PIT)	
Detector model name	Resolution	SV019 setting																												
OHE25K-ET, OHA25K-ET	100,000(p/rev)	100																												
OSE104-ET, OSA104-ET	100,000(p/rev)	100																												
OSE105-ET, OSA105-ET	1,000,000(p/rev)	1000																												
Relative position detection scale	Refer to specification manual for each detector	PIT/Resolution (μm)																												
AT41 (Mitsutoyo)	1 (μm/p)	The same as SV018 (PIT)																												
FME type, FLE type (Futaba)	Refer to specification manual for each detector	PIT/Resolution (μm)																												
MP type (Mitsubishi Heavy Industries)	Refer to specification manual for each detector	PIT/Resolution (μm)																												
AT342 (Mitsutoyo)	0.5 (μm/p)	Twice as big as SV018 (PIT)																												
2220 (PR)	SV020 RNG2	Speed detector resolution	Set the number of pulses per one revolution of the motor end detector.	1 to 9999 (kp/rev)																										
		<table border="1"> <thead> <tr> <th>Detector model name</th> <th>SV020 setting</th> </tr> </thead> <tbody> <tr> <td>Equipped to HA053, HA13 (Only for MDS-B-Vx)</td> <td>10</td> </tr> <tr> <td>OHE25K, OHA25K (Only for MDS-B-Vx)</td> <td>100</td> </tr> <tr> <td>OSE104, OSA104</td> <td>100</td> </tr> <tr> <td>OSE105, OSA105</td> <td>1000</td> </tr> </tbody> </table>	Detector model name	SV020 setting	Equipped to HA053, HA13 (Only for MDS-B-Vx)	10	OHE25K, OHA25K (Only for MDS-B-Vx)	100	OSE104, OSA104	100	OSE105, OSA105	1000																		
Detector model name	SV020 setting																													
Equipped to HA053, HA13 (Only for MDS-B-Vx)	10																													
OHE25K, OHA25K (Only for MDS-B-Vx)	100																													
OSE104, OSA104	100																													
OSE105, OSA105	1000																													
2221	SV021 OLT	Overload detection time constant	Set the detection time constant of Overload 1 (Alarm 50). Set to "60" as a standard. (For machine tool builder adjustment.)	1 to 999 (s)																										
2222	SV022 OLL	Overload detection level	Set the current detection level of Overload 1 (Alarm 50) in respect to the stall (rated) current. Set to "150" as a standard. (For machine tool builder adjustment.)	110 to 500 (Stall [rated] current %)																										
2223	SV023 OD1	Excessive error detection width during servo ON	Set the excessive error detection width when servo ON. <Standard setting value> $OD1=OD2= \frac{\text{Rapid traverse rate (mm/min)}}{60 \cdot PGN1} / 2 \text{ (mm)}$ When "0" is set, the excessive error detection will not be performed.	0 to 32767 (mm)																										

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

No.	Items	Details	Setting range																																																																																																																																																																																																																																																																																																																																																																																					
2224	SV024 INP	In-position detection width	0 to 32767 (μ m)																																																																																																																																																																																																																																																																																																																																																																																					
2225 (PR)	SV025 MTYP	Motor/ Detector type	<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="text-align:center">F</td> <td style="text-align:center">E</td> <td style="text-align:center">D</td> <td style="text-align:center">C</td> <td style="text-align:center">B</td> <td style="text-align:center">A</td> <td style="text-align:center">9</td> <td style="text-align:center">8</td> </tr> <tr> <td colspan="4" style="text-align:center">pen</td> <td colspan="4" style="text-align:center">ent</td> </tr> <tr> <td style="text-align:center">7</td> <td style="text-align:center">6</td> <td style="text-align:center">5</td> <td style="text-align:center">4</td> <td style="text-align:center">3</td> <td style="text-align:center">2</td> <td style="text-align:center">1</td> <td style="text-align:center">0</td> </tr> <tr> <td colspan="8" style="text-align:center">mtyp</td> </tr> </table> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th style="width:5%;">bit</th> <th colspan="8">Explanation</th> </tr> </thead> <tbody> <tr> <td>0</td> <td colspan="8">Set the motor type.</td> </tr> <tr> <td>1</td> <td style="text-align:center">Set- ting</td> <td style="text-align:center">0x</td> <td style="text-align:center">1x</td> <td style="text-align:center">2x</td> <td style="text-align:center">3x</td> <td style="text-align:center">4x</td> <td style="text-align:center">5x</td> <td style="text-align:center">6x</td> <td style="text-align:center">7x</td> </tr> <tr> <td>2</td> <td style="text-align:center">x0</td> <td>HA40N</td> <td></td> <td>HA50L</td> <td>HA53L</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>3</td> <td style="text-align:center">x1</td> <td>HA80N</td> <td></td> <td>HA100L</td> <td>HA103L</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td style="text-align:center">x2</td> <td>HA100N</td> <td></td> <td>HA200L</td> <td>HA203L</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td style="text-align:center">x3</td> <td>HA200N</td> <td></td> <td>HA300L</td> <td>HA303L</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>6</td> <td style="text-align:center">x4</td> <td>HA300N</td> <td></td> <td>HA500L</td> <td>HA503L</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td style="text-align:center">x5</td> <td>HA700N</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td style="text-align:center">x6</td> <td>HA900N</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td style="text-align:center">x7</td> <td></td> <td></td> <td>HA-LH11K2</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td style="text-align:center">x8</td> <td></td> <td></td> <td>HA-LH15K2</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td style="text-align:center">x9</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td style="text-align:center">xA</td> <td></td> <td></td> <td>HA150L</td> <td>HA153L</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td style="text-align:center">xB</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td style="text-align:center">xC</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td style="text-align:center">xD</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td style="text-align:center">xE</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td style="text-align:center">xF</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th style="width:5%;">Set- ting</th> <th style="text-align:center">8x</th> <th style="text-align:center">9x</th> <th style="text-align:center">Ax</th> <th style="text-align:center">Bx</th> <th style="text-align:center">Cx</th> <th style="text-align:center">Dx</th> <th style="text-align:center">Ex</th> <th style="text-align:center">Fx</th> </tr> </thead> <tbody> <tr> <td style="text-align:center">x0</td> <td>HA43N</td> <td></td> <td></td> <td>HC52</td> <td>HC53</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align:center">x1</td> <td>HA83N</td> <td></td> <td></td> <td>HC102</td> <td>HC103</td> <td></td> <td>HC103R</td> <td></td> </tr> <tr> <td style="text-align:center">x2</td> <td>HA103N</td> <td></td> <td></td> <td>HC152</td> <td>HC153</td> <td></td> <td>HC153R</td> <td></td> </tr> <tr> <td style="text-align:center">x3</td> <td>HA203N</td> <td></td> <td></td> <td>HC202</td> <td>HC203</td> <td></td> <td>HC203R</td> <td></td> </tr> <tr> <td style="text-align:center">x4</td> <td>HA303N</td> <td></td> <td></td> <td>HC352</td> <td>HC353</td> <td></td> <td>HC353R</td> <td></td> </tr> <tr> <td style="text-align:center">x5</td> <td>HA703N</td> <td></td> <td></td> <td>HC452</td> <td>HC453</td> <td></td> <td>HC503R</td> <td></td> </tr> <tr> <td style="text-align:center">x6</td> <td></td> <td></td> <td></td> <td>HC702</td> <td>HC703</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align:center">x7</td> <td></td> <td></td> <td></td> <td>HC902</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align:center">x8</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align:center">x9</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align:center">xA</td> <td>HA93N</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align:center">xB</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align:center">xC</td> <td>HA053(N)</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align:center">xD</td> <td>HA13(N)</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align:center">xE</td> <td>HA23N</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align:center">xF</td> <td>HA33N</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table> <p align="right">(To be continued to the next page)</p>	F	E	D	C	B	A	9	8	pen				ent				7	6	5	4	3	2	1	0	mtyp								bit	Explanation								0	Set the motor type.								1	Set- ting	0x	1x	2x	3x	4x	5x	6x	7x	2	x0	HA40N		HA50L	HA53L					3	x1	HA80N		HA100L	HA103L					4	x2	HA100N		HA200L	HA203L					5	x3	HA200N		HA300L	HA303L					6	x4	HA300N		HA500L	HA503L					7	x5	HA700N									x6	HA900N									x7			HA-LH11K2							x8			HA-LH15K2							x9										xA			HA150L	HA153L						xB										xC										xD										xE										xF									Set- ting	8x	9x	Ax	Bx	Cx	Dx	Ex	Fx	x0	HA43N			HC52	HC53				x1	HA83N			HC102	HC103		HC103R		x2	HA103N			HC152	HC153		HC153R		x3	HA203N			HC202	HC203		HC203R		x4	HA303N			HC352	HC353		HC353R		x5	HA703N			HC452	HC453		HC503R		x6				HC702	HC703				x7				HC902					x8									x9									xA	HA93N								xB									xC	HA053(N)								xD	HA13(N)								xE	HA23N								xF	HA33N							
F	E	D	C	B	A	9	8																																																																																																																																																																																																																																																																																																																																																																																	
pen				ent																																																																																																																																																																																																																																																																																																																																																																																				
7	6	5	4	3	2	1	0																																																																																																																																																																																																																																																																																																																																																																																	
mtyp																																																																																																																																																																																																																																																																																																																																																																																								
bit	Explanation																																																																																																																																																																																																																																																																																																																																																																																							
0	Set the motor type.																																																																																																																																																																																																																																																																																																																																																																																							
1	Set- ting	0x	1x	2x	3x	4x	5x	6x	7x																																																																																																																																																																																																																																																																																																																																																																															
2	x0	HA40N		HA50L	HA53L																																																																																																																																																																																																																																																																																																																																																																																			
3	x1	HA80N		HA100L	HA103L																																																																																																																																																																																																																																																																																																																																																																																			
4	x2	HA100N		HA200L	HA203L																																																																																																																																																																																																																																																																																																																																																																																			
5	x3	HA200N		HA300L	HA303L																																																																																																																																																																																																																																																																																																																																																																																			
6	x4	HA300N		HA500L	HA503L																																																																																																																																																																																																																																																																																																																																																																																			
7	x5	HA700N																																																																																																																																																																																																																																																																																																																																																																																						
	x6	HA900N																																																																																																																																																																																																																																																																																																																																																																																						
	x7			HA-LH11K2																																																																																																																																																																																																																																																																																																																																																																																				
	x8			HA-LH15K2																																																																																																																																																																																																																																																																																																																																																																																				
	x9																																																																																																																																																																																																																																																																																																																																																																																							
	xA			HA150L	HA153L																																																																																																																																																																																																																																																																																																																																																																																			
	xB																																																																																																																																																																																																																																																																																																																																																																																							
	xC																																																																																																																																																																																																																																																																																																																																																																																							
	xD																																																																																																																																																																																																																																																																																																																																																																																							
	xE																																																																																																																																																																																																																																																																																																																																																																																							
	xF																																																																																																																																																																																																																																																																																																																																																																																							
Set- ting	8x	9x	Ax	Bx	Cx	Dx	Ex	Fx																																																																																																																																																																																																																																																																																																																																																																																
x0	HA43N			HC52	HC53																																																																																																																																																																																																																																																																																																																																																																																			
x1	HA83N			HC102	HC103		HC103R																																																																																																																																																																																																																																																																																																																																																																																	
x2	HA103N			HC152	HC153		HC153R																																																																																																																																																																																																																																																																																																																																																																																	
x3	HA203N			HC202	HC203		HC203R																																																																																																																																																																																																																																																																																																																																																																																	
x4	HA303N			HC352	HC353		HC353R																																																																																																																																																																																																																																																																																																																																																																																	
x5	HA703N			HC452	HC453		HC503R																																																																																																																																																																																																																																																																																																																																																																																	
x6				HC702	HC703																																																																																																																																																																																																																																																																																																																																																																																			
x7				HC902																																																																																																																																																																																																																																																																																																																																																																																				
x8																																																																																																																																																																																																																																																																																																																																																																																								
x9																																																																																																																																																																																																																																																																																																																																																																																								
xA	HA93N																																																																																																																																																																																																																																																																																																																																																																																							
xB																																																																																																																																																																																																																																																																																																																																																																																								
xC	HA053(N)																																																																																																																																																																																																																																																																																																																																																																																							
xD	HA13(N)																																																																																																																																																																																																																																																																																																																																																																																							
xE	HA23N																																																																																																																																																																																																																																																																																																																																																																																							
xF	HA33N																																																																																																																																																																																																																																																																																																																																																																																							

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

No.	Items	Details	Setting range																																																													
		(Continued from the previous page)																																																														
		<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: center;">bit</th> <th colspan="2" style="text-align: center;">Explanation</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">8</td> <td rowspan="2" style="text-align: center; vertical-align: middle;">ent</td> <td rowspan="2">Set the detector type. Set position detector type for “pen”, and speed detector type for “ent”. In the case of the semi-closed loop control, set the same value for “pen” and “ent”.</td> </tr> <tr> <td style="text-align: center;">9</td> </tr> <tr> <td style="text-align: center;">A</td> <td rowspan="6" style="text-align: center; vertical-align: middle;">pen</td> <td rowspan="6"> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: center;">pen setting</th> <th style="text-align: center;">ent setting</th> <th style="text-align: center;">Detector model name</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">0</td> <td style="text-align: center;">0</td> <td>OHE25K (Only for MDS-B-Vx), OSE104</td> </tr> <tr> <td style="text-align: center;">1</td> <td style="text-align: center;">1</td> <td>OHA25K (Only for MDS-B-Vx), OSA104</td> </tr> <tr> <td style="text-align: center;">2</td> <td style="text-align: center;">2</td> <td>OSE105, OSA105</td> </tr> <tr> <td style="text-align: center;">3</td> <td style="text-align: center;">3</td> <td>Equipped to HA053, HA13 (Only for MDS-B-Vx)</td> </tr> <tr> <td style="text-align: center;">4</td> <td style="text-align: center;">Setting impossible</td> <td>OHE25K-ET, OSE104-ET</td> </tr> <tr> <td style="text-align: center;">5</td> <td style="text-align: center;">Setting impossible</td> <td>OHA25K-ET, OSA104-ET</td> </tr> <tr> <td style="text-align: center;">6</td> <td style="text-align: center;">Setting impossible</td> <td>OSE105-ET, OSA105-ET</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">Setting impossible</td> <td></td> </tr> <tr> <td style="text-align: center;">8</td> <td style="text-align: center;">Setting impossible</td> <td>Relative position detection scale, MP type (Mitsubishi Heavy Industries)</td> </tr> <tr> <td style="text-align: center;">9</td> <td style="text-align: center;">Setting impossible</td> <td>AT41 (Mitsutoyo), FME type, FLE type (Futaba)</td> </tr> <tr> <td style="text-align: center;">A</td> <td style="text-align: center;">Setting impossible</td> <td>AT342 (Mitsutoyo)</td> </tr> <tr> <td style="text-align: center;">B</td> <td style="text-align: center;">Setting impossible</td> <td></td> </tr> <tr> <td style="text-align: center;">C</td> <td style="text-align: center;">C (Current synchronization)</td> <td>The setting of the slave axis in the speed/current synchronization control. When the master axis is the semi-closed control.</td> </tr> <tr> <td style="text-align: center;">D</td> <td style="text-align: center;">Setting impossible</td> <td></td> </tr> <tr> <td style="text-align: center;">E</td> <td style="text-align: center;">Setting impossible</td> <td></td> </tr> <tr> <td style="text-align: center;">F</td> <td style="text-align: center;">Setting impossible</td> <td></td> </tr> </tbody> </table> </td> </tr> </tbody> </table>	bit	Explanation		8	ent	Set the detector type. Set position detector type for “pen”, and speed detector type for “ent”. In the case of the semi-closed loop control, set the same value for “pen” and “ent”.	9	A	pen	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: center;">pen setting</th> <th style="text-align: center;">ent setting</th> <th style="text-align: center;">Detector model name</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">0</td> <td style="text-align: center;">0</td> <td>OHE25K (Only for MDS-B-Vx), OSE104</td> </tr> <tr> <td style="text-align: center;">1</td> <td style="text-align: center;">1</td> <td>OHA25K (Only for MDS-B-Vx), OSA104</td> </tr> <tr> <td style="text-align: center;">2</td> <td style="text-align: center;">2</td> <td>OSE105, OSA105</td> </tr> <tr> <td style="text-align: center;">3</td> <td style="text-align: center;">3</td> <td>Equipped to HA053, HA13 (Only for MDS-B-Vx)</td> </tr> <tr> <td style="text-align: center;">4</td> <td style="text-align: center;">Setting impossible</td> <td>OHE25K-ET, OSE104-ET</td> </tr> <tr> <td style="text-align: center;">5</td> <td style="text-align: center;">Setting impossible</td> <td>OHA25K-ET, OSA104-ET</td> </tr> <tr> <td style="text-align: center;">6</td> <td style="text-align: center;">Setting impossible</td> <td>OSE105-ET, OSA105-ET</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">Setting impossible</td> <td></td> </tr> <tr> <td style="text-align: center;">8</td> <td style="text-align: center;">Setting impossible</td> <td>Relative position detection scale, MP type (Mitsubishi Heavy Industries)</td> </tr> <tr> <td style="text-align: center;">9</td> <td style="text-align: center;">Setting impossible</td> <td>AT41 (Mitsutoyo), FME type, FLE type (Futaba)</td> </tr> <tr> <td style="text-align: center;">A</td> <td style="text-align: center;">Setting impossible</td> <td>AT342 (Mitsutoyo)</td> </tr> <tr> <td style="text-align: center;">B</td> <td style="text-align: center;">Setting impossible</td> <td></td> </tr> <tr> <td style="text-align: center;">C</td> <td style="text-align: center;">C (Current synchronization)</td> <td>The setting of the slave axis in the speed/current synchronization control. When the master axis is the semi-closed control.</td> </tr> <tr> <td style="text-align: center;">D</td> <td style="text-align: center;">Setting impossible</td> <td></td> </tr> <tr> <td style="text-align: center;">E</td> <td style="text-align: center;">Setting impossible</td> <td></td> </tr> <tr> <td style="text-align: center;">F</td> <td style="text-align: center;">Setting impossible</td> <td></td> </tr> </tbody> </table>	pen setting	ent setting	Detector model name	0	0	OHE25K (Only for MDS-B-Vx), OSE104	1	1	OHA25K (Only for MDS-B-Vx), OSA104	2	2	OSE105, OSA105	3	3	Equipped to HA053, HA13 (Only for MDS-B-Vx)	4	Setting impossible	OHE25K-ET, OSE104-ET	5	Setting impossible	OHA25K-ET, OSA104-ET	6	Setting impossible	OSE105-ET, OSA105-ET	7	Setting impossible		8	Setting impossible	Relative position detection scale, MP type (Mitsubishi Heavy Industries)	9	Setting impossible	AT41 (Mitsutoyo), FME type, FLE type (Futaba)	A	Setting impossible	AT342 (Mitsutoyo)	B	Setting impossible		C	C (Current synchronization)	The setting of the slave axis in the speed/current synchronization control. When the master axis is the semi-closed control.	D	Setting impossible		E	Setting impossible		F	Setting impossible		
bit	Explanation																																																															
8	ent	Set the detector type. Set position detector type for “pen”, and speed detector type for “ent”. In the case of the semi-closed loop control, set the same value for “pen” and “ent”.																																																														
9																																																																
A	pen	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: center;">pen setting</th> <th style="text-align: center;">ent setting</th> <th style="text-align: center;">Detector model name</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">0</td> <td style="text-align: center;">0</td> <td>OHE25K (Only for MDS-B-Vx), OSE104</td> </tr> <tr> <td style="text-align: center;">1</td> <td style="text-align: center;">1</td> <td>OHA25K (Only for MDS-B-Vx), OSA104</td> </tr> <tr> <td style="text-align: center;">2</td> <td style="text-align: center;">2</td> <td>OSE105, OSA105</td> </tr> <tr> <td style="text-align: center;">3</td> <td style="text-align: center;">3</td> <td>Equipped to HA053, HA13 (Only for MDS-B-Vx)</td> </tr> <tr> <td style="text-align: center;">4</td> <td style="text-align: center;">Setting impossible</td> <td>OHE25K-ET, OSE104-ET</td> </tr> <tr> <td style="text-align: center;">5</td> <td style="text-align: center;">Setting impossible</td> <td>OHA25K-ET, OSA104-ET</td> </tr> <tr> <td style="text-align: center;">6</td> <td style="text-align: center;">Setting impossible</td> <td>OSE105-ET, OSA105-ET</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">Setting impossible</td> <td></td> </tr> <tr> <td style="text-align: center;">8</td> <td style="text-align: center;">Setting impossible</td> <td>Relative position detection scale, MP type (Mitsubishi Heavy Industries)</td> </tr> <tr> <td style="text-align: center;">9</td> <td style="text-align: center;">Setting impossible</td> <td>AT41 (Mitsutoyo), FME type, FLE type (Futaba)</td> </tr> <tr> <td style="text-align: center;">A</td> <td style="text-align: center;">Setting impossible</td> <td>AT342 (Mitsutoyo)</td> </tr> <tr> <td style="text-align: center;">B</td> <td style="text-align: center;">Setting impossible</td> <td></td> </tr> <tr> <td style="text-align: center;">C</td> <td style="text-align: center;">C (Current synchronization)</td> <td>The setting of the slave axis in the speed/current synchronization control. When the master axis is the semi-closed control.</td> </tr> <tr> <td style="text-align: center;">D</td> <td style="text-align: center;">Setting impossible</td> <td></td> </tr> <tr> <td style="text-align: center;">E</td> <td style="text-align: center;">Setting impossible</td> <td></td> </tr> <tr> <td style="text-align: center;">F</td> <td style="text-align: center;">Setting impossible</td> <td></td> </tr> </tbody> </table>	pen setting	ent setting	Detector model name	0	0	OHE25K (Only for MDS-B-Vx), OSE104	1	1			OHA25K (Only for MDS-B-Vx), OSA104	2	2	OSE105, OSA105	3	3	Equipped to HA053, HA13 (Only for MDS-B-Vx)	4	Setting impossible	OHE25K-ET, OSE104-ET	5	Setting impossible	OHA25K-ET, OSA104-ET	6	Setting impossible	OSE105-ET, OSA105-ET	7	Setting impossible		8	Setting impossible	Relative position detection scale, MP type (Mitsubishi Heavy Industries)	9	Setting impossible	AT41 (Mitsutoyo), FME type, FLE type (Futaba)	A	Setting impossible	AT342 (Mitsutoyo)	B	Setting impossible		C	C (Current synchronization)	The setting of the slave axis in the speed/current synchronization control. When the master axis is the semi-closed control.	D	Setting impossible		E	Setting impossible		F	Setting impossible										
pen setting			ent setting	Detector model name																																																												
0			0	OHE25K (Only for MDS-B-Vx), OSE104																																																												
1			1	OHA25K (Only for MDS-B-Vx), OSA104																																																												
2			2	OSE105, OSA105																																																												
3			3	Equipped to HA053, HA13 (Only for MDS-B-Vx)																																																												
4	Setting impossible	OHE25K-ET, OSE104-ET																																																														
5	Setting impossible	OHA25K-ET, OSA104-ET																																																														
6	Setting impossible	OSE105-ET, OSA105-ET																																																														
7	Setting impossible																																																															
8	Setting impossible	Relative position detection scale, MP type (Mitsubishi Heavy Industries)																																																														
9	Setting impossible	AT41 (Mitsutoyo), FME type, FLE type (Futaba)																																																														
A	Setting impossible	AT342 (Mitsutoyo)																																																														
B	Setting impossible																																																															
C	C (Current synchronization)	The setting of the slave axis in the speed/current synchronization control. When the master axis is the semi-closed control.																																																														
D	Setting impossible																																																															
E	Setting impossible																																																															
F	Setting impossible																																																															
2226	SV026 OD2	Excessive error detection width during servo OFF	Set the excessive error detection width when servo ON. For the standard setting, refer to the explanation of SV023 (OD1). When “0” is set, the excessive error detection will not be performed.	0 to 32767 (mm)																																																												

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

No.	Items	Details	Setting range																																																																										
2227	SV027 SSF1	Servo function selection 1	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center;">F</td> <td style="text-align: center;">E</td> <td style="text-align: center;">D</td> <td style="text-align: center;">C</td> <td style="text-align: center;">B</td> <td style="text-align: center;">A</td> <td style="text-align: center;">9</td> <td style="text-align: center;">8</td> </tr> <tr> <td style="text-align: center;">aflt</td> <td style="text-align: center;">zrn2</td> <td colspan="2" style="text-align: center;">afse</td> <td colspan="2" style="text-align: center;">ovs</td> <td colspan="2" style="text-align: center;">lmc</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> <td style="text-align: center;">1</td> <td style="text-align: center;">0</td> </tr> <tr> <td></td> <td style="text-align: center;">zrn3</td> <td colspan="2" style="text-align: center;">vfct</td> <td></td> <td style="text-align: center;">upc</td> <td colspan="2" style="text-align: center;">vcnt</td> </tr> </table> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: center;">bit</th> <th style="text-align: center;">Meaning when "0" is set</th> <th style="text-align: center;">Meaning when "1" is set</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">0</td> <td rowspan="2" style="vertical-align: top;">vcnt</td> <td rowspan="2">Set the execution changeover type of the speed loop delay compensation. 00: Delay compensation changeover invalid 01: Delay compensation changeover type 1 10: Delay compensation type 2 11: Setting prohibited</td> </tr> <tr> <td style="text-align: center;">1</td> </tr> <tr> <td style="text-align: center;">2</td> <td rowspan="2" style="vertical-align: top;">upc</td> <td>Start torque compensation invalid</td> </tr> <tr> <td style="text-align: center;">3</td> <td>Start torque compensation valid</td> </tr> <tr> <td style="text-align: center;">4</td> <td rowspan="2" style="vertical-align: top;">vfct</td> <td rowspan="2">Set the number of compensation pulses of the jitter compensation. 00: Jitter compensation invalid 01: Jitter compensation 1 pulse 10: Jitter compensation 2 pulses 11: Jitter compensation 3 pulses</td> </tr> <tr> <td style="text-align: center;">5</td> </tr> <tr> <td style="text-align: center;">6</td> <td rowspan="2" style="vertical-align: top;">zrn3</td> <td rowspan="2">ABS scale: Set to "1" in using AT342, AT343, LC191M/491M.</td> </tr> <tr> <td style="text-align: center;">7</td> </tr> <tr> <td style="text-align: center;">8</td> <td rowspan="2" style="vertical-align: top;">lmc</td> <td rowspan="2">Set the compensation amount with SV016 (LMC1) and SV041 (LMC2). 00: Lost motion compensation stop 01: Lost motion compensation type 1 10: Lost motion compensation type 2 11: Setting prohibited</td> </tr> <tr> <td style="text-align: center;">9</td> </tr> <tr> <td style="text-align: center;">A</td> <td rowspan="2" style="vertical-align: top;">ovs</td> <td rowspan="2">Set the compensation amount with SV031 (OVS1) and SV042 (OVS2). 00: Overshooting compensation stop 01: Overshooting compensation type 1 10: Overshooting compensation type 2 11: Overshooting compensation type 3</td> </tr> <tr> <td style="text-align: center;">B</td> </tr> <tr> <td style="text-align: center;">C</td> <td rowspan="2" style="vertical-align: top;">afse</td> <td>00: Adoptive filter sensitivity standard</td> </tr> <tr> <td style="text-align: center;">D</td> <td>11: Adoptive filter sensitivity increase (Set 2bits at a time)</td> </tr> <tr> <td style="text-align: center;">E</td> <td style="text-align: center;">zrn2</td> <td>Set to "1".</td> </tr> <tr> <td style="text-align: center;">F</td> <td style="text-align: center;">aflt</td> <td>Adoptive filter stops</td> </tr> <tr> <td></td> <td></td> <td>Adoptive filter starts</td> </tr> </tbody> </table> <p>(Note) Set to "0" for bits with no particular description.</p>	F	E	D	C	B	A	9	8	aflt	zrn2	afse		ovs		lmc		7	6	5	4	3	2	1	0		zrn3	vfct			upc	vcnt		bit	Meaning when "0" is set	Meaning when "1" is set	0	vcnt	Set the execution changeover type of the speed loop delay compensation. 00: Delay compensation changeover invalid 01: Delay compensation changeover type 1 10: Delay compensation type 2 11: Setting prohibited	1	2	upc	Start torque compensation invalid	3	Start torque compensation valid	4	vfct	Set the number of compensation pulses of the jitter compensation. 00: Jitter compensation invalid 01: Jitter compensation 1 pulse 10: Jitter compensation 2 pulses 11: Jitter compensation 3 pulses	5	6	zrn3	ABS scale: Set to "1" in using AT342, AT343, LC191M/491M.	7	8	lmc	Set the compensation amount with SV016 (LMC1) and SV041 (LMC2). 00: Lost motion compensation stop 01: Lost motion compensation type 1 10: Lost motion compensation type 2 11: Setting prohibited	9	A	ovs	Set the compensation amount with SV031 (OVS1) and SV042 (OVS2). 00: Overshooting compensation stop 01: Overshooting compensation type 1 10: Overshooting compensation type 2 11: Overshooting compensation type 3	B	C	afse	00: Adoptive filter sensitivity standard	D	11: Adoptive filter sensitivity increase (Set 2bits at a time)	E	zrn2	Set to "1".	F	aflt	Adoptive filter stops			Adoptive filter starts
F	E	D	C	B	A	9	8																																																																						
aflt	zrn2	afse		ovs		lmc																																																																							
7	6	5	4	3	2	1	0																																																																						
	zrn3	vfct			upc	vcnt																																																																							
bit	Meaning when "0" is set	Meaning when "1" is set																																																																											
0	vcnt	Set the execution changeover type of the speed loop delay compensation. 00: Delay compensation changeover invalid 01: Delay compensation changeover type 1 10: Delay compensation type 2 11: Setting prohibited																																																																											
1																																																																													
2	upc	Start torque compensation invalid																																																																											
3		Start torque compensation valid																																																																											
4	vfct	Set the number of compensation pulses of the jitter compensation. 00: Jitter compensation invalid 01: Jitter compensation 1 pulse 10: Jitter compensation 2 pulses 11: Jitter compensation 3 pulses																																																																											
5																																																																													
6	zrn3	ABS scale: Set to "1" in using AT342, AT343, LC191M/491M.																																																																											
7																																																																													
8	lmc	Set the compensation amount with SV016 (LMC1) and SV041 (LMC2). 00: Lost motion compensation stop 01: Lost motion compensation type 1 10: Lost motion compensation type 2 11: Setting prohibited																																																																											
9																																																																													
A	ovs	Set the compensation amount with SV031 (OVS1) and SV042 (OVS2). 00: Overshooting compensation stop 01: Overshooting compensation type 1 10: Overshooting compensation type 2 11: Overshooting compensation type 3																																																																											
B																																																																													
C	afse	00: Adoptive filter sensitivity standard																																																																											
D		11: Adoptive filter sensitivity increase (Set 2bits at a time)																																																																											
E	zrn2	Set to "1".																																																																											
F	aflt	Adoptive filter stops																																																																											
		Adoptive filter starts																																																																											
2228	SV028	Not used. Set to "0".	0																																																																										
2229	SV029 VCS	Speed at the change of speed loop gain If the noise is bothersome at high speed during rapid traverse, etc, lower the speed loop gain. Set the speed at which the speed loop gain changes, and use this with SV006 (VGN2). (Refer to SV006.) When not using, set to "0".	0 to 9999 (r/min)																																																																										

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

No.	Items	Details	Setting range
2230	The higher order 8bits and lower order 8bits are used for different functions. "The setting value of SV030" = (lcx*256) + IVC		0 to 32767
	SV030 IVC (Low order)	Voltage dead time compensation When 100% is set, the voltage equivalent to the logical non-energized time will be compensated. When "0" is set, a 100% compensation will be performed. Adjust in increments of 10% from the default value 100%. If increased too much, vibration or vibration noise may be generated.	0 to 255 (%)
	SV030 lcx (High order)	Current bias 1 Set to "0" as a standard. Use this in combination with SV040 and the high order 8bits of SV045.	0 to 127
2231	SV031 OVS1 1	<p>Overshooting compensation 1</p> <p>Set this if overshooting occurs during positioning. This compensates the motor torque during positioning. This is valid only when the overshooting compensation SV027 (SSF1/ovs) is selected.</p> <p>Type 1: When SV027 (SSF1)/ bitB, A (ovs)=01 Set the compensation amount based on the motor's stall current. This compensates overshooting that occurs during pulse feeding. Normally, use Type 2.</p> <p>Type 2: When SV027 (SSF1)/ bitB, A (ovs)=10 Set the compensation amount based on the motor's stall current. Increase by 1% and determine the amount that overshooting doesn't occur. In Type 2, compensation during the feed forward control during circular cutting won't be performed.</p> <p>Type 3: When SV027 (SSF1)/ bitB, A (ovs)=11 Use this to perform the overshooting compensation during circular cutting or the feed forward control. The setting method is the same in Type 2.</p> <p>When you wish different compensation amount depending on the direction When SV042 (OVS2) is "0", compensate with the value of SV031 (OVS1) in both of the + and -directions. If you wish to change the compensation amount depending on the command direction, set this and SV042 (OVS2). (SV031: + direction, SV042: - direction. However, the directions may be opposite depending on other settings.) When "-1" is set, the compensation won't be performed in the direction of the command.</p>	-1 to 100 (Stall [rated] current%)

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

No.	Items	Details	Setting range																																																																																																																	
2232	SV032 TOF	Torque offset	Set the unbalance torque of vertical axis and inclined axis.	-100 to 100 (Stall [rated] current %)																																																																																																																
2233	SV033 SSF2	Servo function selection 2	<table border="1" style="width:100%; text-align:center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td colspan="4">dos</td> <td></td><td></td><td>hvx</td><td>svx</td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td colspan="4">fhz2</td> <td colspan="3">nfd</td><td>zck</td> </tr> </table> <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>bit</th> <th>Meaning when "0" is set</th> <th>Meaning when "1" is set</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>zck</td> <td>Z phase check valid (Alarm 42)</td> <td>Z phase check invalid</td> </tr> <tr> <td>1</td> <td rowspan="3">nfd1</td> <td colspan="2">Set the filter depth for Notch filter 1 (SV038).</td> </tr> <tr> <td>2</td> <td>Value</td> <td>000 001 010 011 100 101 110 111</td> </tr> <tr> <td>3</td> <td>Depth (dB)</td> <td>Infntly deep -18.1 -12.0 -8.5 -6.0 -4.1 -2.5 -1.2</td> </tr> <tr> <td colspan="2"></td> <td>Deep←</td> <td>→ Shallow</td> </tr> <tr> <td>4</td> <td rowspan="4">fhz2</td> <td colspan="2">Set the operation frequency of Notch filter 2.</td> </tr> <tr> <td>5</td> <td>0: Invalid</td> <td>3: 750Hz</td> <td>6: 375Hz</td> </tr> <tr> <td>6</td> <td>1: 2250Hz</td> <td>4: 563Hz</td> <td>7: 321Hz</td> </tr> <tr> <td>7</td> <td>2: 1125Hz</td> <td>5: 450Hz</td> <td>8 to F: 281Hz</td> </tr> <tr> <td>8</td> <td>svx</td> <td colspan="2" rowspan="2">Set the performance mode of the servo control. (Only for MDS-C1-Vx)</td> </tr> <tr> <td>9</td> <td>hvx</td> </tr> <tr> <td colspan="2"></td> <td colspan="2">00: By current loop gain</td> </tr> <tr> <td colspan="2"></td> <td colspan="2">01: MDS-B-Vx compatible mode selected</td> </tr> <tr> <td colspan="2"></td> <td colspan="2">10: High gain mode selected</td> </tr> <tr> <td colspan="2"></td> <td colspan="2">11: High gain mode selected</td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td rowspan="4">dos</td> <td colspan="2">Digital signal output selection</td> </tr> <tr> <td>D</td> <td colspan="2">0 : MP scale absolute position detection, offset demand signal output</td> </tr> <tr> <td>E</td> <td colspan="2">1 : Specified speed signal output</td> </tr> <tr> <td>F</td> <td colspan="2">2 to F : Setting prohibited</td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8	dos						hvx	svx	7	6	5	4	3	2	1	0	fhz2				nfd			zck	bit	Meaning when "0" is set	Meaning when "1" is set	0	zck	Z phase check valid (Alarm 42)	Z phase check invalid	1	nfd1	Set the filter depth for Notch filter 1 (SV038).		2	Value	000 001 010 011 100 101 110 111	3	Depth (dB)	Infntly deep -18.1 -12.0 -8.5 -6.0 -4.1 -2.5 -1.2			Deep←	→ Shallow	4	fhz2	Set the operation frequency of Notch filter 2.		5	0: Invalid	3: 750Hz	6: 375Hz	6	1: 2250Hz	4: 563Hz	7: 321Hz	7	2: 1125Hz	5: 450Hz	8 to F: 281Hz	8	svx	Set the performance mode of the servo control. (Only for MDS-C1-Vx)		9	hvx			00: By current loop gain				01: MDS-B-Vx compatible mode selected				10: High gain mode selected				11: High gain mode selected		A				B				C	dos	Digital signal output selection		D	0 : MP scale absolute position detection, offset demand signal output		E	1 : Specified speed signal output		F	2 to F : Setting prohibited		
F	E	D	C	B	A	9	8																																																																																																													
dos						hvx	svx																																																																																																													
7	6	5	4	3	2	1	0																																																																																																													
fhz2				nfd			zck																																																																																																													
bit	Meaning when "0" is set	Meaning when "1" is set																																																																																																																		
0	zck	Z phase check valid (Alarm 42)	Z phase check invalid																																																																																																																	
1	nfd1	Set the filter depth for Notch filter 1 (SV038).																																																																																																																		
2		Value	000 001 010 011 100 101 110 111																																																																																																																	
3		Depth (dB)	Infntly deep -18.1 -12.0 -8.5 -6.0 -4.1 -2.5 -1.2																																																																																																																	
		Deep←	→ Shallow																																																																																																																	
4	fhz2	Set the operation frequency of Notch filter 2.																																																																																																																		
5		0: Invalid	3: 750Hz	6: 375Hz																																																																																																																
6		1: 2250Hz	4: 563Hz	7: 321Hz																																																																																																																
7		2: 1125Hz	5: 450Hz	8 to F: 281Hz																																																																																																																
8	svx	Set the performance mode of the servo control. (Only for MDS-C1-Vx)																																																																																																																		
9	hvx																																																																																																																			
		00: By current loop gain																																																																																																																		
		01: MDS-B-Vx compatible mode selected																																																																																																																		
		10: High gain mode selected																																																																																																																		
		11: High gain mode selected																																																																																																																		
A																																																																																																																				
B																																																																																																																				
C	dos	Digital signal output selection																																																																																																																		
D		0 : MP scale absolute position detection, offset demand signal output																																																																																																																		
E		1 : Specified speed signal output																																																																																																																		
F		2 to F : Setting prohibited																																																																																																																		

(Note) Set to "0" for bits with no particular description.

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

No.	Items	Details	Setting range																																
2234	SV034 SSF3	Servo function selection 3	<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center;">F</td> <td style="text-align: center;">E</td> <td style="text-align: center;">D</td> <td style="text-align: center;">C</td> <td style="text-align: center;">B</td> <td style="text-align: center;">A</td> <td style="text-align: center;">9</td> <td style="text-align: center;">8</td> </tr> <tr> <td colspan="8" style="text-align: center; border: 1px solid black;">ovsn</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> <td style="text-align: center;">1</td> <td style="text-align: center;">0</td> </tr> <tr> <td style="border: 1px solid black;"></td> <td style="border: 1px solid black;">os2</td> <td style="border: 1px solid black;">zeg</td> <td style="border: 1px solid black;"></td> <td style="border: 1px solid black;"></td> <td style="border: 1px solid black;"></td> <td style="border: 1px solid black;">has2</td> <td style="border: 1px solid black;">has1</td> </tr> </table>	F	E	D	C	B	A	9	8	ovsn								7	6	5	4	3	2	1	0		os2	zeg				has2	has1
			F	E	D	C	B	A	9	8																									
			ovsn																																
			7	6	5	4	3	2	1	0																									
				os2	zeg				has2	has1																									
			0	has1	Setting for normal use (Except for HC)	HAS control 1 valid (HC: High acceleration rate support)																													
			1	has2	Setting for normal use (Except for HC)	HAS control 2 valid (HC: Overshooting support)																													
			2																																
			3																																
			4																																
5	zeg	Z phase normal edge detection (Setting for normal use)	Z phase reverse edge detection (Valid only when SV027/bit6=1)																																
6	os2	Setting for normal use	Overspeed detection level changeover																																
7																																			
8																																			
9																																			
A																																			
B																																			
C		Set the non-sensitive band of the overshooting compensation type 3 in increments of 2μm at a time.																																	
D		In the feed forward control, the non-sensitive band of the model position droop is set, and overshooting of the model is ignored.																																	
E	ovsn	Set the same value as the standard SV040.																																	
F																																			
(Note) Set to "0" for bits with no particular description.																																			

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

No.	Items	Details	Setting range																																
2235	SV035 SSF4	Servo function selection4	<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 12.5%; text-align: center;">F</td> <td style="width: 12.5%; text-align: center;">E</td> <td style="width: 12.5%; text-align: center;">D</td> <td style="width: 12.5%; text-align: center;">C</td> <td style="width: 12.5%; text-align: center;">B</td> <td style="width: 12.5%; text-align: center;">A</td> <td style="width: 12.5%; text-align: center;">9</td> <td style="width: 12.5%; text-align: center;">8</td> </tr> <tr> <td style="border: 1px solid black; text-align: center;">clt</td> <td colspan="3" style="border: 1px solid black; text-align: center;">clG1</td> <td style="border: 1px solid black; text-align: center;">cl2n</td> <td style="border: 1px solid black; text-align: center;">clet</td> <td colspan="2" style="border: 1px solid black; text-align: center;">cltq</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> <td style="text-align: center;">1</td> <td style="text-align: center;">0</td> </tr> <tr> <td colspan="2" style="border: 1px solid black; text-align: center;">iup</td> <td colspan="6" style="border: 1px solid black; text-align: center;">tdt</td> </tr> </table>	F	E	D	C	B	A	9	8	clt	clG1			cl2n	clet	cltq		7	6	5	4	3	2	1	0	iup		tdt					
			F	E	D	C	B	A	9	8																									
			clt	clG1			cl2n	clet	cltq																										
			7	6	5	4	3	2	1	0																									
			iup		tdt																														
			0	tdt	Td creation time setting Set to "0". (For machine tool builder adjustment)																														
			1																																
			2																																
			3																																
			4																																
5																																			
6	iup	Set to "1" in the case of any motors from HC152 to HC702 and from HC153 to HC453.																																	
7																																			
8	cltq	Set the retracting torque for collision detection in respect to the maximum torque of the motor. 00: 100% 01: 90% 10: 80% (Standard) 11: 70%																																	
9																																			
A	clet	Setting for normal use The disturbance torque peak of the latest two seconds is displayed in MPOS of the servo monitor screen.																																	
B																																			
B	cl2n	Collision detection method 2 valid Collision detection method 2 invalid																																	
C																																			
D	clG1	Collision detection method 1 Set the collision detection level during cutting feed (G1). The G1 collision detection level=SV060*clG1. When clG1=0, the collision detection method 1 during cutting feed won't function.																																	
E																																			
F																																			
F	clt	Setting for normal use The guide value of the SV059 setting value is displayed in MPOS of the servo monitor screen.																																	
A																																			

(Note) Set to "0" for bits with no particular description.

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

No.	Items	Details	Setting range																																
2236 (PR)	SV036 PTYP	Power supply type	<table border="1"> <tr> <td align="center">F</td> <td align="center">E</td> <td align="center">D</td> <td align="center">C</td> <td align="center">B</td> <td align="center">A</td> <td align="center">9</td> <td align="center">8</td> </tr> <tr> <td align="center" colspan="4">amp</td> <td align="center" colspan="4">rtyp</td> </tr> <tr> <td align="center">7</td> <td align="center">6</td> <td align="center">5</td> <td align="center">4</td> <td align="center">3</td> <td align="center">2</td> <td align="center">1</td> <td align="center">0</td> </tr> <tr> <td align="center" colspan="8">ptyp</td> </tr> </table>	F	E	D	C	B	A	9	8	amp				rtyp				7	6	5	4	3	2	1	0	ptyp							
			F	E	D	C	B	A	9	8																									
			amp				rtyp																												
			7	6	5	4	3	2	1	0																									
			ptyp																																
			bit	Explanation																															
			0	When the CN4 connector of the drive unit and the power supply are connected, setting below is necessary.																															
			1	To validate the external emergency stop function, add 40h.																															
			2																																
			3	ptyp	Set- ting	0x	1x	2x	3x	4x	5x	6x	7x	8x																					
4		x0	Not used			CV-300																													
5		x1		CV-110							CR-10																								
6		x2			CV-220						CR-15																								
7		x3									CR-22																								
		x4	CV-37								CR-37																								
		x5		CV-150			CV-450	CV-550																											
		x6	CV-55		CV-260						CR-55																								
		x7				CV-370																													
		x8	CV-75								CR-75																								
		x9		CV-185							CR-90																								
8		rtyp	Set the regenerative resistor type when MDS-A-CR is used.																																
9		A	Set- ting	Regenerative resistor model name	Resistance value	Capacity																													
A		B	0	MDS-C1-CV (Setting when using power supply regeneration)																															
			1	GZG200W260HMJ	26Ω	80W																													
			2	GZG300W130HMJ×2	26Ω	150W																													
			3	MR-RB30	13Ω	300W																													
			4	MR-RB50	13Ω	500W																													
			5	GZG200W200HMJ×3	6.7Ω	350W																													
			6	GZG300W200HMJ×3	6.7Ω	500W																													
			7	R-UNIT-1	30Ω	700W																													
			8	R-UNIT-2	15Ω	700W																													
			9	R-UNIT-3	15Ω	2100W																													
			A to F	No setting																															
C		amp	Always set to "0".																																
D																																			
E																																			
F																																			

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

No.	Items	Details	Setting range
2237	SV037 JL	Load inertia scale $SV037 (JL) = \frac{Jl+Jm}{Jm} *100$ Jm: Motor inertia Jl: Motor axis conversion load inertia	0 to 5000 (%)
2238	SV038 FHz1	Notch filter frequency 1	0 to 3000 (Hz)
2239	SV039 LMCD	Lost motion compensation timing	0 to 2000 (ms)
2240	The higher order 8bits and lower order 8bits are used for different functions. "Setting value of SV040" = (lcy*256) + LMCT		0 to 32767
	SV040 LMCT (Low order)	Lost motion compensation non-sensitive band	0 to 100 (μm)
	SV040 lcy (High order)	Current bias 2	Normally, set to "40" if you use HC202 to HC902, HC203 to HC703. Use this in combination with SV030 and the high order 8bits of SV045.
2241	SV041 LMC2	Lost motion compensation 2	-1 to 200 (Stall [rated] current %)
2242	SV042 OVS2	Overshooting compensation 2	-1 to 100 (Stall [rated] current %)
2243	SV043 OBS1	Disturbance observer filter frequency	0 to 1000 (rad/s)
2244	SV044 OBS2	Disturbance observer gain	0 to 500 (%)
2245	The higher order 8bits and lower order 8bits are used for different functions. "Setting value of SV045" = (lcy*256) + LMCT		0 to 32767
	SV045 TRUB (Low order)	Frictional torque	0 to 100 (Stall [rated] current %)
	SV045 lb1 (High order)	Current bias 3	Set to "0" as a standard. Use this in combination with SV030 and the high order 8bits of SV040.

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

No.	Items	Details	Setting range	
2246	SV046		Not used. Set to "0".	0
2247	SV047 EC	Inductive voltage compensation gain	Set the inductive voltage compensation gain. Set to "100" as a standard. If the current FB peak exceeds the current command peak, lower the gain.	0 to 200 (%)
2248	SV048 EMGrT	Vertical axis drop prevention time	Input a length of time to prevent the vertical axis from dropping by delaying Ready OFF until the brake works when the emergency stop occurs. Increase the setting by 100ms at a time and set the value where the axis does not drop.	0 to 20000 (ms)
2249	SV049 PGN1sp	Position loop gain 1 in spindle synchronous control	Set the position loop gain during the spindle synchronous control (synchronous tapping, synchronous control with spindle/C axis). Set the same value as the value of the spindle parameter, position loop gain in synchronous control. When performing the SHG control, set this with SV050 (PGN2sp) and SV058 (SHGCsp).	1 to 200 (rad/s)
2250	PGN2sp	Position loop gain 2 in spindle synchronous control	Set this with SV049 (PGN1sp) and SV058 (SHGCsp) if you wish to perform the SHG control in the spindle synchronous control (synchronous tapping, synchronous control with spindle/C axis). When not performing the SHG control, set to "0".	0 to 999 (rad/s)
2251	SV051 DFBT	Dual feed back control time constant	Set the control time constant in dual feed back. When "0" is set, the actual value that is set is 1ms. The higher the time constant is, the closer it gets to the semi-closed control, so the limit of the position loop gain is raised.	0 to 9999 (ms)
2252	SV052 DFBN	Dual feedback control non-sensitive band	Set the non-sensitive band in the dual feedback control. Set to "0" as a standard.	0 to 9999 (μm)
2253	SV053 OD3	Excessive error detection width in special control	Set the excessive error detection width when servo ON in a special control (initial absolute position setting, stopper control, etc.). If "0" is set, excessive error detection won't be performed when servo ON during a special control.	0 to 32767 (mm)
2254	SV054 ORE	Overrun detection width in closed loop control	Set the overrun detection width in the full-closed loop control. If the gap between the motor end detector and the linear scale (machine end detector) exceeds the value set by this parameter, it is judged to be overrun and Alarm 43 will be detected. When "-1" is set, the alarm detection won't be performed. When "0" is set, overrun is detected with a 2mm width.	-1 to 32767 (mm)

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

No.	Items		Details	Setting range
2255	SV055 EMGx	Max. gate off delay time after emergency stop	Set a length of time from the point when the emergency stop is input to the point when READY OFF is compulsorily executed. Normally, set the same value as the absolute value of SV056. In preventing the vertical axis from dropping, the gate off is delayed for the length of time set by SV048 if SV055's value is smaller than that of SV048.	0 to 20000 (ms)
2256	SV056 EMGt	Deceleration time constant at emergency stop	In the vertical axis drop prevention control, set the time constant used for the deceleration control at emergency stop. Set a length of time that takes from rapid traverse rate (rapid) to stopping. Normally, set the same value as the rapid traverse acceleration/deceleration time constant. When executing the synchronous operation, put the minus sign to the settings of both of the master axis and slave axis.	-20000 to 20000 (ms)
2257	SV057 SHGC	SHG control gain	When performing the SHG control, set this with S003 (PGN1) and SV004 (PGN2). When not performing the SHG control, set to "0".	0 to 999 (rad/s)
2258	SV058 SHGCsp	SHG control gain in spindle synchronous control	Set this with SV049 (PGN1sp) and SV050 (PGN2sp) if you wish to perform the SHG control in the spindle synchronous control (synchronous tapping, synchronous control with spindle/C axis). When not performing the SHG control, set to "0".	0 to 999 (rad/s)
2259	SV059 TCNV	Collision detection torque estimating gain	Set the torque estimating gain when using the collision detection function. After setting as SV035/bitF(ctl)=1 and performing acceleration/deceleration, set the value displayed in MPOS of the NC servo monitor screen. Set to "0" when not using the collision detection function.	-32768 to 32767
2260	SV060 TLMT	Collision detection level	When using the collision detection function, set the collision detection level during the G0 feeding. If "0" is set, none of the collision detection function will work.	0 to 999 (Stall [rated] current %)
2261	SV061 DA1NO	D/A output channel 1 data No.	Input the data number you wish to output to D/A output channel. In the case of MDS-C1-V2, set the axis on the side to which the data will not be output to "-1".	-1 to 127
2262	SV062 DA2NO	D/A output channel 2 data No.		
2263	SV063 DA1MPY	D/A output channel 1 output scale	Set the scale with a 1/256 unit. When "0" is set, output is done with the standard output unit.	-32768 to 32767 (Unit: 1/256)
2264	SV064 DA2MPY	D/A output channel 2 output scale		
2265	SV065		Not used. Set to "0".	0

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

(2) Initial setting value

(a) HC**/HC**R series

Motor		HC 52	HC 102	HC 152	HC 202	HC 352	HC 452	HC 702	HC 902
Drive unit capacity		05	10	20	20	35	45	70	90
SV001	PC1	-	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	33	33	33
SV004	PGN2	0	0	0	0	0	0	0	0
SV005	VGN1	100	100	100	100	100	100	150	150
SV006	VGN2	0	0	0	0	0	0	0	0
SV007	VIL	0	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	2048	2048	2048	2048	2048	2048	2048	2048
SV010	IDA	2048	2048	2048	2048	2048	2048	2048	2048
SV011	IQG	512	512	512	256	256	256	200	200
SV012	IDG	512	512	512	512	512	512	256	256
SV013	ILMT	500	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150	150
SV023	OD1	6	6	6	6	6	6	6	6
SV024	INP	50	50	50	50	50	50	50	50
SV025	MTYP	xxB0	xxB1	xxB2	xxB3	xxB4	xxB5	xxB6	xxB7
SV026	OD2	6	6	6	6	6	6	6	6
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0	0
SV029	VCS	0	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0	0

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

Motor		HC 52	HC 102	HC 152	HC 202	HC 352	HC 452	HC 702	HC 902
Drive unit capacity		05	10	20	20	35	45	70	90
SV033	SSF2	0000	0000	0000	0000	0000	0000	0000	0000
SV034	SSF3	0003	0003	0003	0003	0003	0003	0003	0003
SV035	SSF4	0000	0000	0040	0040	0040	0040	0040	0040
SV036	PTYP	0000	0000	0000	0000	0000	0000	0000	0000
SV037	JL	0	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	10240	10240	10240	10240	10240
SV041	LMC2	0	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0	0
SV046		0	0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100	100
SV048	EMGr	0	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0	0
SV051	DFBT	0	0	0	0	0	0	0	0
SV052	DFBN	0	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0	0
SV054	ORE	0	0	0	0	0	0	0	0
SV055	EMGx	0	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0	0
SV065		0	0	0	0	0	0	0	0

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

Motor		HC 53	HC 103	HC 153	HC 203	HC 353	HC 453	HC 703	HC 103R	HC 153R	HC 203R	HC 353R
Drive unit capacity		05	10	20	35	45	70	90	10	10	20	35
SV001	PC1	-	-	-	-	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	33	33	33	33	33	33
SV004	PGN2	0	0	0	0	0	0	0	0	0	0	0
SV005	VGN1	100	100	100	100	100	100	100	15	15	20	40
SV006	VGN2	0	0	0	0	0	0	0	0	0	0	0
SV007	VIL	0	0	0	0	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	2048	2048	2048	2048	2048	2048	2048	4096	4096	4096	4096
SV010	IDA	2048	2048	2048	2048	2048	2048	2048	4096	4096	4096	4096
SV011	IQG	256	256	256	256	256	256	256	256	256	256	256
SV012	IDG	512	512	512	512	512	512	512	512	512	512	512
SV013	ILMT	500	500	500	500	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150	150	150	150	150
SV023	OD1	6	6	6	6	6	6	6	6	6	6	6
SV024	INP	50	50	50	50	50	50	50	50	50	50	50
SV025	MTYP	xxC0	xxC1	xxC2	xxC3	xxC4	xxC5	xxC6	xxE1	xxE2	xxE3	xxE4
SV026	OD2	6	6	6	6	6	6	6	6	6	6	6
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0	0	0	0	0
SV029	VCS	0	0	0	0	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0	0	0	0	0

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

Motor		HC 53	HC 103	HC 153	HC 203	HC 353	HC 453	HC 703	HC 103R	HC 153R	HC 203R	HC 353R
Drive unit capacity		05	10	20	35	45	70	90	10	10	20	35
SV033	SSF2	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV034	SSF3	0003	0003	0003	0003	0003	0003	0003	0000	0000	0000	0000
SV035	SSF4	0000	0000	0040	0040	0040	0040	0040	0000	0000	0000	0000
SV036	PTYP	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV037	JL	0	0	0	0	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	1024 0	1024 0	1024 0	1024 0	0	0	0	0
SV041	LMC2	0	0	0	0	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0	0	0	0	0
SV046		0	0	0	0	0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100	100	100	100	100
SV048	EMGr	0	0	0	0	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0	0	0	0	0
SV051	DFBT	0	0	0	0	0	0	0	0	0	0	0
SV052	DFBN	0	0	0	0	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0	0	0	0	0
SV054	ORE	0	0	0	0	0	0	0	0	0	0	0
SV055	EMGx	0	0	0	0	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0	0	0	0	0
SV065		0	0	0	0	0	0	0	0	0	0	0

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

(b) HA**N series

Motor		HA 40N	HA 80N	HA 100N	HA 200N	HA 300N	HA 700N	HA 900N
Drive unit capacity		05	10	20	35	45	70	90
SV001	PC1	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	25	25
SV004	PGN2	0	0	0	0	0	0	0
SV005	VGN1	150	150	150	150	150	250	250
SV006	VGN2	0	0	0	0	0	0	0
SV007	VIL	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	2048	2048	2048	2048	2048	2048	2048
SV010	IDA	2048	2048	2048	2048	2048	2048	2048
SV011	IQG	512	512	256	256	256	200	200
SV012	IDG	512	512	512	512	512	256	256
SV013	ILMT	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150
SV023	OD1	6	6	6	6	6	6	6
SV024	INP	50	50	50	50	50	50	50
SV025	MTYP	xx00	xx01	xx02	xx03	xx04	xx05	xx06
SV026	OD2	6	6	6	6	6	6	6
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0
SV029	VCS	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

Motor		HA 40N	HA 80N	HA 100N	HA 200N	HA 300N	HA 700N	HA 900N
Drive unit capacity		05	10	20	35	45	70	90
SV033	SSF2	0000	0000	0000	0000	0000	0000	0000
SV034	SSF3	0000	0000	0000	0000	0000	0000	0000
SV035	SSF4	0000	0000	0000	0000	0000	0000	0000
SV036	PTYP	0000	0000	0000	0000	0000	0000	0000
SV037	JL	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	0	0	0	0
SV041	LMC2	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0
SV046		0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100
SV048	EMGr	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0
SV051	DFBT	0	0	0	0	0	0	0
SV052	DFBN	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0
SV054	ORE	0	0	0	0	0	0	0
SV055	EMGx	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0
SV065		0	0	0	0	0	0	0

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

Motor		HA 43N	HA 83N	HA 93N	HA 103N	HA 203N	HA 303N	HA 703N
Drive unit capacity		05	10	20	35	45	70	90
SV001	PC1	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	33	25
SV004	PGN2	0	0	0	0	0	0	0
SV005	VGN1	150	150	150	150	150	150	250
SV006	VGN2	0	0	0	0	0	0	0
SV007	VIL	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	2048	2048	2048	2048	2048	2048	2048
SV010	IDA	2048	2048	2048	2048	2048	2048	2048
SV011	IQG	256	256	256	256	256	256	200
SV012	IDG	512	512	512	512	512	512	256
SV013	ILMT	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150
SV023	OD1	6	6	6	6	6	6	6
SV024	INP	50	50	50	50	50	50	50
SV025	MTYP	xx80	xx81	xx8A	xx82	xx83	xx84	xx85
SV026	OD2	6	6	6	6	6	6	6
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0
SV029	VCS	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

Motor		HA 43N	HA 83N	HA 93N	HA 103N	HA 203N	HA 303N	HA 703N
Drive unit capacity		05	10	20	35	45	70	90
SV033	SSF2	0000	0000	0000	0000	0000	0000	0000
SV034	SSF3	0000	0000	0000	0000	0000	0000	0000
SV035	SSF4	0000	0000	0000	0000	0000	0000	0000
SV036	PTYP	0000	0000	0000	0000	0000	0000	0000
SV037	JL	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	0	0	0	0
SV041	LMC2	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0
SV046		0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100
SV048	EMGr	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0
SV051	DFBT	0	0	0	0	0	0	0
SV052	DFBN	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0
SV054	ORE	0	0	0	0	0	0	0
SV055	EMGx	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0
SV065		0	0	0	0	0	0	0

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

Motor		HA 053	HA 13	HA 053N	HA 13N	HA 23N	HA 33N
Drive unit capacity		01	01	01	01	03	03
SV001	PC1	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	33
SV004	PGN2	0	0	0	0	0	0
SV005	VGN1	70	70	70	70	100	100
SV006	VGN2	0	0	0	0	0	0
SV007	VIL	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364
SV009	IQA	2048	2048	2048	2048	2048	2048
SV010	IDA	2048	2048	2048	2048	2048	2048
SV011	IQG	256	256	256	256	224	224
SV012	IDG	256	256	256	256	224	224
SV013	ILMT	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-
SV019	RNG1	10	10	-	-	-	-
SV020	RNG2	10	10	-	-	-	-
SV021	OLT	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150
SV023	OD1	6	6	6	6	6	6
SV024	INP	50	50	50	50	50	50
SV025	MTYP	338C	338D	xx8C	xx8D	xx8E	xx8F
SV026	OD2	6	6	6	6	6	6
SV027	SSF1	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0
SV029	VCS	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0

(Note) The HA053 and HA13 are dedicated for the MDS-B-Vx.

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

Motor		HA 053	HA 13	HA 053N	HA 13N	HA 23N	HA 33N
Drive unit capacity		01	01	01	01	03	03
SV033	SSF2	0000	0000	0000	0000	0000	0000
SV034	SSF3	0000	0000	0000	0000	0000	0000
SV035	SSF4	0000	0000	0000	0000	0000	0000
SV036	PTYP	0000	0000	0000	0000	0000	0000
SV037	JL	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0
SV040	LMCT	0	0	0	0	0	0
SV041	LMC2	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0
SV046		0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100
SV048	EMGr	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0
SV051	DFBT	0	0	0	0	0	0
SV052	DFBN	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0
SV054	ORE	0	0	0	0	0	0
SV055	EMGx	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0
SV065		0	0	0	0	0	0

(Note) The HA053 and HA13 are dedicated for the MDS-B-Vx.

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

(c) HA**L series

Motor		HA 50L	HA 100L	HA 150L	HA 200L	HA 300L	HA 500L	HA-A11KL	HA-A15KL
Drive unit capacity		05	10	10	20	35	45	110	150
SV001	PC1	-	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	33	33	33
SV004	PGN2	0	0	0	0	0	0	0	0
SV005	VGN1	30	30	30	30	30	50	150	150
SV006	VGN2	0	0	0	0	0	0	0	0
SV007	VIL	0	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	2048	2048	2048	2048	2048	2048	2048	2048
SV010	IDA	2048	2048	2048	2048	2048	2048	2048	2048
SV011	IQG	512	512	512	512	256	256	512	512
SV012	IDG	512	512	512	512	512	512	512	512
SV013	ILMT	500	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60	60	3
SV022	OLL	150	150	150	150	150	150	150	150
SV023	OD1	6	6	6	6	6	6	6	6
SV024	INP	50	50	50	50	50	50	50	50
SV025	MTYP	xx20	xx21	xx2A	xx22	xx23	xx24	xx27	xx28
SV026	OD2	6	6	6	6	6	6	6	6
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0	0
SV029	VCS	0	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0	0

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

Motor		HA 50L	HA 100L	HA 150L	HA 200L	HA 300L	HA 500L	HA- A11KL	HA- A15KL
Drive unit capacity		05	10	10	20	35	45	110	150
SV033	SSF2	0000	0000	0000	0000	0000	0000	0000	0000
SV034	SSF3	0000	0000	0000	0000	0000	0000	0000	0000
SV035	SSF4	0000	0000	0000	0000	0000	0000	0000	0000
SV036	PTYP	0000	0000	0000	0000	0000	0000	0000	0000
SV037	JL	0	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	0	0	0	0	0
SV041	LMC2	0	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0	0
SV046		0	0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100	100
SV048	EMGr	0	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0	0
SV051	DFBT	0	0	0	0	0	0	0	0
SV052	DFBN	0	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0	0
SV054	ORE	0	0	0	0	0	0	0	0
SV055	EMGx	0	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0	0
SV065		0	0	0	0	0	0	0	0

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

Motor		HA 53L	HA 103L	HA 153L	HA 203L	HA 303L	HA 503L
Drive unit capacity		10	20	20	35	45	70
SV001	PC1	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	33
SV004	PGN2	0	0	0	0	0	0
SV005	VGN1	30	30	30	30	30	50
SV006	VGN2	0	0	0	0	0	0
SV007	VIL	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364
SV009	IQA	2048	2048	2048	2048	2048	2048
SV010	IDA	2048	2048	2048	2048	2048	2048
SV011	IQG	512	512	512	512	256	256
SV012	IDG	512	512	512	512	512	512
SV013	ILMT	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150
SV023	OD1	6	6	6	6	6	6
SV024	INP	50	50	50	50	50	50
SV025	MTYP	xx30	xx31	xx3A	xx32	xx33	xx34
SV026	OD2	6	6	6	6	6	6
SV027	SSF1	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0
SV029	VCS	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0
SV033	SSF2	0000	0000	0000	0000	0000	0000

7. Servo Parameters
7.3 MDS-C1-Vx Standard Specification (MDS-B-Vx Compatible)

Motor		HA 53L	HA 103L	HA 153L	HA 203L	HA 303L	HA 503L
Drive unit capacity		10	20	20	35	45	70
SV034	SSF3	0000	0000	0000	0000	0000	0000
SV035	SSF4	0000	0000	0000	0000	0000	0000
SV036	PTYP	0000	0000	0000	0000	0000	0000
SV037	JL	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0
SV040	LMCT	0	0	0	0	0	0
SV041	LMC2	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0
SV046		0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100
SV048	EMGrt	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0
SV051	DFBT	0	0	0	0	0	0
SV052	DFBN	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0
SV054	ORE	0	0	0	0	0	0
SV055	EMGx	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0
SV065		0	0	0	0	0	0


7.4 Supplement

7.4.1 D/A Output Specifications

(1) MDS-B-SVJ2

(a) D/A output specifications

Item	Explanation
No. of channels	2ch
Output cycle	888 μ s (min. value)
Output precision	8bit
Output voltage range	-10V to 0 to +10V
Output scale setting	$\pm 1/256$ to ± 128 times
Output pins	CN3 connector MO1 = pin 4 MO2 = pin 14 GND = pin 1, 11
Function	Offset amount adjustment function Output clamp function Low path filter function
Option	Relay terminal: MR-J2CN3TM Connect from the CN3 connector using the SH21 cable as a lead-in wire.



7. Servo Parameters
7.4 Supplement

(b) Setting the output data

Set the No. of the data to be outputted to each D/A output channel.

#	No.	Abbrev	Parameter name
2261	SV061	DA1NO	D/A output channel 1 data No.
2262	SV062	DA2NO	D/A output channel 2 data No.

No.	Output data	Standard output unit	Output cycle
0	0V test output	For offset amount adjustment	
1	Speed feedback	1000rpm / 2V	888 μ s
2	Current feedback	Stall (rated) 100% / 2V	888 μ s
3	Speed command	1000rpm / 2V	888 μ s
4	Current command	Stall (rated) 100% / 2V	888 μ s
5	V-phase current value	10A / V	888 μ s
6	W-phase current-value	10A / V	888 μ s
7	Estimated disturbance torque	Stall (rated) 100% / 2V	888 μ s
8	Collision detection disturbance torque	Stall (rated) 100% / 2V	888 μ s
9	Position feedback (stroke)	100mm / V	3.55ms
10	Position feedback (pulse)	10 μ m / V	3.55ms
11	Position droop	mm / V	3.55ms
12	Position droop (x10)	100 μ m / V	3.55ms
13	Position droop (x100)	10 μ m / V	3.55ms
14	Feedrate (F Δ T)	10000(mm/min) / V	888 μ s
15	Feedrate (F Δ T x 10)	1000(mm/min) / V	888 μ s
16	Model position droop	mm / V	3.55ms
17	Model position droop (x10)	100 μ m / V	3.55ms
18	Model position droop (x100)	10 μ m / V	3.55ms
19	q-axis current cumulative value	-	888 μ s
20	d-axis current cumulative value	-	888 μ s
21	Motor load level	100% / 5V	113.7ms
22	Amplifier load level	100% / 5V	113.7ms
23	Regenerative load level	100% / 5V	910.2ms
24	PN bus wire voltage	50V / V (1/50)	888 μ s
25	Speed cumulative item	-	888 μ s
26	Cycle counter	0-5V (Regardless of resolution)	888 μ s
27	Excessive error detection amount	mm / V	3.55ms
28	Collision detection estimated torque	Stall (rated) 100% / 2V	888 μ s
29	Position command (stroke)	100mm / V	3.55ms
30	Position command (pulse)	10 μ m / V	3.55ms
31 to 99	-		
100	5V test output	-	-
101	Saw-tooth wave test output	-5 to 5V Cycle: 113.7ms	888 μ s
102	Rectangular wave test output	0 to 5V Cycle: 227.5ms	888 μ s
103 to	Setting prohibited		

7. Servo Parameters

7.4 Supplement

(c) Setting the output scale

When "0" is set, the output will be made with the standard output unit. To change the output unit, set a value other than "0".

The scale is set with a 1/256 unit. When 256 is set, the unit will be the same as the standard output.

#	No.	Abbrev	Parameter name
2263	SV063	DA1MPY	D/A output channel 1 output scale
2264	SV064	DA2MPY	D/A output channel 2 output scale

(Example 1) When SV061 = 5, SV063 = 2560

The V-phase current value will be output with 1 A/V unit to D/A output ch.1.

(Example 2) When SV063 = 11, SV064 = 128


The position droop will be output with a 2mm/Vunit to D/A output ch.2.

7. Servo Parameters 7.4 Supplement

(2) MDS-C1-Vx, MDS-B-Vx, MDS-B-Vx4

(a) D/A Output specifications

Item	Explanation
No. of channels	2ch
Output cycle	888 μ s (min. value)
Output precision	8bit
Output voltage	0V to 2.5V to +5V
Output scale setting	$\pm 1/256$ to ± 128 times
Output pins	CN9 connector MO1 = pin 9 MO2 = pin 19 GND = pin 1,11
Function	Phase current feed back output function L-axis U-phase current FB : pin 7 L-axis V-phase current FB : pin 17 M-axis U-phase current FB : pin 6 M-axis V-phase current FB : pin 16
Option	An drive unit with 2 axes also has 2 channels for D/A output. Therefore, set the output data of the axis (SV061,62), which is not observed, to "-1".



7. Servo Parameters
7.4 Supplement

(b) Setting the output data

Set the No. of the data to be outputted to each data D/A output channel.

#	No.	Abbrev	Parameter name
2261	SV061	DA1NO	D/A output channel 1 data No.
2262	SV062	DA2NO	D/A output channel 2 data No.

No.	Output data	Standard output unit	Standard setting value of output scale (Setting values in SV063, SV064)	Standard output unit	Output cycle
-1	D/A output non-selected	For a drive unit. with 2 axes (MDS-C1-V2). Set for the parameter of the axis which is not used.			
0	ch1: Speed feedback	r/min	13 (in case of 2000rpm)	1000rpm / V	3.55ms
			9 (in case of 3000rpm)	1500rpm / V	3.55ms
	ch2: Current command	Stall%	131	Stall 100% / V	3.55ms
1	Current command	Stall%	131	Stall 100% / V	3.55ms
2	–				
3	Current feedback	Stall%	131	Stall 100% / V	3.55ms
4	–				
5	–				
6	Position droop	NC display unit / 2	328 (When the display unit=1 μ m)	10 μ m / 0.5V	3.55ms
7	–				
8	Feedrate (F Δ T)	(NC display unit / 2) / communication cycle	55 (When 1 μ m, 3.5ms)	1000 (mm/min) / 0.5V	3.55ms
9	–				
10	Position command	NC display unit / 2	328 (When the display unit=1 μ m)	10 μ m / 0.5V	3.55ms
11	–				
12	Position feedback	NC display unit / 2	328 (When the display unit=1 μ m)	10 μ m / 0.5V	3.55ms
13	–				
14	Collision detection estimated torque	Stall%	131	Stall 100% / V	3.55ms
15	Collision detection disturbance torque	Stall%	131	Stall 100% / V	3.55ms
64	Current command (High-speed)	Internal unit	8 (adjustment required)	–	888 μ s
65	Current feedback (High-speed)	Internal unit	8 (adjustment required)	–	888 μ s

(To be continued to the next page)

7. Servo Parameters 7.4 Supplement

(Continued from the previous page)

No.	Output data	Standard output unit	Standard setting value of output scale (Setting values in SV063, SV064)	Standard output unit	Output cycle
77	Estimated disturbance torque	Internal unit	⁸ (adjustment required)	–	888μs
125	Saw-tooth wave test output	0V to 5V	0 (256)	Cycle: 227.5ms	888μs
126	Rectangular wave test output	0V to 5V	0 (256)	Cycle: 1.7ms	888μs
127	2.5V (data 0) test output	2.5V	0 (256)	–	888μs

(c) Setting the output scale

#	No.	Abbrev	Parameter name
2263	SV063	DA1MPY	D/A output channel 1 output scale
2264	SV064	DA2MPY	D/A output channel 2 output scale

Usually, the standard setting value is set for the output scale (SV063, SV 064). When “0” is set, the output will be made as well as when “256” is set.

$$\text{DATA} \times \frac{\text{SV063}}{256} \times \frac{5 [\text{V}]}{256 \text{ (8bit)}} + 2.5 [\text{V}] \text{ (offset)} = \text{Output voltage} [\text{V}]$$

(Example) When outputting the current FB with 100%/V–stall (SV061=3, SV063=131)

$$100 \times \frac{131}{256} \times \frac{5}{256} + 2.5 = 3.499 [\text{V}]$$

7. Servo Parameters

7.4 Supplement

7.4.2 Electronic Gears

The servo drive unit has internal electronic gears. The command value from the NC is converted into a detector resolution unit to carry out position control. The electronic gears are single gear ratios calculated from multiple parameters as shown below. However, each value (ELG1, ELG2) must be less than 32767.

If the value overflows, the initial parameter error (alarm 37) or error parameter No. 2301 will be output.

If an alarm occurs, the mechanical specifications and electrical specifications must be revised so that the electronic gears are within the specifications range.

<Semi-closed loop>

$$\frac{\text{ELG1}}{\text{ELG2}} = \frac{\text{RNG1} \times \text{PC2}}{\text{PIT} \times \text{PC1} \times \text{IUNIT}} \quad (\text{Reduced fraction})$$

<Closed loop>

$$\frac{\text{ELG1}}{\text{ELG2}} = \frac{\text{PGN} \times \text{RNG2} \times \text{PC2}}{30 \times \text{RNG1} \times \text{PC1}} \quad (\text{Reduced fraction})$$

IUNIT = 2/NC command unit (μm)

1 μm : IUNIT = 2, 0.1 μm : IUNIT = 20

When the above is calculated, the following conditions must be satisfied.

ELG1 \leq 32767

ELG2 \leq 32767

7. Servo Parameters

7.4 Supplement

7.4.3 Lost Motion Compensation


When the motor is to rotate in the clockwise direction (looking from the load side) at the command for the + direction, the command direction is CW. Conversely, when the motor is to rotate in the counterclockwise direction, the command direction is CCW.

This rotation direction can be set with the CNC machine parameters. Note that the meaning of the \pm will differ for some servo parameters according to this motor rotation direction. The servo parameters affected by CW/CCW are shown below.

SV016 (LMC1), SV041 (LMC2) (When different values are set for SV016 and SV041)
 SV031 (OVS1), SV042 (OVS2) (When different values are set for SV031 and SV042)

<Example> If the lost motion compensation amount is to be changed according to the direction, the compensation amount at the quadrant changeover point of each arc where the lost motion compensation is applied will be as shown below according to the command polarity.

	CW	CCW
A	X: SV041	X: SV016
B	Y: SV016	Y: SV041
C	X: SV016	X: SV041
D	Y: SV041	Y: SV016



(Note) The setting value for the parameter is "0" or "-1", the compensation amount is determined as shown below.

Setting value for SV016 (Setting value for SV031)	Setting value for SV041 (Setting value for SV041)	Compensation amount in + direction	Compensation amount in - direction
0	0	No compensation	No compensation
n	0	n	n
0	m	m	m
n	m	n	m
n	-1	n	No compensation
-1	m	No compensation	m

8. Spindle Parameters
8.1 Spindle Base Specifications Parameters

8. Spindle Parameters

8.1 Spindle Base Specifications Parameters


For parameters indicated with a (PR) in the table, turn the NC power OFF after setting. The setting is validated after the power is turned ON again.

No.	Items	Details	Setting range (Unit)
3001 3002 3003 3004	slimit 1 2 3 4	Limit rotation speed	0 to 99999 (r/min)
3005 3006 3007 3008	smax 1 2 3 4	Maximum rotation speed	
3009 3010 3011 3012	ssift 1 2 3 4	Shift rotation speed	0 to 32767 (r/min)
3013 3014 3015 3016	stap 1 2 3 4	Tap rotation speed	0 to 99999 (r/min)
3017 3018 3019 3020	stapt 1 2 3 4	Tap time constant	1 to 5000 (ms)


8. Spindle Parameters

8.1 Spindle Base Specifications Parameters

Relationship between spindle limit rotation speed and maximum spindle rotation speed



Relation between the spindle limit rotation speed and the spindle tap time constant (for the constant inclination synchronized tapping)



8. Spindle Parameters

8.1 Spindle Base Specifications Parameters

#	Items	Details	Setting range (Unit)	
3021	sori	Orientation rotation speed	Set the spindle orientation rotation speed. Set the rotation speed for when the spindle rotates at the constant rotation speed.	0 to 32767 (r/min)
3022	sgear	Encoder gear ratio	Set the gear ratio of the spindle to the encoder.	0: 1/1 1: 1/2 2: 1/4 3: 1/8
3023	smini	Minimum rotation speed	Set the minimum rotation speed of the spindle. If an S command instructs the rotation speed below this setting, the spindle rotates at the minimum rotation speed set with this parameter.	0 to 32767 (r/min)
3024 (PR)	sout	Spindle connection	Set the type of the spindle to be connected. 0: No connection with the spindle 1: Serial connection (bus) 2 to 5: Analog output	0 to 5
3025	enc-on	Spindle encoder	Set connection information of the spindle encoder. 0: No connection 1: Spindle connection (Spindle encoder connection check function valid.) 2: Serial connection of encoder	0 to 2
3026	cs_ori	Selection of winding in orientation mode	0: Perform orientation using the winding selected when the orientation command is issued. 1: Use winding L whenever the orientation command is issued.	0/1
3027	cs_syn	Selection of winding in spindle synchronous mode	0: The winding H/L is selected by the actual spindle rotation speed (calculated from commanded rotation speed) when spindle synchronous control starts. (The winding is not switched during synchronous control. The control is carried out with the winding selected at start.) If the actual spindle rotation speed is less than SP020, the winding L is selected, and if more than the value, the winding H is selected. 1: Use winding H whenever the spindle synchronous command is issued.	0/1
3028	sprcmm	L system tap cycle spindle forward run/reverse run M command	Set the M code of the spindle forward run/reverse run command. High-order three digits : The spindle forward run command's M code is set. Low-order three digits : The spindle reverse run command's M code is set.	0 to 999999

8. Spindle Parameters
8.1 Spindle Base Specifications Parameters

#	Items	Details	Setting range (Unit)	
3037 3038 3039 3040	tapt 21 22 23 24	Synchronized tapping Switching spindle rotation speed 2	Set the spindle rotation speed at which the step-2 acceleration/deceleration time constant is to be switched at gear 00, 01, 10, or 11.	0 to 99999 (r/min)
3041 3042 3043 3044	tapt 21 22 23 24	Synchronized tapping Switching time constant 2	Set the time constant to reach Synchronized tapping switching spindle rotation speed 2 (#3037 to #3040) at gear 00, 01, 10, or 11.	1 to 5000 (ms)
3045 3046 3047 3048	tapt 31 32 33 34	Synchronized tapping Switching time constant 3	Set the time constant to reach the maximum rotation spindle speed (#3005 to #3008) at gear 00, 01, 10, or 11.	1 to 5000 (ms)
3049	spt	Spindle synchronization acceleration/deceleration time constant	Set the acceleration/deceleration time constant for when the spindle synchronization command's rotation speed changes during spindle synchronous control.	0 to 9999 (ms)
3050	sprlv	Spindle synchronization rotation speed attainment level	The spindle rotation speed synchronization complete signal will turn ON when the difference of the reference spindle and synchronous spindle actual rotation speeds is less than the level set for the synchronous spindle rotation speed command value during spindle synchronous control.	0 to 4095 (pulse) (1 pulse = 0.088°)
3051	spplv	Spindle phase synchronization attainment level	The spindle phase synchronization complete signal will turn ON when the phase difference of the reference spindle and synchronous spindle is less than the set level during spindle phase synchronization control.	0 to 4095 (pulse) (1 pulse = 0.088°)
3052	spplr	Spindle motor spindle relative polarity	Set the spindle motor and spindle's relative polarity. Spindle CW rotation at motor CW rotation : Positive polarity Spindle CCW rotation at motor CW rotation : Negative polarity	0: Positive polarity 1: Negative polarity
3053	sppst	Spindle encoder Z -phase position	Set the deviation amount from the spindle's reference position to the spindle encoder's Z phase. The deviation amount is obtained using the clockwise direction looking from the front of the spindle as the positive direction.	0 to 359999 (1/1000°)

8. Spindle Parameters
8.1 Spindle Base Specifications Parameters

#	Items	Details	Setting range (Unit)
3054	sptc1 Spindle synchronization multi-step acceleration/deceleration changeover speed 1	Set the spindle speed for changing the 1st step's acceleration/deceleration time constant.	0 to 99999 (r/min)
3055	sptc2 Spindle synchronization multi-step acceleration/deceleration changeover speed 2	Set the spindle speed for changing the 2nd step's acceleration/deceleration time constant.	0 to 99999 (r/min)
3056	sptc3 Spindle synchronization multi-step acceleration/deceleration changeover speed 3	Set the spindle speed for changing the 3rd step's acceleration/deceleration time constant.	0 to 99999 (r/min)
3057	sptc4 Spindle synchronization multi-step acceleration/deceleration changeover speed 4	Set the spindle speed for changing the 4th step's acceleration/deceleration time constant.	0 to 99999 (r/min)
3058	sptc5 Spindle synchronization multi-step acceleration/deceleration changeover speed 5	Set the spindle speed for changing the 5th step's acceleration/deceleration time constant.	0 to 99999 (r/min)
3059	sptc6 Spindle synchronization multi-step acceleration/deceleration changeover speed 6	Set the spindle speed for changing the 6th step's acceleration/deceleration time constant.	0 to 99999 (r/min)

8. Spindle Parameters
8.1 Spindle Base Specifications Parameters

#	Items	Details	Setting range (Unit)	
3060	sptc7	Spindle synchronization multi-step acceleration/deceleration changeover speed 7	Set the spindle speed for changing the 7th step's acceleration/deceleration time constant.	0 to 99999 (r/min)
3061	spdiv1	Magnification for time constant changeover speed 1	Set the acceleration/deceleration time constant between the spindle synchronization multi-step acceleration/deceleration changeover speed 1 (sptc1) to the spindle synchronization multi-step acceleration/deceleration changeover speed 2 (sptc2) as a magnification in respect to the spindle synchronization acceleration/deceleration time constant (spt).	0 to 127
3062	spdiv2	Magnification for time constant changeover speed 2	Set the acceleration/deceleration time constant between the spindle synchronization multi-step acceleration/deceleration changeover speed 2 (sptc2) to the spindle synchronization multi-step acceleration/deceleration changeover speed 3 (sptc3) as a magnification in respect to the spindle synchronization acceleration/deceleration time constant (spt).	0 to 127
3063	spdiv3	Magnification for time constant changeover speed 3	Set the acceleration/deceleration time constant between the spindle synchronization multi-step acceleration/deceleration changeover speed 3 (sptc3) to the spindle synchronization multi-step acceleration/deceleration changeover speed 4 (sptc4) as a magnification in respect to the spindle synchronization acceleration/deceleration time constant (spt).	0 to 127
3064	spdiv4	Magnification for time constant changeover speed 4	Set the acceleration/deceleration time constant between the spindle synchronization multi-step acceleration/deceleration changeover speed 4 (sptc4) to the spindle synchronization multi-step acceleration/deceleration changeover speed 5 (sptc5) as a magnification in respect to the spindle synchronization acceleration/deceleration time constant (spt).	0 to 127
3065	spdiv5	Magnification for time constant changeover speed 5	Set the acceleration/deceleration time constant between the spindle synchronization multi-step acceleration/deceleration changeover speed 5 (sptc5) to the spindle synchronization multi-step acceleration/deceleration changeover speed 6 (sptc6) as a magnification in respect to the spindle synchronization acceleration/deceleration time constant (spt).	0 to 127

8. Spindle Parameters
8.1 Spindle Base Specifications Parameters

#	Items	Details	Setting range (Unit)	
3066	spdiv6	Magnification for time constant changeover speed 6	Set the acceleration/deceleration time constant between the spindle synchronization multi-step acceleration/deceleration changeover speed 6 (sptc6) to the spindle synchronization multi-step acceleration/deceleration changeover speed 7 (sptc7) as a magnification in respect to the spindle synchronization acceleration/deceleration time constant (spt).	0 to 127
3067	spdiv7	Magnification for time constant changeover speed 7	Set the acceleration/deceleration time constant for the spindle synchronization multi-step acceleration/deceleration changeover speed 7 (sptc7) and higher as a magnification in respect to the spindle synchronization acceleration/deceleration time constant (spt).	0 to 127
3068	symtm1	Phase synchronization start confirmation time	Set the time to confirm that synchronization is attained before phase synchronization control is started. When "0" is set, the time will be 2 seconds. When "100" or less is set, the time will be 100ms.	0 to 9999 (ms)
3069	symtm2	Phase synchronization end confirmation time	Set the time to wait for phase synchronization control to end as the time for the rotation speed to reach the attainment range. When "0" is set, the time will be 2 seconds. When "100" or less is set, the time will be 100ms.	0 to 9999 (ms)
3070	syprt	Phase synchronization speed	Set the fluctuation amount to change the synchronous spindle rotation speed during phase synchronization control as the command speed and rate. When "0" is set, the amount will be 100%.	0 to 100 (%)
3071		(Not used.)		
3072		(Not used.)		

8. Spindle Parameters

8.2 MDS-B-SPJ2

8.2 MDS-B-SPJ2

For parameters marked with a (PR) in the tables, turn the NC power OFF after setting. The parameters will be valid after the power is turned ON again.

The valid spindle parameters will differ according to the motor and amplifier type. Follow the correspondence table given below, and set the correct parameters.

The spindle parameter setting and display method will differ according to the NC being used, so refer to Instruction Manual for each NC and the following spindles.

MELDAS AC Servo and Spindle MDS-A Series MDS-B Series Specifications Manual ...BNP-B3759

The "fixed control constants" and "fixed control bits" in this section are set by Mitsubishi.

CAUTION

 Do not make remarkable adjustments or changes of the parameters as the operation may become unstable.

 In the explanation on bits, set all bits not used, including blank bits, to "0".

No.	Items		Details	Setting range	Standard setting	
3201	SP001	PGM	Magnetic detector and motor built-in encoder orientation-mode position loop gain	As the set value is larger, the orientation time becomes shorter and servo rigidity is increased. On the contrary, however, vibration is increased and the machine becomes likely to overshoot.	0 to 1000 (0.1 1/s)	100
3202	SP002	PGE	Encoder orientation-mode position loop gain	As the set value is larger, the orientation time becomes shorter and servo rigidity is increased. On the contrary, however, vibration is increased and the machine becomes likely to overshoot.	0 to 1000 (0.1 1/s)	100
3203	SP003			Not used. Set to "0".	0	0
3204	SP004	OINP	Orientation in-position width	Set the position error range in which an orientation completion signal is output.	1 to 2880 (1/16°)	16
3205 (PR)	SP005	OSP	Orientation mode changing speed limit value	Set the motor speed limit value to be used when the speed loop is changed to the position loop in orientation mode. When this parameter is set to "0", SP017 (TSP) becomes the limit value.	0 to 32767 (r/min)	0
3206	SP006	CSP	Orientation mode deceleration rate	As the set value is larger, the orientation time becomes shorter. On the contrary, however, the machine becomes likely to overshoot.	1 to 1000	20
3207	SP007	OPST	In-position shift amount for orientation	Set the stop position for orientation. Set the value by dividing 360° by 4096.	0 to 4095	0
3208	SP008			Not used. Set to "0".	0	0
3209	SP009	PGT	Synchronous tapping position loop gain	Set the spindle position loop gain in synchronous tapping mode.	1 to 100 (1/s)	15

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting	
3210	SP010	PGS	Spindle synchronous position loop gain	Set the spindle position loop gain in spindle synchronization mode.	1 to 100 (1/s)	15
3211 to 3216	SP011 to SP016			Use not possible.	0	0
3217 (PR)	SP017	TSP	Maximum motor speed	Set the maximum motor speed of the spindle.	1 to 32767 (r/min)	6000
3218 (PR)	SP018	ZSP	Motor zero speed	Set the motor speed for which zero-speed output is performed.	1 to 1000 (r/min)	50
3219 (PR)	SP019	CSN1	Speed cushion 1	Set the time constant for a speed command from "0" to the maximum speed. (This parameter is invalid in position loop mode.)	0 to 32767 (10ms)	30
3220 (PR)	SP020	SDTS	Speed detection set value	Set the motor speed so for which speed detection output is performed. Usually, the setting value is 10% of SP017 (TSP).	0 to 32767 (r/min)	600
3221	SP021	TLM1	Torque limit 1	Set the torque limit rate for torque limit signal 001.	0 to 120 (%)	10
3222 (PR)	SP022	VGNP1	Speed loop gain proportional term under speed control	Set the speed loop proportional gain in speed control mode. When the gain is increased, response is improved but vibration and sound become larger.	0 to 1000 (1/s)	63
3223 (PR)	SP023	VGNI1	Speed loop gain integral term under speed control	Set the speed loop integral gain in speed control mode. Usually, set a value in proportion to SP022 (VGNP1).	0 to 1000 (0.1 1/s)	60
3224	SP024			Not used. Set to "0".	0	0
3225 (PR)	SP025	GRA1	Spindle gear teeth count 1	Set the number of gear teeth of the spindle corresponding to gear 000.	1 to 32767	1
3226 (PR)	SP026	GRA2	Spindle gear teeth count 2	Set the number of gear teeth of the spindle corresponding to gear 001.	1 to 32767	1
3227 (PR)	SP027	GRA3	Spindle gear teeth count 3	Set the number of gear teeth of the spindle corresponding to gear 010.	1 to 32767	1
3228 (PR)	SP028	GRA4	Spindle gear teeth count 4	Set the number of gear teeth of the spindle corresponding to gear 011.	1 to 32767	1
3229 (PR)	SP029	GRB1	Motor shaft gear teeth count 1	Set the number of gear teeth of the motor shaft corresponding to gear 000.	1 to 32767	1
3230 (PR)	SP030	GRB2	Motor shaft gear teeth count 2	Set the number of gear teeth of the motor shaft corresponding to gear 001.	1 to 32767	1
3231 (PR)	SP031	GRB3	Motor shaft gear teeth count 3	Set the number of gear teeth of the motor shaft corresponding to gear 010.	1 to 32767	1
3232 (PR)	SP032	GRB4	Motor shaft gear teeth count 4	Set the number of gear teeth of the motor shaft corresponding to gear 011.	1 to 32767	1

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting																																																																																																												
3233 (PR)	SP033	SFNC1 Spindle function 1	<p>Set the spindle function 1 in bit units.</p> <table border="1" style="width:100%; text-align:center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td>poff</td><td>hzs</td><td></td><td>ront</td><td></td><td></td><td></td><td></td> </tr> <tr> <td colspan="8"> </td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td></td><td></td><td></td><td></td><td></td><td>sftk</td><td>dflt</td><td>1a2m</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>1a2m</td> <td>1 amplifier 2 motor function: Invalid</td> <td>1 amplifier 2 motor function: Valid</td> </tr> <tr> <td>1</td> <td>dflt</td> <td>Default motor: Main</td> <td>Default motor: Sub</td> </tr> <tr> <td>2</td> <td>sftk</td> <td>SF-TK card invalid</td> <td>SF-TK card valid</td> </tr> <tr><td>3</td><td></td><td></td><td></td></tr> <tr><td>4</td><td></td><td></td><td></td></tr> <tr><td>5</td><td></td><td></td><td></td></tr> <tr><td>6</td><td></td><td></td><td></td></tr> <tr><td>7</td><td></td><td></td><td></td></tr> <tr><td>8</td><td></td><td></td><td></td></tr> <tr><td>9</td><td></td><td></td><td></td></tr> <tr><td>A</td><td></td><td></td><td></td></tr> <tr> <td>B</td> <td></td> <td colspan="2">This is a fixed control bit.</td> </tr> <tr><td>C</td><td>ront</td><td></td><td></td></tr> <tr><td>D</td><td></td><td></td><td></td></tr> <tr><td>E</td><td>hzs</td><td></td><td></td></tr> <tr><td>F</td><td>poff</td><td></td><td></td></tr> </tbody> </table>	F	E	D	C	B	A	9	8	poff	hzs		ront													7	6	5	4	3	2	1	0						sftk	dflt	1a2m	bit	Name	Meaning when set to 0	Meaning when set to 1	0	1a2m	1 amplifier 2 motor function: Invalid	1 amplifier 2 motor function: Valid	1	dflt	Default motor: Main	Default motor: Sub	2	sftk	SF-TK card invalid	SF-TK card valid	3				4				5				6				7				8				9				A				B		This is a fixed control bit.		C	ront			D				E	hzs			F	poff			0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																										
poff	hzs		ront																																																																																																														
7	6	5	4	3	2	1	0																																																																																																										
					sftk	dflt	1a2m																																																																																																										
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																														
0	1a2m	1 amplifier 2 motor function: Invalid	1 amplifier 2 motor function: Valid																																																																																																														
1	dflt	Default motor: Main	Default motor: Sub																																																																																																														
2	sftk	SF-TK card invalid	SF-TK card valid																																																																																																														
3																																																																																																																	
4																																																																																																																	
5																																																																																																																	
6																																																																																																																	
7																																																																																																																	
8																																																																																																																	
9																																																																																																																	
A																																																																																																																	
B		This is a fixed control bit.																																																																																																															
C	ront																																																																																																																
D																																																																																																																	
E	hzs																																																																																																																
F	poff																																																																																																																
3234 (PR)	SP034	SFNC2 Spindle function 2	<p>Set the spindle function 2 in bit units.</p> <table border="1" style="width:100%; text-align:center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td> </tr> <tr> <td colspan="8"> </td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>mts1</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>mts1</td> <td>Special motor constant invalid</td> <td>Special motor constant setting valid</td> </tr> <tr><td>1</td><td></td><td></td><td></td></tr> <tr><td>2</td><td></td><td></td><td></td></tr> <tr><td>3</td><td></td><td></td><td></td></tr> <tr><td>4</td><td></td><td></td><td></td></tr> <tr><td>5</td><td></td><td></td><td></td></tr> <tr><td>6</td><td></td><td></td><td></td></tr> <tr><td>7</td><td></td><td></td><td></td></tr> <tr><td>8</td><td></td><td></td><td></td></tr> <tr><td>9</td><td></td><td></td><td></td></tr> <tr><td>A</td><td></td><td></td><td></td></tr> <tr><td>B</td><td></td><td></td><td></td></tr> <tr><td>C</td><td></td><td></td><td></td></tr> <tr><td>D</td><td></td><td></td><td></td></tr> <tr><td>E</td><td></td><td></td><td></td></tr> <tr><td>F</td><td></td><td></td><td></td></tr> </tbody> </table> <p>(Note1) To validate bit3(mkc2), NC side needs to prepare.</p> <p>(Note1) Always turn the bit2 at the same time to use bit3.</p>	F	E	D	C	B	A	9	8																	7	6	5	4	3	2	1	0								mts1	bit	Name	Meaning when set to 0	Meaning when set to 1	0	mts1	Special motor constant invalid	Special motor constant setting valid	1				2				3				4				5				6				7				8				9				A				B				C				D				E				F				0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																										
7	6	5	4	3	2	1	0																																																																																																										
							mts1																																																																																																										
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																														
0	mts1	Special motor constant invalid	Special motor constant setting valid																																																																																																														
1																																																																																																																	
2																																																																																																																	
3																																																																																																																	
4																																																																																																																	
5																																																																																																																	
6																																																																																																																	
7																																																																																																																	
8																																																																																																																	
9																																																																																																																	
A																																																																																																																	
B																																																																																																																	
C																																																																																																																	
D																																																																																																																	
E																																																																																																																	
F																																																																																																																	

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting																																																																																																												
3235 (PR)	SP035	SFNC3 Spindle function3	Set the spindle function 3 in bit units. <table border="1" style="width:100%; text-align:center; border-collapse: collapse;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;"></td> </tr> <tr> <td colspan="7"></td> <td></td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;">hbsd</td><td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;">hwid</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>hwid</td> <td>H-coil wide-range constant output invalid</td> <td>H-coil wide-range constant output valid</td> </tr> <tr> <td>1</td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>hbsd</td> <td>H-coil base slide invalid</td> <td>H-coil base slide valid</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> <td></td> </tr> <tr> <td>8</td> <td></td> <td></td> <td></td> </tr> <tr> <td>9</td> <td></td> <td></td> <td></td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> <td></td> </tr> <tr> <td>D</td> <td></td> <td></td> <td></td> </tr> <tr> <td>E</td> <td></td> <td></td> <td></td> </tr> <tr> <td>F</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8																	7	6	5	4	3	2	1	0						hbsd		hwid	bit	Name	Meaning when set to 0	Meaning when set to 1	0	hwid	H-coil wide-range constant output invalid	H-coil wide-range constant output valid	1				2	hbsd	H-coil base slide invalid	H-coil base slide valid	3				4				5				6				7				8				9				A				B				C				D				E				F				0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																										
7	6	5	4	3	2	1	0																																																																																																										
					hbsd		hwid																																																																																																										
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																														
0	hwid	H-coil wide-range constant output invalid	H-coil wide-range constant output valid																																																																																																														
1																																																																																																																	
2	hbsd	H-coil base slide invalid	H-coil base slide valid																																																																																																														
3																																																																																																																	
4																																																																																																																	
5																																																																																																																	
6																																																																																																																	
7																																																																																																																	
8																																																																																																																	
9																																																																																																																	
A																																																																																																																	
B																																																																																																																	
C																																																																																																																	
D																																																																																																																	
E																																																																																																																	
F																																																																																																																	
3236 (PR)	SP036	SFNC4 Spindle function 4	Set the spindle function 4 in bit units. <table border="1" style="width:100%; text-align:center; border-collapse: collapse;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;">dslm</td><td style="width:20px; height:20px;">dssm</td> </tr> <tr> <td colspan="7"></td> <td></td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;">enc2</td><td style="width:20px; height:20px;">enc1</td><td style="width:20px; height:20px;">mag2</td><td style="width:20px; height:20px;">mag1</td><td style="width:20px; height:20px;">plg2</td><td style="width:20px; height:20px;">plg1</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>plg1</td> <td>PLG of motor 1 valid</td> <td>PLG of motor 1 invalid</td> </tr> <tr> <td>1</td> <td>plg2</td> <td>PLG of motor 2 valid</td> <td>PLG of motor 2 invalid</td> </tr> <tr> <td>2</td> <td>mag1</td> <td>MAG of motor 1 valid</td> <td>MAG of motor 1 invalid</td> </tr> <tr> <td>3</td> <td>mag2</td> <td>MAG of motor 2 valid</td> <td>MAG of motor 2 invalid</td> </tr> <tr> <td>4</td> <td>enc1</td> <td>ENC of motor 1 valid</td> <td>ENC of motor 1 invalid</td> </tr> <tr> <td>5</td> <td>enc2</td> <td>ENC of motor 2 valid</td> <td>ENC of motor 2 invalid</td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> <td></td> </tr> <tr> <td>8</td> <td>dssm</td> <td>Speedometer valid</td> <td>Speedometer invalid</td> </tr> <tr> <td>9</td> <td>dslm</td> <td>Load meter valid</td> <td>Load meter invalid</td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> <td></td> </tr> <tr> <td>D</td> <td></td> <td></td> <td></td> </tr> <tr> <td>E</td> <td></td> <td></td> <td></td> </tr> <tr> <td>F</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8							dslm	dssm									7	6	5	4	3	2	1	0			enc2	enc1	mag2	mag1	plg2	plg1	bit	Name	Meaning when set to 0	Meaning when set to 1	0	plg1	PLG of motor 1 valid	PLG of motor 1 invalid	1	plg2	PLG of motor 2 valid	PLG of motor 2 invalid	2	mag1	MAG of motor 1 valid	MAG of motor 1 invalid	3	mag2	MAG of motor 2 valid	MAG of motor 2 invalid	4	enc1	ENC of motor 1 valid	ENC of motor 1 invalid	5	enc2	ENC of motor 2 valid	ENC of motor 2 invalid	6				7				8	dssm	Speedometer valid	Speedometer invalid	9	dslm	Load meter valid	Load meter invalid	A				B				C				D				E				F					
F	E	D	C	B	A	9	8																																																																																																										
						dslm	dssm																																																																																																										
7	6	5	4	3	2	1	0																																																																																																										
		enc2	enc1	mag2	mag1	plg2	plg1																																																																																																										
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																														
0	plg1	PLG of motor 1 valid	PLG of motor 1 invalid																																																																																																														
1	plg2	PLG of motor 2 valid	PLG of motor 2 invalid																																																																																																														
2	mag1	MAG of motor 1 valid	MAG of motor 1 invalid																																																																																																														
3	mag2	MAG of motor 2 valid	MAG of motor 2 invalid																																																																																																														
4	enc1	ENC of motor 1 valid	ENC of motor 1 invalid																																																																																																														
5	enc2	ENC of motor 2 valid	ENC of motor 2 invalid																																																																																																														
6																																																																																																																	
7																																																																																																																	
8	dssm	Speedometer valid	Speedometer invalid																																																																																																														
9	dslm	Load meter valid	Load meter invalid																																																																																																														
A																																																																																																																	
B																																																																																																																	
C																																																																																																																	
D																																																																																																																	
E																																																																																																																	
F																																																																																																																	

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting																																																																																																				
3237 (PR)	SP037	SFNC5 Spindle function 5	<p>Set the spindle function 5 in bit units.</p> <table border="1" style="width:100%; text-align:center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>nstv</td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td></td><td></td><td></td><td></td><td></td><td>plgo</td><td></td><td>enco</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>enco</td> <td>Encoder orientation invalid</td> <td>Encoder orientation valid</td> </tr> <tr> <td>1</td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>plgo</td> <td>PLG orientation invalid</td> <td>PLG orientation valid</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> <td></td> </tr> <tr> <td>8</td> <td>nstv</td> <td>No-signal detection type (Always monitoring)</td> <td>Monitoring only in position loop or orientation-mode</td> </tr> <tr> <td>9</td> <td></td> <td></td> <td></td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> <td></td> </tr> <tr> <td>D</td> <td></td> <td></td> <td></td> </tr> <tr> <td>E</td> <td></td> <td></td> <td></td> </tr> <tr> <td>F</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8								nstv	7	6	5	4	3	2	1	0						plgo		enco	bit	Name	Meaning when set to 0	Meaning when set to 1	0	enco	Encoder orientation invalid	Encoder orientation valid	1				2	plgo	PLG orientation invalid	PLG orientation valid	3				4				5				6				7				8	nstv	No-signal detection type (Always monitoring)	Monitoring only in position loop or orientation-mode	9				A				B				C				D				E				F				0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																		
							nstv																																																																																																		
7	6	5	4	3	2	1	0																																																																																																		
					plgo		enco																																																																																																		
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																						
0	enco	Encoder orientation invalid	Encoder orientation valid																																																																																																						
1																																																																																																									
2	plgo	PLG orientation invalid	PLG orientation valid																																																																																																						
3																																																																																																									
4																																																																																																									
5																																																																																																									
6																																																																																																									
7																																																																																																									
8	nstv	No-signal detection type (Always monitoring)	Monitoring only in position loop or orientation-mode																																																																																																						
9																																																																																																									
A																																																																																																									
B																																																																																																									
C																																																																																																									
D																																																																																																									
E																																																																																																									
F																																																																																																									
3238 (PR)	SP038	SFNC6 Spindle function 6	<p>Set the spindle function 6 in bit units.</p> <table border="1" style="width:100%; text-align:center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td>oplp</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td></td><td></td><td></td><td></td><td></td><td>pftm</td><td></td><td>alty</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>alty</td> <td>Deceleration stop during special alarm invalid</td> <td>Deceleration stop during special alarm valid</td> </tr> <tr> <td>1</td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>pftm</td> <td>Thread cutting position data invalid</td> <td>Thread cutting position data valid</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> <td></td> </tr> <tr> <td>8</td> <td></td> <td></td> <td></td> </tr> <tr> <td>9</td> <td></td> <td></td> <td></td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> <td></td> </tr> <tr> <td>D</td> <td></td> <td></td> <td></td> </tr> <tr> <td>E</td> <td></td> <td></td> <td></td> </tr> <tr> <td>F</td> <td>oplp</td> <td>Open loop operation invalid</td> <td>Open loop operation valid</td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8	oplp								7	6	5	4	3	2	1	0						pftm		alty	bit	Name	Meaning when set to 0	Meaning when set to 1	0	alty	Deceleration stop during special alarm invalid	Deceleration stop during special alarm valid	1				2	pftm	Thread cutting position data invalid	Thread cutting position data valid	3				4				5				6				7				8				9				A				B				C				D				E				F	oplp	Open loop operation invalid	Open loop operation valid	0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																		
oplp																																																																																																									
7	6	5	4	3	2	1	0																																																																																																		
					pftm		alty																																																																																																		
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																						
0	alty	Deceleration stop during special alarm invalid	Deceleration stop during special alarm valid																																																																																																						
1																																																																																																									
2	pftm	Thread cutting position data invalid	Thread cutting position data valid																																																																																																						
3																																																																																																									
4																																																																																																									
5																																																																																																									
6																																																																																																									
7																																																																																																									
8																																																																																																									
9																																																																																																									
A																																																																																																									
B																																																																																																									
C																																																																																																									
D																																																																																																									
E																																																																																																									
F	oplp	Open loop operation invalid	Open loop operation valid																																																																																																						


8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting																																												
3239 (PR)	SP039	ATYP Amplifier type	Set the amplifier type. Set each amplifier type or "0". This parameter corresponds to MDS-B-SPJ2. <table border="1" data-bbox="660 539 1118 909"> <thead> <tr> <th>Parameter setting</th> <th>Amplifier type</th> </tr> </thead> <tbody> <tr><td>0000</td><td>--</td></tr> <tr><td>0001</td><td>SPJ2-02</td></tr> <tr><td>0002</td><td>SPJ2-04</td></tr> <tr><td>0003</td><td>SPJ2-075</td></tr> <tr><td>0004</td><td>SPJ2-15</td></tr> <tr><td>0005</td><td>SPJ2-22</td></tr> <tr><td>0006</td><td>SPJ2-37</td></tr> <tr><td>0007</td><td>SPJ2-55</td></tr> <tr><td>0008</td><td>SPJ2-75</td></tr> <tr><td>0009</td><td>SPJ2-110/110C</td></tr> </tbody> </table>	Parameter setting	Amplifier type	0000	--	0001	SPJ2-02	0002	SPJ2-04	0003	SPJ2-075	0004	SPJ2-15	0005	SPJ2-22	0006	SPJ2-37	0007	SPJ2-55	0008	SPJ2-75	0009	SPJ2-110/110C	0000 to FFFF HEX setting	0000																						
Parameter setting	Amplifier type																																																
0000	--																																																
0001	SPJ2-02																																																
0002	SPJ2-04																																																
0003	SPJ2-075																																																
0004	SPJ2-15																																																
0005	SPJ2-22																																																
0006	SPJ2-37																																																
0007	SPJ2-55																																																
0008	SPJ2-75																																																
0009	SPJ2-110/110C																																																
3240 (PR)	SP040	MTYP Motor type	This is valid when SP034 (SFNC2) bit 0 is set to 0. Refer to the following standard motors, and set the applicable motor number. <table border="1" data-bbox="644 1099 1169 1435"> <thead> <tr> <th>Parameter setting</th> <th>Motor type</th> <th>Maximum speed</th> <th>Corresponding amplifier</th> </tr> </thead> <tbody> <tr><td>1000</td><td></td><td></td><td></td></tr> <tr><td>1001</td><td>SJ-P0.2A</td><td>10000 r/min</td><td>SPJ2-02</td></tr> <tr><td>1002</td><td>SJ-P0.4A</td><td>10000 r/min</td><td>SPJ2-04</td></tr> <tr><td>1003</td><td>SJ-P0.75A</td><td>10000 r/min</td><td>SPJ2-075</td></tr> <tr><td>1004</td><td>SJ-P1.5A</td><td>10000 r/min</td><td>SPJ2-15</td></tr> <tr><td>1005</td><td>SJ-P2.2A</td><td>8000 r/min</td><td>SPJ2-22</td></tr> <tr><td>1006</td><td>SJ-P3.7A</td><td>8000 r/min</td><td>SPJ2-37</td></tr> <tr><td>1007</td><td>SJ-PF5.5-01</td><td>8000 r/min</td><td>SPJ2-55</td></tr> <tr><td>1008</td><td>SJ-PF7.5-01</td><td>8000 r/min</td><td>SPJ2-75</td></tr> <tr><td>1009</td><td>SJ-PF11-01</td><td>6000 r/min</td><td>SPJ2-110/110C</td></tr> </tbody> </table>	Parameter setting	Motor type	Maximum speed	Corresponding amplifier	1000				1001	SJ-P0.2A	10000 r/min	SPJ2-02	1002	SJ-P0.4A	10000 r/min	SPJ2-04	1003	SJ-P0.75A	10000 r/min	SPJ2-075	1004	SJ-P1.5A	10000 r/min	SPJ2-15	1005	SJ-P2.2A	8000 r/min	SPJ2-22	1006	SJ-P3.7A	8000 r/min	SPJ2-37	1007	SJ-PF5.5-01	8000 r/min	SPJ2-55	1008	SJ-PF7.5-01	8000 r/min	SPJ2-75	1009	SJ-PF11-01	6000 r/min	SPJ2-110/110C	0000 to FFFF HEX setting	0000
Parameter setting	Motor type	Maximum speed	Corresponding amplifier																																														
1000																																																	
1001	SJ-P0.2A	10000 r/min	SPJ2-02																																														
1002	SJ-P0.4A	10000 r/min	SPJ2-04																																														
1003	SJ-P0.75A	10000 r/min	SPJ2-075																																														
1004	SJ-P1.5A	10000 r/min	SPJ2-15																																														
1005	SJ-P2.2A	8000 r/min	SPJ2-22																																														
1006	SJ-P3.7A	8000 r/min	SPJ2-37																																														
1007	SJ-PF5.5-01	8000 r/min	SPJ2-55																																														
1008	SJ-PF7.5-01	8000 r/min	SPJ2-75																																														
1009	SJ-PF11-01	6000 r/min	SPJ2-110/110C																																														

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting																																																													
3241 (PR)	SP041	PTYP	Power supply type	<p>When this unit is a signal connection axis with power supply unit, set this parameter. Set "0" for this parameter for the unit which is not a signal connection axis.</p> <p>Select a value from the following table according to the regenerative resistance being used.</p> <table border="1"> <thead> <tr> <th>Setting value</th> <th>Regenerative resistance type</th> <th>Resistance value (Ω)</th> <th>Capacity (W)</th> </tr> </thead> <tbody> <tr><td>0000</td><td>—</td><td>—</td><td>—</td></tr> <tr><td>2000</td><td>Not connected</td><td>—</td><td>—</td></tr> <tr><td>2100</td><td>FCUA-RB04</td><td>200</td><td>60</td></tr> <tr><td>2200</td><td>FCUA-RB075</td><td>100</td><td>80</td></tr> <tr><td>2300</td><td>FCUA-RB15</td><td>60</td><td>120</td></tr> <tr><td>2400</td><td>FCUA-RB22</td><td>40</td><td>155</td></tr> <tr><td>2500</td><td>FCUA-RB37</td><td>25</td><td>185</td></tr> <tr><td>2600</td><td>FCUA-RB55</td><td>20</td><td>340</td></tr> <tr><td>2700</td><td>FCUA-RB75/2</td><td>30/15</td><td>340/680</td></tr> <tr><td>2800</td><td>R-UNIT-1</td><td>30</td><td>700</td></tr> <tr><td>2900</td><td>R-UNIT-2</td><td>15</td><td>700</td></tr> <tr><td>2A00</td><td>R-UNIT-3</td><td>15</td><td>2100</td></tr> <tr><td>2B00</td><td>R-UNIT-4</td><td>10</td><td>2100</td></tr> <tr><td>2C00</td><td>R-UNIT-5</td><td>10</td><td>3100</td></tr> </tbody> </table> <p>(Note 1) This setting is used when using one FCUA-RB75/2 and when using two in parallel.</p>	Setting value	Regenerative resistance type	Resistance value (Ω)	Capacity (W)	0000	—	—	—	2000	Not connected	—	—	2100	FCUA-RB04	200	60	2200	FCUA-RB075	100	80	2300	FCUA-RB15	60	120	2400	FCUA-RB22	40	155	2500	FCUA-RB37	25	185	2600	FCUA-RB55	20	340	2700	FCUA-RB75/2	30/15	340/680	2800	R-UNIT-1	30	700	2900	R-UNIT-2	15	700	2A00	R-UNIT-3	15	2100	2B00	R-UNIT-4	10	2100	2C00	R-UNIT-5	10	3100	0000 to FFFF HEX setting	0000
Setting value	Regenerative resistance type	Resistance value (Ω)	Capacity (W)																																																															
0000	—	—	—																																																															
2000	Not connected	—	—																																																															
2100	FCUA-RB04	200	60																																																															
2200	FCUA-RB075	100	80																																																															
2300	FCUA-RB15	60	120																																																															
2400	FCUA-RB22	40	155																																																															
2500	FCUA-RB37	25	185																																																															
2600	FCUA-RB55	20	340																																																															
2700	FCUA-RB75/2	30/15	340/680																																																															
2800	R-UNIT-1	30	700																																																															
2900	R-UNIT-2	15	700																																																															
2A00	R-UNIT-3	15	2100																																																															
2B00	R-UNIT-4	10	2100																																																															
2C00	R-UNIT-5	10	3100																																																															
3242 (PR)	SP042			Not used. Set to "0".	0	0																																																												
3243 (PR)	SP043			Not used. Set to "0".	0	0																																																												
3244 (PR)	SP044	TRANS	NC communication frequency	Set a frequency of data communication with NC.	0 to 32767	Standard: 0 Special: 1028																																																												
3245	SP045			Not used. Set to "0".	0	0																																																												
3246 (PR)	SP046	CSN2	Speed command dual cushion	<p>For an acceleration/deceleration time constant defined in SP019 (CSN1), this parameter is used to provide smooth movement only at the start of acceleration/deceleration.</p> <p>As the value of this parameter is smaller, it moves smoother but the acceleration/deceleration time becomes longer.</p> <p>To make this parameter invalid, set "0".</p>	0 to 1000	0																																																												
3247 (PR)	SP047	SDTR	Speed detection reset value	Set the reset hysteresis width for a speed detection set value defined in SP020 (SDTS).	0 to 1000 (r/min)	30																																																												

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting
3248 (PR)	SP048	SUT	Speed reach range	Set the speed deviation rate with respect to the commanded speed for output of the speed reach signal.	0 to 100 (%) 15
3249	SP049	TLM2	Torque limit 2	Set the torque limit rate for the torque limit signal 010.	1 to 120 (%) 20
3250	SP050	TLM3	Torque limit 3	Set the torque limit rate for the torque limit signal 011.	1 to 120 (%) 30
3251	SP051	TLM4	Torque limit 4	Set the torque limit rate for the torque limit signal 100.	1 to 120 (%) 40
3252	SP052	TLM5	Torque limit 5	Set the torque limit rate for the torque limit signal 101.	1 to 120 (%) 50
3253	SP053	TLM6	Torque limit 6	Set the torque limit rate for the torque limit signal 110.	1 to 120 (%) 60
3254	SP054	TLM7	Torque limit 7	Set the torque limit rate for the torque limit signal 111.	1 to 120 (%) 70
3255 (PR)	SP055	SETM	Excessive speed deviation timer	Set the timer value until the excessive speed deviation alarm is output. The value of this parameter should be longer than the acceleration/deceleration time.	0 to 60 (s) 12
3256	SP056	PYVR	Variable excitation (min value)	Set the minimum value of the variable excitation rate. Select a smaller value when gear noise is too high. However, a larger value is effective for impact response.	0 to 100 (%) 50
3257 (PR)	SP057	STOD	Fixed control constant	Set by Mitsubishi. Set "0" unless designated in particular.	0 0
3258 to 3262	SP058 to SP062			Not used. Set to "0".	0 0
3263 (PR)	SP063	OLT	Overload alarm detection time	Set the time constant for detection of the motor overload alarm.	0 to 1000 (s) 60
3264 (PR)	SP064	OLL	Overload alarm detection level	Set the detection level of the motor overload alarm.	0 to 120 (%) 110
3265 (PR)	SP065	VCGN1	Target value of variable speed loop proportional gain	Set the magnification of speed loop proportional gain with respect to SP022 (VGNP1) at the maximum motor speed defined in SP017 (TSP).	0 to 100 (%) 100
3266 (PR)	SP066	VCSN1	Change starting speed of variable speed loop proportional gain	Set the speed for starting change of speed loop proportional gain. 	0 to 32767 (r/min) 0

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting																	
3267 (PR)	SP067	VIGWA	Change starting speed of variable current loop gain	Set the speed for starting change of current loop gain.	0 to 32767 (r/min)	0																
3268 (PR)	SP068	VIGWB	Change ending speed of variable current loop gain	Set the speed for ending change of current loop gain.	0 to 32767 (r/min)	0																
3269 (PR)	SP069	VIGN	Target value of variable current loop gain	Set the magnification of current loop gain (torque component and excitation component) for a change ending speed defined in SP068 (VIGWB). When this parameter is set to "0", the magnification is 1. <div style="text-align: center;"> <p>Gain</p> <p>SP069x(1/16)-fold</p> <p>1-fold</p> <p>Speed</p> <p>SP067 SP068 SP017</p> </div> <table border="1" style="margin-left: auto; margin-right: auto;"> <thead> <tr> <th>SP017 (TSP) Maximum motor speed</th> <th>SP067 (VIGWA)</th> <th>SP068 (VIGWB)</th> <th>SP069 (VIGN)</th> </tr> </thead> <tbody> <tr> <td>0 to 6000</td> <td>0</td> <td>0</td> <td>0</td> </tr> <tr> <td>6001 to 8000</td> <td>5000</td> <td>8000</td> <td>45</td> </tr> <tr> <td>8001 or more</td> <td>5000</td> <td>10000</td> <td>64</td> </tr> </tbody> </table>	SP017 (TSP) Maximum motor speed	SP067 (VIGWA)	SP068 (VIGWB)	SP069 (VIGN)	0 to 6000	0	0	0	6001 to 8000	5000	8000	45	8001 or more	5000	10000	64	0 to 32767 (1/16-fold)	0
SP017 (TSP) Maximum motor speed	SP067 (VIGWA)	SP068 (VIGWB)	SP069 (VIGN)																			
0 to 6000	0	0	0																			
6001 to 8000	5000	8000	45																			
8001 or more	5000	10000	64																			
3270	SP070			Not used. Set to "0".	0	0																
3271 (PR)	SP071	VR2WA	Fixed control constant	Set by Mitsubishi. Set "0" unless designated in particular.	0	0																
3272 (PR)	SP072	VR2WB																				
3273 (PR)	SP073	VR2GN																				
3274 (PR)	SP074	IGDEC																				
3275	SP075	R2KWS																				

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting	
3276	SP076			Not used. Set to "0".	0	0
3277	SP077	TDSL	Fixed control constant	Set by Mitsubishi. Set "0" unless designated in particular.	0	0
3278 (PR)	SP078	FPWM				
3279 (PR)	SP079	ILMT				
3280	SP080					
3281	SP081	LMCA				
3282	SP082	LMCB				
3283 to 3286	SP083 to SP086			Not used. Set to "0".	0	0
3287 (PR)	SP087	DIQM	Target value of variable torque limit magnification at deceleration	Set the minimum value of variable torque limit at deceleration.	0 to 150 (%)	75
3288 (PR)	SP088	DIQN	Speed for starting change of variable torque limit magnification at deceleration	Set the speed for starting change of torque limit value at deceleration.	0 to 32767 (r/min)	3000
				<p>The graph plots Torque limit (Y-axis) against Speed (X-axis). The torque limit starts at 100% and remains constant until speed SP088. After SP088, the torque limit decreases, labeled as 'Inversely proportional to speed'. It reaches a value SP087 at speed SP017 and remains constant thereafter.</p>		
3289 to 3292	SP089 to SP092			Not used. Set to "0".	0	0
3293 (PR)	SP093	ORE	Fixed control constant	Set by Mitsubishi. Set "0" unless designated in particular.	0	0
3294 (PR)	SP094			Not used. Set to "0".	0	0
3295 (PR)	SP095	VFAV	Fixed control constant	Set by Mitsubishi. Set "0" unless designated in particular.	0	0

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting																																																																																																													
3296 (PR)	SP096	EGAR	Encoder gear ratio	Set the gear ratio between the spindle end and the encoder end (except for the motor-built-in encoder) as indicated below.	-3 to 4	0																																																																																																												
				<table border="1"> <thead> <tr> <th>Setting value</th> <th>Gear ratio (deceleration)</th> <th>Setting value</th> <th>Gear ratio (Acceleration)</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>1 : 1</td> <td>-1</td> <td>1 : 2</td> </tr> <tr> <td>1</td> <td>1 : 1/2</td> <td>-2</td> <td>1 : 4</td> </tr> <tr> <td>2</td> <td>1 : 1/4</td> <td>-3</td> <td>1 : 3</td> </tr> <tr> <td>3</td> <td>1 : 1/8</td> <td></td> <td></td> </tr> <tr> <td>4</td> <td>1 : 1/16</td> <td></td> <td></td> </tr> </tbody> </table>	Setting value	Gear ratio (deceleration)	Setting value	Gear ratio (Acceleration)	0	1 : 1	-1	1 : 2	1	1 : 1/2	-2	1 : 4	2	1 : 1/4	-3	1 : 3	3	1 : 1/8			4	1 : 1/16																																																																																								
Setting value	Gear ratio (deceleration)	Setting value	Gear ratio (Acceleration)																																																																																																															
0	1 : 1	-1	1 : 2																																																																																																															
1	1 : 1/2	-2	1 : 4																																																																																																															
2	1 : 1/4	-3	1 : 3																																																																																																															
3	1 : 1/8																																																																																																																	
4	1 : 1/16																																																																																																																	
3297 (PR)	SP097	SPECO	Orientation specification	Set the orientation specifications in bit units.	0000 to FFFF HEX setting	0000																																																																																																												
				<table border="1"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>tlet</td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td></td><td></td><td>fdir</td><td></td><td>pyfx</td><td>dmin</td><td>odi2</td><td>odi1</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>odi1</td> <td colspan="2">Orientation rotation direction</td> </tr> <tr> <td rowspan="3">1</td> <td rowspan="3">odi2</td> <td>00:</td> <td>Previous (the direction in which the motor has so far rotated under speed control)</td> </tr> <tr> <td>01:</td> <td>Forward rotation</td> </tr> <tr> <td>10:</td> <td>Backward rotation</td> </tr> <tr> <td></td> <td></td> <td>11:</td> <td>Prohibited (Same as setting value = 10)</td> </tr> <tr> <td>2</td> <td>dmin</td> <td>Dummy in-position invalid</td> <td>Dummy in-position valid</td> </tr> <tr> <td>3</td> <td>pyfx</td> <td>Excitation min. (50%) during orientation servo lock invalid</td> <td>Excitation min. (50%) during orientation servo lock valid</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td>fdir</td> <td>Encoder detector polarity: +</td> <td>Encoder detector polarity: -</td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> <td></td> </tr> <tr> <td>8</td> <td>tlet</td> <td>Turret indexing invalid</td> <td>Turret indexing valid</td> </tr> <tr> <td>9</td> <td></td> <td></td> <td></td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> <td></td> </tr> <tr> <td>D</td> <td></td> <td></td> <td></td> </tr> <tr> <td>E</td> <td></td> <td></td> <td></td> </tr> <tr> <td>F</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8								tlet	7	6	5	4	3	2	1	0			fdir		pyfx	dmin	odi2	odi1	bit	Name	Meaning when set to 0	Meaning when set to 1	0	odi1	Orientation rotation direction		1	odi2	00:	Previous (the direction in which the motor has so far rotated under speed control)	01:	Forward rotation	10:	Backward rotation			11:	Prohibited (Same as setting value = 10)	2	dmin	Dummy in-position invalid	Dummy in-position valid	3	pyfx	Excitation min. (50%) during orientation servo lock invalid	Excitation min. (50%) during orientation servo lock valid	4				5	fdir	Encoder detector polarity: +	Encoder detector polarity: -	6				7				8	tlet	Turret indexing invalid	Turret indexing valid	9				A				B				C				D				E				F					
F	E	D	C	B	A	9	8																																																																																																											
							tlet																																																																																																											
7	6	5	4	3	2	1	0																																																																																																											
		fdir		pyfx	dmin	odi2	odi1																																																																																																											
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																															
0	odi1	Orientation rotation direction																																																																																																																
1	odi2	00:	Previous (the direction in which the motor has so far rotated under speed control)																																																																																																															
		01:	Forward rotation																																																																																																															
		10:	Backward rotation																																																																																																															
		11:	Prohibited (Same as setting value = 10)																																																																																																															
2	dmin	Dummy in-position invalid	Dummy in-position valid																																																																																																															
3	pyfx	Excitation min. (50%) during orientation servo lock invalid	Excitation min. (50%) during orientation servo lock valid																																																																																																															
4																																																																																																																		
5	fdir	Encoder detector polarity: +	Encoder detector polarity: -																																																																																																															
6																																																																																																																		
7																																																																																																																		
8	tlet	Turret indexing invalid	Turret indexing valid																																																																																																															
9																																																																																																																		
A																																																																																																																		
B																																																																																																																		
C																																																																																																																		
D																																																																																																																		
E																																																																																																																		
F																																																																																																																		
3298 (PR)	SP098	VGOP	Speed loop gain proportional term in orientation mode	Set the speed loop proportional gain in orientation mode. When the gain is increased, rigidity is improved in the orientation stop but vibration and sound become larger.	0 to 1000 (1/s)																																																																																																													
3299 (PR)	SP099	VGOI	Orientation mode speed loop gain integral term	Set the speed loop integral gain in orientation mode.	0 to 1000 (0.1 1/s)	60																																																																																																												
3300 (PR)	SP100	VGOD	Orientation mode speed loop gain delay advance term	Set the a loop gain delay advance gain in orientation mode. When this parameter is set to "0", PI control is exercised.	0 to 1000 (0.1 1/s)	15																																																																																																												

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting	
3301 (PR)	SP101	DINP	Orientation advance in-position width	When using the orientation in-position advance function, set the in-position width that is larger than the normal in-position width defined in SP004 (OINP).	1 to 2880 (1/16°)	16
3302 (PR)	SP102	OODR	Excessive error value in orientation mode	Set the excessive error width in orientation mode.	1 to 32767 (1/4 pulse) (1 pulse= 0.088°)	32767
3303 (PR)	SP103	FTM	Index positioning completion OFF time timer	Set the time for forcedly turn OFF the index positioning completion signal (different from the orientation completion signal) after the leading edge of the indexing start signal.	1 to 10000 (ms)	200
3304 (PR)	SP104	TLOR	Torque limit value for orientation servo locking	Set the torque limit value for orientation in-position output. If the external torque limit signal is input the torque limit value set by this parameter is made invalid.	1 to 120 (%)	100
3305 (PR)	SP105	IQG0	Current loop gain magnification 1 in orientation mode	Set the magnification for current loop gain (torque component) at orientation completion.	1 to 1000 (%)	100
3306	SP106	IDG0	Current loop gain magnification 2 in orientation mode	Set the magnification for current loop gain (excitation component) at orientation completion.	1 to 1000 (%)	100
3307	SP107	CSP2	Deceleration rate 2 in orientation mode	Set the deceleration rate in orientation mode corresponding to the gear 001. When this parameter is set to "0", same as SP006 (CSP).	0 to 1000	0
3308	SP108	CSP3	Deceleration rate 3 in orientation mode	Set the deceleration rate in orientation mode corresponding to the gear 010. When this parameter is set to "0", same as SP006 (CSP).	0 to 1000	0
3309 (PR)	SP109	CSP4	Deceleration rate 4 in orientation mode	Set the deceleration rate in orientation mode corresponding to the gear 011. When this parameter is set to "0", same as SP006 (CSP).	0 to 1000	0
3310 (PR)	SP110	WCML	Turret index command magnification	The integer magnification (gear ratio 1 : N) for the index position command (0 to 359) is set.	0 to 32767 (fold)	0
3311	SP111	WDEL	Turret index deceleration magnification	The magnification for the orientation deceleration rate is set using 256 as 1.	0 to 32767 (1/256 -fold)	0
3312	SP112	WCLP	Turret index clamp speed	The max. speed during indexing is set. This becomes the max. speed of the motor when set to "0".	0 to 32767 (r/min)	0


8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting	
3313 (PR)	SP113	WINP	Turret index in-position width	The position error range is set in which an orientation (indexing) completed signal is output during turret indexing. This becomes the same as SP004 (OINP) when set to "0".	0 to 32767 (1/16°)	0
3314	SP114	OPER	Orientation pulse miss check value	An alarm "5C" will occur if the pulse miss value in the orientation stop exceed this setting value. (Note that this is invalid when set to "0".) In this parameter, set the value to fulfill the following conditions. SP114 setting value > 1.5 × SP004 (orientation in-position width)	0 to 32767 (360°/4096)	0
3315	SP115	OSP2	Orientation changeover speed limit value 2	When the door interlock spindle speed clamp signal is ON, this setting is used instead of OSP(SP005), CZRN(SP149) and TZRN(SP214). (Note that SP149 and SP214 are used only for the M65V.)	0 to 32767 (r/min)	0
3316	SP116	OPYVR	Fixed control constants	Set by Mitsubishi. Set "0" unless designated in particular.	0	0
3317	SP117	ORUT				
3318	SP118	ORCT	Number of orientation retry times	Set the number of times to retry when an orientation or feedback error occurs. The warning (A9) is issued while retrying orientation, and an alarm (5C) is issued when the set number of times is exceeded.	0 to 100 (time)	0
3319 to 3376	SP119 to SP176			Not used. Set to "0".	0	0

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting																																																																																												
3377 (PR)	SP177	SPECS	Spindle synchronous specifications Set the spindle synchronous specifications in bit units. F E D C B A 9 8 <table border="1" style="width:100%; text-align:center;"> <tr> <td style="width:12.5%;"></td> <td style="width:12.5%;"></td> <td style="width:12.5%;">odx8</td> <td style="width:12.5%;"></td> <td style="width:12.5%;"></td> <td style="width:12.5%;"></td> <td style="width:12.5%;"></td> <td style="width:12.5%;"></td> </tr> <tr> <td colspan="8"> </td> </tr> <tr> <td style="width:12.5%;"></td> <td style="width:12.5%;"></td> <td style="width:12.5%;">fdir</td> <td style="width:12.5%;"></td> <td style="width:12.5%;">pyfx</td> <td style="width:12.5%;"></td> <td style="width:12.5%;"></td> <td style="width:12.5%;">fclx</td> </tr> </table> (Note) Always set "0" for the empty bits. <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>fclx</td> <td>Closed loop</td> <td>Semi-closed loop</td> </tr> <tr> <td>1</td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td></td> <td></td> <td></td> </tr> <tr> <td>3</td> <td>pyfx</td> <td>Normal excitation</td> <td>Position loop excitation fixed (strong)</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td>fdir</td> <td>Position detector polarity (+)</td> <td>Position detector polarity (-)</td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> <td></td> </tr> <tr> <td>8</td> <td></td> <td></td> <td></td> </tr> <tr> <td>9</td> <td></td> <td></td> <td></td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> <td></td> </tr> <tr> <td>D</td> <td>odx8</td> <td>Magnification of excessive error width x 8 times invalid</td> <td>Magnification of excessive error width x 8 times valid</td> </tr> <tr> <td>E</td> <td></td> <td></td> <td></td> </tr> <tr> <td>F</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>			odx8																fdir		pyfx			fclx	bit	Name	Meaning when set to 0	Meaning when set to 1	0	fclx	Closed loop	Semi-closed loop	1				2				3	pyfx	Normal excitation	Position loop excitation fixed (strong)	4				5	fdir	Position detector polarity (+)	Position detector polarity (-)	6				7				8				9				A				B				C				D	odx8	Magnification of excessive error width x 8 times invalid	Magnification of excessive error width x 8 times valid	E				F				0000 to FFFF HEX setting	0000
		odx8																																																																																															
		fdir		pyfx			fclx																																																																																										
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																														
0	fclx	Closed loop	Semi-closed loop																																																																																														
1																																																																																																	
2																																																																																																	
3	pyfx	Normal excitation	Position loop excitation fixed (strong)																																																																																														
4																																																																																																	
5	fdir	Position detector polarity (+)	Position detector polarity (-)																																																																																														
6																																																																																																	
7																																																																																																	
8																																																																																																	
9																																																																																																	
A																																																																																																	
B																																																																																																	
C																																																																																																	
D	odx8	Magnification of excessive error width x 8 times invalid	Magnification of excessive error width x 8 times valid																																																																																														
E																																																																																																	
F																																																																																																	
3378 (PR)	SP178	VGSP	Spindle synchronous speed loop gain proportional term	Set the speed loop proportional gain in spindle synchronization mode.	0 to 1000 (1/s)	63																																																																																											
3379 (PR)	SP179	VGSI	Spindle synchronous speed loop gain integral term	Set the speed loop integral gain in spindle synchronization mode.	0 to 1000 (0.1 1/s)	60																																																																																											
3380 (PR)	SP180	VGSD	Spindle synchronous speed loop gain delay advance term	Set the speed loop delay advance gain in spindle synchronization mode. When this parameter is set to "0", PI control is exercised.	0 to 1000 (0.1 1/s)	15																																																																																											
3381 (PR)	SP181	VCGS	Target value of variable speed loop proportional gain at spindle synchronization	Set the magnification of speed loop proportional gain with respect to SP178 (VGSP) at the maximum speed defined in SP017 (TSP) at spindle synchronization.	0 to 100 (%)	100																																																																																											


8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting	
3382 (PR)	SP182	VCSS	Change starting speed of variable speed loop proportional gain at spindle synchronization	Set the speed for starting change of speed loop proportional gain at spindle synchronization. 	0 to 32767 (r/min)	0
3383	SP183	SYNV	Sync matching speed at spindle synchronization	For changeover from the speed loop to the position loop at spindle synchronization, set a speed command error range for output of the sync speed matching signal.	0 to 1000 (r/min)	20
3384 (PR)	SP184	FFCS	Acceleration rate feed forward gain at spindle synchronization	Set the acceleration rate feed forward gain at spindle synchronization. This parameter is used only with the SPJ2.	0 to 1000 (%)	0
3385	SP185	SINP	Spindle sync in-position width	Set the position error range for output of the in-position signal at spindle synchronization.	1 to 2880 (1/16°)	16
3386 (PR)	SP186	SODR	Excessive error width at spindle synchronization	Set the excessive error width at spindle synchronization.	1 to 32767 (1/4 pulse) (1 pulse =0.088°)	32767
3387 (PR)	SP187	IQGS	Current loop gain magnification1 at spindle synchronization	Set the magnification of current loop gain (torque component) at spindle synchronization.	1 to 1000 (%)	100
3388 (PR)	SP188	IDGS	Current loop gain magnification 2 at spindle synchronization	Set the magnification of current loop gain (excitation component) at spindle synchronization.	1 to 1000 (%)	100
3389 to 3392	SP189 to SP192			Not used. Set to "0".	0	0

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting																																																																																																												
3393 (PR)	SP193	SPECT	Synchronous tapping specifications Set the synchronous tapping specifications in bit units. <table border="1" style="width:100%; text-align:center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td>zrtn</td><td>ptyp</td><td>od8x</td><td></td><td></td><td></td><td></td><td></td> </tr> <tr> <td colspan="8"> </td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td></td><td></td><td>fdir</td><td>cdir</td><td>pyfx</td><td></td><td></td><td>fclx</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr><td>0</td><td>fclx</td><td>Closed loop</td><td>Semi-closed loop</td></tr> <tr><td>1</td><td></td><td></td><td></td></tr> <tr><td>2</td><td></td><td></td><td></td></tr> <tr><td>3</td><td>pyfx</td><td>Normal excitation</td><td>Position loop excitation fixed (strong)</td></tr> <tr><td>4</td><td>cdir</td><td>Command polarity (+)</td><td>Command polarity (-)</td></tr> <tr><td>5</td><td>fdir</td><td>Position detector polarity (+)</td><td>Position detector polarity (-)</td></tr> <tr><td>6</td><td></td><td></td><td></td></tr> <tr><td>7</td><td></td><td></td><td></td></tr> <tr><td>8</td><td></td><td></td><td></td></tr> <tr><td>9</td><td></td><td></td><td></td></tr> <tr><td>A</td><td></td><td></td><td></td></tr> <tr><td>B</td><td></td><td></td><td></td></tr> <tr><td>C</td><td></td><td></td><td></td></tr> <tr><td>D</td><td>od8x</td><td>Magnification of excessive error width x 8 times invalid</td><td>Magnification of excessive error width x 8 times valid</td></tr> <tr><td>E</td><td>ptyp</td><td>Position control switch type: After zero point return</td><td>Position control switch type: After deceleration stop</td></tr> <tr><td>F</td><td>zrtn</td><td>Zero point return direction: CCW</td><td>Zero point return direction: CW</td></tr> </tbody> </table>	F	E	D	C	B	A	9	8	zrtn	ptyp	od8x														7	6	5	4	3	2	1	0			fdir	cdir	pyfx			fclx	bit	Name	Meaning when set to 0	Meaning when set to 1	0	fclx	Closed loop	Semi-closed loop	1				2				3	pyfx	Normal excitation	Position loop excitation fixed (strong)	4	cdir	Command polarity (+)	Command polarity (-)	5	fdir	Position detector polarity (+)	Position detector polarity (-)	6				7				8				9				A				B				C				D	od8x	Magnification of excessive error width x 8 times invalid	Magnification of excessive error width x 8 times valid	E	ptyp	Position control switch type: After zero point return	Position control switch type: After deceleration stop	F	zrtn	Zero point return direction: CCW	Zero point return direction: CW	0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																										
zrtn	ptyp	od8x																																																																																																															
7	6	5	4	3	2	1	0																																																																																																										
		fdir	cdir	pyfx			fclx																																																																																																										
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																														
0	fclx	Closed loop	Semi-closed loop																																																																																																														
1																																																																																																																	
2																																																																																																																	
3	pyfx	Normal excitation	Position loop excitation fixed (strong)																																																																																																														
4	cdir	Command polarity (+)	Command polarity (-)																																																																																																														
5	fdir	Position detector polarity (+)	Position detector polarity (-)																																																																																																														
6																																																																																																																	
7																																																																																																																	
8																																																																																																																	
9																																																																																																																	
A																																																																																																																	
B																																																																																																																	
C																																																																																																																	
D	od8x	Magnification of excessive error width x 8 times invalid	Magnification of excessive error width x 8 times valid																																																																																																														
E	ptyp	Position control switch type: After zero point return	Position control switch type: After deceleration stop																																																																																																														
F	zrtn	Zero point return direction: CCW	Zero point return direction: CW																																																																																																														
3394 (PR)	SP194	VGTP	Synchronous tapping speed loop gain proportional term	Set the speed loop proportional gain in synchronous tapping mode.	0 to 1000 (1/s)	63																																																																																																											
3395 (PR)	SP195	VGTI	Synchronous tapping speed loop gain integral term	Set the speed loop integral gain in synchronous tapping mode.	0 to 1000 (0.1 1/s)	60																																																																																																											
3396 (PR)	SP196	VGTD	Synchronous tapping speed loop gain delay advance term	Set the speed loop delay advance gain in synchronous tapping mode. When this parameter is set to "0", PI control is exercised.	0 to 1000 (0.1 1/s)	15																																																																																																											
3397	SP197			Not used. Set to "0".	0	0																																																																																																											
3398 (PR)	SP198	VCGT	Target value of variable speed loop proportional gain at synchronous tapping	Set the magnification of speed loop proportional gain with respect to SP194 (VGTP) at the maximum motor speed defined in SP017 (TSP) at synchronous tapping.	0 to 100 (%)	100																																																																																																											

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting	
3399 (PR)	SP199	VCST	Change starting speed of variable speed loop proportional gain at synchronous tapping	Set the speed for starting change of speed loop proportional gain at synchronous tapping. 	0 to 32767 (r/min)	0
3400 (PR)	SP200	FFC1	Synchronous tapping acceleration feed forward gain (gear 1)	Set the acceleration feed-forward gain for selection of gear 000 at synchronous tapping. This parameter should be used when an error of relative position to Z-axis servo is large.	0 to 1000 (%)	0
3401 (PR)	SP201	FFC2	Synchronous tapping acceleration feed forward gain (gear 2)	Set the acceleration feed-forward gain for selection of gear 001 at synchronous tapping.	0 to 1000 (%)	0
3402 (PR)	SP202	FFC3	Synchronous tapping acceleration feed forward gain (gear 3)	Set the acceleration feed-forward gain for selection of gear 010 at synchronous tapping.	0 to 1000 (%)	0
3403 (PR)	SP203	FFC4	Synchronous tapping acceleration feed forward gain (gear 4)	Set the acceleration feed-forward gain for selection of gear 011 at synchronous tapping.	0 to 1000 (%)	0
3404 to 3413	SP204 to SP213			Not used. Set to "0".	0	0
3414	SP214	TZRN	Synchronous tapping zero point return speed	This parameter is valid when SP193 (SPECT) bitE is set to "0". Set the zero point return speed used when the speed loop changes to the position loop.	0 to 500 (r/min)	50
3415	SP215	TPDT	Synchronous tapping zero point return deceleration rate	This parameter is valid when SP193 (SPECT) bitE is set to "0". Set the deceleration rate where the machine starts to decelerate when it returns to the target stop point during synchronous tapping zero point return. When the machine tends to overshoot at the stop point set a smaller value.	1 to 10000 (pulse)	1
3416	SP216	TPST	Synchronous tapping zero point return shift amount	This parameter is valid when SP193 (SPECT) bitE is set to "0". Set the synchronous tapping zero point position.	0 to 4095	0

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting	
3417	SP217	TINP	Synchronous tapping in-position width	Set the position error range in which in-position signal is output during synchronize tapping.	1 to 2880 (1/16°)	16
3418 (PR)	SP218	TODR	Excessive error width at synchronous tapping	Set the excessive error width at synchronous tapping.	1 to 32767 (pulse) (1 pulse =0.088°)	32767
3419 (PR)	SP219	IQGT	Current loop gain magnification 1 at synchronous tapping	Set the magnification of current loop gain (torque component) during synchronous tapping.	1 to 1000 (%)	100
3420 (PR)	SP220	IDGT	Current loop gain magnification 2 at synchronous tapping	Set the magnification of current loop gain (excitation component) during synchronous tapping.	1 to 1000 (%)	100
3421 to 3424	SP221 to SP224			Not used. Set to "0".	0	0
3425	SP225	OXKPH	Fixed control constant	Set by Mitsubishi. Set "0" unless designated in particular.	0	0
3426	SP226	OXKPL				
3427	SP227	OXVKP				
3428	SP228	OXVKI				
3429	SP229	OXSFT				
3430	SP230					
3431	SP231					
3432	SP232					
3433 (PR)	SP233	JL	Disturbance observer general inertia scale	Set the ratio of the motor inertia + load inertia and motor inertia. $\text{Setting value} = \frac{\text{Motor inertia} + \text{load inertia}}{\text{Motor inertia}} \times 100$ (Normally, set "100" or more. When less than "50" is set, the setting will be invalid.)	0 to 5000 (%)	0

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting	
3434 (PR)	SP234	OBS1	Disturbance observer low path filter frequency	Set the frequency of the low path filter for when the disturbance observer is valid. Setting (1/s) = $2\pi f$ f: Approx. 1.5 times the disturbance frequency	0 to 1000 (1/s)	0
3435 (PR)	SP235	OBS2	Disturbance observer gain	Set the gain for the disturbance observer.	0 to 500 (%)	0
3436 to 3452	SP236 to SP252			Not used. Set to "0".	0	0
3453	SP253	DA1NO	D/A output channel 1 data number	Set the output data number for channel 1 of the D/A output function. When the setting value is "0", the output is speedometer. Refer to "8.5.1 D/A OUTPUT SPECIFICATIONS".	-32768 to 32767	0
3454	SP254	DA2NO	D/A output channel 2 data number	Set the output data number for channel 2 of the D/A output function. When the setting value is "0", the output is load meter. Refer to "8.5.1 D/A OUTPUT SPECIFICATIONS".	-32768 to 32767	0
3455	SP255	DA1MPY	DA output channel 1 magnification	Set the data magnification for channel 1 of the D/A output function. The output magnification is (setting value)/256. When set to "0", the output magnification becomes 1-fold, in the same manner as when "256" is set. Refer to "8.5.1 D/A OUTPUT SPECIFICATIONS".	-32768 to 32767 (1/256-fold)	0
3456	SP256	DA2MPY	DA output channel 2 magnification	Set the data magnification for channel 2 of the D/A output function. The output magnification is (setting value)/256. When set to "0", the output magnification becomes 1-fold, in the same manner as when "256" is set. Refer to "8.5.1 D/A OUTPUT SPECIFICATIONS".	-32768 to 32767 (1/256-fold)	0

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting	
3457 (PR) to 3520 (PR)	SP257 to SP320	RPM BSD	Motor constant (H coil)	<p>This parameter is valid only in the following two conditional cases:</p> <p>(a) In case that SP034 (SFNC2) bit0=1 and SP034 (SFNC2) bit2=0 Set the motor constants when using a special motor, not described in the SP040 (MTYP) explanation and when not using the coil changeover motor.</p> <p>(b) In case that SP034 (SFNC2) bit0=1 and SP034 (SFNC2) bit2=1 Set the motor constant of the H coil of the coil changeover motor.</p> <p>(Note) It is not allowed for the user to change the setting.</p>	0000 to FFFF HEX setting	0000
3521 (PR) to 3584 (PR)	SP321 to SP384	RPML BSDL	Motor constant (L coil)	<p>This parameter is valid only in the following conditional case:</p> <p>(a) In case that SP034 (SFNC2) bit0=1 and SP034 (SFNC2) bit2=1 Set the motor constant of the L coil of the coil changeover motor.</p> <p>(Note) It is not allowed for the user to change the setting.</p>	0000 to FFFF HEX setting	0000

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

The spindle parameter setting and display method will differ according to the NC being used, so refer to Instruction Manual for each NC and the following spindles.

MELDAS AC Servo and Spindle MDS-A Series MDS-B Series Specifications Manual .BNP-B3759
MELDAS AC Servo and Spindle MDS-C1 Series Specifications ManualBNP-C3000

For parameters marked with a (PR) in the tables, turn the NC power OFF after setting. The parameters will be valid after the power is turned ON again.

The "fixed control constants" and "fixed control bits" in this section are set by Mitsubishi.

⚠ CAUTION

- ⚠ Do not make remarkable adjustments or changes of the parameters as the operation may become unstable.
- ⚠ In the explanation on bits, set all bits not used, including blank bits, to "0".

No.	Items	Details	Setting range	Standard setting	
3201	SP001 PGM	Magnetic sensor and motor built-in encoder orientation position loop gain	As the set value is larger, the orientation time becomes shorter and servo rigidity is increased. However, vibration is increased and the machine becomes likely to overshoot.	0 to 1000 (0.1 1/s)	100
3202	SP002 PGE	Encoder orientation position loop gain	As the set value is larger, the orientation time becomes shorter and servo rigidity is increased. However, vibration is increased and the machine becomes likely to overshoot.	0 to 1000 (0.1 1/s)	100
3203	SP003 PGC0	C-axis non-cutting position loop gain	Set the position loop gain in C-axis non-cutting mode. During non-cutting (rapid traverse, etc.) with the C axis control, this position loop gain setting is valid.	1 to 100 (1/s)	15
3204	SP004 OINP	Orientation in-position width	Set the position error range in which an orientation completion signal is output.	1 to 2880 (1/16 °)	16
3205 (PR)	SP005 OSP	Orientation mode changing speed limit value	Set the motor speed limit value to be used when the speed loop is changed to the position loop in orientation mode. When this parameter is set to "0", SP017 (TSP) becomes the limit value.	0 to 32767 (r/min)	0
3206	SP006 CSP	Orientation mode deceleration rate	As the set value is larger, the orientation time becomes shorter. However, the machine becomes likely to overshoot.	1 to 1000	20

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3207	SP007	OPST	In-position shift amount for orientation	Set the stop position for orientation. (i) Motor built-in encoder, encoder: Set the value by dividing 360° by 4096. (ii) Magnetic sensor: Divide -5° to +5° by 1024 and put 0° for 0.	(i) 0 to 4095 (ii) -512 to 512	0
3208	SP008			Not used. Set to "0".	0	0
3209	SP009	PGT	Synchronized tapping Position loop gain	Set the spindle position loop gain in synchronized tapping mode.	1 to 100 (1/s)	15
3210	SP010	PGS	Spindle synchronous position loop gain	Set the spindle position loop gain in spindle synchronization mode.	1 to 100 (1/s)	15
3211 to 3216	SP011 to SP016			Use not possible.	0	0
3217 (PR)	SP017	TSP	Maximum motor speed	Set the maximum motor speed of the spindle.	1 to 32767 (r/min)	6000
3218 (PR)	SP018	ZSP	Motor zero speed	Set the motor speed for which zero-speed output is performed.	1 to 1000 (r/min)	50
3219 (PR)	SP019	CSN1	Speed cushion 1	Set the time constant for a speed command from "0" to the maximum speed. (This parameter is invalid in position loop mode.)	1 to 32767 (10ms)	30
3220 (PR)	SP020	SDTS	Speed detection set value	Set the motor speed so for which speed detection output is performed. Usually, the setting value is 10% of SP017 (TSP).	0 to 32767 (r/min)	600
3221	SP021	TLM1	Torque limit 1	Set the torque limit rate for torque limit signal 001.	0 to 120 (%)	10
3222 (PR)	SP022	VGNP1	Speed loop gain proportional term under speed control	Set the speed loop proportional gain in speed control mode. When the gain is increased, response is improved but vibration and sound become larger.	0 to 1000 (1/s)	63
3223 (PR)	SP023	VGNI1	Speed loop gain integral term under speed control	Set the speed loop integral gain in speed control mode. Usually, set a value in proportion to SP022 (VGNP1).	0 to 1000 (0.1 1/s)	60

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items			Details	Setting range	Standard setting
3224	SP024			Use not possible.	0	0
3225 (PR)	SP025	GRA1	Spindle gear teeth count 1	Set the number of gear teeth of the spindle corresponding to gear 000.	1 to 32767	1
3226 (PR)	SP026	GRA2	Spindle gear teeth count 2	Set the number of gear teeth of the spindle corresponding to gear 001.	1 to 32767	1
3227 (PR)	SP027	GRA3	Spindle gear teeth count 3	Set the number of gear teeth of the spindle corresponding to gear 010.	1 to 32767	1
3228 (PR)	SP028	GRA4	Spindle gear teeth count 4	Set the number of gear teeth of the spindle corresponding to gear 011.	1 to 32767	1
3229 (PR)	SP029	GRB1	Motor shaft gear teeth count 1	Set the number of gear teeth of the motor shaft corresponding to gear 000.	1 to 32767	1
3230 (PR)	SP030	GRB2	Motor shaft gear teeth count 2	Set the number of gear teeth of the motor shaft corresponding to gear 001.	1 to 32767	1
3231 (PR)	SP031	GRB3	Motor shaft gear teeth count 3	Set the number of gear teeth of the motor shaft corresponding to gear 010.	1 to 32767	1
3232 (PR)	SP032	GRB4	Motor shaft gear teeth count 4	Set the number of gear teeth of the motor shaft corresponding to gear 011.	1 to 32767	1

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting																																																																																																				
3233 (PR)	SP033	SFNC1	Spindle function 1 Set the spindle function 1 in bit units. <table style="width: 100%; border-collapse: collapse; text-align: center;"> <tr> <td style="border: none;">F</td><td style="border: none;">E</td><td style="border: none;">D</td><td style="border: none;">C</td><td style="border: none;">B</td><td style="border: none;">A</td><td style="border: none;">9</td><td style="border: none;">8</td> </tr> <tr> <td style="border: 1px solid black;">poff</td><td style="border: 1px solid black;">hzs</td><td style="border: 1px solid black;"></td><td style="border: 1px solid black;">ront</td><td style="border: 1px solid black;"></td><td style="border: 1px solid black;"></td><td style="border: 1px solid black;">pycal</td><td style="border: 1px solid black;">pychg</td> </tr> <tr> <td style="border: none;">7</td><td style="border: none;">6</td><td style="border: none;">5</td><td style="border: none;">4</td><td style="border: none;">3</td><td style="border: none;">2</td><td style="border: none;">1</td><td style="border: none;">0</td> </tr> <tr> <td style="border: 1px solid black;">pyst</td><td style="border: 1px solid black;">pyoff</td><td style="border: 1px solid black;"></td><td style="border: 1px solid black;"></td><td style="border: 1px solid black;"></td><td style="border: 1px solid black;">sftk</td><td style="border: 1px solid black;">dflt</td><td style="border: 1px solid black;">1a2m</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width: 100%; border-collapse: collapse; text-align: left;"> <thead> <tr> <th style="text-align: left;">bit</th> <th style="text-align: left;">Name</th> <th style="text-align: left;">Meaning when set to 0</th> <th style="text-align: left;">Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>1a2m</td> <td>1 amplifier 2 motor function: Invalid</td> <td>1 amplifier 2 motor function: Valid</td> </tr> <tr> <td>1</td> <td>dflt</td> <td>Default motor: Main</td> <td>Default motor: Sub</td> </tr> <tr> <td>2</td> <td>sftk</td> <td>SF-TK card invalid</td> <td>SF-TK card valid</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> </tr> <tr> <td>6</td> <td>pyoff</td> <td colspan="2">This is used by Mitsubishi. Set to "0" unless particularly designated.</td> </tr> <tr> <td>7</td> <td>pyst</td> <td colspan="2"></td> </tr> <tr> <td>8</td> <td>pychg</td> <td colspan="2"></td> </tr> <tr> <td>9</td> <td>pycal</td> <td>(Conventional specifications)</td> <td>High-speed rate deceleration method valid for minimum excitation rate</td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td colspan="2">This is used by Mitsubishi. Set to "0" unless particularly designated.</td> </tr> <tr> <td>C</td> <td>ront</td> <td>Normal ready ON</td> <td>High-speed ready ON</td> </tr> <tr> <td>D</td> <td></td> <td colspan="2">This is used by Mitsubishi. Set to "0" unless particularly designated.</td> </tr> <tr> <td>E</td> <td>hzs</td> <td>Gate OFF by high-cycle zero speed invalid</td> <td>Gate OFF by high-cycle zero speed valid</td> </tr> <tr> <td>F</td> <td>poff</td> <td>Contactorm hold at NC power OFF invalid</td> <td>Contactorm hold at NC power OFF valid</td> </tr> </tbody> </table> <p>(Note) When SPH is used, bit 0 and bit 1 will be invalid.</p>	F	E	D	C	B	A	9	8	poff	hzs		ront			pycal	pychg	7	6	5	4	3	2	1	0	pyst	pyoff				sftk	dflt	1a2m	bit	Name	Meaning when set to 0	Meaning when set to 1	0	1a2m	1 amplifier 2 motor function: Invalid	1 amplifier 2 motor function: Valid	1	dflt	Default motor: Main	Default motor: Sub	2	sftk	SF-TK card invalid	SF-TK card valid	3				4				5				6	pyoff	This is used by Mitsubishi. Set to "0" unless particularly designated.		7	pyst			8	pychg			9	pycal	(Conventional specifications)	High-speed rate deceleration method valid for minimum excitation rate	A				B		This is used by Mitsubishi. Set to "0" unless particularly designated.		C	ront	Normal ready ON	High-speed ready ON	D		This is used by Mitsubishi. Set to "0" unless particularly designated.		E	hzs	Gate OFF by high-cycle zero speed invalid	Gate OFF by high-cycle zero speed valid	F	poff	Contactorm hold at NC power OFF invalid	Contactorm hold at NC power OFF valid	0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																		
poff	hzs		ront			pycal	pychg																																																																																																		
7	6	5	4	3	2	1	0																																																																																																		
pyst	pyoff				sftk	dflt	1a2m																																																																																																		
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																						
0	1a2m	1 amplifier 2 motor function: Invalid	1 amplifier 2 motor function: Valid																																																																																																						
1	dflt	Default motor: Main	Default motor: Sub																																																																																																						
2	sftk	SF-TK card invalid	SF-TK card valid																																																																																																						
3																																																																																																									
4																																																																																																									
5																																																																																																									
6	pyoff	This is used by Mitsubishi. Set to "0" unless particularly designated.																																																																																																							
7	pyst																																																																																																								
8	pychg																																																																																																								
9	pycal	(Conventional specifications)	High-speed rate deceleration method valid for minimum excitation rate																																																																																																						
A																																																																																																									
B		This is used by Mitsubishi. Set to "0" unless particularly designated.																																																																																																							
C	ront	Normal ready ON	High-speed ready ON																																																																																																						
D		This is used by Mitsubishi. Set to "0" unless particularly designated.																																																																																																							
E	hzs	Gate OFF by high-cycle zero speed invalid	Gate OFF by high-cycle zero speed valid																																																																																																						
F	poff	Contactorm hold at NC power OFF invalid	Contactorm hold at NC power OFF valid																																																																																																						

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting																																																																																																				
3234 (PR)	SP034	SFNC2	Spindle function 2 Set the spindle function 2 in bit units. <table style="width: 100%; text-align: center; border-collapse: collapse;"> <tr> <td style="border: 1px solid black; width: 25px;">F</td> <td style="border: 1px solid black; width: 25px;">E</td> <td style="border: 1px solid black; width: 25px;">D</td> <td style="border: 1px solid black; width: 25px;">C</td> <td style="border: 1px solid black; width: 25px;">B</td> <td style="border: 1px solid black; width: 25px;">A</td> <td style="border: 1px solid black; width: 25px;">9</td> <td style="border: 1px solid black; width: 25px;">8</td> </tr> <tr> <td style="border: 1px solid black; height: 20px;"></td> </tr> <tr> <td style="border: 1px solid black; width: 25px;">7</td> <td style="border: 1px solid black; width: 25px;">6</td> <td style="border: 1px solid black; width: 25px;">5</td> <td style="border: 1px solid black; width: 25px;">4</td> <td style="border: 1px solid black; width: 25px;">3</td> <td style="border: 1px solid black; width: 25px;">2</td> <td style="border: 1px solid black; width: 25px;">1</td> <td style="border: 1px solid black; width: 25px;">0</td> </tr> <tr> <td style="border: 1px solid black; height: 20px;"></td> <td style="border: 1px solid black; height: 20px;">mkc2</td> <td style="border: 1px solid black; height: 20px;">mkch</td> <td style="border: 1px solid black; height: 20px;">invm</td> <td style="border: 1px solid black; height: 20px;">mts1</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 5%;">bit</th> <th style="width: 15%;">Name</th> <th style="width: 35%;">Meaning when set to 0</th> <th style="width: 45%;">Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">0</td> <td style="text-align: center;">mts1</td> <td>Special motor constant invalid</td> <td>Special motor constant setting valid</td> </tr> <tr> <td style="text-align: center;">1</td> <td style="text-align: center;">invm</td> <td>A general-purpose motor FV control invalid</td> <td>A general-purpose motor FV control valid</td> </tr> <tr> <td style="text-align: center;">2</td> <td style="text-align: center;">mkch</td> <td>Coil switch function invalid</td> <td>Coil switch function valid</td> </tr> <tr> <td style="text-align: center;">3</td> <td style="text-align: center;">mkc2</td> <td>Coil switch specification 2 invalid</td> <td>Coil switch specification 2 valid (Note1) (Note2)</td> </tr> <tr><td style="text-align: center;">4</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">5</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">6</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">7</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">8</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">9</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">A</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">B</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">C</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">D</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">E</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">F</td><td></td><td></td><td></td></tr> </tbody> </table> <p>(Note1) To validate bit3(mkc2), NC side needs to prepare. (Note2) Always turn the bit2 at the same time to use bit3.</p>	F	E	D	C	B	A	9	8									7	6	5	4	3	2	1	0					mkc2	mkch	invm	mts1	bit	Name	Meaning when set to 0	Meaning when set to 1	0	mts1	Special motor constant invalid	Special motor constant setting valid	1	invm	A general-purpose motor FV control invalid	A general-purpose motor FV control valid	2	mkch	Coil switch function invalid	Coil switch function valid	3	mkc2	Coil switch specification 2 invalid	Coil switch specification 2 valid (Note1) (Note2)	4				5				6				7				8				9				A				B				C				D				E				F				0000 to FFFF HEX setting	000C
F	E	D	C	B	A	9	8																																																																																																		
7	6	5	4	3	2	1	0																																																																																																		
				mkc2	mkch	invm	mts1																																																																																																		
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																						
0	mts1	Special motor constant invalid	Special motor constant setting valid																																																																																																						
1	invm	A general-purpose motor FV control invalid	A general-purpose motor FV control valid																																																																																																						
2	mkch	Coil switch function invalid	Coil switch function valid																																																																																																						
3	mkc2	Coil switch specification 2 invalid	Coil switch specification 2 valid (Note1) (Note2)																																																																																																						
4																																																																																																									
5																																																																																																									
6																																																																																																									
7																																																																																																									
8																																																																																																									
9																																																																																																									
A																																																																																																									
B																																																																																																									
C																																																																																																									
D																																																																																																									
E																																																																																																									
F																																																																																																									
3235 (PR)	SP035	SFNC3	Spindle function 3 Set the spindle function 3 in bit units. <table style="width: 100%; text-align: center; border-collapse: collapse;"> <tr> <td style="border: 1px solid black; width: 25px;">F</td> <td style="border: 1px solid black; width: 25px;">E</td> <td style="border: 1px solid black; width: 25px;">D</td> <td style="border: 1px solid black; width: 25px;">C</td> <td style="border: 1px solid black; width: 25px;">B</td> <td style="border: 1px solid black; width: 25px;">A</td> <td style="border: 1px solid black; width: 25px;">9</td> <td style="border: 1px solid black; width: 25px;">8</td> </tr> <tr> <td style="border: 1px solid black; height: 20px;"></td> </tr> <tr> <td style="border: 1px solid black; width: 25px;">7</td> <td style="border: 1px solid black; width: 25px;">6</td> <td style="border: 1px solid black; width: 25px;">5</td> <td style="border: 1px solid black; width: 25px;">4</td> <td style="border: 1px solid black; width: 25px;">3</td> <td style="border: 1px solid black; width: 25px;">2</td> <td style="border: 1px solid black; width: 25px;">1</td> <td style="border: 1px solid black; width: 25px;">0</td> </tr> <tr> <td style="border: 1px solid black; height: 20px;"></td> <td style="border: 1px solid black; height: 20px;">lbsd</td> <td style="border: 1px solid black; height: 20px;">hbsd</td> <td style="border: 1px solid black; height: 20px;">lwid</td> <td style="border: 1px solid black; height: 20px;">hwid</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 5%;">bit</th> <th style="width: 15%;">Name</th> <th style="width: 35%;">Meaning when set to 0</th> <th style="width: 45%;">Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">0</td> <td style="text-align: center;">hwid</td> <td>H-coil wide-range constant output invalid</td> <td>H-coil wide-range constant output valid</td> </tr> <tr> <td style="text-align: center;">1</td> <td style="text-align: center;">lwid</td> <td>L-coil wide-range constant output invalid</td> <td>L-coil wide-range constant output valid</td> </tr> <tr> <td style="text-align: center;">2</td> <td style="text-align: center;">hbsd</td> <td>H-coil base slide invalid</td> <td>H-coil base slide valid</td> </tr> <tr> <td style="text-align: center;">3</td> <td style="text-align: center;">lbsd</td> <td>L-coil base slide invalid</td> <td>L-coil base slide valid</td> </tr> <tr><td style="text-align: center;">4</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">5</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">6</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">7</td><td></td><td></td><td></td></tr> <tr> <td style="text-align: center;">8</td> <td></td> <td>(Used with SPJ.)</td> <td></td> </tr> <tr><td style="text-align: center;">9</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">A</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">B</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">C</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">D</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">E</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">F</td><td></td><td></td><td></td></tr> </tbody> </table>	F	E	D	C	B	A	9	8									7	6	5	4	3	2	1	0					lbsd	hbsd	lwid	hwid	bit	Name	Meaning when set to 0	Meaning when set to 1	0	hwid	H-coil wide-range constant output invalid	H-coil wide-range constant output valid	1	lwid	L-coil wide-range constant output invalid	L-coil wide-range constant output valid	2	hbsd	H-coil base slide invalid	H-coil base slide valid	3	lbsd	L-coil base slide invalid	L-coil base slide valid	4				5				6				7				8		(Used with SPJ.)		9				A				B				C				D				E				F				0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																		
7	6	5	4	3	2	1	0																																																																																																		
				lbsd	hbsd	lwid	hwid																																																																																																		
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																						
0	hwid	H-coil wide-range constant output invalid	H-coil wide-range constant output valid																																																																																																						
1	lwid	L-coil wide-range constant output invalid	L-coil wide-range constant output valid																																																																																																						
2	hbsd	H-coil base slide invalid	H-coil base slide valid																																																																																																						
3	lbsd	L-coil base slide invalid	L-coil base slide valid																																																																																																						
4																																																																																																									
5																																																																																																									
6																																																																																																									
7																																																																																																									
8		(Used with SPJ.)																																																																																																							
9																																																																																																									
A																																																																																																									
B																																																																																																									
C																																																																																																									
D																																																																																																									
E																																																																																																									
F																																																																																																									

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting																																																																																																												
3236 (PR)	SP036	SFNC4	Spindle function 4 Set the spindle function 4 in bit units. <table style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center;">F</td><td style="text-align: center;">E</td><td style="text-align: center;">D</td><td style="text-align: center;">C</td><td style="text-align: center;">B</td><td style="text-align: center;">A</td><td style="text-align: center;">9</td><td style="text-align: center;">8</td> </tr> <tr> <td style="border: 1px solid black; width: 20px; height: 20px;"></td> <td style="border: 1px solid black; width: 20px; height: 20px;"></td> <td style="border: 1px solid black; width: 20px; height: 20px;"></td> <td style="border: 1px solid black; width: 20px; height: 20px;"></td> <td style="border: 1px solid black; width: 20px; height: 20px;"></td> <td style="border: 1px solid black; width: 20px; height: 20px;"></td> <td style="border: 1px solid black; width: 20px; height: 20px; text-align: center;">dslm</td> <td style="border: 1px solid black; width: 20px; height: 20px; text-align: center;">dssm</td> </tr> <tr> <td colspan="8" style="text-align: center;"> </td> </tr> <tr> <td style="text-align: center;">7</td><td style="text-align: center;">6</td><td style="text-align: center;">5</td><td style="text-align: center;">4</td><td style="text-align: center;">3</td><td style="text-align: center;">2</td><td style="text-align: center;">1</td><td style="text-align: center;">0</td> </tr> <tr> <td style="border: 1px solid black; width: 20px; height: 20px;"></td> <td style="border: 1px solid black; width: 20px; height: 20px;"></td> <td style="border: 1px solid black; width: 20px; height: 20px; text-align: center;">enc2</td> <td style="border: 1px solid black; width: 20px; height: 20px; text-align: center;">enc1</td> <td style="border: 1px solid black; width: 20px; height: 20px; text-align: center;">mag2</td> <td style="border: 1px solid black; width: 20px; height: 20px; text-align: center;">mag1</td> <td style="border: 1px solid black; width: 20px; height: 20px; text-align: center;">plg2</td> <td style="border: 1px solid black; width: 20px; height: 20px; text-align: center;">plg1</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: center;">bit</th> <th style="text-align: center;">Name</th> <th style="text-align: center;">Meaning when set to 0</th> <th style="text-align: center;">Meaning when set to 1</th> </tr> </thead> <tbody> <tr><td style="text-align: center;">0</td><td style="text-align: center;">plg1</td><td>PLG of motor 1 valid</td><td>PLG of motor 1 invalid</td></tr> <tr><td style="text-align: center;">1</td><td style="text-align: center;">plg2</td><td>PLG of motor 2 valid</td><td>PLG of motor 2 invalid</td></tr> <tr><td style="text-align: center;">2</td><td style="text-align: center;">mag1</td><td>MAG of motor 1 valid</td><td>MAG of motor 1 invalid</td></tr> <tr><td style="text-align: center;">3</td><td style="text-align: center;">mag2</td><td>MAG of motor 2 valid</td><td>MAG of motor 2 invalid</td></tr> <tr><td style="text-align: center;">4</td><td style="text-align: center;">enc1</td><td>ENC of motor 1 valid</td><td>ENC of motor 1 invalid</td></tr> <tr><td style="text-align: center;">5</td><td style="text-align: center;">enc2</td><td>ENC of motor 2 valid</td><td>ENC of motor 2 invalid</td></tr> <tr><td style="text-align: center;">6</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">7</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">8</td><td style="text-align: center;">dssm</td><td>Speedometer output valid</td><td>Speedometer output invalid</td></tr> <tr><td style="text-align: center;">9</td><td style="text-align: center;">dslm</td><td>Load meter output valid</td><td>Load meter output invalid</td></tr> <tr><td style="text-align: center;">A</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">B</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">C</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">D</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">E</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">F</td><td></td><td></td><td></td></tr> </tbody> </table>	F	E	D	C	B	A	9	8							dslm	dssm									7	6	5	4	3	2	1	0			enc2	enc1	mag2	mag1	plg2	plg1	bit	Name	Meaning when set to 0	Meaning when set to 1	0	plg1	PLG of motor 1 valid	PLG of motor 1 invalid	1	plg2	PLG of motor 2 valid	PLG of motor 2 invalid	2	mag1	MAG of motor 1 valid	MAG of motor 1 invalid	3	mag2	MAG of motor 2 valid	MAG of motor 2 invalid	4	enc1	ENC of motor 1 valid	ENC of motor 1 invalid	5	enc2	ENC of motor 2 valid	ENC of motor 2 invalid	6				7				8	dssm	Speedometer output valid	Speedometer output invalid	9	dslm	Load meter output valid	Load meter output invalid	A				B				C				D				E				F				0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																										
						dslm	dssm																																																																																																										
7	6	5	4	3	2	1	0																																																																																																										
		enc2	enc1	mag2	mag1	plg2	plg1																																																																																																										
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																														
0	plg1	PLG of motor 1 valid	PLG of motor 1 invalid																																																																																																														
1	plg2	PLG of motor 2 valid	PLG of motor 2 invalid																																																																																																														
2	mag1	MAG of motor 1 valid	MAG of motor 1 invalid																																																																																																														
3	mag2	MAG of motor 2 valid	MAG of motor 2 invalid																																																																																																														
4	enc1	ENC of motor 1 valid	ENC of motor 1 invalid																																																																																																														
5	enc2	ENC of motor 2 valid	ENC of motor 2 invalid																																																																																																														
6																																																																																																																	
7																																																																																																																	
8	dssm	Speedometer output valid	Speedometer output invalid																																																																																																														
9	dslm	Load meter output valid	Load meter output invalid																																																																																																														
A																																																																																																																	
B																																																																																																																	
C																																																																																																																	
D																																																																																																																	
E																																																																																																																	
F																																																																																																																	
3237 (PR)	SP037	SFNC5	Spindle function 5 Set the spindle function 5 in bit units. <table style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center;">F</td><td style="text-align: center;">E</td><td style="text-align: center;">D</td><td style="text-align: center;">C</td><td style="text-align: center;">B</td><td style="text-align: center;">A</td><td style="text-align: center;">9</td><td style="text-align: center;">8</td> </tr> <tr> <td style="border: 1px solid black; width: 20px; height: 20px; text-align: center;">splg</td> <td style="border: 1px solid black; width: 20px; height: 20px; text-align: center;">dplg</td> <td style="border: 1px solid black; width: 20px; height: 20px;"></td> <td style="border: 1px solid black; width: 20px; height: 20px;"></td> <td style="border: 1px solid black; width: 20px; height: 20px;"></td> <td style="border: 1px solid black; width: 20px; height: 20px; text-align: center;">noplg</td> <td style="border: 1px solid black; width: 20px; height: 20px; text-align: center;">nsno</td> <td style="border: 1px solid black; width: 20px; height: 20px; text-align: center;">nosg</td> </tr> <tr> <td colspan="8" style="text-align: center;"> </td> </tr> <tr> <td style="text-align: center;">7</td><td style="text-align: center;">6</td><td style="text-align: center;">5</td><td style="text-align: center;">4</td><td style="text-align: center;">3</td><td style="text-align: center;">2</td><td style="text-align: center;">1</td><td style="text-align: center;">0</td> </tr> <tr> <td style="border: 1px solid black; width: 20px; height: 20px;"></td> <td style="border: 1px solid black; width: 20px; height: 20px;"></td> <td style="border: 1px solid black; width: 20px; height: 20px;"></td> <td style="border: 1px solid black; width: 20px; height: 20px;"></td> <td style="border: 1px solid black; width: 20px; height: 20px;"></td> <td style="border: 1px solid black; width: 20px; height: 20px; text-align: center;">plgo</td> <td style="border: 1px solid black; width: 20px; height: 20px; text-align: center;">mago</td> <td style="border: 1px solid black; width: 20px; height: 20px; text-align: center;">enco</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: center;">bit</th> <th style="text-align: center;">Name</th> <th style="text-align: center;">Meaning when set to 0</th> <th style="text-align: center;">Meaning when set to 1</th> </tr> </thead> <tbody> <tr><td style="text-align: center;">0</td><td style="text-align: center;">enco</td><td>Encoder orientation invalid</td><td>Encoder orientation valid</td></tr> <tr><td style="text-align: center;">1</td><td style="text-align: center;">mago</td><td>Magnetic sensor orientation invalid</td><td>Magnetic sensor orientation valid</td></tr> <tr><td style="text-align: center;">2</td><td style="text-align: center;">plgo</td><td>PLG orientation invalid</td><td>PLG orientation valid</td></tr> <tr><td style="text-align: center;">3</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">4</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">5</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">6</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">7</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">8</td><td style="text-align: center;">nosg</td><td>No-signal detection type (Always monitoring)</td><td>Monitoring only in position loop or orientation-mode</td></tr> <tr><td style="text-align: center;">9</td><td style="text-align: center;">nsno</td><td>No-signal detection valid</td><td>No-signal detection invalid</td></tr> <tr><td style="text-align: center;">A</td><td style="text-align: center;">noplg</td><td>Constant monitor of PLG-Z phase no-signal invalid</td><td>Constant monitor of PLG-Z phase no-signal valid</td></tr> <tr><td style="text-align: center;">B</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">C</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">D</td><td></td><td></td><td></td></tr> <tr><td style="text-align: center;">E</td><td style="text-align: center;">dplg</td><td colspan="2">This is used by Mitsubishi.</td></tr> <tr><td style="text-align: center;">F</td><td style="text-align: center;">splg</td><td colspan="2">Set to "0" unless particularly designated.</td></tr> </tbody> </table> <p>(Note) For bit0 to 2, do not set two bits or more to "1" at the same time.</p>	F	E	D	C	B	A	9	8	splg	dplg				noplg	nsno	nosg									7	6	5	4	3	2	1	0						plgo	mago	enco	bit	Name	Meaning when set to 0	Meaning when set to 1	0	enco	Encoder orientation invalid	Encoder orientation valid	1	mago	Magnetic sensor orientation invalid	Magnetic sensor orientation valid	2	plgo	PLG orientation invalid	PLG orientation valid	3				4				5				6				7				8	nosg	No-signal detection type (Always monitoring)	Monitoring only in position loop or orientation-mode	9	nsno	No-signal detection valid	No-signal detection invalid	A	noplg	Constant monitor of PLG-Z phase no-signal invalid	Constant monitor of PLG-Z phase no-signal valid	B				C				D				E	dplg	This is used by Mitsubishi.		F	splg	Set to "0" unless particularly designated.		0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																										
splg	dplg				noplg	nsno	nosg																																																																																																										
7	6	5	4	3	2	1	0																																																																																																										
					plgo	mago	enco																																																																																																										
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																														
0	enco	Encoder orientation invalid	Encoder orientation valid																																																																																																														
1	mago	Magnetic sensor orientation invalid	Magnetic sensor orientation valid																																																																																																														
2	plgo	PLG orientation invalid	PLG orientation valid																																																																																																														
3																																																																																																																	
4																																																																																																																	
5																																																																																																																	
6																																																																																																																	
7																																																																																																																	
8	nosg	No-signal detection type (Always monitoring)	Monitoring only in position loop or orientation-mode																																																																																																														
9	nsno	No-signal detection valid	No-signal detection invalid																																																																																																														
A	noplg	Constant monitor of PLG-Z phase no-signal invalid	Constant monitor of PLG-Z phase no-signal valid																																																																																																														
B																																																																																																																	
C																																																																																																																	
D																																																																																																																	
E	dplg	This is used by Mitsubishi.																																																																																																															
F	splg	Set to "0" unless particularly designated.																																																																																																															

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items	Details	Setting range	Standard setting																																																																																																																																																														
3238 (PR)	SP038 SFNC6	Spindle function 6 Set the spindle function 6 in bit units. <table style="margin-left: auto; margin-right: auto; border-collapse: collapse;"> <tr> <td style="text-align: center;">F</td><td style="text-align: center;">E</td><td style="text-align: center;">D</td><td style="text-align: center;">C</td><td style="text-align: center;">B</td><td style="text-align: center;">A</td><td style="text-align: center;">9</td><td style="text-align: center;">8</td> </tr> <tr> <td style="text-align: center;">opl</td><td style="text-align: center;">lmx</td><td style="text-align: center;">iqsv</td><td style="text-align: center;">XFzs</td><td style="text-align: center;">dcsn</td><td style="text-align: center;">lmp</td><td style="text-align: center;">pl80</td><td style="text-align: center;">sdt2</td> </tr> <tr> <td colspan="8" style="text-align: center;"> </td> </tr> <tr> <td style="text-align: center;">7</td><td style="text-align: center;">6</td><td style="text-align: center;">5</td><td style="text-align: center;">4</td><td style="text-align: center;">3</td><td style="text-align: center;">2</td><td style="text-align: center;">1</td><td style="text-align: center;">0</td> </tr> <tr> <td style="text-align: center;">vfbs</td><td style="text-align: center;">orm</td><td style="text-align: center;">adin</td><td style="text-align: center;">tdn</td><td style="text-align: center;">plg2</td><td style="text-align: center;">pftm</td><td style="text-align: center;"></td><td style="text-align: center;">alty</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <div style="border: 1px solid black; padding: 2px; margin-bottom: 5px;">For MDS-C1-SP/SPH</div> <table border="1" style="width: 100%; border-collapse: collapse; margin-bottom: 5px;"> <thead> <tr> <th style="width: 5%;">bit</th> <th style="width: 10%;">Name</th> <th style="width: 30%;">Meaning when set to 0</th> <th style="width: 30%;">Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">0</td> <td style="text-align: center;">alty</td> <td>Deceleration stop during special alarm invalid</td> <td>Deceleration stop during special alarm valid</td> </tr> <tr> <td style="text-align: center;">1</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">2</td> <td style="text-align: center;">pftm</td> <td>Encoder feedback serial communication invalid</td> <td>Encoder feedback serial communication valid</td> </tr> <tr> <td style="text-align: center;">3</td> <td style="text-align: center;">plg2</td> <td>Semi-closed pulse output signal x2 invalid</td> <td>Semi-closed pulse output signal x2 valid</td> </tr> <tr> <td style="text-align: center;">4</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">5</td> <td style="text-align: center;">adin</td> <td>Interpolation during thread cutting invalid</td> <td>Interpolation during thread cutting valid</td> </tr> <tr> <td style="text-align: center;">6</td> <td style="text-align: center;">orm</td> <td>Orientation start memo invalid</td> <td>Orientation start memo valid</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">vfbs</td> <td colspan="2">This is used by Mitsubishi. Set to "0" unless particularly designated.</td> </tr> <tr> <td style="text-align: center;">8</td> <td style="text-align: center;">sdt2</td> <td>(Follows SFNC6-bitC setting)</td> <td>Set output 2 to 2nd speed detection output</td> </tr> <tr> <td style="text-align: center;">9</td> <td style="text-align: center;">pl80</td> <td>MHE90K detector's 180 wave PLG</td> <td>180 wave PLG other than MHE90K</td> </tr> <tr> <td style="text-align: center;">A</td> <td style="text-align: center;">lmp</td> <td colspan="2">This is used by Mitsubishi. Set to "0" unless particularly designated.</td> </tr> <tr> <td style="text-align: center;">B</td> <td style="text-align: center;">dcsn</td> <td>Dual cushion during acceleration/ deceleration valid</td> <td>Dual cushion during acceleration/ deceleration invalid</td> </tr> <tr> <td style="text-align: center;">C</td> <td style="text-align: center;">XFzs</td> <td>Set output 2 to MP scale low (L) speed mode</td> <td>Set output 2 to zero speed output</td> </tr> <tr> <td style="text-align: center;">D</td> <td style="text-align: center;">iqsv</td> <td colspan="2">This is used by Mitsubishi. Set to "0" unless particularly designated</td> </tr> <tr> <td style="text-align: center;">E</td> <td style="text-align: center;">lmx</td> <td colspan="2"></td> </tr> <tr> <td style="text-align: center;">F</td> <td style="text-align: center;">opl</td> <td>Open loop operation invalid</td> <td>Open loop operation valid</td> </tr> </tbody> </table> <div style="border: 1px solid black; padding: 2px; margin-bottom: 5px;">For MDS-B-SP/SPH</div> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 5%;">bit</th> <th style="width: 10%;">Name</th> <th style="width: 30%;">Meaning when set to 0</th> <th style="width: 30%;">Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">0</td> <td style="text-align: center;">alty</td> <td>Deceleration stop during special alarm invalid</td> <td>Deceleration stop during special alarm valid</td> </tr> <tr> <td style="text-align: center;">1</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">2</td> <td style="text-align: center;">pftm</td> <td>Encoder feedback serial communication invalid</td> <td>Encoder feedback serial communication valid</td> </tr> <tr> <td style="text-align: center;">3</td> <td style="text-align: center;">plg2</td> <td>Semi-closed pulse output signal x2 invalid</td> <td>Semi-closed pulse output signal x2 valid</td> </tr> <tr> <td style="text-align: center;">4</td> <td style="text-align: center;">tdn</td> <td rowspan="7">Fixed control bit</td> <td rowspan="7"></td> </tr> <tr> <td style="text-align: center;">5</td> <td style="text-align: center;">adin</td> </tr> <tr> <td style="text-align: center;">6</td> <td style="text-align: center;">orm</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">vfbs</td> </tr> <tr> <td style="text-align: center;">8</td> <td style="text-align: center;">sdt2</td> </tr> <tr> <td style="text-align: center;">9</td> <td style="text-align: center;">pl80</td> </tr> <tr> <td style="text-align: center;">A</td> <td style="text-align: center;">lmp</td> </tr> <tr> <td style="text-align: center;">B</td> <td style="text-align: center;">dcsn</td> <td rowspan="4">Fixed control bit</td> <td rowspan="4"></td> </tr> <tr> <td style="text-align: center;">C</td> <td style="text-align: center;">XFzs</td> </tr> <tr> <td style="text-align: center;">D</td> <td style="text-align: center;">iqsv</td> </tr> <tr> <td style="text-align: center;">E</td> <td style="text-align: center;">lmx</td> </tr> <tr> <td style="text-align: center;">F</td> <td style="text-align: center;">opl</td> <td>Open loop operation invalid</td> <td>Open loop operation valid</td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8	opl	lmx	iqsv	XFzs	dcsn	lmp	pl80	sdt2									7	6	5	4	3	2	1	0	vfbs	orm	adin	tdn	plg2	pftm		alty	bit	Name	Meaning when set to 0	Meaning when set to 1	0	alty	Deceleration stop during special alarm invalid	Deceleration stop during special alarm valid	1				2	pftm	Encoder feedback serial communication invalid	Encoder feedback serial communication valid	3	plg2	Semi-closed pulse output signal x2 invalid	Semi-closed pulse output signal x2 valid	4				5	adin	Interpolation during thread cutting invalid	Interpolation during thread cutting valid	6	orm	Orientation start memo invalid	Orientation start memo valid	7	vfbs	This is used by Mitsubishi. Set to "0" unless particularly designated.		8	sdt2	(Follows SFNC6-bitC setting)	Set output 2 to 2nd speed detection output	9	pl80	MHE90K detector's 180 wave PLG	180 wave PLG other than MHE90K	A	lmp	This is used by Mitsubishi. Set to "0" unless particularly designated.		B	dcsn	Dual cushion during acceleration/ deceleration valid	Dual cushion during acceleration/ deceleration invalid	C	XFzs	Set output 2 to MP scale low (L) speed mode	Set output 2 to zero speed output	D	iqsv	This is used by Mitsubishi. Set to "0" unless particularly designated		E	lmx			F	opl	Open loop operation invalid	Open loop operation valid	bit	Name	Meaning when set to 0	Meaning when set to 1	0	alty	Deceleration stop during special alarm invalid	Deceleration stop during special alarm valid	1				2	pftm	Encoder feedback serial communication invalid	Encoder feedback serial communication valid	3	plg2	Semi-closed pulse output signal x2 invalid	Semi-closed pulse output signal x2 valid	4	tdn	Fixed control bit		5	adin	6	orm	7	vfbs	8	sdt2	9	pl80	A	lmp	B	dcsn	Fixed control bit		C	XFzs	D	iqsv	E	lmx	F	opl	Open loop operation invalid	Open loop operation valid	0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																																																																											
opl	lmx	iqsv	XFzs	dcsn	lmp	pl80	sdt2																																																																																																																																																											
7	6	5	4	3	2	1	0																																																																																																																																																											
vfbs	orm	adin	tdn	plg2	pftm		alty																																																																																																																																																											
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																																																																															
0	alty	Deceleration stop during special alarm invalid	Deceleration stop during special alarm valid																																																																																																																																																															
1																																																																																																																																																																		
2	pftm	Encoder feedback serial communication invalid	Encoder feedback serial communication valid																																																																																																																																																															
3	plg2	Semi-closed pulse output signal x2 invalid	Semi-closed pulse output signal x2 valid																																																																																																																																																															
4																																																																																																																																																																		
5	adin	Interpolation during thread cutting invalid	Interpolation during thread cutting valid																																																																																																																																																															
6	orm	Orientation start memo invalid	Orientation start memo valid																																																																																																																																																															
7	vfbs	This is used by Mitsubishi. Set to "0" unless particularly designated.																																																																																																																																																																
8	sdt2	(Follows SFNC6-bitC setting)	Set output 2 to 2nd speed detection output																																																																																																																																																															
9	pl80	MHE90K detector's 180 wave PLG	180 wave PLG other than MHE90K																																																																																																																																																															
A	lmp	This is used by Mitsubishi. Set to "0" unless particularly designated.																																																																																																																																																																
B	dcsn	Dual cushion during acceleration/ deceleration valid	Dual cushion during acceleration/ deceleration invalid																																																																																																																																																															
C	XFzs	Set output 2 to MP scale low (L) speed mode	Set output 2 to zero speed output																																																																																																																																																															
D	iqsv	This is used by Mitsubishi. Set to "0" unless particularly designated																																																																																																																																																																
E	lmx																																																																																																																																																																	
F	opl	Open loop operation invalid	Open loop operation valid																																																																																																																																																															
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																																																																															
0	alty	Deceleration stop during special alarm invalid	Deceleration stop during special alarm valid																																																																																																																																																															
1																																																																																																																																																																		
2	pftm	Encoder feedback serial communication invalid	Encoder feedback serial communication valid																																																																																																																																																															
3	plg2	Semi-closed pulse output signal x2 invalid	Semi-closed pulse output signal x2 valid																																																																																																																																																															
4	tdn	Fixed control bit																																																																																																																																																																
5	adin																																																																																																																																																																	
6	orm																																																																																																																																																																	
7	vfbs																																																																																																																																																																	
8	sdt2																																																																																																																																																																	
9	pl80																																																																																																																																																																	
A	lmp																																																																																																																																																																	
B	dcsn	Fixed control bit																																																																																																																																																																
C	XFzs																																																																																																																																																																	
D	iqsv																																																																																																																																																																	
E	lmx																																																																																																																																																																	
F	opl	Open loop operation invalid	Open loop operation valid																																																																																																																																																															

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items			Details	Setting range	Standard setting																																				
3239 (PR)	SP039	ATYP	Amplifier type	Set the amplifier type. Set each amplifier type or "0" <table border="1" data-bbox="624 465 1082 1070"> <thead> <tr> <th>Parameter setting</th> <th>Amplifier type</th> </tr> </thead> <tbody> <tr><td>0000</td><td>—</td></tr> <tr><td>0001</td><td>SP-075</td></tr> <tr><td>0002</td><td>SP-15</td></tr> <tr><td>0003</td><td>SP-22</td></tr> <tr><td>0004</td><td>SP-37</td></tr> <tr><td>0005</td><td>SP-55</td></tr> <tr><td>0006</td><td>SP-75</td></tr> <tr><td>0007</td><td>SP-110</td></tr> <tr><td>0008</td><td>SP-150</td></tr> <tr><td>0009</td><td>SP-185</td></tr> <tr><td>000A</td><td>SP-220</td></tr> <tr><td>000B</td><td>SP-260</td></tr> <tr><td>000C</td><td>SP-300</td></tr> <tr><td>000D</td><td>SP (H)-370</td></tr> <tr><td>000E</td><td>SP (H)-450</td></tr> <tr><td>000F</td><td>SP-04</td></tr> <tr><td>0010</td><td>SP-550</td></tr> </tbody> </table>	Parameter setting	Amplifier type	0000	—	0001	SP-075	0002	SP-15	0003	SP-22	0004	SP-37	0005	SP-55	0006	SP-75	0007	SP-110	0008	SP-150	0009	SP-185	000A	SP-220	000B	SP-260	000C	SP-300	000D	SP (H)-370	000E	SP (H)-450	000F	SP-04	0010	SP-550	0000 to FFFF HEX setting	0000
Parameter setting	Amplifier type																																									
0000	—																																									
0001	SP-075																																									
0002	SP-15																																									
0003	SP-22																																									
0004	SP-37																																									
0005	SP-55																																									
0006	SP-75																																									
0007	SP-110																																									
0008	SP-150																																									
0009	SP-185																																									
000A	SP-220																																									
000B	SP-260																																									
000C	SP-300																																									
000D	SP (H)-370																																									
000E	SP (H)-450																																									
000F	SP-04																																									
0010	SP-550																																									

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items			Details	Setting range	Standard setting																																																																																																																																				
3240 (PR)	SP040	MTYP	Motor type	<p>This parameter is valid when SP034 (SFNC2) bit0 is set to "0". Set the appropriate motor number from the standard motors listed below.</p> <table border="1" data-bbox="628 546 1139 1563"> <thead> <tr> <th>Parameter setting</th> <th>Motor type</th> <th>Maximum speed</th> <th>Corre-sponding amplifier</th> </tr> </thead> <tbody> <tr><td>0000</td><td></td><td></td><td></td></tr> <tr><td>0001</td><td>SJ-2.2A</td><td>10000 r/min</td><td>SP-22</td></tr> <tr><td>0002</td><td>SJ-3.7A</td><td>10000 r/min</td><td>SP-37</td></tr> <tr><td>0003</td><td>SJ-5.5A</td><td>8000 r/min</td><td>SP-55</td></tr> <tr><td>0004</td><td>SJ-7.5A</td><td>8000 r/min</td><td>SP-75</td></tr> <tr><td>0005</td><td>SJ-11A</td><td>6000 r/min</td><td>SP-110</td></tr> <tr><td>0006</td><td>SJ-15A</td><td>6000 r/min</td><td>SP-150</td></tr> <tr><td>0007</td><td>SJ-18.5A</td><td>6000 r/min</td><td>SP-185</td></tr> <tr><td>0008</td><td>SJ-22A</td><td>4500 r/min</td><td>SP-220</td></tr> <tr><td>0009</td><td>SJ-26A</td><td>4500 r/min</td><td>SP-260</td></tr> <tr><td>000A</td><td>SJ-30A</td><td>4500 r/min</td><td>SP-300</td></tr> <tr><td>000B</td><td></td><td></td><td></td></tr> <tr><td>000C</td><td></td><td></td><td></td></tr> <tr><td>000D</td><td></td><td></td><td></td></tr> <tr><td>000E</td><td></td><td></td><td></td></tr> <tr><td>000F</td><td></td><td></td><td></td></tr> <tr><td>0010</td><td></td><td></td><td></td></tr> <tr><td>0011</td><td>SJ-N0.75A</td><td>10000 r/min</td><td>SP-075</td></tr> <tr><td>0012</td><td>SJ-N1.5A</td><td>10000 r/min</td><td>SP-15</td></tr> <tr><td>0013</td><td>SJ-N2.2A</td><td>10000 r/min</td><td>SP-22</td></tr> <tr><td>0014</td><td>SJ-N3.7A</td><td>10000 r/min</td><td>SP-37</td></tr> <tr><td>0015</td><td>SJ-N5.5A</td><td>8000 r/min</td><td>SP-55</td></tr> <tr><td>0016</td><td>SJ-N7.5A</td><td>8000 r/min</td><td>SP-75</td></tr> <tr><td>0017</td><td></td><td></td><td></td></tr> <tr><td>0018</td><td></td><td></td><td></td></tr> <tr><td>0019</td><td></td><td></td><td></td></tr> <tr><td>001A</td><td></td><td></td><td></td></tr> <tr><td>001B</td><td>SJ-J2.2A</td><td>10000 r/min</td><td>SP-22</td></tr> <tr><td>001C</td><td>SJ-J3.7A</td><td>10000 r/min</td><td>SP-37</td></tr> <tr><td>001D</td><td>SJ-J5.5A</td><td>8000 r/min</td><td>SP-55</td></tr> <tr><td>001E</td><td>SJ-J7.5A</td><td>8000 r/min</td><td>SP-75</td></tr> <tr><td>001F</td><td></td><td></td><td></td></tr> </tbody> </table>	Parameter setting	Motor type	Maximum speed	Corre-sponding amplifier	0000				0001	SJ-2.2A	10000 r/min	SP-22	0002	SJ-3.7A	10000 r/min	SP-37	0003	SJ-5.5A	8000 r/min	SP-55	0004	SJ-7.5A	8000 r/min	SP-75	0005	SJ-11A	6000 r/min	SP-110	0006	SJ-15A	6000 r/min	SP-150	0007	SJ-18.5A	6000 r/min	SP-185	0008	SJ-22A	4500 r/min	SP-220	0009	SJ-26A	4500 r/min	SP-260	000A	SJ-30A	4500 r/min	SP-300	000B				000C				000D				000E				000F				0010				0011	SJ-N0.75A	10000 r/min	SP-075	0012	SJ-N1.5A	10000 r/min	SP-15	0013	SJ-N2.2A	10000 r/min	SP-22	0014	SJ-N3.7A	10000 r/min	SP-37	0015	SJ-N5.5A	8000 r/min	SP-55	0016	SJ-N7.5A	8000 r/min	SP-75	0017				0018				0019				001A				001B	SJ-J2.2A	10000 r/min	SP-22	001C	SJ-J3.7A	10000 r/min	SP-37	001D	SJ-J5.5A	8000 r/min	SP-55	001E	SJ-J7.5A	8000 r/min	SP-75	001F				0000 to FFFF HEX setting	0000
Parameter setting	Motor type	Maximum speed	Corre-sponding amplifier																																																																																																																																							
0000																																																																																																																																										
0001	SJ-2.2A	10000 r/min	SP-22																																																																																																																																							
0002	SJ-3.7A	10000 r/min	SP-37																																																																																																																																							
0003	SJ-5.5A	8000 r/min	SP-55																																																																																																																																							
0004	SJ-7.5A	8000 r/min	SP-75																																																																																																																																							
0005	SJ-11A	6000 r/min	SP-110																																																																																																																																							
0006	SJ-15A	6000 r/min	SP-150																																																																																																																																							
0007	SJ-18.5A	6000 r/min	SP-185																																																																																																																																							
0008	SJ-22A	4500 r/min	SP-220																																																																																																																																							
0009	SJ-26A	4500 r/min	SP-260																																																																																																																																							
000A	SJ-30A	4500 r/min	SP-300																																																																																																																																							
000B																																																																																																																																										
000C																																																																																																																																										
000D																																																																																																																																										
000E																																																																																																																																										
000F																																																																																																																																										
0010																																																																																																																																										
0011	SJ-N0.75A	10000 r/min	SP-075																																																																																																																																							
0012	SJ-N1.5A	10000 r/min	SP-15																																																																																																																																							
0013	SJ-N2.2A	10000 r/min	SP-22																																																																																																																																							
0014	SJ-N3.7A	10000 r/min	SP-37																																																																																																																																							
0015	SJ-N5.5A	8000 r/min	SP-55																																																																																																																																							
0016	SJ-N7.5A	8000 r/min	SP-75																																																																																																																																							
0017																																																																																																																																										
0018																																																																																																																																										
0019																																																																																																																																										
001A																																																																																																																																										
001B	SJ-J2.2A	10000 r/min	SP-22																																																																																																																																							
001C	SJ-J3.7A	10000 r/min	SP-37																																																																																																																																							
001D	SJ-J5.5A	8000 r/min	SP-55																																																																																																																																							
001E	SJ-J7.5A	8000 r/min	SP-75																																																																																																																																							
001F																																																																																																																																										

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting																																																																																																																																																										
3241 (PR)	SP041	PTYP	Power supply type	0000 to FFFF HEX setting	0000																																																																																																																																																										
			Power supply type F E D C B A 9 8 <table border="1" style="width:100%; text-align:center;"> <tr> <td colspan="4">amp</td> <td colspan="4">rtyp</td> </tr> </table> 7 6 5 4 3 2 1 0 <table border="1" style="width:100%; text-align:center;"> <tr> <td colspan="8">ptyp</td> </tr> </table>	amp				rtyp				ptyp																																																																																																																																																			
amp				rtyp																																																																																																																																																											
ptyp																																																																																																																																																															
			<table border="1"> <thead> <tr> <th>bit</th> <th colspan="10">Explanation</th> </tr> </thead> <tbody> <tr> <td>0</td> <td colspan="10">When the CN4 connector of the drive unit and the power supply are connected, setting below is necessary.</td> </tr> <tr> <td>1</td> <td colspan="10">To validate the external emergency stop function, add 40h.</td> </tr> <tr> <td>3</td> <td>Set-ting</td> <td>0x</td> <td>1x</td> <td>2x</td> <td>3x</td> <td>4x</td> <td>5x</td> <td>6x</td> <td>7x</td> <td>8x</td> </tr> <tr> <td>4</td> <td>ptyp</td> <td>x0</td> <td>Not used</td> <td></td> <td></td> <td>CV-300</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td>x1</td> <td></td> <td>CV-110</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-10</td> </tr> <tr> <td>6</td> <td></td> <td>x2</td> <td></td> <td></td> <td>CV-220</td> <td></td> <td></td> <td></td> <td></td> <td>CR-15</td> </tr> <tr> <td>7</td> <td></td> <td>x3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-22</td> </tr> <tr> <td></td> <td></td> <td>x4</td> <td>CV-37</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-37</td> </tr> <tr> <td></td> <td></td> <td>x5</td> <td></td> <td>CV-150</td> <td></td> <td></td> <td>CV-450</td> <td>CV-550</td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td>x6</td> <td>CV-55</td> <td></td> <td>CV-260</td> <td></td> <td></td> <td></td> <td></td> <td>CR-55</td> </tr> <tr> <td></td> <td></td> <td>x7</td> <td></td> <td></td> <td></td> <td>CV-370</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td>x8</td> <td>CV-75</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-75</td> </tr> <tr> <td></td> <td></td> <td>x9</td> <td></td> <td>CV-185</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-90</td> </tr> </tbody> </table>	bit	Explanation										0	When the CN4 connector of the drive unit and the power supply are connected, setting below is necessary.										1	To validate the external emergency stop function, add 40h.										3	Set-ting	0x	1x	2x	3x	4x	5x	6x	7x	8x	4	ptyp	x0	Not used			CV-300					5		x1		CV-110						CR-10	6		x2			CV-220					CR-15	7		x3								CR-22			x4	CV-37							CR-37			x5		CV-150			CV-450	CV-550					x6	CV-55		CV-260					CR-55			x7				CV-370							x8	CV-75							CR-75			x9		CV-185						CR-90		
bit	Explanation																																																																																																																																																														
0	When the CN4 connector of the drive unit and the power supply are connected, setting below is necessary.																																																																																																																																																														
1	To validate the external emergency stop function, add 40h.																																																																																																																																																														
3	Set-ting	0x	1x	2x	3x	4x	5x	6x	7x	8x																																																																																																																																																					
4	ptyp	x0	Not used			CV-300																																																																																																																																																									
5		x1		CV-110						CR-10																																																																																																																																																					
6		x2			CV-220					CR-15																																																																																																																																																					
7		x3								CR-22																																																																																																																																																					
		x4	CV-37							CR-37																																																																																																																																																					
		x5		CV-150			CV-450	CV-550																																																																																																																																																							
		x6	CV-55		CV-260					CR-55																																																																																																																																																					
		x7				CV-370																																																																																																																																																									
		x8	CV-75							CR-75																																																																																																																																																					
		x9		CV-185						CR-90																																																																																																																																																					
			<table border="1"> <thead> <tr> <th>bit</th> <th colspan="3">Explanation</th> </tr> </thead> <tbody> <tr> <td>8</td> <td colspan="3">Set the regenerative resistor type when MDS-A-CR is used.</td> </tr> <tr> <td>9</td> <td>rtyp</td> <td>Set-ting</td> <td>Regenerative resistor model name</td> </tr> <tr> <td>A</td> <td></td> <td>0</td> <td>MDS-C1-CV (Setting when using power supply regeneration)</td> </tr> <tr> <td>B</td> <td></td> <td>1</td> <td>GZG200W260HMJ</td> </tr> <tr> <td></td> <td></td> <td>2</td> <td>GZG300W130HMJ×2</td> </tr> <tr> <td></td> <td></td> <td>3</td> <td>MR-RB30</td> </tr> <tr> <td></td> <td></td> <td>4</td> <td>MR-RB50</td> </tr> <tr> <td></td> <td></td> <td>5</td> <td>GZG200W200HMJ×3</td> </tr> <tr> <td></td> <td></td> <td>6</td> <td>GZG300W200HMJ×3</td> </tr> <tr> <td></td> <td></td> <td>7</td> <td>R-UNIT-1</td> </tr> <tr> <td></td> <td></td> <td>8</td> <td>R-UNIT-2</td> </tr> <tr> <td></td> <td></td> <td>9</td> <td>R-UNIT-3</td> </tr> <tr> <td></td> <td></td> <td>A to D</td> <td>No setting</td> </tr> <tr> <td></td> <td></td> <td>E</td> <td>Large capacity + ready ON high-speed sequence</td> </tr> <tr> <td></td> <td></td> <td>F</td> <td>Ready ON high-speed sequence</td> </tr> </tbody> </table>	bit	Explanation			8	Set the regenerative resistor type when MDS-A-CR is used.			9	rtyp	Set-ting	Regenerative resistor model name	A		0	MDS-C1-CV (Setting when using power supply regeneration)	B		1	GZG200W260HMJ			2	GZG300W130HMJ×2			3	MR-RB30			4	MR-RB50			5	GZG200W200HMJ×3			6	GZG300W200HMJ×3			7	R-UNIT-1			8	R-UNIT-2			9	R-UNIT-3			A to D	No setting			E	Large capacity + ready ON high-speed sequence			F	Ready ON high-speed sequence																																																																																												
bit	Explanation																																																																																																																																																														
8	Set the regenerative resistor type when MDS-A-CR is used.																																																																																																																																																														
9	rtyp	Set-ting	Regenerative resistor model name																																																																																																																																																												
A		0	MDS-C1-CV (Setting when using power supply regeneration)																																																																																																																																																												
B		1	GZG200W260HMJ																																																																																																																																																												
		2	GZG300W130HMJ×2																																																																																																																																																												
		3	MR-RB30																																																																																																																																																												
		4	MR-RB50																																																																																																																																																												
		5	GZG200W200HMJ×3																																																																																																																																																												
		6	GZG300W200HMJ×3																																																																																																																																																												
		7	R-UNIT-1																																																																																																																																																												
		8	R-UNIT-2																																																																																																																																																												
		9	R-UNIT-3																																																																																																																																																												
		A to D	No setting																																																																																																																																																												
		E	Large capacity + ready ON high-speed sequence																																																																																																																																																												
		F	Ready ON high-speed sequence																																																																																																																																																												
			<table border="1"> <thead> <tr> <th>bit</th> <th colspan="1">Explanation</th> </tr> </thead> <tbody> <tr> <td>C</td> <td>Always set to "0".</td> </tr> <tr> <td>D</td> <td></td> </tr> <tr> <td>E</td> <td>amp</td> </tr> <tr> <td>F</td> <td></td> </tr> </tbody> </table>	bit	Explanation	C	Always set to "0".	D		E	amp	F																																																																																																																																																			
bit	Explanation																																																																																																																																																														
C	Always set to "0".																																																																																																																																																														
D																																																																																																																																																															
E	amp																																																																																																																																																														
F																																																																																																																																																															
3242 (PR)	SP042	CRNG	C-axis detector range	0 to 7	0																																																																																																																																																										
			This parameter is used to set the C-axis detector range. Set "0" for this parameter. "2" is used by Mitsubishi for testing.																																																																																																																																																												



8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting
3243 (PR)	SP043	TRNG	Synchronous tapping, spindle synchronous detector range	This parameter is used to set the synchronous tapping or spindle synchronous detector range. Set "0" for this parameter.	0 to 7 0
3244 (PR)	SP044	TRANS	NC communication frequency	Set a frequency of data communication with NC.	0 to 32767 Standard: 0 Special: 1028
3245	SP045	CSNT	Dual cushion timer	Set the cycle to add the increment values in the dual cushion process. When this setting value is increased, the dual cushion will increase, and the changes in the speed during acceleration/deceleration will become gradual.	0 to 1000 (ms) 0
3246 (PR)	SP046	CSN2	Speed command dual cushion	For an acceleration/deceleration time constant defined in SP019 (CSN1) , this parameter is used to provide smooth movement only at the start of acceleration/deceleration. As the value of this parameter is smaller, it moves smoother but the acceleration/deceleration time becomes longer. To make this parameter invalid, set "0".	0 to 1000 0
3247 (PR)	SP047	SDTR	Speed detection reset value	Set the reset hysteresis width for a speed detection set value defined in SP020 (SDTS).	0 to 1000 (r/min) 30
3247 (PR)	SP047	SDTR	Speed detection reset value	Set the reset hysteresis width for a speed detection set value defined in SP020 (SDTS).	0 to 1000 (r/min) 30
3248 (PR)	SP048	SUT	Speed reach range	Set the speed deviation rate with respect to the commanded speed for output of the speed reach signal.	0 to 100 (%) 15
3249	SP049	TLM2	Torque limit 2	Set the torque limit rate for the torque limit signal 010.	1 to 120 (%) 20
3250	SP050	TLM3	Torque limit 3	Set the torque limit rate for the torque limit signal 011.	1 to 120 (%) 30
3251	SP051	TLM4	Torque limit 4	Set the torque limit rate for the torque limit signal 100.	1 to 120 (%) 40
3252	SP052	TLM5	Torque limit 5	Set the torque limit rate for the torque limit signal 101.	1 to 120 (%) 50
3253	SP053	TLM6	Torque limit 6	Set the torque limit rate for the torque limit signal 110.	1 to 120 (%) 60
3254	SP054	TLM7	Torque limit 7	Set the torque limit rate for the torque limit signal 111.	1 to 120 (%) 70

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting
3255 (PR)	SP055	SETM	Excessive speed deviation timer	Set the timer value until the excessive speed deviation alarm is output. The value of this parameter should be longer than the acceleration/deceleration time.	0 to 60 (s) 12
3256	SP056	PYVR	Variable excitation (min value)	Set the minimum value of the variable excitation rate. Select a smaller value when gear noise is too high. However, a larger value is effective for impact response.	0 to 100 (%) 50
3257 (PR)	SP057	STOD	Constant → excessive judgment value	Set the value for judging when changing from a constant to excessive speed command.	0 to 50 (r/min) 0
3258 (PR)	SP058	SDT2	Fixed control constant	Set by Mitsubishi. Set "0" unless designated in particular.	0 0
3259 (PR)	SP059	MKT	Winding changeover base shut-off timer	Set the base shut-off time for contactor switching at winding changeover. Note that the contactor may be damaged with burning if the value of this parameter is too small.	50 to 10000 (ms) 150
3260 (PR)	SP060	MKT2	Current limit timer after winding changeover	Set the current limit time to be taken after completion of contactor switching at winding changeover.	0 to 10000 (ms) 500
3261 (PR)	SP061	MKIL	Current limit value after winding changeover	Set the current limit value during a period defined in SP060 (MKT2) after completion of contactor switching at winding changeover.	0 to 120 (%) 75
3262	SP062			Not used. Set to "0".	0 0

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH


No.	Items		Details	Setting range	Standard setting
3263 (PR)	SP063	OLT	Overload alarm detection time	Set the time constant for detection of the motor overload alarm.	0 to 1000 (s) 60
3264 (PR)	SP064	OLL	Overload alarm detection level	Set the detection level of the motor overload alarm.	0 to 120 (%) 110
3265 (PR)	SP065	VCGN1	Target value of variable speed loop proportional gain	Set the magnification of speed loop proportional gain with respect to SP022 (VGNP1) at the maximum motor speed defined in SP017 (TSP).	0 to 100 (%) 100
3266 (PR)	SP066	VCSN1	Change starting speed of variable speed loop proportional gain	Set the speed when the speed loop proportional gain change starts. 	0 to 32767 (r/min) 0
3267 (PR)	SP067	VIGWA	Change starting speed of variable current loop gain	Set the speed where the current loop gain change starts.	0 to 32767 (r/min) 0
3268 (PR)	SP068	VIGWB	Change ending speed of variable current loop gain	Set the speed where the current loop gain change ends.	0 to 32767 (r/min) 0
3269 (PR)	SP069	VIGN	Target value of variable current loop gain	Set the magnification of current loop gain (torque component and excitation component) for a change ending speed defined in SP068 (VIGWB). When this parameter is set to "0", the magnification is 1. 	0 to 32767 (1/16-fold) 0

SP017 (TSP) Maximum motor speed	SP067 (VIGWA)	SP068 (VIGWB)	SP069 (VIGN)
0 to 6000	0	0	0
6001 to 8000	5000	8000	45
8001 or more	5000	10000	64

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting																																																																																																				
3270	SP070	FHz	Machine resonance suppression filter frequency	When machine vibration occurs in speed and position control, set the frequency of the required vibration suppression. Note that a value of 100Hz or more is set. Set to "0" when not used.	0 to 3000 (Hz)	0																																																																																																			
3271 (PR)	SP071	VR2WA	Fixed control constant	Set by Mitsubishi. Set "0" unless designated in particular.	0	0																																																																																																			
3272 (PR)	SP072	VR2WB																																																																																																							
3273 (PR)	SP073	VR2GN																																																																																																							
3274 (PR)	SP074	IGDEC																																																																																																							
3275	SP075	R2KWS	<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td align="center">F</td><td align="center">E</td><td align="center">D</td><td align="center">C</td><td align="center">B</td><td align="center">A</td><td align="center">9</td><td align="center">8</td> </tr> <tr> <td align="center"> </td><td align="center">r2ini</td> </tr> <tr> <td align="center">7</td><td align="center">6</td><td align="center">5</td><td align="center">4</td><td align="center">3</td><td align="center">2</td><td align="center">1</td><td align="center">0</td> </tr> <tr> <td align="center"> </td><td align="center"> </td><td align="center"> </td><td align="center">r2am</td><td align="center">r2lm</td><td align="center">r2dn</td><td align="center">no51</td><td align="center">r2ch</td> </tr> </table> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>bit</th><th>Name</th><th>Meaning when set to 0</th><th>Meaning when set to 1</th></tr> </thead> <tbody> <tr> <td align="center">0</td><td>r2ch</td><td colspan="2">This is used by Mitsubishi.</td></tr> <tr> <td align="center">1</td><td>no51</td><td colspan="2">Set to "0" unless particularly designated.</td></tr> <tr> <td align="center">2</td><td>r2dm</td><td colspan="2"> </td></tr> <tr> <td align="center">3</td><td>r2lm</td><td colspan="2"> </td></tr> <tr> <td align="center">4</td><td>r2am</td><td colspan="2"> </td></tr> <tr> <td align="center">5</td><td> </td><td> </td><td> </td></tr> <tr> <td align="center">6</td><td> </td><td> </td><td> </td></tr> <tr> <td align="center">7</td><td> </td><td> </td><td> </td></tr> <tr> <td align="center">8</td><td>r2ini</td><td colspan="2">This is used by Mitsubishi. Set to "0" unless particularly designated</td></tr> <tr> <td align="center">9</td><td> </td><td> </td><td> </td></tr> <tr> <td align="center">A</td><td> </td><td> </td><td> </td></tr> <tr> <td align="center">B</td><td> </td><td> </td><td> </td></tr> <tr> <td align="center">C</td><td> </td><td> </td><td> </td></tr> <tr> <td align="center">D</td><td> </td><td> </td><td> </td></tr> <tr> <td align="center">E</td><td> </td><td> </td><td> </td></tr> <tr> <td align="center">F</td><td> </td><td> </td><td> </td></tr> </tbody> </table>	F	E	D	C	B	A	9	8								r2ini	7	6	5	4	3	2	1	0				r2am	r2lm	r2dn	no51	r2ch	bit	Name	Meaning when set to 0	Meaning when set to 1	0	r2ch	This is used by Mitsubishi.		1	no51	Set to "0" unless particularly designated.		2	r2dm			3	r2lm			4	r2am			5				6				7				8	r2ini	This is used by Mitsubishi. Set to "0" unless particularly designated		9				A				B				C				D				E				F					
F	E	D	C	B	A	9	8																																																																																																		
							r2ini																																																																																																		
7	6	5	4	3	2	1	0																																																																																																		
			r2am	r2lm	r2dn	no51	r2ch																																																																																																		
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																						
0	r2ch	This is used by Mitsubishi.																																																																																																							
1	no51	Set to "0" unless particularly designated.																																																																																																							
2	r2dm																																																																																																								
3	r2lm																																																																																																								
4	r2am																																																																																																								
5																																																																																																									
6																																																																																																									
7																																																																																																									
8	r2ini	This is used by Mitsubishi. Set to "0" unless particularly designated																																																																																																							
9																																																																																																									
A																																																																																																									
B																																																																																																									
C																																																																																																									
D																																																																																																									
E																																																																																																									
F																																																																																																									
3276	SP076	FONS	Machine resonance suppression filter operation speed	When the vibration increases in motor stop (ex. in orientation stop) when the machine vibration suppression filter is operated by SP070, operate the machine vibration suppression filter at a speed of this parameter or more. When set to "0", this is validated for all speeds.	0 to 32767 (r/min)	0																																																																																																			
3277 (PR)	SP077	TDSL	Fixed control constant	Set by Mitsubishi. Set "14" unless designated in particular.		14																																																																																																			
3278 (PR)	SP078	FPWM	Fixed control constant	Set by Mitsubishi. Set "0" unless designated in particular.	0	0																																																																																																			
3279 (PR)	SP079	ILMT																																																																																																							

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3280	SP080			Use not possible.	0	0
3281	SP081	LMCA	Fixed control constant	This is used by Mitsubishi. Set to "0" unless particularly designated.	0	0
3282	SP082	LMCB				
3283	SP083					
3284 to 3286	SP084 to SP086			Use not possible.	0	0
3287 (PR)	SP087	DIQM	Target value of variable torque limit magnification at deceleration	Set the minimum value of variable torque limit at deceleration.	0 to 150 (%)	75
3288 (PR)	SP088	DIQN	Speed for starting change of variable torque limit magnification at deceleration	Set the speed where the torque limit value at deceleration starts to change. 	0 to 32767 (r/min)	3000
3289	SP089			Use not possible.	0	0
3290	SP090			Use not possible.	0	0
3291	SP091	OFSN	Motor PLG forward rotation offset compensation	Set the PLG offset value for the forward rotation. Normally set to "0".	-2048 to 2047 (-1mv)	0
3292	SP092	OFSI	Motor PLG reverse rotation offset compensation	Set the PLG offset value for the reverse rotation. Normally set to "0".	-2048 to 2047 (-1mv)	0
3293 (PR)	SP093	ORE	Tolerable pulse check error	Set this when detecting the pulse detector's pulse mistakes. (Valid only for full close control.)	0 to 32767	0
3294 (PR)	SP094	LMAV	Load meter output filter	Set the filter time constant of load meter output. When "0" is set, a filter time constant is set to 100ms.	0 to 32767 (2ms)	0
3295 (PR)	SP095	VFAV	Fixed control constant	Set by Mitsubishi. Set "0" unless designated in particular.	0	0

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting																																																																																																						
3296 (PR)	SP096	EGAR	Encoder gear ratio <table border="1"> <thead> <tr> <th>Setting value</th> <th>Gear ratio (deceleration)</th> <th>Setting value</th> <th>Gear ratio (acceleration)</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>1 : 1</td> <td>-1</td> <td>1 : 2</td> </tr> <tr> <td>1</td> <td>1 : 1/2</td> <td>-2</td> <td>1 : 4</td> </tr> <tr> <td>2</td> <td>1 : 1/4</td> <td>-3</td> <td>1 : 3</td> </tr> <tr> <td>3</td> <td>1 : 1/8</td> <td></td> <td></td> </tr> <tr> <td>4</td> <td>1 : 1/16</td> <td></td> <td></td> </tr> </tbody> </table>	Setting value	Gear ratio (deceleration)	Setting value	Gear ratio (acceleration)	0	1 : 1	-1	1 : 2	1	1 : 1/2	-2	1 : 4	2	1 : 1/4	-3	1 : 3	3	1 : 1/8			4	1 : 1/16			-3 to 4	0																																																																														
Setting value	Gear ratio (deceleration)	Setting value	Gear ratio (acceleration)																																																																																																								
0	1 : 1	-1	1 : 2																																																																																																								
1	1 : 1/2	-2	1 : 4																																																																																																								
2	1 : 1/4	-3	1 : 3																																																																																																								
3	1 : 1/8																																																																																																										
4	1 : 1/16																																																																																																										
3297 (PR)	SP097	SPECO	Orientation specification Set the orientation specifications in bit units. F E D C B A 9 8 <table border="1"> <tr> <td>ostp</td> <td>orze</td> <td>ksft</td> <td>gchg</td> <td></td> <td>ips2</td> <td>zdir</td> <td></td> </tr> </table> 7 6 5 4 3 2 1 0 <table border="1"> <tr> <td>vg8x</td> <td>mdir</td> <td>fdir</td> <td>osc1</td> <td>pyfx</td> <td>dmin</td> <td>odi2</td> <td>odi1</td> </tr> </table> (Note) Always set "0" for the empty bits. <table border="1"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>odi1</td> <td colspan="2">Orientation rotation direction</td> </tr> <tr> <td rowspan="2">1</td> <td>odi2</td> <td colspan="2">00: Previous (the direction in which the motor has so far rotated under speed control)</td> </tr> <tr> <td></td> <td colspan="2">01: Forward rotation 10: Backward rotation 11: Prohibited (Same as setting value = 10)</td> </tr> <tr> <td>2</td> <td>dmin</td> <td>Orientation in-position advance invalid</td> <td>Orientation in-position advance valid</td> </tr> <tr> <td>3</td> <td>pyfx</td> <td>Excitation min. (50%) during orientation servo lock invalid</td> <td>Excitation min. (50%) during orientation servo lock valid</td> </tr> <tr> <td>4</td> <td>osc1</td> <td>Indexing speed clamp invalid</td> <td>Indexing speed clamp valid</td> </tr> <tr> <td>5</td> <td>fdir</td> <td>Encoder detector polarity: +</td> <td>Encoder detector polarity: -</td> </tr> <tr> <td>6</td> <td>mdir</td> <td>Magnetic sensor polarity: +</td> <td>Magnetic sensor polarity: -</td> </tr> <tr> <td>7</td> <td>vg8x</td> <td>Speed gain *1/8 during torque limit valid</td> <td>Speed gain *1/8 during torque limit invalid</td> </tr> <tr> <td>8</td> <td></td> <td></td> <td></td> </tr> <tr> <td>9</td> <td>zdir</td> <td colspan="2">This is used by Mitsubishi. Set to "0" unless particularly designated.</td> </tr> <tr> <td>A</td> <td>ips2</td> <td>2nd in-position invalid</td> <td>2nd in-position valid</td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td>gchg</td> <td>Gain changeover during orientation invalid</td> <td>Gain changeover during orientation valid</td> </tr> <tr> <td>D</td> <td>ksft</td> <td>Orientation virtual target shift invalid</td> <td>Orientation virtual target shift valid</td> </tr> <tr> <td>E</td> <td>orze</td> <td colspan="2">This is used by Mitsubishi.</td> </tr> <tr> <td>F</td> <td>ostp</td> <td colspan="2">Set to "0" unless particularly designated.</td> </tr> </tbody> </table> <table border="1"> <thead> <tr> <th colspan="2"></th> <th colspan="2">In-position advance (bit 2)</th> </tr> <tr> <th colspan="2"></th> <th>0 (invalid)</th> <th>1 (valid)</th> </tr> </thead> <tbody> <tr> <td rowspan="2">Second in-position</td> <td>0 (Invalid)</td> <td>In-position signal in OINP width=1 Control output 4/ bit 4=1 Second in-position signal=0 Control output 4/ bit F=1</td> <td>In-position signal in OINP width=1 Control output 4/ bit 4=1 Second in-position signal=0 Control output 4/ bit F=0</td> </tr> <tr> <td>1 (Valid)</td> <td></td> <td>In-position signal in DINP width=1 Control output 4/ bit 4=1 Second in-position signal in OINP width = 0 Control output 4/ bit F=1</td> </tr> </tbody> </table>	ostp	orze	ksft	gchg		ips2	zdir		vg8x	mdir	fdir	osc1	pyfx	dmin	odi2	odi1	bit	Name	Meaning when set to 0	Meaning when set to 1	0	odi1	Orientation rotation direction		1	odi2	00: Previous (the direction in which the motor has so far rotated under speed control)			01: Forward rotation 10: Backward rotation 11: Prohibited (Same as setting value = 10)		2	dmin	Orientation in-position advance invalid	Orientation in-position advance valid	3	pyfx	Excitation min. (50%) during orientation servo lock invalid	Excitation min. (50%) during orientation servo lock valid	4	osc1	Indexing speed clamp invalid	Indexing speed clamp valid	5	fdir	Encoder detector polarity: +	Encoder detector polarity: -	6	mdir	Magnetic sensor polarity: +	Magnetic sensor polarity: -	7	vg8x	Speed gain *1/8 during torque limit valid	Speed gain *1/8 during torque limit invalid	8				9	zdir	This is used by Mitsubishi. Set to "0" unless particularly designated.		A	ips2	2nd in-position invalid	2nd in-position valid	B				C	gchg	Gain changeover during orientation invalid	Gain changeover during orientation valid	D	ksft	Orientation virtual target shift invalid	Orientation virtual target shift valid	E	orze	This is used by Mitsubishi.		F	ostp	Set to "0" unless particularly designated.				In-position advance (bit 2)				0 (invalid)	1 (valid)	Second in-position	0 (Invalid)	In-position signal in OINP width=1 Control output 4/ bit 4=1 Second in-position signal=0 Control output 4/ bit F=1	In-position signal in OINP width=1 Control output 4/ bit 4=1 Second in-position signal=0 Control output 4/ bit F=0	1 (Valid)		In-position signal in DINP width=1 Control output 4/ bit 4=1 Second in-position signal in OINP width = 0 Control output 4/ bit F=1	0000 to FFFF HEX setting	0000
ostp	orze	ksft	gchg		ips2	zdir																																																																																																					
vg8x	mdir	fdir	osc1	pyfx	dmin	odi2	odi1																																																																																																				
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																								
0	odi1	Orientation rotation direction																																																																																																									
1	odi2	00: Previous (the direction in which the motor has so far rotated under speed control)																																																																																																									
		01: Forward rotation 10: Backward rotation 11: Prohibited (Same as setting value = 10)																																																																																																									
2	dmin	Orientation in-position advance invalid	Orientation in-position advance valid																																																																																																								
3	pyfx	Excitation min. (50%) during orientation servo lock invalid	Excitation min. (50%) during orientation servo lock valid																																																																																																								
4	osc1	Indexing speed clamp invalid	Indexing speed clamp valid																																																																																																								
5	fdir	Encoder detector polarity: +	Encoder detector polarity: -																																																																																																								
6	mdir	Magnetic sensor polarity: +	Magnetic sensor polarity: -																																																																																																								
7	vg8x	Speed gain *1/8 during torque limit valid	Speed gain *1/8 during torque limit invalid																																																																																																								
8																																																																																																											
9	zdir	This is used by Mitsubishi. Set to "0" unless particularly designated.																																																																																																									
A	ips2	2nd in-position invalid	2nd in-position valid																																																																																																								
B																																																																																																											
C	gchg	Gain changeover during orientation invalid	Gain changeover during orientation valid																																																																																																								
D	ksft	Orientation virtual target shift invalid	Orientation virtual target shift valid																																																																																																								
E	orze	This is used by Mitsubishi.																																																																																																									
F	ostp	Set to "0" unless particularly designated.																																																																																																									
		In-position advance (bit 2)																																																																																																									
		0 (invalid)	1 (valid)																																																																																																								
Second in-position	0 (Invalid)	In-position signal in OINP width=1 Control output 4/ bit 4=1 Second in-position signal=0 Control output 4/ bit F=1	In-position signal in OINP width=1 Control output 4/ bit 4=1 Second in-position signal=0 Control output 4/ bit F=0																																																																																																								
	1 (Valid)		In-position signal in DINP width=1 Control output 4/ bit 4=1 Second in-position signal in OINP width = 0 Control output 4/ bit F=1																																																																																																								

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3298 (PR)	SP098	VGOP	Speed loop gain proportional term in orientation mode	Set the speed loop proportional gain in orientation mode. When the gain is increased, rigidity is improved in the orientation stop but vibration and sound become larger.	0 to 1000 (1/s)	63
3299 (PR)	SP099	VGOI	Orientation mode speed loop gain integral term	Set the speed loop integral gain in orientation mode.	0 to 1000 (0.1 1/s)	60
3300 (PR)	SP100	VGOD	Orientation mode speed loop gain delay advance term	Set a loop gain delay advance gain in orientation mode. When this parameter is set to "0", PI control is applied.	0 to 1000 (0.1 1/s)	15
3301 (PR)	SP101	DINP	Orientation advance in-position width	When using the orientation in-position advance function, set the in-position width that is larger than the normal in-position width defined in SP004 (OINP).	1 to 2880 (1/16°)	16
3302 (PR)	SP102	OODR	Excessive error value in orientation mode	Set the excessive error width in orientation mode.	0 to 32767 (1/4 pulse) (1 pulse= 0.088°)	32767
3303 (PR)	SP103	FTM	Index positioning completion OFF time timer	Set the time for forcedly turn OFF the index positioning completion signal (different from the orientation completion signal) after the leading edge of the indexing start signal.	0 to 10000 (ms)	200
3304 (PR)	SP104	TLOR	Torque limit value for orientation servo locking	Set the torque limit value for orientation in-position output. If the external torque limit signal is input, the torque limit value set by this parameter is made invalid.	0 to 120 (%)	100
3305 (PR)	SP105	IQG0	Current loop gain magnification 1 in orientation mode	Set the magnification for current loop gain (torque component) at orientation completion.	1 to 1000 (%)	100
3306 (PR)	SP106	IDG0	Current loop gain magnification 2 in orientation mode	Set the magnification for current loop gain (excitation component) at orientation completion.	1 to 1000 (%)	100
3307	SP107	CSP2	Deceleration rate 2 in orientation mode	Set the deceleration rate in orientation mode corresponding to the gear 001. When this parameter is set to "0", same as SP006 (CSP).	0 to 1000	0

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting
3308	SP108	CSP3	Deceleration rate 3 in orientation mode	Set the deceleration rate in orientation mode corresponding to the gear 010. When this parameter is set to "0", same as SP006 (CSP).	0 to 1000 0
3309	SP109	CSP4	Deceleration rate 4 in orientation mode	Set the deceleration rate in orientation mode corresponding to the gear 011. When this parameter is set to "0", same as SP006 (CSP).	0 to 1000 0
3310 to 3313	SP110 to SP113			Use not possible.	0
3314	SP114	OPER	Orientation pulse miss check value	An alarm "5C" will occur if the pulse miss value at the orientation stop exceeds this setting value. (Note that this is invalid when set to "0".) In this parameter, set the value to fulfill the following conditions. SP114 setting value > 1.5 × SP004 (orientation in-position width)	0 to 32767 (360°/4096) 0
3315	SP115	OSP2	Orientation motor speed clamp value 2	When the orientation clamp speed is changed by the control input, this parameter setting will be used instead of SP005: OSP. Indexing speed clamp valid This parameter is used when (SP097: SPEC0-bit4 = 1).	0 to 32767 (r/min) 0
3316	SP116	OPYVR	Minimum excitation value after changeover (2nd minimum excitation rate)	Minimum excitation rate when position control input or external input is selected.	0 to 100 (%) 0
3317	SP117	ORUT		This is used by Mitsubishi. Set to "0" unless particularly designated.	0 0
3318	SP118	ORCT	Number of orientation retry times	Set the number of times to retry when an orientation or feedback error occurs. The warning (A9) is issued while retrying orientation, and an alarm (5C) is issued when the set number of times is exceeded.	0 to 100 (time) 0
3319	SP119	MPGH	Orientation position gain H winding compensation magnification	Set the compensation magnification of the orientation position loop gain for the H winding. H winding orientation position loop gain = SP001 (or SP002) × SP119/256 When set to "0", will become the same as SP001 or SP002.	0 to 2560 (1/256-fold) 0

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3320	SP120	MPGL	Orientation position gain L winding compensation magnification	Set the compensation magnification of the orientation position loop gain for the L winding. L winding orientation position loop gain = SP001 (or SP002) × SP120/256 When set to "0", will become the same as SP001 or SP002.	0 to 2560 (1/256-fold)	0
3321	SP121	MPCSH	Orientation deceleration rate H winding compensation magnification	Set the compensation magnification of the orientation deceleration rate for the H winding. Orientation deceleration rate for the H winding = SP006 × SP121/256 When set to "0", will become the same as SP006.	0 to 2560 (1/256-fold)	0
3322	SP122	MPCSL	Orientation deceleration rate L winding compensation magnification	Set the compensation magnification of the orientation deceleration rate for the L winding. Orientation deceleration rate for the L winding = SP006 × SP122/256 When set to "0", will become the same as SP006.	0 to 2560 (1/256-fold)	0
3323	SP123	MGD0	Magnetic sensor output peak value	This parameter is used for adjustment of orientation operation of the magnetic sensor. Set the output peak value of the magnetic sensor. If a gap between the sensor and the magnetizing element is small, increase the value of this parameter. If it is large, decrease the value of this parameter.	1 to 10000	Standard magnetizing element: 542 Small magnetizing element: 500
3324	SP124	MGD1	Magnetic sensor linear zone width	This parameter is used for adjustment of orientation operation of the magnetic sensor. Set the linear zone width of the magnetic sensor. If the radius of the mounted magnetizing element is large, decrease the value of this parameter. If it is small, increase the value of this parameter.	1 to 10000	Standard magnetizing element: 768 Small magnetizing element: 440

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting																																																																																																													
3325	SP125	MGD2	Magnetic sensor switching point	This parameter is used for adjustment of orientation operation of the magnetic sensor. Set the distance dimension from the target stop point at switching from position feedback to magnetic sensor output. Normally, set a value that is approx. 1/2 of the value defined in SP124.	1 to 10000	Standard magnetizing element: 384 Small magnetizing element: 220																																																																																																												
3326 to 3328	SP126 to SP128			Use not possible.	0	0																																																																																																												
3329 (PR)	SP129	SPECC	C-axis specifications	<p>Set the C-axis specifications in bit units.</p> <table border="1" style="width: 100%; text-align: center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td>zrtn</td><td>ptyp</td><td>fb9x</td><td>zrtd</td><td>zrn2</td><td></td><td>zdir</td><td>ztyp</td> </tr> <tr> <td colspan="8"> </td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td>vg8x</td><td></td><td>fdir</td><td></td><td>phos</td><td>rtrn</td><td>adin</td><td>fclx</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width: 100%; text-align: center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>fclx</td> <td>Closed loop</td> <td>Semi-closed loop (Gear 1 : 1 only)</td> </tr> <tr> <td>1</td> <td>adin</td> <td>Interpolation A/D compensation invalid</td> <td>Interpolation A/D compensation valid</td> </tr> <tr> <td>2</td> <td>rtrn</td> <td>Position monitor during ready OFF invalid</td> <td>Position monitor during ready OFF valid</td> </tr> <tr> <td>3</td> <td>phos</td> <td>Normal (no compensation)</td> <td>Vx4 synchronization compensation valid</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td>fdir</td> <td>Position detector polarity (+)</td> <td>Position detector polarity (-)</td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td>vg8x</td> <td>Speed gain × 1/8 during torque limit valid</td> <td>Speed gain × 1/8 during torque limit invalid</td> </tr> <tr> <td>8</td> <td>ztyp</td> <td>Z-phase type: Normal start up</td> <td>Z-phase type: Start up only</td> </tr> <tr> <td>9</td> <td>zdir</td> <td>Z-phase rising polarity (+)</td> <td>Z-phase rising polarity (-)</td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td>zrn2</td> <td colspan="2">This is used by Mitsubishi. Set to "0" unless particularly designated.</td> </tr> <tr> <td>C</td> <td>zrtd</td> <td></td> <td></td> </tr> <tr> <td>D</td> <td>fb9x</td> <td>Speed feedback Standard (PLG)</td> <td>Speed feedback 90,000 pulse detector</td> </tr> <tr> <td>E</td> <td>ptyp</td> <td>Position control switch type: After zero point return</td> <td>Position control switch type: After deceleration stop</td> </tr> <tr> <td>F</td> <td>zrtn</td> <td>Zero point return direction: CCW</td> <td>Zero point return direction: CW</td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8	zrtn	ptyp	fb9x	zrtd	zrn2		zdir	ztyp									7	6	5	4	3	2	1	0	vg8x		fdir		phos	rtrn	adin	fclx	bit	Name	Meaning when set to 0	Meaning when set to 1	0	fclx	Closed loop	Semi-closed loop (Gear 1 : 1 only)	1	adin	Interpolation A/D compensation invalid	Interpolation A/D compensation valid	2	rtrn	Position monitor during ready OFF invalid	Position monitor during ready OFF valid	3	phos	Normal (no compensation)	Vx4 synchronization compensation valid	4				5	fdir	Position detector polarity (+)	Position detector polarity (-)	6				7	vg8x	Speed gain × 1/8 during torque limit valid	Speed gain × 1/8 during torque limit invalid	8	ztyp	Z-phase type: Normal start up	Z-phase type: Start up only	9	zdir	Z-phase rising polarity (+)	Z-phase rising polarity (-)	A				B	zrn2	This is used by Mitsubishi. Set to "0" unless particularly designated.		C	zrtd			D	fb9x	Speed feedback Standard (PLG)	Speed feedback 90,000 pulse detector	E	ptyp	Position control switch type: After zero point return	Position control switch type: After deceleration stop	F	zrtn	Zero point return direction: CCW	Zero point return direction: CW		0000
F	E	D	C	B	A	9	8																																																																																																											
zrtn	ptyp	fb9x	zrtd	zrn2		zdir	ztyp																																																																																																											
7	6	5	4	3	2	1	0																																																																																																											
vg8x		fdir		phos	rtrn	adin	fclx																																																																																																											
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																															
0	fclx	Closed loop	Semi-closed loop (Gear 1 : 1 only)																																																																																																															
1	adin	Interpolation A/D compensation invalid	Interpolation A/D compensation valid																																																																																																															
2	rtrn	Position monitor during ready OFF invalid	Position monitor during ready OFF valid																																																																																																															
3	phos	Normal (no compensation)	Vx4 synchronization compensation valid																																																																																																															
4																																																																																																																		
5	fdir	Position detector polarity (+)	Position detector polarity (-)																																																																																																															
6																																																																																																																		
7	vg8x	Speed gain × 1/8 during torque limit valid	Speed gain × 1/8 during torque limit invalid																																																																																																															
8	ztyp	Z-phase type: Normal start up	Z-phase type: Start up only																																																																																																															
9	zdir	Z-phase rising polarity (+)	Z-phase rising polarity (-)																																																																																																															
A																																																																																																																		
B	zrn2	This is used by Mitsubishi. Set to "0" unless particularly designated.																																																																																																																
C	zrtd																																																																																																																	
D	fb9x	Speed feedback Standard (PLG)	Speed feedback 90,000 pulse detector																																																																																																															
E	ptyp	Position control switch type: After zero point return	Position control switch type: After deceleration stop																																																																																																															
F	zrtn	Zero point return direction: CCW	Zero point return direction: CW																																																																																																															
3330	SP130	PGC1	First position loop gain for cutting on C-axis	Set the position loop gain when the first gain is selected for C axis cutting.	1 to 100 (1/s)	15																																																																																																												
3331	SP131	PGC2	Second position loop gain for cutting on C-axis	Set the position loop gain when the second gain is selected for C axis cutting.	1 to 100 (1/s)	15																																																																																																												

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3332	SP132	PGC3	Third position loop gain for cutting on C-axis	Set the position loop gain when the third gain is selected for C-axis cutting.	1 to 100 (1/s)	15
3333	SP133	PGC4	Stop position loop gain for cutting on C-axis	Set the position loop gain for stopping when carrying out C-axis cutting.	1 to 100 (1/s)	15
3334 (PR)	SP134	VGCP0	C-axis non-cutting speed loop gain proportional item	Set the speed loop proportional gain in C-axis non-cutting mode.	0 to 5000 (1/s)	63
3335 (PR)	SP135	VGCI0	C-axis non-cutting speed loop gain integral item	Set the speed loop integral gain in C-axis non-cutting mode.	0 to 5000 (0.1 1/s)	60
3336 (PR)	SP136	VGCD0	C-axis non-cutting speed loop gain delay advance item	Set the speed loop delay advance gain in C-axis non-cutting mode. When this parameter is set to "0", PI control is exercised.	0 to 5000 (0.1 1/s)	15
3337 (PR)	SP137	VGCP1	First speed loop gain proportional item for C-axis cutting	Set the speed loop proportional gain when the first gain is selected for C-axis cutting.	0 to 5000 (1/s)	63
3338 (PR)	SP138	VGCI1	First speed loop gain integral item for cutting on C-axis	Set the speed loop integral gain when the first gain is selected for C-axis cutting.	0 to 5000 (0.1 1/s)	60
3339 (PR)	SP139	VGCD1	First speed loop gain delay advance item for cutting on C-axis	Set the speed loop delay advance gain when the first gain is selected for curing on the C-axis. When this parameter is set to "0", PI control is applied.	0 to 5000 (0.1 1/s)	15
3340 (PR)	SP140	VGCP2	Second speed loop gain proportional item for cutting on C-axis	Set the speed loop proportional gain when the second gain is selected for C-axis cutting.	0 to 5000 (1/s)	63

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3341 (PR)	SP141	VGCI2	Second speed loop gain integral item for cutting on C-axis	Set the speed loop integral gain when the second gain is selected for C-axis cutting.	0 to 5000 (0.1 1/s)	60
3342 (PR)	SP142	VGCD2	Second speed loop gain delay advance item for cutting on C-axis	Set the speed loop delay advance gain when the second gain is selected for C-axis cutting. When this parameter is set to "0", PI control is applied.	0 to 5000 (0.1 1/s)	15
3343 (PR)	SP143	VGCP3	Third speed loop gain proportional item for cutting on C-axis	Set the speed loop proportional gain when the third gain is selected for C-axis cutting.	0 to 5000 (1/s)	63
3344 (PR)	SP144	VGCI3	Third speed loop gain integral item for cutting on C-axis	Set the speed loop integral gain when the third gain is selected for C-axis cutting.	0 to 5000 (0.1 1/s)	60
3345 (PR)	SP145	VGCD3	Third speed loop gain delay advance item for cutting on C-axis	Set the speed loop delay advance gain when the third gain is selected for C-axis cutting. When this parameter is set to "0", PI control is applied.	0 to 5000 (0.1 1/s)	15
3346 (PR)	SP146	VGCP4	Speed loop gain proportional item for stop of cutting on C-axis	Set the speed loop proportional gain when C-axis cutting is stopped.	0 to 5000 (1/s)	63
3347 (PR)	SP147	VGCI4	Speed loop gain integral item for stop of cutting on C-axis	Set the speed loop integral gain when C-axis cutting is stopped.	0 to 5000 (0.1 1/s)	60
3348 (PR)	SP148	VGCD4	Speed loop gain delay advance item for stop of cutting on C-axis	Set the speed loop delay advance gain when C-axis cutting is stopped. When this parameter is set to "0", PI control is applied.	0 to 5000 (0.1 1/s)	15

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3349	SP149	CZRN	C-axis zero point return speed	This parameter is valid when SP129 (SPECC) bitE is set to "0". Set the zero point return speed used when the speed loop changes to the position loop.	1 to 500 (r/min)	50
3350	SP150	CPDT	C-axis zero point return deceleration point	This parameter is valid when SP129 (SPECC) bitE is set to "0". Set the deceleration rate where the machine starts to decelerate when it returns to the target stop point during C-axis zero point return. When the machine tends to overshoot at the stop point, set the smaller value.	1 to 10000	1
3351	SP151	CPSTL	C-axis zero point return shift amount (low byte)	This parameter is valid when SPECC (SP129) bitE is set to "0". Set the C-axis zero point position.	HEX setting 00000000 to FFFFFFFF (1/1000°)	H: 0000 L: 0000
3352	SP152	CPSTH	C-axis zero point return shift amount (high byte)			
3354 (PR)	SP154	CODRL	Excessive error width on C-axis (low byte)	Set the excessive error width on the C-axis.	HEX setting 00000000 to FFFFFFFF (1/1000°)	H: 0001 L: D4C0
3355 (PR)	SP155	CODRH	Excessive error width on C-axis (high byte)			
3356	SP156	OVSH	C-axis overshoot compensation	Set this to prevent overshooting when shifting from movement to stopping with C-axis control. (Set this referring to the load meter display when overshooting occurred.)	0 to 1000 (0.1%)	0
3357 to 3358	SP157 to SP158			Not used. Set to "0".	0	0
3359	SP159	CPY0	C-axis non-cutting variable excitation ratio	Set the minimum value of variable excitation ratio for non-cutting on the C-axis .	0 to 100 (%)	50
3360	SP160	CPY1	C-axis cutting variable excitation ratio	Set the minimum variable excitation ratio for cutting on the C-axis.	0 to 100 (%)	100


8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3361 (PR)	SP161	IQGC0	Current loop gain magnification 1 for non-cutting on C-axis	Set the magnification of current loop gain (torque component) for C-axis non-cutting.	1 to 1000 (%)	100
3362 (PR)	SP162	IDGC0	Current loop gain magnification 2 for non-cutting on C-axis	Set the magnification of current loop gain (excitation component) for C-axis non-cutting.	1 to 1000 (%)	100
3363 (PR)	SP163	IQGC1	Current loop gain magnification 1 for cutting on C-axis	Set the magnification of current loop gain (torque component) for C-axis cutting.	1 to 1000 (%)	100
3364 (PR)	SP164	IDGC1	Current loop gain magnification 2 for cutting on C-axis	Set the magnification of current loop gain (excitation component) for C-axis cutting.	1 to 1000 (%)	100
3365	SP165	PG2C	C-axis position loop gain 2	Set the second position loop gain when high-gain control is carried out for control of the C-axis. This parameter is applied to all the operation modes of C-axis control. When this function is not used, assign "0".	0 to 999 (1/s)	0
3366	SP166	PG3C	C-axis position loop gain 3	Set the third position loop gain when high-gain control is carried out for control of the C-axis. This parameter is applied to all the operation modes of C-axis control. When this function is not used, assign "0".	0 to 999 (1/s)	0
3367 (PR)	SP167	PGU	Position loop gain for increased spindle holding force	Set the position loop gain for when the disturbance observer is valid.	0 to 100 (1/s)	15
3368 (PR)	SP168	VGUP	Speed loop gain proportional item for increased spindle holding force	Set the speed loop gain proportional item for when the disturbance observer is valid.	0 to 5000 (1/s)	63
3369 (PR)	SP169	VGUI	Speed loop gain integral item for increased spindle holding force	Set the speed loop gain integral item for when the disturbance observer is valid.	0 to 5000 (0.1 1/s)	60

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting																																																																																																					
3370 (PR)	SP170	VGUD	Speed loop gain delay advance item for increased spindle holding force	Set the speed loop gain delay advance item for when the disturbance observer is valid.	0 to 5000 (0.1 1/s)	15																																																																																																				
3371 to 3376	SP171 to SP176			Not used. Set to "0".	0	0																																																																																																				
3377 (PR)	SP177	SPECS	Spindle synchronous specifications	Set the spindle synchronous specifications in bit units. <table style="width: 100%; border-collapse: collapse; margin-bottom: 5px;"> <tr> <td style="text-align: center;">F</td> <td style="text-align: center;">E</td> <td style="text-align: center;">D</td> <td style="text-align: center;">C</td> <td style="text-align: center;">B</td> <td style="text-align: center;">A</td> <td style="text-align: center;">9</td> <td style="text-align: center;">8</td> </tr> <tr> <td style="border: 1px solid black; width: 20px;"></td> <td style="border: 1px solid black; width: 20px;"></td> <td style="border: 1px solid black; width: 20px; text-align: center;">Odx8</td> <td style="border: 1px solid black; width: 20px;"></td> <td style="border: 1px solid black; width: 20px; text-align: center;">phos</td> </tr> </table> <table style="width: 100%; border-collapse: collapse; margin-bottom: 5px;"> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> <td style="text-align: center;">1</td> <td style="text-align: center;">0</td> </tr> <tr> <td style="border: 1px solid black; width: 20px;"></td> <td style="border: 1px solid black; width: 20px;"></td> <td style="border: 1px solid black; width: 20px; text-align: center;">fdir</td> <td style="border: 1px solid black; width: 20px;"></td> <td style="border: 1px solid black; width: 20px; text-align: center;">pyfx</td> <td style="border: 1px solid black; width: 20px; text-align: center;">rtrn</td> <td style="border: 1px solid black; width: 20px; text-align: center;">adin</td> <td style="border: 1px solid black; width: 20px; text-align: center;">fclx</td> </tr> </table> <table border="1" style="width: 100%; border-collapse: collapse; margin-bottom: 5px;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>fclx</td> <td>Closed loop</td> <td>Semi-closed loop</td> </tr> <tr> <td>1</td> <td>adin</td> <td>Interpolation A/D compensation invalid</td> <td>Interpolation A/D compensation valid</td> </tr> <tr> <td>2</td> <td>rtrn</td> <td>Position monitor during ready OFF invalid</td> <td>Position monitor during ready OFF valid</td> </tr> <tr> <td>3</td> <td>pyfx</td> <td>Normal excitation</td> <td>Position loop excitation fixed (strong)</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td>fdir</td> <td>Position detector direction (positive direction)</td> <td>Position detector direction (negative direction)</td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> <td></td> </tr> <tr> <td>8</td> <td></td> <td></td> <td></td> </tr> <tr> <td>9</td> <td></td> <td></td> <td></td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> <td></td> </tr> <tr> <td>D</td> <td>odx8</td> <td>Magnification of excessive error width x 8 times invalid</td> <td>Magnification of excessive error width x 8 times valid</td> </tr> <tr> <td>E</td> <td></td> <td></td> <td></td> </tr> <tr> <td>F</td> <td></td> <td colspan="2" style="text-align: center;">(Used with SPJ)</td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8			Odx8					phos	7	6	5	4	3	2	1	0			fdir		pyfx	rtrn	adin	fclx	bit	Name	Meaning when set to 0	Meaning when set to 1	0	fclx	Closed loop	Semi-closed loop	1	adin	Interpolation A/D compensation invalid	Interpolation A/D compensation valid	2	rtrn	Position monitor during ready OFF invalid	Position monitor during ready OFF valid	3	pyfx	Normal excitation	Position loop excitation fixed (strong)	4				5	fdir	Position detector direction (positive direction)	Position detector direction (negative direction)	6				7				8				9				A				B				C				D	odx8	Magnification of excessive error width x 8 times invalid	Magnification of excessive error width x 8 times valid	E				F		(Used with SPJ)		0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																			
		Odx8					phos																																																																																																			
7	6	5	4	3	2	1	0																																																																																																			
		fdir		pyfx	rtrn	adin	fclx																																																																																																			
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																							
0	fclx	Closed loop	Semi-closed loop																																																																																																							
1	adin	Interpolation A/D compensation invalid	Interpolation A/D compensation valid																																																																																																							
2	rtrn	Position monitor during ready OFF invalid	Position monitor during ready OFF valid																																																																																																							
3	pyfx	Normal excitation	Position loop excitation fixed (strong)																																																																																																							
4																																																																																																										
5	fdir	Position detector direction (positive direction)	Position detector direction (negative direction)																																																																																																							
6																																																																																																										
7																																																																																																										
8																																																																																																										
9																																																																																																										
A																																																																																																										
B																																																																																																										
C																																																																																																										
D	odx8	Magnification of excessive error width x 8 times invalid	Magnification of excessive error width x 8 times valid																																																																																																							
E																																																																																																										
F		(Used with SPJ)																																																																																																								
3378 (PR)	SP178	VGSP	Spindle synchronous speed loop gain proportional term	Set the speed loop proportional gain in spindle synchronous mode.	0 to 1000 (1/s)	63																																																																																																				
3379 (PR)	SP179	VGSI	Spindle synchronous speed loop gain integral term	Set the speed loop integral gain in spindle synchronous mode.	0 to 1000 (0.1 1/s)	60																																																																																																				


8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3380 (PR)	SP180	VGSD	Spindle synchronous speed loop gain delay advance term	Set the speed loop delay advance gain in spindle synchronous mode. When this parameter is set to "0", PI control is applied.	0 to 1000 (0.1 1/s)	15
3381 (PR)	SP181	VCGS	Spindle synchronous Target value of variable speed loop proportional gain	Set the magnification of speed loop proportional gain with respect to SP178 (VGSP) at the maximum speed defined in SP017 (TSP) in spindle synchronous mode.	0 to 100 (%)	100
3382 (PR)	SP182	VCSS	Spindle synchronous Change starting speed of variable speed loop proportional gain	Set the speed when the speed loop proportional gain change starts in the spindle synchronous mode. 	0 to 32767 (r/min)	0
3383	SP183	SYNV	Spindle synchronous Sync matching speed	For changeover from the speed loop to the position loop in the spindle synchronous mode, set a speed command error range for output of the synchronous speed matching signal.	0 to 1000 (r/min)	20
3384 (PR)	SP184	FFCS	Spindle synchronous Acceleration rate feed forward gain	Set the acceleration rate feed forward gain in the spindle synchronous mode. This parameter is used only with the SPJ2.	0 to 1000 (%)	0
3385	SP185	SINP	Spindle synchronous In-position width	Set the position error range for output of the in-position signal in the spindle synchronous mode.	1 to 2880 (1/16°)	16
3386 (PR)	SP186	SODR	Spindle synchronous Excessive error width	Set the excessive error width in the spindle synchronous mode.	1 to 32767 (pulse) (1 pulse =0.088°)	32767
3387 (PR)	SP187	IQGS	Spindle synchronous Current loop gain magnification1	Set the magnification of current loop gain (torque component) in the spindle synchronous mode.	1 to 1000 (%)	100

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting																																																																																																				
3388 (PR)	SP188	IDGS	Spindle synchronous Current loop gain magnification 2	Set the magnification of current loop gain (excitation component) in the spindle synchronous mode.	1 to 1000 (%) 100																																																																																																				
3389	SP189	PG2S	Spindle synchronous Position loop gain 2	Set the second position loop gain when high-gain control is carried out in the spindle synchronous mode. When this parameter function is not used, set to "0".	0 to 999 (1/s) 0																																																																																																				
3390	SP190	PG3S	Spindle synchronous Position loop gain 3	Set the third position loop gain when high-gain control is carried out in the spindle synchronous mode. When this parameter function is not used, set to "0".	0 to 999 (1/s) 0																																																																																																				
3391	SP191			Use not possible.	0 0																																																																																																				
3392	SP192			Not used. Set to "0".																																																																																																					
3393 (PR)	SP193	SPECT	Synchronized tapping specifications	Set the synchronized tapping specifications in bit units. <table border="1" style="margin: 5px 0;"> <tr> <td style="text-align: center;">F</td><td style="text-align: center;">E</td><td style="text-align: center;">D</td><td style="text-align: center;">C</td><td style="text-align: center;">B</td><td style="text-align: center;">A</td><td style="text-align: center;">9</td><td style="text-align: center;">8</td> </tr> <tr> <td style="text-align: center;">zrtn</td><td style="text-align: center;">ptyp</td><td style="text-align: center;">od8x</td><td></td><td></td><td></td><td></td><td style="text-align: center;">phos</td> </tr> </table> <table border="1" style="margin: 5px 0;"> <tr> <td style="text-align: center;">7</td><td style="text-align: center;">6</td><td style="text-align: center;">5</td><td style="text-align: center;">4</td><td style="text-align: center;">3</td><td style="text-align: center;">2</td><td style="text-align: center;">1</td><td style="text-align: center;">0</td> </tr> <tr> <td></td><td></td><td style="text-align: center;">fdir</td><td style="text-align: center;">cdir</td><td style="text-align: center;">pyfx</td><td></td><td style="text-align: center;">adin</td><td style="text-align: center;">fclx</td> </tr> </table> <table border="1" style="margin: 5px 0;"> <thead> <tr> <th>bit</th><th>Name</th><th>Meaning when set to 0</th><th>Meaning when set to 1</th></tr> </thead> <tbody> <tr> <td>0</td><td>fclx</td><td>Closed loop</td><td>Semi-closed loop (Gear 1 : 1 only)</td></tr> <tr> <td>1</td><td>adin</td><td>Interpolation A/D compensation invalid</td><td>Interpolation A/D compensation valid</td></tr> <tr> <td>2</td><td>rtrn</td><td>Position monitor during ready OFF invalid</td><td>Position monitor during ready OFF valid</td></tr> <tr> <td>3</td><td>pyfx</td><td>Normal excitation</td><td>Position loop excitation fixed (strong)</td></tr> <tr> <td>4</td><td>cdir</td><td>Command polarity (+)</td><td>Command polarity (-)</td></tr> <tr> <td>5</td><td>fdir</td><td>Position detector polarity (+)</td><td>Position detector polarity (-)</td></tr> <tr> <td>6</td><td></td><td></td><td></td></tr> <tr> <td>7</td><td></td><td></td><td></td></tr> <tr> <td>8</td><td>phos</td><td>Normal (no compensation)</td><td>Synchronized tapping position compensation valid</td></tr> <tr> <td>9</td><td></td><td></td><td></td></tr> <tr> <td>A</td><td></td><td></td><td></td></tr> <tr> <td>B</td><td></td><td></td><td></td></tr> <tr> <td>C</td><td></td><td></td><td></td></tr> <tr> <td>D</td><td>od8x</td><td>Magnification of excessive error width x 8 times invalid</td><td>Magnification of excessive error width x 8 times valid</td></tr> <tr> <td>E</td><td>ptyp</td><td>Position control switch type: After zero point return</td><td>Position control switch type: After deceleration stop</td></tr> <tr> <td>F</td><td>zrtn</td><td>Zero point return direction: CCW</td><td>Zero point return direction: CW</td></tr> </tbody> </table>	F	E	D	C	B	A	9	8	zrtn	ptyp	od8x					phos	7	6	5	4	3	2	1	0			fdir	cdir	pyfx		adin	fclx	bit	Name	Meaning when set to 0	Meaning when set to 1	0	fclx	Closed loop	Semi-closed loop (Gear 1 : 1 only)	1	adin	Interpolation A/D compensation invalid	Interpolation A/D compensation valid	2	rtrn	Position monitor during ready OFF invalid	Position monitor during ready OFF valid	3	pyfx	Normal excitation	Position loop excitation fixed (strong)	4	cdir	Command polarity (+)	Command polarity (-)	5	fdir	Position detector polarity (+)	Position detector polarity (-)	6				7				8	phos	Normal (no compensation)	Synchronized tapping position compensation valid	9				A				B				C				D	od8x	Magnification of excessive error width x 8 times invalid	Magnification of excessive error width x 8 times valid	E	ptyp	Position control switch type: After zero point return	Position control switch type: After deceleration stop	F	zrtn	Zero point return direction: CCW	Zero point return direction: CW	0000 to FFFF HEX setting 0000
F	E	D	C	B	A	9	8																																																																																																		
zrtn	ptyp	od8x					phos																																																																																																		
7	6	5	4	3	2	1	0																																																																																																		
		fdir	cdir	pyfx		adin	fclx																																																																																																		
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																						
0	fclx	Closed loop	Semi-closed loop (Gear 1 : 1 only)																																																																																																						
1	adin	Interpolation A/D compensation invalid	Interpolation A/D compensation valid																																																																																																						
2	rtrn	Position monitor during ready OFF invalid	Position monitor during ready OFF valid																																																																																																						
3	pyfx	Normal excitation	Position loop excitation fixed (strong)																																																																																																						
4	cdir	Command polarity (+)	Command polarity (-)																																																																																																						
5	fdir	Position detector polarity (+)	Position detector polarity (-)																																																																																																						
6																																																																																																									
7																																																																																																									
8	phos	Normal (no compensation)	Synchronized tapping position compensation valid																																																																																																						
9																																																																																																									
A																																																																																																									
B																																																																																																									
C																																																																																																									
D	od8x	Magnification of excessive error width x 8 times invalid	Magnification of excessive error width x 8 times valid																																																																																																						
E	ptyp	Position control switch type: After zero point return	Position control switch type: After deceleration stop																																																																																																						
F	zrtn	Zero point return direction: CCW	Zero point return direction: CW																																																																																																						

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3394 (PR)	SP194	VGTP	Synchronized tapping speed loop gain proportional term	Set the speed loop proportional gain in synchronized tapping mode.	0 to 1000 (1/s)	63
3395 (PR)	SP195	VGTI	Synchronized tapping speed loop gain integral term	Set the speed loop integral gain in synchronized tapping mode.	0 to 1000 (0.1 1/s)	60
3396 (PR)	SP196	VGTD	Synchronized tapping speed loop gain delay advance term	Set the speed loop delay advance gain in synchronized tapping mode. When this parameter is set to "0", PI control is applied.	0 to 1000 (0.1 1/s)	15
3397	SP197			This is used by Mitsubishi. Set to "0" unless particularly designated.	0	0
3398 (PR)	SP198	VCGT	Synchronized tapping target value of variable speed loop proportional gain	Set the magnification of speed loop proportional gain with respect to SP194 (VGTP) at the maximum motor speed defined in SP017 (TSP) in synchronized tapping mode.	0 to 100 (%)	100
3399 (PR)	SP199	VCST	Synchronized tapping change starting speed of variable speed loop proportional gain	Set the speed where the speed loop proportional gain change starts during synchronized tapping. 	0 to 32767 (r/min)	0
3400 (PR)	SP200	FFC1	Synchronized tapping acceleration feed forward gain (gear 1)	Set the acceleration feed forward gain for selection of gear 000 during synchronized tapping. This parameter should be used when an error of relative position to Z-axis servo is large.	0 to 1000 (%)	0
3401 (PR)	SP201	FFC2	Synchronized tapping acceleration feed forward gain (gear 2)	Set the acceleration feed forward gain for selection of gear 001 during synchronized tapping.	0 to 1000 (%)	0
3402 (PR)	SP202	FFC3	Synchronized tapping acceleration feed forward gain (gear 3)	Set the acceleration feed forward gain for selection of gear 010 during synchronized tapping.	0 to 1000 (%)	0

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting
3403 (PR)	SP203	FFC4	Synchronized tapping acceleration feed forward gain (gear 4)	Set the acceleration feed forward gain for selection of gear 011 during synchronized tapping.	0 to 1000 (%) 0
3404 to 3413	SP204 to SP213			Not used. Set to "0".	0 0
3414	SP214	TZRN	Synchronized tapping zero point return speed	This parameter is valid when SP193 (SPECT) bitE is set to "0". Set the zero point return speed used when the speed loop changes to the position loop.	0 to 500 (r/min) 50
3415	SP215	TPDT	Synchronized tapping zero point return deceleration rate	This parameter is valid when SP193 (SPECT) bitE is set to "0". Set the deceleration rate where the machine starts to decelerate when it returns to the target stop point during synchronized tapping zero point return. When the machine tends to overshoot at the stop point set a smaller value.	0 to 10000 (pulse) 1
3416	SP216	TPST	Synchronized tapping zero point return shift amount	This parameter is valid when SP193 (SPECT) bitE is set to "0". Set the synchronized tapping zero point position.	0 to 4095 0
3417	SP217	TINP	Synchronized tapping in-position width	Set the position error range for output of the in-position during synchronized tapping.	1 to 2880 (1/16°) 16
3418 (PR)	SP218	TODR	Synchronized tapping excessive error width	Set the excessive error width during synchronized tapping.	1 to 32767 (pulse) (1 pulse =0.088°) 32767
3419 (PR)	SP219	IQGT	Synchronized tapping current loop gain magnification 1	Set the magnification of current loop gain (torque component) during synchronized tapping.	1 to 1000 (%) 100
3420 (PR)	SP220	IDGT	Synchronized tapping current loop gain magnification 2	Set the magnification of current loop gain (excitation component) during synchronized tapping.	1 to 1000 (%) 100

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items			Details	Setting range	Standard setting
3421	SP221	PG2T	Synchronized tapping position loop gain 2	Set the second position loop gain when high-gain control is applied during synchronized tapping. When this parameter is not used, set to "0".	0 to 999 (1/s)	0
3422	SP222	PG3T	Synchronized tapping position loop gain 3	Set the third position loop gain when high-gain control is applied during synchronized tapping. When this parameter is not used, set to "0".	0 to 999 (1/s)	0
3423	SP223	SPDV	Speed monitor speed	Set the spindle limit speed in the door open state. (Invalid when 0 is set.) If the spindle end speed exceeds this setting value when the door is open, the speed monitor error (5E) will occur.	0 to 800 (r/min)	0
3424	SP224	SPDF	Speed monitor time	Set the time (continuous) to detect alarms. (Detected instantly when 0 is set.)	0 to 2813 (3.5ms)	0
3425	SP225	OXKPH	Position loop gain magnification after orientation gain changeover (H coil)	If gain changeover is valid (SP097: SPEC0-bitC=1) during orientation, set the magnification of each gain changed to after in-position.	0 to 2560 (1/256-fold)	0
3426	SP226	OXKPL	Position loop gain magnification after orientation gain changeover (L coil)		0 to 2560 (1/256-fold)	0
3427	SP227	OXVKP	Speed loop proportional gain magnification after orientation gain changeover		0 to 2560 (1/256-fold)	0
3428	SP228	OXVKI	Speed loop cumulative gain magnification after orientation gain changeover		0 to 2560 (1/256-fold)	0
3429	SP229	OXSFT	Orientation virtual target shift amount	Set the amount to shift the target position when orientation virtual target position is valid (SP097: SPEC0-bitD=1).	0 to 2048 (360°/4096)	0
3430 to 3432	SP230 to SP232			Use not possible.		

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3433 (PR)	SP233	JL	Disturbance observer general inertia scale	Set the ratio of the motor inertia + load inertia and motor inertia. Setting value = $\frac{\text{Motor inertia} + \text{load inertia}}{\text{Motor inertia}} \times 100$ (Normally, set "100" or more. When less than "50" is set, the setting will be invalid.)	0 to 5000 (%)	0
3434 (PR)	SP234	OBS1	Disturbance observer low path filter frequency	Set the frequency of the low path filter for when the disturbance observer is valid. Setting (1/s) = $2\pi f$ f: Approx. 1.5 times the disturbance frequency	0 to 1000 (1/s)	0
3435 (PR)	SP235	OBS2	Disturbance observer gain	Set the gain for the disturbance observer.	0 to 500 (%)	0
3436	SP236	OBS3		This is used by Mitsubishi. Set to "0" unless particularly designated.	0	0
3437	SP237			Not used. Set to "0".	0	0
3438 to 3441	SP238 to SP241			Use not possible.	0	0
3442	SP242	Vavx		This is used by Mitsubishi. Set to "0" unless particularly designated.	0	0
3443	SP243	UTTM			0	0
3444	SP244	OPLP			0	0
3445	SP245	PGHS			0	0
3446	SP246	TEST			0	0
3447 to 3448	SP247 to SP248			Use not possible.	0	0
3449	SP249	SM0	Speed meter speed	Set the motor rotation speed when the speed meter 10V is output. When set to "0", this parameter becomes the same as SP017 (TSP).	0 to 32767 (r/min)	0
3450	SP250	LM0	Load meter voltage	Set the voltage when the load meter 120% is output. When set to "0", this becomes 10V.	0 to 10 (V)	0
3451 to 3452	SP251 to SP252			Use not possible.	0	0

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items			Details	Setting range	Standard setting
3453	SP253	DA1NO	D/A output channel 1 data number	Set the output data number for channel 1 of the D/A output function. When set to "0", the output is speedometer. Refer to "9.4 (1) For D/A output functions".	-32768 to 32767	0
3454	SP254	DA2NO	D/A output channel 2 data number	Set the output data number for channel 2 of the D/A output function. When set to "0", the output is load meter. Refer to "9.4 (1) For D/A output functions".	-32768 to 32767	0
3455	SP255	DA1MPY	DA output channel 1 magnification	Set the data magnification for channel 1 of the D/A output function. The output magnification is the setting value divided by 256. When set to "0", the output magnification becomes 1-fold, in the same manner as when "256" is set. Refer to "9.4 (1) For D/A output functions".	-32768 to 32767 (1/256-fold)	0
3456	SP256	DA2MPY	DA output channel 2 magnification	Set the data magnification for channel 2 of the D/A output function. The output magnification is the setting value divided by 256. When set to "0", the output magnification becomes 1-fold, in the same manner as when "256" is set. Refer to "9.4 (1) For D/A output functions".	-32768 to 32767 (1/256-fold)	0

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items			Details	Setting range	Standard setting
3457 (PR) to 3520 (PR)	SP257 to SP320	RPM BSD	Motor constant (H coil)	<p>This parameter is valid only in the following two conditional cases:</p> <p>(a) In case that SP034 (SFNC2) bit0=1 and SP034 (SFNC2) bit2=0 Set the motor constants when using a special motor, not described in the SP040 (MTYP) explanation and when not using the coil changeover motor.</p> <p>(b) In case that SP034 (SFNC2) bit0=1 and SP034 (SFNC2) bit2=1 Set the motor constant of the H coil of the coil changeover motor.</p> <p>(Note) It is not allowed for the user to change the setting.</p>	0000 to FFFF HEX setting	0000
3521 (PR) to 3584 (PR)	SP321 to SP384	RPML BSDL	Motor constant (L coil)	<p>This parameter is valid only in the following conditional case:</p> <p>(a) In case that SP034 (SFNC2) bit0=1 and SP034 (SFNC2) bit2=1 Set the motor constant of the L coil of the coil changeover motor.</p> <p>(Note) It is not allowed for the user to change the setting.</p>	0000 to FFFF HEX setting	0000

8. Spindle Parameters

8.4 MDS-C1-SPM

8.4 MDS-C1-SPM

The spindle parameter setting and display method will differ according to the NC being used, so refer to Instruction Manual for each NC and the following spindles.

MELDAS AC Servo and Spindle MDS-C1 Series Specifications ManualBNP-C3000

For parameters marked with a (PR) in the tables, turn the NC power OFF after setting. The parameters will be valid after the power is turned ON again.

The "fixed control constants" and "fixed control bits" in this section are set by Mitsubishi.

⚠ CAUTION

⚠ Do not make remarkable adjustments or changes of the parameters as the operation may become unstable.

⚠ In the explanation on bits, set all bits not used, including blank bits, to "0".

No.	Items		Details	Setting range	Standard setting	
3201	SP001	PGM	Magnetic sensor and motor built-in encoder orientation position loop gain	As the set value is larger, the orientation time becomes shorter and servo rigidity is increased. However, vibration is increased and the machine becomes likely to overshoot.	0 to 2000 (0.1 1/s)	100
3202	SP002	PGE	Encoder orientation position loop gain	As the set value is larger, the orientation time becomes shorter and servo rigidity is increased. However, vibration is increased and the machine becomes likely to overshoot.	0 to 2000 (0.1 1/s)	100
3203	SP003	PGC0	C-axis non-cutting position loop gain	Set the position loop gain in C-axis non-cutting mode. During non-cutting (rapid traverse, etc.) with the C axis control, this position loop gain setting is valid.	1 to 200 (1/s)	15
3204	SP004	OINP	Orientation in-position width	Set the position error range in which an orientation completion signal is output.	1 to 2880 (1/16 °)	16
3205 (PR)	SP005	OSP	Orientation mode changing speed limit value	Set the motor speed limit value to be used when the speed loop is changed to the position loop in orientation mode. When this parameter is set to "0", SP017 (TSP) becomes the limit value.	0 to 32767 (r/min)	0
3206	SP006	CSP	Orientation mode deceleration rate	As the set value is larger, the orientation time becomes shorter. However, the machine becomes likely to overshoot.	1 to 1000	20
3207	SP007	OPST	In-position shift amount for orientation	Set the stop position for orientation. (i) Motor built-in encoder, encoder: Set the value by dividing 360° by 4096. (ii) Magnetic sensor: Divide -5° to +5° by 1024 and put 0° for 0.	(i) 0 to 4095 (ii) -512 to 512	0
3208	SP008			Not used. Set to "0".	0	0

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3209	SP009	PGT	Synchronized tapping Position loop gain	Set the spindle position loop gain in synchronized tapping mode.	1 to 200 (1/s)	15
3210	SP010	PGS	Spindle synchronous position loop gain	Set the spindle position loop gain in spindle synchronization mode.	1 to 200 (1/s)	15
3211 to 3216	SP011 to SP016			Use not possible.	0	0
3217 (PR)	SP017	TSP	Maximum motor speed	Set the maximum motor speed of the spindle.	1 to 32767 (r/min)	6000
3218 (PR)	SP018	ZSP	Motor zero speed	Set the motor speed for which zero-speed output is performed.	1 to 1000 (r/min)	50
3219 (PR)	SP019	CSN1	Speed cushion 1	Set the time constant for a speed command from "0" to the maximum speed. (This parameter is invalid in position loop mode.)	1 to 32767 (10ms)	30
3220 (PR)	SP020	SDTS	Speed detection set value	Set the motor speed so for which speed detection output is performed. Usually, the setting value is 10% of SP017 (TSP).	0 to 32767 (r/min)	600
3221	SP021	TLM1	Torque limit 1	Set the torque limit rate for torque limit signal 001.	0 to 120 (%)	10
3222 (PR)	SP022	VGNP1	Speed loop gain proportional term under speed control	Set the speed loop proportional gain in speed control mode. When the gain is increased, response is improved but vibration and sound become larger.	0 to 1000 (1/s)	63
3223 (PR)	SP023	VGNI1	Speed loop gain integral term under speed control	Set the speed loop integral gain in speed control mode. Usually, set a value in proportion to SP022 (VGNP1).	0 to 1000 (0.1 1/s)	60
3224	SP024			Use not possible.	0	0
3225 (PR)	SP025	GRA1	Spindle gear teeth count 1	Set the number of gear teeth of the spindle corresponding to gear 000.	1 to 32767	1
3226 (PR)	SP026	GRA2	Spindle gear teeth count 2	Set the number of gear teeth of the spindle corresponding to gear 001.	1 to 32767	1
3227 (PR)	SP027	GRA3	Spindle gear teeth count 3	Set the number of gear teeth of the spindle corresponding to gear 010.	1 to 32767	1
3228 (PR)	SP028	GRA4	Spindle gear teeth count 4	Set the number of gear teeth of the spindle corresponding to gear 011.	1 to 32767	1
3229 (PR)	SP029	GRB1	Motor shaft gear teeth count 1	Set the number of gear teeth of the motor shaft corresponding to gear 000.	1 to 32767	1

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting																																																																																																					
3230 (PR)	SP030	GRB2	Motor shaft gear teeth count 2	Set the number of gear teeth of the motor shaft corresponding to gear 001.	1 to 32767	1																																																																																																				
3231 (PR)	SP031	GRB3	Motor shaft gear teeth count 3	Set the number of gear teeth of the motor shaft corresponding to gear 010.	1 to 32767	1																																																																																																				
3232 (PR)	SP032	GRB4	Motor shaft gear teeth count 4	Set the number of gear teeth of the motor shaft corresponding to gear 011.	1 to 32767	1																																																																																																				
3233 (PR)	SP033	SFNC1	Spindle function 1	Set the spindle function 1 in bit units. <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center;">F</td><td style="text-align: center;">E</td><td style="text-align: center;">D</td><td style="text-align: center;">C</td><td style="text-align: center;">B</td><td style="text-align: center;">A</td><td style="text-align: center;">9</td><td style="text-align: center;">8</td> </tr> <tr> <td style="text-align: center;">poff</td><td></td><td></td><td style="text-align: center;">ront</td><td></td><td></td><td style="text-align: center;">pycal</td><td style="text-align: center;">pychg</td> </tr> </table> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center;">7</td><td style="text-align: center;">6</td><td style="text-align: center;">5</td><td style="text-align: center;">4</td><td style="text-align: center;">3</td><td style="text-align: center;">2</td><td style="text-align: center;">1</td><td style="text-align: center;">0</td> </tr> <tr> <td style="text-align: center;">pyst</td><td style="text-align: center;">pyoff</td><td></td><td></td><td></td><td></td><td></td><td></td> </tr> </table> (Note) Always set "0" for the empty bits. <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>bit</th><th>Name</th><th>Meaning when set to 0</th><th>Meaning when set to 1</th></tr> </thead> <tbody> <tr><td>0</td><td></td><td></td><td></td></tr> <tr><td>1</td><td></td><td></td><td></td></tr> <tr><td>2</td><td></td><td></td><td></td></tr> <tr><td>3</td><td></td><td></td><td></td></tr> <tr><td>4</td><td></td><td></td><td></td></tr> <tr><td>5</td><td></td><td></td><td></td></tr> <tr><td>6</td><td></td><td></td><td></td></tr> <tr><td>7</td><td></td><td></td><td></td></tr> <tr><td>8</td><td></td><td></td><td></td></tr> <tr><td>9</td><td></td><td></td><td></td></tr> <tr><td>A</td><td></td><td></td><td></td></tr> <tr><td>B</td><td></td><td colspan="2">This is used by Mitsubishi. Set to "0" unless particularly designated.</td></tr> <tr><td>C</td><td>ront</td><td>Normal ready ON</td><td>High-speed ready ON</td></tr> <tr><td>D</td><td></td><td colspan="2">This is used by Mitsubishi. Set to "0" unless particularly designated.</td></tr> <tr><td>E</td><td></td><td></td><td></td></tr> <tr><td>F</td><td>poff</td><td>Contactora hold at NC power OFF invalid</td><td>Contactora hold at NC power OFF valid</td></tr> </tbody> </table>	F	E	D	C	B	A	9	8	poff			ront			pycal	pychg	7	6	5	4	3	2	1	0	pyst	pyoff							bit	Name	Meaning when set to 0	Meaning when set to 1	0				1				2				3				4				5				6				7				8				9				A				B		This is used by Mitsubishi. Set to "0" unless particularly designated.		C	ront	Normal ready ON	High-speed ready ON	D		This is used by Mitsubishi. Set to "0" unless particularly designated.		E				F	poff	Contactora hold at NC power OFF invalid	Contactora hold at NC power OFF valid	0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																			
poff			ront			pycal	pychg																																																																																																			
7	6	5	4	3	2	1	0																																																																																																			
pyst	pyoff																																																																																																									
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																							
0																																																																																																										
1																																																																																																										
2																																																																																																										
3																																																																																																										
4																																																																																																										
5																																																																																																										
6																																																																																																										
7																																																																																																										
8																																																																																																										
9																																																																																																										
A																																																																																																										
B		This is used by Mitsubishi. Set to "0" unless particularly designated.																																																																																																								
C	ront	Normal ready ON	High-speed ready ON																																																																																																							
D		This is used by Mitsubishi. Set to "0" unless particularly designated.																																																																																																								
E																																																																																																										
F	poff	Contactora hold at NC power OFF invalid	Contactora hold at NC power OFF valid																																																																																																							

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting																																																																																																				
3234 (PR)	SP034	SFNC2 Spindle function 2	<p>Set the spindle function 2 in bit units.</p> <table border="1" style="width: 100%; text-align: center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td style="width: 20px; height: 20px;"></td><td style="width: 20px; height: 20px;"></td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td style="width: 20px; height: 20px;"></td><td style="width: 20px; height: 20px;"></td><td style="width: 20px; height: 20px;"></td><td style="width: 20px; height: 20px;"></td><td style="width: 20px; height: 20px;">mkc2</td><td style="width: 20px; height: 20px;">mkch</td><td style="width: 20px; height: 20px;">Mk3c</td><td style="width: 20px; height: 20px;">mts1</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width: 100%; text-align: center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>mts1</td> <td>Special motor constant invalid</td> <td>Special motor constant setting valid</td> </tr> <tr> <td>1</td> <td>Mk3c</td> <td>3-step coil changeover function invalid</td> <td>3-step coil changeover function valid</td> </tr> <tr> <td>2</td> <td>mkch</td> <td>Coil switch function invalid</td> <td>Coil switch function valid</td> </tr> <tr> <td>3</td> <td>mkc2</td> <td>Coil switch specification 2 invalid</td> <td>Coil switch specification 2 valid (Note1) (Note2)</td> </tr> <tr><td>4</td><td></td><td></td><td></td></tr> <tr><td>5</td><td></td><td></td><td></td></tr> <tr><td>6</td><td></td><td></td><td></td></tr> <tr><td>7</td><td></td><td></td><td></td></tr> <tr><td>8</td><td></td><td></td><td></td></tr> <tr><td>9</td><td></td><td></td><td></td></tr> <tr><td>A</td><td></td><td></td><td></td></tr> <tr><td>B</td><td></td><td></td><td></td></tr> <tr><td>C</td><td></td><td></td><td></td></tr> <tr><td>D</td><td></td><td></td><td></td></tr> <tr><td>E</td><td></td><td></td><td></td></tr> <tr><td>F</td><td></td><td></td><td></td></tr> </tbody> </table> <p>(Note1) To validate bit3(mkc2), NC side needs to prepare. (Note2) Always turn the bit2 at the same time to use bit3.</p>	F	E	D	C	B	A	9	8									7	6	5	4	3	2	1	0					mkc2	mkch	Mk3c	mts1	bit	Name	Meaning when set to 0	Meaning when set to 1	0	mts1	Special motor constant invalid	Special motor constant setting valid	1	Mk3c	3-step coil changeover function invalid	3-step coil changeover function valid	2	mkch	Coil switch function invalid	Coil switch function valid	3	mkc2	Coil switch specification 2 invalid	Coil switch specification 2 valid (Note1) (Note2)	4				5				6				7				8				9				A				B				C				D				E				F				0000 to FFFF HEX setting	000C
F	E	D	C	B	A	9	8																																																																																																		
7	6	5	4	3	2	1	0																																																																																																		
				mkc2	mkch	Mk3c	mts1																																																																																																		
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																						
0	mts1	Special motor constant invalid	Special motor constant setting valid																																																																																																						
1	Mk3c	3-step coil changeover function invalid	3-step coil changeover function valid																																																																																																						
2	mkch	Coil switch function invalid	Coil switch function valid																																																																																																						
3	mkc2	Coil switch specification 2 invalid	Coil switch specification 2 valid (Note1) (Note2)																																																																																																						
4																																																																																																									
5																																																																																																									
6																																																																																																									
7																																																																																																									
8																																																																																																									
9																																																																																																									
A																																																																																																									
B																																																																																																									
C																																																																																																									
D																																																																																																									
E																																																																																																									
F																																																																																																									

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting																																																																																																				
3235 (PR)	SP035	SFNC3 Spindle function 3	<p>Set the spindle function 3 in bit units.</p> <table border="1" style="width: 100%; text-align: center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td><input type="text"/></td><td><input type="text"/></td><td><input type="text"/></td><td><input type="text"/></td><td><input type="text"/></td><td><input type="text"/></td><td><input type="text"/></td><td><input type="text"/></td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td><input type="text"/></td><td><input type="text"/></td><td><input type="text"/></td><td><input type="text"/></td><td><input type="text"/></td><td>mwid</td><td>lwid</td><td>hwid</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width: 100%; text-align: center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>hwid</td> <td>H coil output characteristics change invalid</td> <td>H coil output characteristics change valid</td> </tr> <tr> <td>1</td> <td>lwid</td> <td>L coil output characteristics change invalid</td> <td>L coil output characteristics change valid</td> </tr> <tr> <td>2</td> <td>mwid</td> <td>M coil output characteristics change invalid</td> <td>M coil output characteristics change valid</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> <td></td> </tr> <tr> <td>8</td> <td></td> <td colspan="2">(Used with SPJ.)</td> </tr> <tr> <td>9</td> <td></td> <td></td> <td></td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> <td></td> </tr> <tr> <td>D</td> <td></td> <td></td> <td></td> </tr> <tr> <td>E</td> <td></td> <td></td> <td></td> </tr> <tr> <td>F</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8	<input type="text"/>	7	6	5	4	3	2	1	0	<input type="text"/>	mwid	lwid	hwid	bit	Name	Meaning when set to 0	Meaning when set to 1	0	hwid	H coil output characteristics change invalid	H coil output characteristics change valid	1	lwid	L coil output characteristics change invalid	L coil output characteristics change valid	2	mwid	M coil output characteristics change invalid	M coil output characteristics change valid	3				4				5				6				7				8		(Used with SPJ.)		9				A				B				C				D				E				F				0000 to FFFF HEX setting	0000											
F	E	D	C	B	A	9	8																																																																																																		
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>																																																																																																		
7	6	5	4	3	2	1	0																																																																																																		
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	mwid	lwid	hwid																																																																																																		
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																						
0	hwid	H coil output characteristics change invalid	H coil output characteristics change valid																																																																																																						
1	lwid	L coil output characteristics change invalid	L coil output characteristics change valid																																																																																																						
2	mwid	M coil output characteristics change invalid	M coil output characteristics change valid																																																																																																						
3																																																																																																									
4																																																																																																									
5																																																																																																									
6																																																																																																									
7																																																																																																									
8		(Used with SPJ.)																																																																																																							
9																																																																																																									
A																																																																																																									
B																																																																																																									
C																																																																																																									
D																																																																																																									
E																																																																																																									
F																																																																																																									

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting																																																																																																													
3236	SP036		Not used. Set to "0".																																																																																																															
3237 (PR)	SP037	SFNC5 Spindle function 5	<p>Set the spindle function 5 in bit units.</p> <table border="1" style="width: 100%; text-align: center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td>nsno</td><td>nosg</td> </tr> <tr> <td colspan="7"></td><td></td><td></td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td>plgo</td><td><input type="checkbox"/></td><td>enco</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width: 100%; text-align: center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>enco</td> <td>Encoder orientation invalid</td> <td>Encoder orientation valid</td> </tr> <tr> <td>1</td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>plgo</td> <td>PLG orientation invalid</td> <td>PLG orientation valid</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> <td></td> </tr> <tr> <td>8</td> <td>nosg</td> <td>No-signal detection type (Always monitoring)</td> <td>Monitoring only in position loop or orientation-mode</td> </tr> <tr> <td>9</td> <td>nsno</td> <td>No-signal detection valid</td> <td>No-signal detection invalid</td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> <td></td> </tr> <tr> <td>D</td> <td></td> <td></td> <td></td> </tr> <tr> <td>E</td> <td></td> <td></td> <td></td> </tr> <tr> <td>F</td> <td></td> <td></td> <td></td> </tr> </tbody> </table> <p>(Note) For bit0 to 2, do not set two bits or more to "1" at the same time.</p>	F	E	D	C	B	A	9	8	<input type="checkbox"/>	nsno	nosg										7	6	5	4	3	2	1	0	<input type="checkbox"/>	plgo	<input type="checkbox"/>	enco	bit	Name	Meaning when set to 0	Meaning when set to 1	0	enco	Encoder orientation invalid	Encoder orientation valid	1				2	plgo	PLG orientation invalid	PLG orientation valid	3				4				5				6				7				8	nosg	No-signal detection type (Always monitoring)	Monitoring only in position loop or orientation-mode	9	nsno	No-signal detection valid	No-signal detection invalid	A				B				C				D				E				F				0000 to FFFF HEX setting	0000									
F	E	D	C	B	A	9	8																																																																																																											
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	nsno	nosg																																																																																																											
7	6	5	4	3	2	1	0																																																																																																											
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	plgo	<input type="checkbox"/>	enco																																																																																																											
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																															
0	enco	Encoder orientation invalid	Encoder orientation valid																																																																																																															
1																																																																																																																		
2	plgo	PLG orientation invalid	PLG orientation valid																																																																																																															
3																																																																																																																		
4																																																																																																																		
5																																																																																																																		
6																																																																																																																		
7																																																																																																																		
8	nosg	No-signal detection type (Always monitoring)	Monitoring only in position loop or orientation-mode																																																																																																															
9	nsno	No-signal detection valid	No-signal detection invalid																																																																																																															
A																																																																																																																		
B																																																																																																																		
C																																																																																																																		
D																																																																																																																		
E																																																																																																																		
F																																																																																																																		

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting																																																																																																												
3238 (PR)	SP038	SFNC6 Spindle function 6	<p>Set the spindle function 6 in bit units.</p> <table border="1" style="width:100%; text-align:center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td></td><td></td><td></td><td>XFzs</td><td></td><td></td><td>pl80</td><td>sdt2</td> </tr> <tr> <td colspan="8"> </td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td>hzrn</td><td>orm</td><td></td><td>tdn</td><td>plg2</td><td>pftm</td><td></td><td>alty</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>bit</th><th>Name</th><th>Meaning when set to 0</th><th>Meaning when set to 1</th></tr> </thead> <tbody> <tr> <td>0</td><td>alty</td><td>Deceleration stop during special alarm invalid</td><td>Deceleration stop during special alarm valid</td></tr> <tr> <td>1</td><td></td><td></td><td></td></tr> <tr> <td>2</td><td>pftm</td><td>Encoder feedback serial communication invalid</td><td>Encoder feedback serial communication valid</td></tr> <tr> <td>3</td><td>plg2</td><td>Semi-closed pulse output signal x2 invalid</td><td>Semi-closed pulse output signal x2 valid</td></tr> <tr> <td>4</td><td>tdn</td><td>Fixed control bit</td><td></td></tr> <tr> <td>5</td><td></td><td></td><td></td></tr> <tr> <td>6</td><td>orm</td><td>Orientation start memo invalid</td><td>Orientation start memo valid</td></tr> <tr> <td>7</td><td>hzrn</td><td>Fixed control bit</td><td></td></tr> <tr> <td>8</td><td>sdt2</td><td></td><td></td></tr> <tr> <td>9</td><td>pl80</td><td></td><td></td></tr> <tr> <td>A</td><td></td><td></td><td></td></tr> <tr> <td>B</td><td></td><td></td><td></td></tr> <tr> <td>C</td><td>XFzs</td><td>Fixed control bit</td><td></td></tr> <tr> <td>D</td><td></td><td></td><td></td></tr> <tr> <td>E</td><td></td><td></td><td></td></tr> <tr> <td>F</td><td></td><td></td><td></td></tr> </tbody> </table>	F	E	D	C	B	A	9	8				XFzs			pl80	sdt2									7	6	5	4	3	2	1	0	hzrn	orm		tdn	plg2	pftm		alty	bit	Name	Meaning when set to 0	Meaning when set to 1	0	alty	Deceleration stop during special alarm invalid	Deceleration stop during special alarm valid	1				2	pftm	Encoder feedback serial communication invalid	Encoder feedback serial communication valid	3	plg2	Semi-closed pulse output signal x2 invalid	Semi-closed pulse output signal x2 valid	4	tdn	Fixed control bit		5				6	orm	Orientation start memo invalid	Orientation start memo valid	7	hzrn	Fixed control bit		8	sdt2			9	pl80			A				B				C	XFzs	Fixed control bit		D				E				F				0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																										
			XFzs			pl80	sdt2																																																																																																										
7	6	5	4	3	2	1	0																																																																																																										
hzrn	orm		tdn	plg2	pftm		alty																																																																																																										
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																														
0	alty	Deceleration stop during special alarm invalid	Deceleration stop during special alarm valid																																																																																																														
1																																																																																																																	
2	pftm	Encoder feedback serial communication invalid	Encoder feedback serial communication valid																																																																																																														
3	plg2	Semi-closed pulse output signal x2 invalid	Semi-closed pulse output signal x2 valid																																																																																																														
4	tdn	Fixed control bit																																																																																																															
5																																																																																																																	
6	orm	Orientation start memo invalid	Orientation start memo valid																																																																																																														
7	hzrn	Fixed control bit																																																																																																															
8	sdt2																																																																																																																
9	pl80																																																																																																																
A																																																																																																																	
B																																																																																																																	
C	XFzs	Fixed control bit																																																																																																															
D																																																																																																																	
E																																																																																																																	
F																																																																																																																	

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting																																																																																	
3239 (PR)	SP039	ATYP Amplifier type	Set the amplifier type. Set each amplifier type or "0" <table border="1" data-bbox="628 461 1083 1072"> <thead> <tr> <th>Parameter setting</th> <th>Amplifier type</th> </tr> </thead> <tbody> <tr><td>0000</td><td>—</td></tr> <tr><td>0001</td><td>—</td></tr> <tr><td>0002</td><td>—</td></tr> <tr><td>0003</td><td>—</td></tr> <tr><td>0004</td><td>—</td></tr> <tr><td>0005</td><td>—</td></tr> <tr><td>0006</td><td>—</td></tr> <tr><td>0007</td><td>SPM-110</td></tr> <tr><td>0008</td><td>SPM-150</td></tr> <tr><td>0009</td><td>SPM-185</td></tr> <tr><td>000A</td><td>SPM-220</td></tr> <tr><td>000B</td><td>SPM-260</td></tr> <tr><td>000C</td><td>SPM-300</td></tr> <tr><td>000D</td><td>(SPM-370)</td></tr> <tr><td>000E</td><td>(SPM-450)</td></tr> <tr><td>000F</td><td>—</td></tr> <tr><td>0010</td><td>—</td></tr> </tbody> </table> <p>(Note) (SPM-370) and (SPM-450) are used with MDS-B-SPM.</p>	Parameter setting	Amplifier type	0000	—	0001	—	0002	—	0003	—	0004	—	0005	—	0006	—	0007	SPM-110	0008	SPM-150	0009	SPM-185	000A	SPM-220	000B	SPM-260	000C	SPM-300	000D	(SPM-370)	000E	(SPM-450)	000F	—	0010	—	0000 to FFFF HEX setting	0000																																													
Parameter setting	Amplifier type																																																																																					
0000	—																																																																																					
0001	—																																																																																					
0002	—																																																																																					
0003	—																																																																																					
0004	—																																																																																					
0005	—																																																																																					
0006	—																																																																																					
0007	SPM-110																																																																																					
0008	SPM-150																																																																																					
0009	SPM-185																																																																																					
000A	SPM-220																																																																																					
000B	SPM-260																																																																																					
000C	SPM-300																																																																																					
000D	(SPM-370)																																																																																					
000E	(SPM-450)																																																																																					
000F	—																																																																																					
0010	—																																																																																					
3240 (PR)	SP040	MTYP Motor type	<table border="1" data-bbox="632 1189 1169 1352"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td> </tr> </table> <p align="center">motr</p> <table border="1" data-bbox="628 1402 1169 1843"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Details</th> </tr> </thead> <tbody> <tr> <td>0</td> <td rowspan="2">motr</td> <td rowspan="2">Set the motor type. Set "0" when using a special motor.</td> </tr> <tr> <td>1</td> </tr> <tr><td>2</td><td></td><td></td></tr> <tr><td>3</td><td></td><td></td></tr> <tr><td>4</td><td></td><td></td></tr> <tr><td>5</td><td></td><td></td></tr> <tr><td>6</td><td></td><td></td></tr> <tr><td>7</td><td></td><td></td></tr> <tr><td>8</td><td></td><td></td></tr> <tr><td>9</td><td></td><td></td></tr> <tr><td>A</td><td></td><td></td></tr> <tr><td>B</td><td></td><td></td></tr> <tr><td>C</td><td></td><td></td></tr> <tr><td>D</td><td></td><td></td></tr> <tr><td>E</td><td></td><td></td></tr> <tr><td>F</td><td></td><td></td></tr> </tbody> </table>	F	E	D	C	B	A	9	8	<input type="checkbox"/>	7	6	5	4	3	2	1	0	<input type="checkbox"/>	bit	Name	Details	0	motr	Set the motor type. Set "0" when using a special motor.	1	2			3			4			5			6			7			8			9			A			B			C			D			E			F			0000 to FFFF HEX setting	0000														
F	E	D	C	B	A	9	8																																																																															
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>																																																																															
7	6	5	4	3	2	1	0																																																																															
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>																																																																															
bit	Name	Details																																																																																				
0	motr	Set the motor type. Set "0" when using a special motor.																																																																																				
1																																																																																						
2																																																																																						
3																																																																																						
4																																																																																						
5																																																																																						
6																																																																																						
7																																																																																						
8																																																																																						
9																																																																																						
A																																																																																						
B																																																																																						
C																																																																																						
D																																																																																						
E																																																																																						
F																																																																																						

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting																																																																																																											
3241 (PR)	SP041	PTYP	Power supply type	Power supply type	0000 to FFFF HEX setting	0000																																																																																																										
				F E D C B A 9 8																																																																																																												
				amp rtyp																																																																																																												
				7 6 5 4 3 2 1 0																																																																																																												
				ptyp																																																																																																												
				bit			Explanation																																																																																																									
				0			When the CN4 connector of the drive unit and the power supply are connected, setting below is necessary.																																																																																																									
				1			To validate the external emergency stop function, add 40h.																																																																																																									
				2																																																																																																												
				3																																																																																																												
4	ptyp	<table border="1"> <thead> <tr> <th>Set-ting</th> <th>0x</th> <th>1x</th> <th>2x</th> <th>3x</th> <th>4x</th> <th>5x</th> <th>6x</th> <th>7x</th> <th>8x</th> </tr> </thead> <tbody> <tr> <td>x0</td> <td>Not used</td> <td></td> <td></td> <td>CV-300</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>x1</td> <td></td> <td>CV-110</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-10</td> </tr> <tr> <td>x2</td> <td></td> <td></td> <td>CV-220</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-15</td> </tr> <tr> <td>x3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-22</td> </tr> <tr> <td>x4</td> <td>CV-37</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-37</td> </tr> <tr> <td>x5</td> <td></td> <td>CV-150</td> <td></td> <td></td> <td>CV-450</td> <td>CV-550</td> <td></td> <td></td> <td></td> </tr> <tr> <td>x6</td> <td>CV-55</td> <td></td> <td>CV-260</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-55</td> </tr> <tr> <td>x7</td> <td></td> <td></td> <td></td> <td>CV-370</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>x8</td> <td>CV-75</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-75</td> </tr> <tr> <td>x9</td> <td></td> <td>CV-185</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-90</td> </tr> </tbody> </table>	Set-ting	0x	1x	2x	3x	4x	5x	6x	7x	8x	x0	Not used			CV-300						x1		CV-110							CR-10	x2			CV-220						CR-15	x3									CR-22	x4	CV-37								CR-37	x5		CV-150			CV-450	CV-550				x6	CV-55		CV-260						CR-55	x7				CV-370						x8	CV-75								CR-75	x9		CV-185							CR-90
Set-ting		0x	1x	2x	3x	4x	5x	6x	7x	8x																																																																																																						
x0		Not used			CV-300																																																																																																											
x1			CV-110							CR-10																																																																																																						
x2				CV-220						CR-15																																																																																																						
x3										CR-22																																																																																																						
x4		CV-37								CR-37																																																																																																						
x5			CV-150			CV-450	CV-550																																																																																																									
x6		CV-55		CV-260						CR-55																																																																																																						
x7					CV-370																																																																																																											
x8	CV-75								CR-75																																																																																																							
x9		CV-185							CR-90																																																																																																							
8	rtyp	Set the regenerative resistor type when MDS-A-CR is used.																																																																																																														
9		<table border="1"> <thead> <tr> <th>Set-ting</th> <th>Regenerative resistor model name</th> <th>Resistance value</th> <th>Capacity</th> </tr> </thead> <tbody> <tr> <td>0</td> <td colspan="3">MDS-C1-CV (Setting when using power supply regeneration)</td> </tr> <tr> <td>1</td> <td>GZG200W260HMJ</td> <td>26Ω</td> <td>80W</td> </tr> <tr> <td>2</td> <td>GZG300W130HMJ×2</td> <td>26Ω</td> <td>150W</td> </tr> <tr> <td>3</td> <td>MR-RB30</td> <td>13Ω</td> <td>300W</td> </tr> <tr> <td>4</td> <td>MR-RB50</td> <td>13Ω</td> <td>500W</td> </tr> <tr> <td>5</td> <td>GZG200W200HMJ×3</td> <td>6.7Ω</td> <td>350W</td> </tr> <tr> <td>6</td> <td>GZG300W200HMJ×3</td> <td>6.7Ω</td> <td>500W</td> </tr> <tr> <td>7</td> <td>R-UNIT-1</td> <td>30Ω</td> <td>700W</td> </tr> <tr> <td>8</td> <td>R-UNIT-2</td> <td>15Ω</td> <td>700W</td> </tr> <tr> <td>9</td> <td>R-UNIT-3</td> <td>15Ω</td> <td>2100W</td> </tr> <tr> <td>A to D</td> <td colspan="3">No setting</td> </tr> <tr> <td>E</td> <td colspan="3">Large capacity + ready ON high-speed sequence</td> </tr> <tr> <td>F</td> <td colspan="3">Ready ON high-speed sequence</td> </tr> </tbody> </table>	Set-ting	Regenerative resistor model name	Resistance value	Capacity	0	MDS-C1-CV (Setting when using power supply regeneration)			1	GZG200W260HMJ	26Ω	80W	2	GZG300W130HMJ×2	26Ω	150W	3	MR-RB30	13Ω	300W	4	MR-RB50	13Ω	500W	5	GZG200W200HMJ×3	6.7Ω	350W	6	GZG300W200HMJ×3	6.7Ω	500W	7	R-UNIT-1	30Ω	700W	8	R-UNIT-2	15Ω	700W	9	R-UNIT-3	15Ω	2100W	A to D	No setting			E	Large capacity + ready ON high-speed sequence			F	Ready ON high-speed sequence																																																								
Set-ting		Regenerative resistor model name	Resistance value	Capacity																																																																																																												
0		MDS-C1-CV (Setting when using power supply regeneration)																																																																																																														
1		GZG200W260HMJ	26Ω	80W																																																																																																												
2		GZG300W130HMJ×2	26Ω	150W																																																																																																												
3		MR-RB30	13Ω	300W																																																																																																												
4		MR-RB50	13Ω	500W																																																																																																												
5		GZG200W200HMJ×3	6.7Ω	350W																																																																																																												
6		GZG300W200HMJ×3	6.7Ω	500W																																																																																																												
7	R-UNIT-1	30Ω	700W																																																																																																													
8	R-UNIT-2	15Ω	700W																																																																																																													
9	R-UNIT-3	15Ω	2100W																																																																																																													
A to D	No setting																																																																																																															
E	Large capacity + ready ON high-speed sequence																																																																																																															
F	Ready ON high-speed sequence																																																																																																															
A																																																																																																																
B																																																																																																																
C																																																																																																																
D	amp	Always set to "0".																																																																																																														
E																																																																																																																
F																																																																																																																
3242 (PR)	SP042	CRNG	C-axis detector range	This parameter is used to set the C-axis detector range. Set "0" for this parameter. "2" is used by Mitsubishi for testing.	0 to 7	0																																																																																																										



8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3243 (PR)	SP043	TRNG	Synchronous tapping, spindle synchronous detector range	This parameter is used to set the synchronous tapping or spindle synchronous detector range. Set "0" for this parameter.	0 to 7	0
3244 (PR)	SP044	TRANS	NC communication frequency	Set a frequency of data communication with NC.	0 to 32767	Standard: 0 Special: 1028
3245	SP045	CSNT	Dual cushion timer	Set the cycle to add the increment values in the dual cushion process. When this setting value is increased, the dual cushion will increase, and the changes in the speed during acceleration/deceleration will become gradual.	0 to 1000 (ms)	0
3246 (PR)	SP046	CSN2	Speed command dual cushion	For an acceleration/deceleration time constant defined in SP019 (CSN1) , this parameter is used to provide smooth movement only at the start of acceleration/deceleration. As the value of this parameter is smaller, it moves smoother but the acceleration/deceleration time becomes longer. To make this parameter invalid, set "0".	0 to 1000	0
3247 (PR)	SP047	SDTR	Speed detection reset value	Set the reset hysteresis width for a speed detection set value defined in SP020 (SDTS).	0 to 1000 (r/min)	30
3248 (PR)	SP048	SUT	Speed reach range	Set the speed deviation rate with respect to the commanded speed for output of the speed reach signal.	0 to 100 (%)	15
3249	SP049	TLM2	Torque limit 2	Set the torque limit rate for the torque limit signal 010.	1 to 120 (%)	20
3250	SP050	TLM3	Torque limit 3	Set the torque limit rate for the torque limit signal 011.	1 to 120 (%)	30
3251	SP051	TLM4	Torque limit 4	Set the torque limit rate for the torque limit signal 100.	1 to 120 (%)	40
3252	SP052	TLM5	Torque limit 5	Set the torque limit rate for the torque limit signal 101.	1 to 120 (%)	50
3253	SP053	TLM6	Torque limit 6	Set the torque limit rate for the torque limit signal 110.	1 to 120 (%)	60
3254	SP054	TLM7	Torque limit 7	Set the torque limit rate for the torque limit signal 111.	1 to 120 (%)	70
3255 (PR)	SP055	SETM	Excessive speed deviation timer	Set the timer value until the excessive speed deviation alarm is output. The value of this parameter should be longer than the acceleration/deceleration time.	0 to 60 (s)	12


8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3256	SP056			Use not possible.	0	0
3257 (PR)	SP057	STOD	Constant → excessive judgment value	Set the value for judging when changing from a constant to excessive speed command.	0 to 50 (r/min)	0
3258 (PR)	SP058	SDT2	2nd speed detection speed	Set the speed for turning the 2nd speed detection ON. (This is valid only when SP038: SFNC6-bit8 is set to "1".) If the speed drops below this set speed, the 2nd speed detection will turn ON. When the speed reaches this set speed +15r/min or more, the 2nd speed detection will turn OFF. If SP034: SFNC2-bit1 is set to "1", this will be the medium-speed and high-speed coil changeover speed. The speed detection reset width follows the SP047 (speed detection reset width) setting.	0 to 32767 (r/min)	0
3259 (PR)	SP059	MKT	Winding changeover base shut-off timer	Set the base shut-off time for contactor switching at winding changeover. Note that the contactor may be damaged with burning if the value of this parameter is too small.	50 to 10000 (ms)	150
3260 (PR)	SP060	MKT2	Current limit timer after winding changeover	Set the current limit time to be taken after completion of contactor switching at winding changeover.	0 to 10000 (ms)	500
3261 (PR)	SP061	MKIL	Current limit value after winding changeover	Set the current limit value during a period defined in SP060 (MKT2) after completion of contactor switching at winding changeover.	0 to 120 (%)	75
3262	SP062			Not used. Set to "0".	0	0
3263 (PR)	SP063	OLT	Overload alarm detection time	Set the time constant for detection of the motor overload alarm.	0 to 1000 (s)	60
3264 (PR)	SP064	OLL	Overload alarm detection level	Set the detection level of the motor overload alarm.	0 to 180 (%)	110
3265 (PR)	SP065	VCGN1	Target value of variable speed loop proportional gain	Set the magnification of speed loop proportional gain with respect to SP022 (VGNP1) at the maximum motor speed defined in SP017 (TSP).	0 to 100 (%)	100

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting																
3266 (PR)	SP066	VCSN1	Change starting speed of variable speed loop proportional gain	Set the speed when the speed loop proportional gain change starts. 	0 to 32767 (r/min)	0															
3267 (PR)	SP067	VIGWA	Change starting speed of variable current loop gain	Set the speed where the current loop gain change starts.	0 to 32767 (r/min)	0															
3268 (PR)	SP068	VIGWB	Change ending speed of variable current loop gain	Set the speed where the current loop gain change ends.	0 to 32767 (r/min)	0															
3269 (PR)	SP069	VIGN	Target value of variable current loop gain	Set the magnification of current loop gain (torque component and excitation component) for a change ending speed defined in SP068 (VIGWB). When this parameter is set to "0", the magnification is 1. 	0 to 32767 (1/16-fold)	0															
			<table border="1" data-bbox="654 1550 1158 1729"> <thead> <tr> <th>SP017 (TSP) Maximum motor speed</th> <th>SP067 (VIGWA)</th> <th>SP068 (VIGWB)</th> <th>SP069 (VIGN)</th> </tr> </thead> <tbody> <tr> <td>0 to 6000</td> <td>0</td> <td>0</td> <td>0</td> </tr> <tr> <td>6001 to 8000</td> <td>5000</td> <td>8000</td> <td>45</td> </tr> <tr> <td>8001 or more</td> <td>5000</td> <td>10000</td> <td>64</td> </tr> </tbody> </table>	SP017 (TSP) Maximum motor speed	SP067 (VIGWA)	SP068 (VIGWB)	SP069 (VIGN)	0 to 6000	0	0	0	6001 to 8000	5000	8000	45	8001 or more	5000	10000	64		
SP017 (TSP) Maximum motor speed	SP067 (VIGWA)	SP068 (VIGWB)	SP069 (VIGN)																		
0 to 6000	0	0	0																		
6001 to 8000	5000	8000	45																		
8001 or more	5000	10000	64																		
3270	SP070	FHz	Machine resonance suppression filter frequency	When machine vibration occurs in speed and position control, set the frequency of the required vibration suppression. Note that a value of 100Hz or more is set. Set to "0" when not used.	0 to 3000 (Hz)	0															
3271 to 3275	SP071 to SP075			Use not possible.	0	0															

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3276	SP076	FONS	Machine resonance suppression filter operation speed	When the vibration increases in motor stop (ex. in orientation stop) when the machine vibration suppression filter is operated by SP070, operate the machine vibration suppression filter at a speed of this parameter or more. When set to "0", this is validated for all speeds.	0 to 32767 (r/min)	0
3277 (PR)	SP077	TDSL	Fixed control constant	Set by Mitsubishi. Set "14" unless designated in particular.		14
3278 (PR)	SP078	FPWM	Fixed control constant	Set by Mitsubishi. Set "1" unless designated in particular.	1	1
3279	SP079			Use not possible.	0	0
3280	SP080	SWTD	Fixed control constant	Set by Mitsubishi. Set "0" unless designated in particular.	0	0
3281 to 3286	SP081 to SP086			Use not possible.	0	0
3287 (PR)	SP087	DIQM	Target value of variable torque limit magnification at deceleration	Set the minimum value of variable torque limit at deceleration.	0 to 150 (%)	75
3288 (PR)	SP088	DIQN	Speed for starting change of variable torque limit magnification at deceleration	Set the speed where the torque limit value at deceleration starts to change. 	0 to 32767 (r/min)	3000
3289 to 3292	SP089 to SP092			Use not possible.	0	0
3293 (PR)	SP093	ORE	Tolerable pulse check error	Set this when detecting the pulse detector's pulse mistakes. (Valid only for full close control.)	0 to 32767	0
3294 (PR)	SP094	LMAV	Load meter output filter	Set the filter time constant of load meter output. When "0" is set, a filter time constant is set to 100ms.	0 to 32767 (2ms)	0
3295 (PR)	SP095	VFAV	Fixed control constant	Set by Mitsubishi. Set "0" unless designated in particular.	0	0

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting																																																																																																																									
3296 (PR)	SP096	EGAR	Encoder gear ratio	0 to 4	0																																																																																																																									
<p>Set the gear ratio between the spindle end and the encoder end (except for the motor-built-in encoder) as indicated below.</p> <table border="1"> <thead> <tr> <th>Setting value</th> <th>Gear ratio (deceleration)</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>1 : 1</td> </tr> <tr> <td>1</td> <td>1 : 2</td> </tr> <tr> <td>2</td> <td>1 : 4</td> </tr> <tr> <td>3</td> <td>1 : 8</td> </tr> <tr> <td>4</td> <td>1 : 16</td> </tr> </tbody> </table> <p>(Note) Use a combination so that the encoder end is slower than the spindle end.</p>				Setting value	Gear ratio (deceleration)	0	1 : 1	1	1 : 2	2	1 : 4	3	1 : 8	4	1 : 16																																																																																																															
Setting value	Gear ratio (deceleration)																																																																																																																													
0	1 : 1																																																																																																																													
1	1 : 2																																																																																																																													
2	1 : 4																																																																																																																													
3	1 : 8																																																																																																																													
4	1 : 16																																																																																																																													
3297 (PR)	SP097	SPECO	Orientation specification	0000 to FFFF HEX setting	0000																																																																																																																									
<p>Set the orientation specifications in bit units.</p> <table border="1"> <thead> <tr> <th>F</th> <th>E</th> <th>D</th> <th>C</th> <th>B</th> <th>A</th> <th>9</th> <th>8</th> </tr> </thead> <tbody> <tr> <td>ostp</td> <td>orze</td> <td>ksft</td> <td>gchg</td> <td></td> <td>ips2</td> <td></td> <td></td> </tr> <tr> <th>7</th> <th>6</th> <th>5</th> <th>4</th> <th>3</th> <th>2</th> <th>1</th> <th>0</th> </tr> <tr> <td>vg8x</td> <td></td> <td>fdir</td> <td>osc1</td> <td></td> <td>dmin</td> <td>odi2</td> <td>odi1</td> </tr> </tbody> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>odi1</td> <td colspan="2">Orientation rotation direction</td> </tr> <tr> <td rowspan="4">1</td> <td rowspan="4">odi2</td> <td colspan="2">00: Previous (the direction in which the motor has so far rotated under speed control)</td> </tr> <tr> <td colspan="2">01: Forward rotation</td> </tr> <tr> <td colspan="2">10: Backward rotation</td> </tr> <tr> <td colspan="2">11: Prohibited (Same as setting value = 10)</td> </tr> <tr> <td>2</td> <td>dmin</td> <td>Orientation in-position advance invalid</td> <td>Orientation in-position advance valid</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td>osc1</td> <td>Indexing speed clamp invalid</td> <td>Indexing speed clamp valid</td> </tr> <tr> <td>5</td> <td>fdir</td> <td>Encoder detector polarity: +</td> <td>Encoder detector polarity: -</td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td>vg8x</td> <td>Speed gain *1/8 during torque limit valid</td> <td>Speed gain *1/8 during torque limit invalid</td> </tr> <tr> <td>8</td> <td></td> <td></td> <td></td> </tr> <tr> <td>9</td> <td></td> <td></td> <td></td> </tr> <tr> <td>A</td> <td>ips2</td> <td>2nd in-position invalid</td> <td>2nd in-position valid</td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td>gchg</td> <td>Gain changeover during orientation invalid</td> <td>Gain changeover during orientation valid</td> </tr> <tr> <td>D</td> <td>ksft</td> <td>Orientation virtual target shift invalid</td> <td>Orientation virtual target shift valid</td> </tr> <tr> <td>E</td> <td>orze</td> <td colspan="2">This is used by Mitsubishi.</td> </tr> <tr> <td>F</td> <td>ostp</td> <td colspan="2">Set to "0" unless particularly designated.</td> </tr> </tbody> </table> <table border="1"> <thead> <tr> <th colspan="4">In-position advance (bit 2)</th> </tr> <tr> <th colspan="2"></th> <th>0 (invalid)</th> <th>1 (valid)</th> </tr> </thead> <tbody> <tr> <td rowspan="2">Second in-position</td> <td>0 (Invalid)</td> <td>In-position signal in OINP width=1 Control output 4/ bit 4=1 Second in-position signal=0 Control output 4/ bit F=1</td> <td>In-position signal in OINP width=1 Control output 4/ bit 4=1 Second in-position signal=0 Control output 4/ bit F=0</td> </tr> <tr> <td>1 (Valid)</td> <td></td> <td>In-position signal in DINP width=1 Control output 4/ bit 4=1 Second in-position signal in OINP width = 0 Control output 4/ bit F=1</td> </tr> </tbody> </table>				F	E	D	C	B	A	9	8	ostp	orze	ksft	gchg		ips2			7	6	5	4	3	2	1	0	vg8x		fdir	osc1		dmin	odi2	odi1	bit	Name	Meaning when set to 0	Meaning when set to 1	0	odi1	Orientation rotation direction		1	odi2	00: Previous (the direction in which the motor has so far rotated under speed control)		01: Forward rotation		10: Backward rotation		11: Prohibited (Same as setting value = 10)		2	dmin	Orientation in-position advance invalid	Orientation in-position advance valid	3				4	osc1	Indexing speed clamp invalid	Indexing speed clamp valid	5	fdir	Encoder detector polarity: +	Encoder detector polarity: -	6				7	vg8x	Speed gain *1/8 during torque limit valid	Speed gain *1/8 during torque limit invalid	8				9				A	ips2	2nd in-position invalid	2nd in-position valid	B				C	gchg	Gain changeover during orientation invalid	Gain changeover during orientation valid	D	ksft	Orientation virtual target shift invalid	Orientation virtual target shift valid	E	orze	This is used by Mitsubishi.		F	ostp	Set to "0" unless particularly designated.		In-position advance (bit 2)						0 (invalid)	1 (valid)	Second in-position	0 (Invalid)	In-position signal in OINP width=1 Control output 4/ bit 4=1 Second in-position signal=0 Control output 4/ bit F=1	In-position signal in OINP width=1 Control output 4/ bit 4=1 Second in-position signal=0 Control output 4/ bit F=0	1 (Valid)		In-position signal in DINP width=1 Control output 4/ bit 4=1 Second in-position signal in OINP width = 0 Control output 4/ bit F=1		
F	E	D	C	B	A	9	8																																																																																																																							
ostp	orze	ksft	gchg		ips2																																																																																																																									
7	6	5	4	3	2	1	0																																																																																																																							
vg8x		fdir	osc1		dmin	odi2	odi1																																																																																																																							
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																																											
0	odi1	Orientation rotation direction																																																																																																																												
1	odi2	00: Previous (the direction in which the motor has so far rotated under speed control)																																																																																																																												
		01: Forward rotation																																																																																																																												
		10: Backward rotation																																																																																																																												
		11: Prohibited (Same as setting value = 10)																																																																																																																												
2	dmin	Orientation in-position advance invalid	Orientation in-position advance valid																																																																																																																											
3																																																																																																																														
4	osc1	Indexing speed clamp invalid	Indexing speed clamp valid																																																																																																																											
5	fdir	Encoder detector polarity: +	Encoder detector polarity: -																																																																																																																											
6																																																																																																																														
7	vg8x	Speed gain *1/8 during torque limit valid	Speed gain *1/8 during torque limit invalid																																																																																																																											
8																																																																																																																														
9																																																																																																																														
A	ips2	2nd in-position invalid	2nd in-position valid																																																																																																																											
B																																																																																																																														
C	gchg	Gain changeover during orientation invalid	Gain changeover during orientation valid																																																																																																																											
D	ksft	Orientation virtual target shift invalid	Orientation virtual target shift valid																																																																																																																											
E	orze	This is used by Mitsubishi.																																																																																																																												
F	ostp	Set to "0" unless particularly designated.																																																																																																																												
In-position advance (bit 2)																																																																																																																														
		0 (invalid)	1 (valid)																																																																																																																											
Second in-position	0 (Invalid)	In-position signal in OINP width=1 Control output 4/ bit 4=1 Second in-position signal=0 Control output 4/ bit F=1	In-position signal in OINP width=1 Control output 4/ bit 4=1 Second in-position signal=0 Control output 4/ bit F=0																																																																																																																											
	1 (Valid)		In-position signal in DINP width=1 Control output 4/ bit 4=1 Second in-position signal in OINP width = 0 Control output 4/ bit F=1																																																																																																																											

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3298 (PR)	SP098	VGOP	Speed loop gain proportional term in orientation mode	Set the speed loop proportional gain in orientation mode. When the gain is increased, rigidity is improved in the orientation stop but vibration and sound become larger.	0 to 2000 (1/s)	63
3299 (PR)	SP099	VGOI	Orientation mode speed loop gain integral term	Set the speed loop integral gain in orientation mode.	0 to 2000 (0.1 1/s)	60
3300 (PR)	SP100	VGOD	Orientation mode speed loop gain delay advance term	Set a loop gain delay advance gain in orientation mode. When this parameter is set to "0", PI control is applied.	0 to 1000 (0.1 1/s)	15
3301 (PR)	SP101	DINP	Orientation advance in-position width	When using the orientation in-position advance function, set the in-position width that is larger than the normal in-position width defined in SP004 (OINP).	1 to 2880 (1/16°)	16
3302 (PR)	SP102	OODR	Excessive error value in orientation mode	Set the excessive error width in orientation mode.	0 to 32767 (1/4 pulse) (1 pulse= 0.088°)	32767
3303 (PR)	SP103	FTM	Index positioning completion OFF time timer	Set the time for forcedly turn OFF the index positioning completion signal (different from the orientation completion signal) after the leading edge of the indexing start signal.	0 to 10000 (ms)	200
3304 (PR)	SP104	TLOR	Torque limit value for orientation servo locking	Set the torque limit value for orientation in-position output. If the external torque limit signal is input, the torque limit value set by this parameter is made invalid.	0 to 120 (%)	100
3305 (PR)	SP105	IQG0	Current loop gain magnification 1 in orientation mode	Set the magnification for current loop gain (torque component) at orientation completion.	1 to 1000 (%)	100
3306 (PR)	SP106	IDG0	Current loop gain magnification 2 in orientation mode	Set the magnification for current loop gain (excitation component) at orientation completion.	1 to 1000 (%)	100
3307	SP107	CSP2	Deceleration rate 2 in orientation mode	Set the deceleration rate in orientation mode corresponding to the gear 001. When this parameter is set to "0", same as SP006 (CSP).	0 to 1000	0
3308	SP108	CSP3	Deceleration rate 3 in orientation mode	Set the deceleration rate in orientation mode corresponding to the gear 010. When this parameter is set to "0", same as SP006 (CSP).	0 to 1000	0

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3309	SP109	CSP4	Deceleration rate 4 in orientation mode	Set the deceleration rate in orientation mode corresponding to the gear 011. When this parameter is set to "0", same as SP006 (CSP).	0 to 1000	0
3310 to 3313	SP110 to SP003			Use not possible.		0
3314	SP114	OPER	Orientation pulse miss check value	An alarm "5C" will occur if the pulse miss value at the orientation stop exceeds this setting value. (Note that this is invalid when set to "0".) In this parameter, set the value to fulfill the following conditions. SP114 setting value > 1.5 × SP004 (orientation in-position width)	0 to 32767 (360°/4096)	0
3315	SP115	OSP2	Orientation motor speed clamp value 2	When the orientation clamp speed is changed by the control input, this parameter setting will be used instead of SP005: OSP. Indexing speed clamp valid This parameter is used when (SP097: SPEC0-bit4 = 1).	0 to 32767 (r/min)	0
3316	SP116			Use not possible.	0	0
3317	SP117	ORUT		Set by Mitsubishi. Set "0" unless designated in particular.	0	0
3318	SP118	ORCT	Number of orientation retry times	Set the number of times to retry when an orientation or feedback error occurs. The warning (A9) is issued while retrying orientation, and an alarm (5C) is issued when the set number of times is exceeded.	0 to 100 (time)	0
3319	SP119	MPGH	Orientation position gain H winding compensation magnification	Set the compensation magnification of the orientation position loop gain for the H winding. H winding orientation position loop gain = SP001 (or SP002) × SP119/256 When set to "0", will become the same as SP001 or SP002.	0 to 2560 (1/256-fold)	0
3320	SP120	MPGL	Orientation position gain L winding compensation magnification	Set the compensation magnification of the orientation position loop gain for the L winding. L winding orientation position loop gain = SP001 (or SP002) × SP120/256 When set to "0", will become the same as SP001 or SP002.	0 to 2560 (1/256-fold)	0

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3321	SP121	MPCSH	Orientation deceleration rate H winding compensation magnification	Set the compensation magnification of the orientation deceleration rate for the H winding. Orientation deceleration rate for the H winding = SP006 × SP121/256 When set to "0", will become the same as SP006.	0 to 2560 (1/256-fold)	0
3322	SP122	MPCSL	Orientation deceleration rate L winding compensation magnification	Set the compensation magnification of the orientation deceleration rate for the L winding. Orientation deceleration rate for the L winding = SP006 × SP122/256 When set to "0", will become the same as SP006.	0 to 2560 (1/256-fold)	0
3323 to 3325	SP123 to SP125			Use not possible.	0	0
3326	SP126	MPGH	Orientation position gain M coil compensation	Set this to set the orientation position loop gain for the coil changeover motor to the M coil's unique value.	0 to 2560 (1/256-fold)	0
3327	SP127	MPCSM	Orientation deceleration rate M coil compensation	Set this to set the orientation deceleration rate for the coil motor to the M coil's unique value.	0 to 2560 (1/256-fold)	0
3328	SP128	OXKPM	Position loop gain magnification after orientation gain change-over (M coil)	Set the M coil gain magnification to be used after in-position when gain changeover is valid (SP097: SPEC0-bitC=1) during orientation.	0 to 2560 (1/256-fold)	0

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting																																																																																																												
3329 (PR)	SP129	SPECC C-axis specifications	<p>Set the C-axis specifications in bit units.</p> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:12.5%; text-align:center;">F</td> <td style="width:12.5%; text-align:center;">E</td> <td style="width:12.5%; text-align:center;">D</td> <td style="width:12.5%; text-align:center;">C</td> <td style="width:12.5%; text-align:center;">B</td> <td style="width:12.5%; text-align:center;">A</td> <td style="width:12.5%; text-align:center;">9</td> <td style="width:12.5%; text-align:center;">8</td> </tr> <tr> <td style="text-align:center;">zrtn</td> <td style="text-align:center;">ptyp</td> <td style="text-align:center;">fb9x</td> <td style="text-align:center;">zrtd</td> <td style="text-align:center;">zrn2</td> <td style="text-align:center;"></td> <td style="text-align:center;">zdir</td> <td style="text-align:center;">ztyp</td> </tr> <tr> <td colspan="8"> </td> </tr> <tr> <td style="text-align:center;">7</td> <td style="text-align:center;">6</td> <td style="text-align:center;">5</td> <td style="text-align:center;">4</td> <td style="text-align:center;">3</td> <td style="text-align:center;">2</td> <td style="text-align:center;">1</td> <td style="text-align:center;">0</td> </tr> <tr> <td style="text-align:center;">vg8x</td> <td style="text-align:center;"></td> <td style="text-align:center;">fdir</td> <td style="text-align:center;"></td> <td style="text-align:center;">phos</td> <td style="text-align:center;">rtrn</td> <td style="text-align:center;"></td> <td style="text-align:center;">fclx</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>fclx</td> <td>Closed loop</td> <td>Semi-closed loop (Gear 1 : 1 only)</td> </tr> <tr> <td>1</td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>rtrn</td> <td>Position monitor during ready OFF invalid</td> <td>Position monitor during ready OFF valid</td> </tr> <tr> <td>3</td> <td>phos</td> <td>Normal (no compensation)</td> <td>Vx4 synchronization compensation valid</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td>fdir</td> <td>Position detector polarity (+)</td> <td>Position detector polarity (-)</td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td>vg8x</td> <td>Speed gain × 1/8 during torque limit valid</td> <td>Speed gain × 1/8 during torque limit invalid</td> </tr> <tr> <td>8</td> <td>ztyp</td> <td>Z-phase type: Normal start up</td> <td>Z-phase type: Start up only</td> </tr> <tr> <td>9</td> <td>zdir</td> <td>Z-phase rising polarity (+)</td> <td>Z-phase rising polarity (-)</td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td>zrn2</td> <td colspan="2">This is used by Mitsubishi. Set to "0" unless particularly designated.</td> </tr> <tr> <td>C</td> <td>zrtd</td> <td colspan="2">Set to "0" unless particularly designated.</td> </tr> <tr> <td>D</td> <td>fb9x</td> <td>Speed feedback Standard (PLG)</td> <td>Speed feedback 90,000 pulse detector</td> </tr> <tr> <td>E</td> <td>ptyp</td> <td>Position control switch type: After zero point return</td> <td>Position control switch type: After deceleration stop</td> </tr> <tr> <td>F</td> <td>zrtn</td> <td>Zero point return direction: CCW</td> <td>Zero point return direction: CW</td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8	zrtn	ptyp	fb9x	zrtd	zrn2		zdir	ztyp									7	6	5	4	3	2	1	0	vg8x		fdir		phos	rtrn		fclx	bit	Name	Meaning when set to 0	Meaning when set to 1	0	fclx	Closed loop	Semi-closed loop (Gear 1 : 1 only)	1				2	rtrn	Position monitor during ready OFF invalid	Position monitor during ready OFF valid	3	phos	Normal (no compensation)	Vx4 synchronization compensation valid	4				5	fdir	Position detector polarity (+)	Position detector polarity (-)	6				7	vg8x	Speed gain × 1/8 during torque limit valid	Speed gain × 1/8 during torque limit invalid	8	ztyp	Z-phase type: Normal start up	Z-phase type: Start up only	9	zdir	Z-phase rising polarity (+)	Z-phase rising polarity (-)	A				B	zrn2	This is used by Mitsubishi. Set to "0" unless particularly designated.		C	zrtd	Set to "0" unless particularly designated.		D	fb9x	Speed feedback Standard (PLG)	Speed feedback 90,000 pulse detector	E	ptyp	Position control switch type: After zero point return	Position control switch type: After deceleration stop	F	zrtn	Zero point return direction: CCW	Zero point return direction: CW		0000
F	E	D	C	B	A	9	8																																																																																																										
zrtn	ptyp	fb9x	zrtd	zrn2		zdir	ztyp																																																																																																										
7	6	5	4	3	2	1	0																																																																																																										
vg8x		fdir		phos	rtrn		fclx																																																																																																										
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																														
0	fclx	Closed loop	Semi-closed loop (Gear 1 : 1 only)																																																																																																														
1																																																																																																																	
2	rtrn	Position monitor during ready OFF invalid	Position monitor during ready OFF valid																																																																																																														
3	phos	Normal (no compensation)	Vx4 synchronization compensation valid																																																																																																														
4																																																																																																																	
5	fdir	Position detector polarity (+)	Position detector polarity (-)																																																																																																														
6																																																																																																																	
7	vg8x	Speed gain × 1/8 during torque limit valid	Speed gain × 1/8 during torque limit invalid																																																																																																														
8	ztyp	Z-phase type: Normal start up	Z-phase type: Start up only																																																																																																														
9	zdir	Z-phase rising polarity (+)	Z-phase rising polarity (-)																																																																																																														
A																																																																																																																	
B	zrn2	This is used by Mitsubishi. Set to "0" unless particularly designated.																																																																																																															
C	zrtd	Set to "0" unless particularly designated.																																																																																																															
D	fb9x	Speed feedback Standard (PLG)	Speed feedback 90,000 pulse detector																																																																																																														
E	ptyp	Position control switch type: After zero point return	Position control switch type: After deceleration stop																																																																																																														
F	zrtn	Zero point return direction: CCW	Zero point return direction: CW																																																																																																														
3330	SP130	PGC1 First position loop gain for cutting on C-axis	Set the position loop gain when the first gain is selected for C axis cutting.	1 to 200 (1/s)	15																																																																																																												

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3331	SP131	PGC2	Second position loop gain for cutting on C-axis	Set the position loop gain when the second gain is selected for C axis cutting.	1 to 200 (1/s)	15
3332	SP132	PGC3	Third position loop gain for cutting on C-axis	Set the position loop gain when the third gain is selected for C-axis cutting.	1 to 200 (1/s)	15
3333	SP133	PGC4	Stop position loop gain for cutting on C-axis	Set the position loop gain for stopping when carrying out C-axis cutting.	1 to 200 (1/s)	15
3334 (PR)	SP134	VGCP0*	C-axis non-cutting speed loop gain proportional item	Set the speed loop proportional gain in C-axis non-cutting mode.	0 to 5000 (1/s)	63
3335 (PR)	SP135	VGCI0	C-axis non-cutting speed loop gain integral item	Set the speed loop integral gain in C-axis non-cutting mode.	0 to 5000 (0.1 1/s)	60
3336 (PR)	SP136	VGCD0	C-axis non-cutting speed loop gain delay advance item	Set the speed loop delay advance gain in C-axis non-cutting mode. When this parameter is set to "0", PI control is exercised.	0 to 5000 (0.1 1/s)	15
3337 (PR)	SP137	VGCP1	First speed loop gain proportional item for C-axis cutting	Set the speed loop proportional gain when the first gain is selected for C-axis cutting.	0 to 5000 (1/s)	63
3338 (PR)	SP138	VGCI1	First speed loop gain integral item for cutting on C-axis	Set the speed loop integral gain when the first gain is selected for C-axis cutting.	0 to 5000 (0.1 1/s)	60
3339 (PR)	SP139	VGCD1	First speed loop gain delay advance item for cutting on C-axis	Set the speed loop delay advance gain when the first gain is selected for curing on the C-axis. When this parameter is set to "0", PI control is applied.	0 to 5000 (0.1 1/s)	15
3340 (PR)	SP140	VGCP2	Second speed loop gain proportional item for cutting on C-axis	Set the speed loop proportional gain when the second gain is selected for C-axis cutting.	0 to 5000 (1/s)	63
3341 (PR)	SP141	VGCI2	Second speed loop gain integral item for cutting on C-axis	Set the speed loop integral gain when the second gain is selected for C-axis cutting.	0 to 5000 (0.1 1/s)	60
3342 (PR)	SP142	VGCD2	Second speed loop gain delay advance item for cutting on C-axis	Set the speed loop delay advance gain when the second gain is selected for C-axis cutting. When this parameter is set to "0", PI control is applied.	0 to 5000 (0.1 1/s)	15

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3343 (PR)	SP143	VGCP3	Third speed loop gain proportional item for cutting on C-axis	Set the speed loop proportional gain when the third gain is selected for C-axis cutting.	0 to 5000 (1/s)	63
3344 (PR)	SP144	VGCI3	Third speed loop gain integral item for cutting on C-axis	Set the speed loop integral gain when the third gain is selected for C-axis cutting.	0 to 5000 (0.1 1/s)	60
3345 (PR)	SP145	VGCD3	Third speed loop gain delay advance item for cutting on C-axis	Set the speed loop delay advance gain when the third gain is selected for C-axis cutting. When this parameter is set to "0", PI control is applied.	0 to 5000 (0.1 1/s)	15
3346 (PR)	SP146	VGCP4	Speed loop gain proportional item for stop of cutting on C-axis	Set the speed loop proportional gain when C-axis cutting is stopped.	0 to 5000 (1/s)	63
3347 (PR)	SP147	VGCI4	Speed loop gain integral item for stop of cutting on C-axis	Set the speed loop integral gain when C-axis cutting is stopped.	0 to 5000 (0.1 1/s)	60
3348 (PR)	SP148	VGCD4	Speed loop gain delay advance item for stop of cutting on C-axis	Set the speed loop delay advance gain when C-axis cutting is stopped. When this parameter is set to "0", PI control is applied.	0 to 5000 (0.1 1/s)	15
3349	SP149	CZRN	C-axis zero point return speed	This parameter is valid when SP129 (SPECC) bitE is set to "0". Set the zero point return speed used when the speed loop changes to the position loop.	1 to 500 (r/min)	50
3350	SP150	CPDT	C-axis zero point return deceleration point	This parameter is valid when SP129 (SPECC) bitE is set to "0". Set the deceleration rate where the machine starts to decelerate when it returns to the target stop point during C-axis zero point return. When the machine tends to overshoot at the stop point, set the smaller value.	1 to 10000	1
3351	SP151	CPSTL	C-axis zero point return shift amount (low byte)	This parameter is valid when SPECC (SP129) bitE is set to "0". Set the C-axis zero point position.	HEX setting 00000000 to FFFFFFFF (1/1000°)	H: 0000 L: 0000
3352	SP152	CPSTH	C-axis zero point return shift amount (high byte)			

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3353	SP153	CINP	C-axis in-position width	Set the position error range in which the in-position signal is output on the C-axis.	0000 to FFFF (1/1000°) HEX setting	03E8
3354 (PR)	SP154	CODRL	Excessive error width on C-axis (low byte)	Set the excessive error width on the C-axis.	HEX setting 00000000 to FFFFFFFF (1/1000°)	H: 0001 L: D4C0
3355 (PR)	SP155	CODRH	Excessive error width on C-axis (high byte)			
3356	SP156	OVSH	C-axis overshoot compensation	Set this to prevent overshooting when shifting from movement to stopping with C-axis control. (Set this referring to the load meter display when overshooting occurred.)	0 to 1000 (0.1%)	0
3357	SP157			Not used. Set to "0".	0	0
3358	SP158			Not used. Set to "0".	0	0
3359	SP159			Use not possible.	0	0
3360	SP160			Use not possible.	0	0
3361 (PR)	SP161	IQGC0	Current loop gain magnification 1 for non-cutting on C-axis	Set the magnification of current loop gain (torque component) for C-axis non-cutting.	1 to 1000 (%)	100
3362 (PR)	SP162	IDGC0	Current loop gain magnification 2 for non-cutting on C-axis	Set the magnification of current loop gain (excitation component) for C-axis non-cutting.	1 to 1000 (%)	100
3363 (PR)	SP163	IQGC1	Current loop gain magnification 1 for cutting on C-axis	Set the magnification of current loop gain (torque component) for C-axis cutting.	1 to 1000 (%)	100
3364 (PR)	SP164	IDGC1	Current loop gain magnification 2 for cutting on C-axis	Set the magnification of current loop gain (excitation component) for C-axis cutting.	1 to 1000 (%)	100
3365	SP165	PG2C	C-axis position loop gain 2	Set the second position loop gain when high-gain control is carried out for control of the C-axis. This parameter is applied to all the operation modes of C-axis control. When this function is not used, assign "0".	0 to 999 (1/s)	0


8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3366	SP166	PG3C	C-axis position loop gain 3	Set the third position loop gain when high-gain control is carried out for control of the C-axis. This parameter is applied to all the operation modes of C-axis control. When this function is not used, assign "0".	0 to 999 (1/s)	0
3367 (PR)	SP167	PGU	Position loop gain for increased spindle holding force	Set the position loop gain for when the disturbance observer is valid.	0 to 100 (1/s)	15
3368 (PR)	SP168	VGUP	Speed loop gain proportional item for increased spindle holding force	Set the speed loop gain proportional item for when the disturbance observer is valid.	0 to 5000 (1/s)	63
3369 (PR)	SP169	VGUI	Speed loop gain integral item for increased spindle holding force	Set the speed loop gain integral item for when the disturbance observer is valid.	0 to 5000 (0.1 1/s)	60
3370 (PR)	SP170	VGUD	Speed loop gain delay advance item for increased spindle holding force	Set the speed loop gain delay advance item for when the disturbance observer is valid.	0 to 5000 (0.1 1/s)	15
3371 to 3376	SP171 to SP176			Not used. Set to "0".	0	0

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting																																																																																													
3377 (PR)	SP177	SPECS	Spindle synchronous specifications	Set the spindle synchronous specifications in bit units. F E D C B A 9 8 <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:12.5%;"></td> <td style="width:12.5%;"></td> <td style="width:12.5%; text-align:center;">odx8</td> <td style="width:12.5%;"></td> <td style="width:12.5%;"></td> <td style="width:12.5%;"></td> <td style="width:12.5%;"></td> <td style="width:12.5%; text-align:right;">phos</td> </tr> <tr> <td style="text-align:center;">7</td> <td style="text-align:center;">6</td> <td style="text-align:center;">5</td> <td style="text-align:center;">4</td> <td style="text-align:center;">3</td> <td style="text-align:center;">2</td> <td style="text-align:center;">1</td> <td style="text-align:center;">0</td> </tr> <tr> <td></td> <td></td> <td style="text-align:center;">fdir</td> <td></td> <td style="text-align:center;">mach</td> <td></td> <td></td> <td style="text-align:right;">fclx</td> </tr> </table> <table border="1" style="width:100%; border-collapse: collapse; margin-top: 5px;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>fclx</td> <td>Closed loop</td> <td>Semi-closed loop</td> </tr> <tr> <td>1</td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td></td> <td></td> <td></td> </tr> <tr> <td>3</td> <td>mach</td> <td>Automatic coil change-over during spindle synchronization invalid</td> <td>Automatic coil change-over during spindle synchronization valid</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td>fdir</td> <td>Position detector direction (positive direction)</td> <td>Position detector direction (negative direction)</td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> <td></td> </tr> <tr> <td>8</td> <td></td> <td></td> <td></td> </tr> <tr> <td>9</td> <td></td> <td></td> <td></td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> <td></td> </tr> <tr> <td>D</td> <td>odx8</td> <td>Magnification of excessive error width x 8 times invalid</td> <td>Magnification of excessive error width x 8 times valid</td> </tr> <tr> <td>E</td> <td></td> <td></td> <td></td> </tr> <tr> <td>F</td> <td></td> <td colspan="2">(Used with SPJ)</td> </tr> </tbody> </table>			odx8					phos	7	6	5	4	3	2	1	0			fdir		mach			fclx	bit	Name	Meaning when set to 0	Meaning when set to 1	0	fclx	Closed loop	Semi-closed loop	1				2				3	mach	Automatic coil change-over during spindle synchronization invalid	Automatic coil change-over during spindle synchronization valid	4				5	fdir	Position detector direction (positive direction)	Position detector direction (negative direction)	6				7				8				9				A				B				C				D	odx8	Magnification of excessive error width x 8 times invalid	Magnification of excessive error width x 8 times valid	E				F		(Used with SPJ)		0000 to FFFF HEX setting	0000
		odx8					phos																																																																																											
7	6	5	4	3	2	1	0																																																																																											
		fdir		mach			fclx																																																																																											
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																															
0	fclx	Closed loop	Semi-closed loop																																																																																															
1																																																																																																		
2																																																																																																		
3	mach	Automatic coil change-over during spindle synchronization invalid	Automatic coil change-over during spindle synchronization valid																																																																																															
4																																																																																																		
5	fdir	Position detector direction (positive direction)	Position detector direction (negative direction)																																																																																															
6																																																																																																		
7																																																																																																		
8																																																																																																		
9																																																																																																		
A																																																																																																		
B																																																																																																		
C																																																																																																		
D	odx8	Magnification of excessive error width x 8 times invalid	Magnification of excessive error width x 8 times valid																																																																																															
E																																																																																																		
F		(Used with SPJ)																																																																																																
3378 (PR)	SP178	VGSP	Spindle synchronous speed loop gain proportional term	Set the speed loop proportional gain in spindle synchronous mode.	0 to 2000 (1/s)	63																																																																																												
3379 (PR)	SP179	VGSI	Spindle synchronous speed loop gain integral term	Set the speed loop integral gain in spindle synchronous mode.	0 to 2000 (0.1 1/s)	60																																																																																												
3380 (PR)	SP180	VGSD	Spindle synchronous speed loop gain delay advance term	Set the speed loop delay advance gain in spindle synchronous mode. When this parameter is set to "0", PI control is applied.	0 to 1000 (0.1 1/s)	15																																																																																												
3381 (PR)	SP181	VCGS	Spindle synchronous Target value of variable speed loop proportional gain	Set the magnification of speed loop proportional gain with respect to SP178 (VGSP) at the maximum speed defined in SP017 (TSP) in spindle synchronous mode.	0 to 100 (%)	100																																																																																												


8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3382 (PR)	SP182	VCSS	Spindle synchronous Change starting speed of variable speed loop proportional gain	Set the speed when the speed loop proportional gain change starts in the spindle synchronous mode. 	0 to 32767 (r/min)	0
3383	SP183	SYNV	Spindle synchronous Sync matching speed	For changeover from the speed loop to the position loop in the spindle synchronous mode, set a speed command error range for output of the synchronous speed matching signal.	0 to 1000 (r/min)	20
3384 (PR)	SP184	FFCS	Spindle synchronous Acceleration rate feed forward gain	Set the acceleration rate feed forward gain in the spindle synchronous mode. This parameter is used only with the SPJ2.	0 to 1000 (%)	0
3385	SP185	SINP	Spindle synchronous In-position width	Set the position error range for output of the in-position signal in the spindle synchronous mode.	1 to 2880 (1/16°)	16
3386 (PR)	SP186	SODR	Spindle synchronous Excessive error width	Set the excessive error width in the spindle synchronous mode.	1 to 32767 (pulse) (1 pulse = 0.088°)	32767
3387 (PR)	SP187	IQGS	Spindle synchronous Current loop gain magnification1	Set the magnification of current loop gain (torque component) in the spindle synchronous mode.	1 to 1000 (%)	100
3388 (PR)	SP188	IDGS	Spindle synchronous Current loop gain magnification 2	Set the magnification of current loop gain (excitation component) in the spindle synchronous mode.	1 to 1000 (%)	100
3389	SP189	PG2S	Spindle synchronous Position loop gain 2	Set the second position loop gain when high-gain control is carried out in the spindle synchronous mode. When this parameter function is not used, set to "0".	0 to 999 (1/s)	0

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting																																																																																																					
3390	SP190	PG3S	Spindle synchronous Position loop gain 3	Set the third position loop gain when high-gain control is carried out in the spindle synchronous mode. When this parameter function is not used, set to "0".	0 to 999 (1/s)	0																																																																																																				
3391	SP191			Use not possible.	0	0																																																																																																				
3392	SP192			Not used. Set to "0".																																																																																																						
3393 (PR)	SP193	SPECT	Synchronized tapping specifications	Set the synchronized tapping specifications in bit units. <table border="1" style="margin-left: 20px;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td>zrtn</td><td>ptyp</td><td>od8x</td><td></td><td></td><td></td><td></td><td>phos</td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td></td><td></td><td>fdir</td><td>cdir</td><td>pyfx</td><td>rtrn</td><td></td><td>fclx</td> </tr> </table> <table border="1" style="margin-left: 20px;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>fclx</td> <td>Closed loop</td> <td>Semi-closed loop (Gear 1 : 1 only)</td> </tr> <tr> <td>1</td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>rtrn</td> <td>Position monitor during ready OFF invalid</td> <td>Position monitor during ready OFF valid</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td>cdir</td> <td>Command polarity (+)</td> <td>Command polarity (-)</td> </tr> <tr> <td>5</td> <td>fdir</td> <td>Position detector polarity (+)</td> <td>Position detector polarity (-)</td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> <td></td> </tr> <tr> <td>8</td> <td>phos</td> <td>Normal (no compensation)</td> <td>Synchronized tapping position command compensation (for synchronization with high-gain servo)</td> </tr> <tr> <td>9</td> <td></td> <td></td> <td></td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> <td></td> </tr> <tr> <td>D</td> <td>od8x</td> <td>Magnification of excessive error width x 8 times invalid</td> <td>Magnification of excessive error width x 8 times valid</td> </tr> <tr> <td>E</td> <td>ptyp</td> <td>Position control switch type: After zero point return</td> <td>Position control switch type: After deceleration stop</td> </tr> <tr> <td>F</td> <td>zrtn</td> <td>Zero point return direction: CCW</td> <td>Zero point return direction: CW</td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8	zrtn	ptyp	od8x					phos	7	6	5	4	3	2	1	0			fdir	cdir	pyfx	rtrn		fclx	bit	Name	Meaning when set to 0	Meaning when set to 1	0	fclx	Closed loop	Semi-closed loop (Gear 1 : 1 only)	1				2	rtrn	Position monitor during ready OFF invalid	Position monitor during ready OFF valid	3				4	cdir	Command polarity (+)	Command polarity (-)	5	fdir	Position detector polarity (+)	Position detector polarity (-)	6				7				8	phos	Normal (no compensation)	Synchronized tapping position command compensation (for synchronization with high-gain servo)	9				A				B				C				D	od8x	Magnification of excessive error width x 8 times invalid	Magnification of excessive error width x 8 times valid	E	ptyp	Position control switch type: After zero point return	Position control switch type: After deceleration stop	F	zrtn	Zero point return direction: CCW	Zero point return direction: CW	0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																			
zrtn	ptyp	od8x					phos																																																																																																			
7	6	5	4	3	2	1	0																																																																																																			
		fdir	cdir	pyfx	rtrn		fclx																																																																																																			
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																							
0	fclx	Closed loop	Semi-closed loop (Gear 1 : 1 only)																																																																																																							
1																																																																																																										
2	rtrn	Position monitor during ready OFF invalid	Position monitor during ready OFF valid																																																																																																							
3																																																																																																										
4	cdir	Command polarity (+)	Command polarity (-)																																																																																																							
5	fdir	Position detector polarity (+)	Position detector polarity (-)																																																																																																							
6																																																																																																										
7																																																																																																										
8	phos	Normal (no compensation)	Synchronized tapping position command compensation (for synchronization with high-gain servo)																																																																																																							
9																																																																																																										
A																																																																																																										
B																																																																																																										
C																																																																																																										
D	od8x	Magnification of excessive error width x 8 times invalid	Magnification of excessive error width x 8 times valid																																																																																																							
E	ptyp	Position control switch type: After zero point return	Position control switch type: After deceleration stop																																																																																																							
F	zrtn	Zero point return direction: CCW	Zero point return direction: CW																																																																																																							


8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3394 (PR)	SP194	VGTP	Synchronized tapping speed loop gain proportional term	Set the speed loop proportional gain in synchronized tapping mode.	0 to 2000 (1/s)	63
3395 (PR)	SP195	VGTI	Synchronized tapping speed loop gain integral term	Set the speed loop integral gain in synchronized tapping mode.	0 to 2000 (0.1 1/s)	60
3396 (PR)	SP196	VGTD	Synchronized tapping speed loop gain delay advance term	Set the speed loop delay advance gain in synchronized tapping mode. When this parameter is set to "0", PI control is applied.	0 to 1000 (0.1 1/s)	15
3397	SP197			Use not possible.	0	0
3398 (PR)	SP198	VCGT	Synchronized tapping target value of variable speed loop proportional gain	Set the magnification of speed loop proportional gain with respect to SP194 (VGTP) at the maximum motor speed defined in SP017 (TSP) in synchronized tapping mode.	0 to 100 (%)	100
3399 (PR)	SP199	VCST	Synchronized tapping change starting speed of variable speed loop proportional gain	Set the speed where the speed loop proportional gain change starts during synchronized tapping. 	0 to 32767 (r/min)	0

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3400 (PR)	SP200	FFC1	Synchronized tapping acceleration feed forward gain (gear 1)	Set the acceleration feed forward gain for selection of gear 000 during synchronized tapping. This parameter should be used when an error of relative position to Z-axis servo is large.	0 to 1000 (%)	0
3401 (PR)	SP201	FFC2	Synchronized tapping acceleration feed forward gain (gear 2)	Set the acceleration feed forward gain for selection of gear 001 during synchronized tapping.	0 to 1000 (%)	0
3402 (PR)	SP202	FFC3	Synchronized tapping acceleration feed forward gain (gear 3)	Set the acceleration feed forward gain for selection of gear 010 during synchronized tapping.	0 to 1000 (%)	0
3403 (PR)	SP203	FFC4	Synchronized tapping acceleration feed forward gain (gear 4)	Set the acceleration feed forward gain for selection of gear 011 during synchronized tapping.	0 to 1000 (%)	0
3404	SP204		Fixed control constant	This is used by Mitsubishi. Set to "0" unless particularly designated.	0	0
3405	SP205					
3406	SP206	GCK	Reverse run detection error detection width	When the motor moves (including movement with external force), the motor overrun alarm (3E) will be detected even if the speed command is 0 (including position control stop command) during servo ON (gate ON). Set the movement amount to be detected as an alarm. 0: Detect with 10° motor movement amount (Recommended setting) 1: Detect with 20° motor movement amount 2: Detect with 40° motor movement amount	0/1/2	0

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting
3407	SP207	GDL Sequential mode startup timing	<p>To carry out spindle synchronization or C-axis control in the both-chuck state with no movement immediately after the power is turned ON, set this parameter so that the reverse run detection function will function correctly. Set so that servo ON timing for the opposing spindle has the combination of (1) and (2) shown in the drawing below.</p> <p>0: Servo turns ON simultaneously with servo ON command, and servo ON status is returned immediately.</p> <p>1: Gate turns ON at pattern (1) shown below, and servo ON status is returned two seconds later.</p> <p>2: Gate turns ON at pattern (2) shown below, and servo ON status is returned two seconds later.</p> 	0/1/2	0
3408	SP208	W2	This is used by Mitsubishi. Set to "0" unless particularly designated.	0	0
3409 to 3413	SP209 to SP213		Not used. Set to "0".	0	0
3414	SP214	TZRN Synchronized tapping zero point return speed	This parameter is valid when SP193 (SPECT) bitE is set to "0". Set the zero point return speed used when the speed loop changes to the position loop.		
3415	SP215	TPDT Synchronized tapping zero point return deceleration rate	This parameter is valid when SP193 (SPECT) bitE is set to "0". Set the deceleration rate where the machine starts to decelerate when it returns to the target stop point during synchronized tapping zero point return. When the machine tends to overshoot at the stop point set a smaller value.	0 to 10000 (pulse)	1
3416	SP216	TPST Synchronized tapping zero point return shift amount	This parameter is valid when SP193 (SPECT) bitE is set to "0". Set the synchronized tapping zero point position.	0 to 4095	0

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3417	SP217	TINP	Synchronized tapping in-position width	Set the position error range for output of the in-position during synchronized tapping.	1 to 2880 (1/16°)	16
3418 (PR)	SP218	TODR	Synchronized tapping excessive error width	Set the excessive error width during synchronized tapping.	1 to 32767 (pulse) (1 pulse =0.088°)	32767
3419 (PR)	SP219	IQGT	Synchronized tapping current loop gain magnification 1	Set the magnification of current loop gain (torque component) during synchronized tapping.	1 to 1000 (%)	100
3420 (PR)	SP220	IDGT	Synchronized tapping current loop gain magnification 2	Set the magnification of current loop gain (excitation component) during synchronized tapping.	1 to 1000 (%)	100
3421	SP221	PG2T	Synchronized tapping position loop gain 2	Set the second position loop gain when high-gain control is applied during synchronized tapping. When this parameter is not used, set to "0".	0 to 999 (1/s)	0
3422	SP222	PG3T	Synchronized tapping position loop gain 3	Set the third position loop gain when high-gain control is applied during synchronized tapping. When this parameter is not used, set to "0".	0 to 999 (1/s)	0
3423	SP223	SPDV	Speed monitor speed	Set the spindle limit speed in the door open state. (Invalid when 0 is set.) If the spindle end speed exceeds this setting value when the door is open, the speed monitor error (5E) will occur.	0 to 800 (r/min)	0
3424	SP224	SPDF	Speed monitor time	Set the time (continuous) to detect alarms. (Detected instantly when 0 is set.)	0 to 2813 (3.5ms)	0

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3425	SP225	O XKPH	Position loop gain magnification after orientation gain changeover (H coil)	If gain changeover is valid (SP097: SPEC0-bitC=1) during orientation, set the magnification of each gain changed to after in-position.	0 to 2560 (1/256-fold)	0
3426	SP226	O XKPL	Position loop gain magnification after orientation gain changeover (L coil)		0 to 2560 (1/256-fold)	0
3427	SP227	O XVKP	Speed loop proportional gain magnification after orientation gain changeover		0 to 2560 (1/256-fold)	0
3428	SP228	O XVKI	Speed loop cumulative gain magnification after orientation gain changeover	If gain changeover is valid (SP097: SPEC0-bitC=1) during orientation, set the magnification of each gain changed to after in-position.	0 to 2560 (1/256-fold)	0
3429	SP229	O XSFT	Orientation virtual target shift amount	Set the amount to shift the target position when orientation virtual target position is valid (SP097: SPEC0-bitD=1).	0 to 2048 (360°/4096)	0
3430 to 3432	SP230 to SP232			Use not possible.		
3433 (PR)	SP233	JL	Disturbance observer general inertia scale	Set the ratio of the motor inertia + load inertia and motor inertia. Setting value = $\frac{\text{Motor inertia} + \text{load inertia}}{\text{Motor inertia}} \times 100$ (Normally, set "100" or more. When less than "50" is set, the setting will be invalid.) To calculate speed loop gain with general inertia scale: The effective proportional gain and effective cumulative gain during the speed control are changed at the set scale.	0 to 5000 (%)	0
3434 (PR)	SP234	OBS1	Disturbance observer low path filter frequency	Set the frequency of the low path filter for when the disturbance observer is valid. Setting (1/s) = $2\pi f$ f: Approx. 1.5 times the disturbance frequency	0 to 1000 (1/s)	0

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3435 (PR)	SP235	OBS2	Disturbance observer gain	Set the gain for the disturbance observer.	0 to 500 (%)	0
3436	SP236	OBS3	Fixed control constant	This is used by Mitsubishi. Set to "0" unless particularly designated.	0	0
3437	SP237	KSCP	Fixed control constant	This is used by Mitsubishi. Set to "0" unless particularly designated.	0	0
3438	SP238	SEZR				
3439	SP239	SEZT				
3440	SP240			Use not possible.	0	0
3441	SP241			Use not possible.	0	0
3442	SP242	Vavx		This is used by Mitsubishi. Set to "0" unless particularly designated.	0	0
3443	SP243	UTTM			0	0
3444	SP244	OPLP		Use not possible.	0	0
3445	SP245	PGHS		This is used by Mitsubishi. Set to "0" unless particularly designated.	0	0
3446	SP246	TEST			0	0
3447 to 3448	SP247 to SP248			Use not possible.	0	0
3449	SP249	SM0	Speed meter speed	Set the motor rotation speed when the speed meter 10V is output. When set to "0", this parameter becomes the same as SP017 (TSP).	0 to 32767 (r/min)	0
3450	SP250	LM0	Load meter voltage	Set the voltage when the load meter 120% is output. When set to "0", this becomes 10V.	0 to 10 (V)	0
3451 to 3452	SP251 to SP252			Use not possible.	0	0

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3453	SP253	DA1NO	D/A output channel 1 data number	Set the output data number for channel 1 of the D/A output function. When set to "0", the output is speedometer. Refer to "9.4 (1) For D/A output functions".	-32768 to 32767	0
3454	SP254	DA2NO	D/A output channel 2 data number	Set the output data number for channel 2 of the D/A output function. When set to "0", the output is load meter. Refer to "9.4 (1) For D/A output functions".	-32768 to 32767	0
3455	SP255	DA1MPY	DA output channel 1 magnification	Set the data magnification for channel 1 of the D/A output function. The output magnification is the setting value divided by 256. When set to "0", the output magnification becomes 1-fold, in the same manner as when "256" is set. Refer to "9.4 (1) For D/A output functions".	-32768 to 32767 (1/256-fold)	0
3456	SP256	DA2MPY	DA output channel 2 magnification	Set the data magnification for channel 2 of the D/A output function. The output magnification is the setting value divided by 256. When set to "0", the output magnification becomes 1-fold, in the same manner as when "256" is set. Refer to "9.4 (1) For D/A output functions".	-32768 to 32767 (1/256-fold)	0
3457 (PR) to 3520 (PR)	SP257 to SP320	RPM BSD	Motor constant (H coil)	This parameter is valid only in the following two conditional cases: (a) In case that SP034 (SFNC2) bit0=1 and SP034 (SFNC2) bit2=0 Set the motor constants when using a special motor, not described in the SP040 (MTYP) explanation and when not using the coil changeover motor. (b) In case that SP034 (SFNC2) bit0=1 and SP034 (SFNC2) bit2=1 Set the motor constant of the H coil of the coil changeover motor. (Note) It is not allowed for the user to change the setting.	0000 to FFFF HEX setting	0000
3521 (PR) to 3584 (PR)	SP321 to SP384	RPML BSDL	Motor constant (L coil)	This parameter is valid only in the following conditional case: (a) In case that SP034 (SFNC2) bit0=1 and SP034 (SFNC2) bit2=1 Set the motor constant of the L coil of the coil changeover motor. (Note) It is not allowed for the user to change the setting.	0000 to FFFF HEX setting	0000


8. Spindle Parameters 8.5 Supplement

8.5 Supplement

8.5.1 D/A Output Specifications

(1) D/A output specifications

Item	Explanation
No. of channels	2ch
Output cycle	444 μ s (min. value)
Output precision	8bit
Output voltage range	0V to +5V (zero) to +10V, 0V to +10V during meter output
Output scale setting	1/256 to \pm 128 tiems
Output pins	CN9 connector MO1 = 9 pin MO2 = 19 pin GND = 11 pin
Function	Phase current feedback output function U-phase current FB : 7 pin



8. Spindle Parameters 8.5 Supplement

(2) Setting the output data

Input the No. of the data to be output to each D/A output channel.

#	No.	Abbrev	Parameter name
3453	SP253	DA1NO	D/A output channel 1 data No.
3454	SP254	DA2NO	D/A output channel 2 data No.

No.	Output data	Original data unit	Standard setting value for output scale (Setting values in SP255, SP256)	Standard output unit	Output cycle
0	ch1: Speed meter output	10V=max. speed (0=0V)	0	Depends on the max. speed	3.55ms
	ch2: Load meter output	10V=120% load (0=0V)	0	Rated 12%/V	3.55ms
1	–				
2	Current command	Rated 100% = 4096	8	Rated 20%/V	3.55ms
3	Current feedback	Rated 100% = 4096	8	Rated 20%/V	3.55ms
4	Speed feedback	r/min	13	500rpm/V	3.55ms
5	–				
6	Position droop	1° = (64000/65536)	671	10°/V	888μs
7	–				
8	Feedrate (FΔT)	1° = (64000/65536)	629 (When communicating by 3.5ms)	500rpm/V	888μs
9	–				
10	Position command	1° = (64000/65536)	19 (18.64)	360°/V	888μs
11	–				
12	Position feedback	1° = (64000/65536)	19 (18.64)	360°/V	888μs
13	–				
80	Control input 1	HEX	Bit correspondence		3.55ms
81	Control input 2				
82	Control input 3				
83	Control input 4				
84	Control output 1	HEX	Bit correspondence		3.55ms
85	Control output 2				
86	Control output 3				
87	Control output 4				
125	Saw-tooth wave test output		0 (256)	Cycle 227.5ms	444μs
126	Rectangular wave test output		0 (256)	Cycle 1.7ms	444μs
127	2.5V(data0) test output		0 (256)	–	444μs

8. Spindle Parameters 8.5 Supplement

(3) Setting the output scale

#	No.	Abbrev	Parameter name
3455	SP255	DA1MPY	D/A output channel 1 magnification
3456	SP256	DA2MPY	D/A output channel 2 magnification

Usually, the standard setting value is set for the output scale (SV063, SV 064). When "0" is set, the output will be made as well as when "256" is set.

$$\text{DATA} \times \frac{\text{SP255}}{256} \times \frac{10 \text{ [V]}}{256 \text{ (8bit)}} + 5 \text{ [V] (offset)} = \text{Output voltage [V]}$$

(Example) When outputting the position droop with 10°/V.

$$\frac{64000}{65536} \times \frac{671}{256} \times \frac{10}{256} + 5 = 5.999 \text{ [V]}$$

9. Machine Error Compensation


9.1 Function Outline

Machine error compensation includes two independent functions: memorized pitch error compensation and memorized relative position compensation.

(1) Memorized pitch error compensation

According to the specified parameters, this method compensates an axis feed error caused by a ball screw pitch error, etc.

With the reference point defined as the base, as shown in the following figure, set the compensation amount in the division points obtained by equally dividing the machine coordinates. The compensation amount can be set by either the absolute or incremental system. Select the desired method with the "#4000 Pinc". Machine position is compensated between division points n and $n+1$ as much as compensation amount between them by linear approximation.



Relationship between the compensation amount and machine position

9. Machine Error Compensation

9.1 Function Outline


(2) Memorized relative position compensation

This method, according to the parameters specified in advance, compensates the relative position error between two orthogonal axes caused by deflection of the moving stand.

For this, as shown in the following figure, specify the compensation amount in the compensation axis direction in the division points obtained by equally dividing the machine coordinates of the base axis.

The base axis is one of the two orthogonal axes to which relative position compensation applies. This axis is used as the criterion for relative-error measurement. The compensation axis is the coordinate axis that is orthogonal to the base axis. The compensation is actually made for this coordinate axis.

The section between division points n and $n+1$ is compensated smoothly by linear approximation.



Relationship between the compensation amount and machine position

9. Machine Error Compensation

9.1 Function Outline

#	Item	Details	Setting range
4000 (PR)	Pinc	Machine error offset increment method	Specify whether the incremental volume method or absolute volume method is to be used to set machine error offset data. 0: Absolute volume method 1: Incremental volume method

<1st axis>

#	Item	Details	Setting range	
4001	cmpax	Basic axis	Specify the basic axis address for machine error compensation. 1) For pitch error compensation, set the name of the axis to be compensated. 2) For relative position compensation, set the name of the axis to be the base axis.	X, Y, Z, U, V, W, A, B, or C axis address
4002	drcax	Compensation axis	Set the compensation axis address for machine error compensation. 1) For pitch error compensation, set the same axis name as "#4001 cmpax". 2) For relative position compensation, set the name of the axis to be actually compensated.	X, Y, Z, U, V, W, A, B, or C axis address
4003	rdvno	Division point number at reference point position	Set the compensation data No. corresponding to the reference point position. The reference point is actually the base, so there is no compensation No. Set the number that is decremented by 1.	4101 to 5124
4004	mdvno	Division point number at the most negative side	Set the compensation data No. that is on the farthest negative side.	4101 to 5124
4005	pdvno	Division point number at the most positive side	Set the compensation data No. that is on the farthest positive side.	4101 to 5124
4006	sc	Compensation scale factor	Set the compensation amount's scale. When the compensation scale is set to "1", the compensation amount unit will be the same as the output unit. Compensation amount unit = unit of output × compensation scale	0 to 99
4007	spcdv	Division interval	Set the interval to divide the basic axis. Each compensation data will be the compensation amount for each of these intervals.	1 to 9999999(μm)

2nd axis	3rd axis	4th axis	5th axis	6th axis	7th axis	8th axis	9th axis	10th axis	
4011	4021	4031	4041	4051	4061	4071	4081	4091	Set the parameters corresponding to the 1st axis' parameters 4001 to 4007 for each axis. A maximum of 6 axes can be controlled, but as the relative position is compensated, settings for 10 axes can be made.
4012	4022	4032	4042	4052	4062	4072	4082	4092	
4013	4023	4033	4043	4053	4063	4073	4083	4093	
4014	4024	4034	4044	4054	4064	4074	4084	4094	
4015	4025	4035	4045	4055	4065	4075	4085	4095	
4016	4026	4036	4046	4056	4066	4076	4086	4096	
4017	4027	4037	4047	4057	4067	4077	4087	4097	

9. Machine Error Compensation
9.1 Function Outline

#	Item	Details	Setting range
4101 • • • 5124		Set the compensation amount for each axis.	-128 to 127 The actual compensation amount will be the value obtained by multiplying the setting value with the compensation scale.

9. Machine Error Compensation

9.2 Setting Compensation Data

9.2 Setting Compensation Data

Compensation data can be set according to either absolute or incremental system.

"#4000:Pinc" 0: Absolute system
 1: Incremental system

(1) Absolute system

Feed from the reference point to each division point is executed as shown in the following figure. The following is obtained at this time. Set it as the compensation amount.


$(\text{Specified position} - \text{Real machine position}) \times 2$ (Unit of output)

For example, assume that the feed from the reference point to the +100mm position is executed. Also, assume that the real machine position is 99.990mm. In this case, the following value is defined as the compensation amount used at the +100mm position:

$(100000 - 99990) \times 2 = 20$ pulses

The resultant value is defined as the compensation amount. Assume that the real machine position resulting when feed to the -100mm position is executed, is -99.990mm. In this case, the following value is defined as the compensation amount used at the -100mm position:

$(-100000 - (-99990)) \times 2 = -20$ pulses



9. Machine Error Compensation

9.2 Setting Compensation Data


(2) Incremental system

The following figure (left) contains a machine position that is placed in the positive direction with respect to the reference point. Assume that feed from division $n-1$ to n (division interval) is executed. In this case, the following value is defined as the compensation amount:

$$(\text{Division interval} - \text{Actual movement distance}) \times 2 (\text{Unit of output})$$

The following figure (right) contains a machine position that is placed in the negative direction with respect to the reference point. Assume that feed from division point $n+1$ to n by the division interval is executed. In this case, the following value is defined as the compensation amount:

$$(\text{Division interval} + \text{Actual movement distance}) \times 2 (\text{Unit of output})$$



Unit : Unit of output
 Range : -128 to 127


(Note) The unit of output is used as the unit of setting. The actual unit of compensation pulses depends on the compensation scale factor.

9. Machine Error Compensation

9.3 Example in Using a Linear Axis as the Base Axis

9.3 Example in Using a Linear Axis as the Base Axis

(1) When "mdvno" or "pdvno" exists at both ends of "rdvno":




Division point number		#4101	#4102	#4103	#4104	#4105	#4106
Specified machine position		-300.000	-200.000	-100.000	100.000	200.000	300.000
Real machine position		-299.999	-200.000	-100.003	100.002	200.002	299.999
Compensation amount	Incremental	2	6	-6	-4	0	6
	Absolute	-2	0	6	-4	-4	2

rdvno	4103
mdvno	4101
pdvno	4106
sc	1
spcdv	100000

If the setting range (mdvno to "pdvno") is exceeded, the compensation will be based on compensation amount at mdvno or "pdvno".

(2) When the range compensated is only the positive range:



Division point number		#4113	#4114	#4115	#4116	#4117
Compensation amount	Incremental	-4	2	0	6	2
	Absolute	-4	-2	-2	4	6


rdvno	4112
mdvno	4113
pdvno	4117

If the machine position exceeds "pdvno", the compensation will be based on the compensation amount at "pdvno". If the machine position is negative in this case, no compensation will be executed.

9. Machine Error Compensation

9.3 Example in Using a Linear Axis as the Base Axis

(3) When the range compensated is only the negative range:




Division point number		#4125	#4126	#4127	#4128	#4129	#4130
Compensation amount	Incremental	-2	2	6	2	0	-6
	Absolute	-2	-4	-2	4	6	6

rdvno	4130
mdvno	4125
pdvno	4130

If the machine position exceeds "mdvno", the compensation will be based on compensation amount at "mdvno".

(4) When compensation is executed in a range that contains no reference point:




Division point number		#4135	#4136	#4137	#4138	#4139	#4140
Compensation amount	Incremental			-2	-2	6	2
	Absolute			-2	-4	2	4

rdvno	4134
mdvno	4136
pdvno	4140

In this case, the compensation is executed in the range from "mdvno" to "pdvno". This setting rule applies also when the compensation is executed in a range which contains negative machine positions and no reference point.

9. Machine Error Compensation
9.4 Example in Using a Rotation Axis as the Base Axis

9.4 Example in Using a Rotation Axis as the Base Axis



Division point number		#4123	#4124	#4125	#4126	#4127	#4128
Compensation amount	Incremental	-4	2	0	6	2	-6
	Absolute	-4	-2	-2	4	6	0

rdvno	4122
mdvno	4123
pdvno	4128

In this case, the sum of the compensation amounts set according to the incremental system is always 0. For the absolute system, the compensation amount at the terminal point (360 degrees) is always 0.

10. PLC Constants
10.1 PLC Timer

10. PLC Constants

10.1 PLC Timer

(SETUP PARAM 6. 1/6) to (SETUP PARAM 6. 2/6)

#	PLC device	Item	Details	Setting range
6000 6015	T000 T015	10ms adding timer <10ms>	Set the time for the timer used in the PLC program (ladder). (Note) This setting value is valid when parameter "#6449 bit0" in the following "[BIT SELECT]" is set to "0".	0 to 32767 (×10ms)
6016 6095	T016 T095	100ms adding timer <10ms>	Set the time for the timer used in the PLC program (ladder). (Note) This setting value is valid when parameter "#6449 bit0" in the following "[BIT SELECT]" is set to "0".	0 to 32767 (×100ms)
6096 6103	T096 T103	100ms cumulative timer <100ms INC>	Set the time for the timer used in the PLC program (ladder). (Note) This setting value is valid when parameter "#6449 bit0" in the following "[BIT SELECT]" is set to "0".	0 to 32767 (×100ms)

10.2 PLC Counter

(SETUP PARAM 6. 3/6)

#	PLC device	Item	Details	Setting range
6200 6223	C000 C023	Counter	Set the time for the counter used in the PLC program (ladder). (Note) This setting value is valid when parameter "#6449 bit1" in the following "[BIT SELECT]" is set to "0".	0 to 32767

10. PLC Constants
10.3 PLC Constants

10.3 PLC Constants

(SETUP PARAM 6. 4/6)

#	PLC device	Item	Details	Setting range
6301 6348	R4500,4501 R4594,4595	PLC constant	Set the value to be set in the data type R register used in the PLC program (ladder). Even if the data is set in the R register that corresponds to the PLC side when this parameter is displayed, the screen will not change. Enter a different screen once, and then select this screen again. Note that some parameters have limited uses.	-99999999 to 99999999
6325	—	Check timer of input signal for safety	Reserved for the system. Used for only C64T.	0 to 32767(X100ms) Standard: 2 Set "0" for C6/C64.
6326	—	Check timer of output signal for safety		

10. PLC Constants
10.4 PLC Bit Selection

10.4 PLC Bit Selection

(SETUP PARAM 6. 5/6) to (SETUP PARAM 6. 6/6)

#	PLC device	Item	Details	Setting range
6401 6402 6495 6496	R4600-Low R4600-High R4647-Low R4647-High	Bit selection	This is the bit type parameter used in the PLC program (ladder). Even if the data is set in the R register that corresponds to the PLC side when this parameter is displayed, the screen will not change. Enter a different screen once, and then select this screen again. Note that some parameters have limited uses.	0: OFF 1: ON
6413	—	bit0 Dual monitoring interruption	Reserved for the system. Used for only C64T.	0/1 Standard: 0
6449	—	bit6 Communication terminal overheat detected	Designate whether to detect the communication terminal overheat alarm or not. 0: Detects the overheat alarm. 1: Does not detect the overheat alarm.	0: Detect 1: Not detect
		bit7 Control unit overheat detected	Designate whether to detect the control unit overheat alarm or not. 0: Detects the overheat alarm. 1: Does not detect the overheat alarm.	0: Detect 1: Not detect
6454	—	bit0 Macro interface for respective part systems	Designate whether to use the macro interface for respective part systems or not. 0: Conventional macro interface common to part systems. 1: Available to respective part systems.	0/1
6457	—	bit0,1 High-speed input specification	bit0: High-speed input from R54. bit1: High-speed input from R55. Note that this is used for only C64T.	bit0: 0/1 bit1: 0/1
6458	—	bit0,1 High-speed output specification	bit0: High-speed output to R56 bit1: High-speed output to R57 Note that this is used for only C64T.	bit0: 0/1 bit1: 0/1

 **CAUTION**

- ❗ When setting the parameter (#6449/bit6,7) not to check the overheat, the control unit and the communication terminal may not be controlled because of overheat. In such case, axis runaway may cause a machine breakage, an accident resulting in injury or death, or device breakage. To prevent the serious results, ordinarily set the parameters so that the overheat check is valid.

10. PLC Constants

10.4 PLC Bit Selection

Table: "Contents of bit selection parameters #6449 to #6496"

	Symbol name	7	6	5	4	3	2	1	0	
0	#6449 R2924 L	NC card Controller thermal alarm disable	Setting display unit thermal alarm disable	-		Counter C retention	Integrating timer T retention	PLC counter program on	PLC timer program on	
1	#6450 R2924 H			Alarm/operator change	Full screen display of message	-	Operator message on	1 R system	0 F system	Alarm message on
2	#6451 R2925 L	-	-	-	-		-	-	1 F0 screen	0 APLC release
3	#6452 R2925 H	-		-		Counter (fixed) retention	Integrating timer (fixed) retention			-
4	#6453 R2926 L	-	-	-	-	-		Message language change code		
5	#6454 R2926 H								Macro I/F for respective part system	
6	#6455 R2927 L	-	-	-	-	-	-	-	-	
7	#6456 R2927 H	-	-	-	-	-	-	-	-	
8	#6457 R2928 L	High-speed input specification 1 (Note4)								
9	#6458 R2928 H	High-speed input specification 2								
A	#6459 R2929 L	High-speed input specification 3 (Spare)								
B	#6460 R2929 H	High-speed input specification 4 (Spare)								
C	#6461 R2930 L	High-speed output specification 1 (Note4)								
D	#6462 R2930 H	High-speed output specification 2								
E	#6463 R2931 L	High-speed output specification 3 (Spare)								
F	#6464 R2931 H	High-speed output specification 4 (Spare)								

(Note 1) Be sure to set the bits indicated - and blanks to 0.

(Note 2) Parameters #6481 to #6496 are reserved for debugging by Mitsubishi.

(Note 3) High-speed input specification is valid for only the devices allocated to remote I/O. As for the devices allocated to the input signals from network such as HR863 Q-bus bridge or H865 CC-Link, high-speed input specification is not applied to.

(Note 4) When using C64T system, these parameters are used as follows;

#6457	bit0	High-speed input specification from R54.
	bit1	High-speed input specification from R55.
#6458	bit0	High-speed output specification to R56.
	bit1	High-speed output specification to R57.

10. PLC Constants

10.4 PLC Bit Selection

	Symbol name	7	6	5	4	3	2	1	0
0	#6465 R2932 L	-	-	-	-	-	-	-	-
1	#6466 R2932 H	-	-	-	-	-	-	-	-
2	#6467 R2933 L	-	-	-	-	-	-	-	-
3	#6468 R2933 H								
4	#6469 R2934 L			Standard PLC parameter				-	NC alarm output disable
5	#6470 R2934 H								
6	#6471 R2935 L	-	-	-	-	-	-	-	-
7	#6472 R2935 H	-	-	-	-	-	-	-	-
8	#6473 R2936 L	-							-
9	#6474 R2936 H								
A	#6475 R2937 L								
B	#6476 R2937 H								
C	#6477 R2938 L								
D	#6478 R2938 H								
E	#6479 R2939 L								
F	#6480 R2939 H								

(Note 1) Be sure to set the bits indicated - and blanks to 0.

(Note 2) Parameters #6481 to #6496 are reserved for debugging by Mitsubishi.

11. Macro List

11. Macro List

#	Item	Details	Setting range (unit)										
7001 to 7091	M [01] to M [10]	<Code> Set the M code used for calling out the macro with the M command. This is valid when "#1195 Mmac" is set to 1.	1 to 9999										
7002 to 7092		<Type> Set the macro call out type. <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center;">0</td> <td>M98 P△△△△; and equivalent value call</td> </tr> <tr> <td style="text-align: center;">1</td> <td>G65 P△△△△; and equivalent value call</td> </tr> <tr> <td style="text-align: center;">2</td> <td>G66 P△△△△; and equivalent value call</td> </tr> <tr> <td style="text-align: center;">3</td> <td>G66.1 P△△△△; and equivalent value call</td> </tr> <tr> <td style="text-align: center;">others</td> <td>M98 P△△△△; and equivalent value call</td> </tr> </table>	0	M98 P△△△△; and equivalent value call	1	G65 P△△△△; and equivalent value call	2	G66 P△△△△; and equivalent value call	3	G66.1 P△△△△; and equivalent value call	others	M98 P△△△△; and equivalent value call	0 to 3
0	M98 P△△△△; and equivalent value call												
1	G65 P△△△△; and equivalent value call												
2	G66 P△△△△; and equivalent value call												
3	G66.1 P△△△△; and equivalent value call												
others	M98 P△△△△; and equivalent value call												
7003 to 7093		<Program No.> Set the No. of the program to be called out.	1 to 99999999										
	M2mac	Set the type and program No. for when calling out the macro with the 2nd miscellaneous command. The macro will be called out with the "#1170 M2name" address command when "#1198 M2mac" is set to 1.											
7102		<Type> Same as the M call macro.	0 to 3										
7103		<Program No.> Same as the M call macro.	0 to 99999999										
7201 to 7291	G [01] to G [10]	<Code> Set the G code to be used when calling the macro with a G command. Do not set a G code used in the system.	1 to 255										
7202 to 7292		<Type> Same as the M call macro.	0 to 3										
7203 to 7293		<Program No.> Same as the M call macro.	1 to 99999999										
	Smac	Set the type and program No. for when calling the macro with an S command. This is valid when "#1196 Smac" is set to 1.											
7302		<Type> Same as the M call macro.	0 to 3										
7303		<Program No.> Same as the M call macro.	1 to 99999999										
	Tmac	Set the type and program No. for when calling the macro with a T command. This is valid when "#1197 Tmac" is set to 1.											
7312		<Type> Same as the M call macro.	0 to 3										
7313		<Program No.> Same as the M call macro.	0 to 99999999										
27000	Nmac	Not used.	0										
27001 to 27071	N [0] to N [08]	<Code> Not used.	0										
27002 to 27072		<Program No.> Not used.	0										

12. Position Switch
12.1 Outline of Function

12. Position Switch

12.1 Outline of Function

The position switch (PSW) is used as an imaginary dog switch by assigning an axis name and coordinate values that indicate the imaginary dog position to be used instead of the dog switch on the machine axis. When the machine reaches the imaginary dog position, a signal is output to the PLC interface. This imaginary dog switch is called the position switch (PSW).

No.	Item	Details	Setting range (unit)
7500	Pcheck High-speed switching of position switch	Specify whether to perform position switch area checking at high speeds. 0: Does not perform position switch area checking at high speed (do it the same as before). 1: Performs position switch area checking at high speed.	0/1
75*1	<axis> Axis name	Specify the name of the axis for which a position switch is provided.	X, Y, Z, U, V, W, A, B, or C axis address
75*2	<dog1> Imaginary dog position 1	When the machine enters the range between imaginary dog positions 1 and 2, a signal is output to the PLC.	-99999.999 to 99999.999 (0.001mm)
75*3	<dog2> Imaginary dog position 2	Part system 1 device X 660 Part system 2 device Y 6E0	
75*4	<check> Selection of area check method	When position switch area checking at high speed is selected, specify the mode of area checking, i.e., whether to use the command type machine position or detector feedback position, for each position switch point. 0: Use the command type machine position as the machine position for position switch area checking. 1: Use the detector feedback position as the machine position for position switch area checking. (Note) This parameter is valid only when 1 set in "#7500 Pcheck."	0/1

12. Position Switch

12.1 Outline of Function


Position switch numbers of PSW1 to PSW16 and signal devices

	<axis>	<dog1>	<dog2>	1st part system	2nd part system	3rd part system	4th part system	5th part system	6th part system	7th part system
PSW1	7501	7502	7503	X660	X6E0	X760	X7E0	X860	X8E0	X960
PSW2	7511	7512	7513	X661	X6E1	X761	X7E1	X861	X8E1	X961
PSW3	7521	7522	7523	X662	X6E2	X762	X7E2	X862	X8E2	X962
PSW4	7531	7532	7533	X663	X6E3	X763	X7E3	X863	X8E3	X963
PSW5	7541	7542	7543	X664	X6E4	X764	X7E4	X864	X8E4	X964
PSW6	7551	7552	7553	X665	X6E5	X765	X7E5	X865	X8E5	X965
PSW7	7561	7562	7563	X666	X6E6	X766	X7E6	X866	X8E6	X966
PSW8	7571	7572	7573	X667	X6E7	X767	X7E7	X867	X8E7	X967
PSW9	7581	7582	7583	X670	X6F0	X770	X7F0	X870	X8F0	X970
PSW10	7591	7592	7593	X671	X6F1	X771	X7F1	X871	X8F1	X971
PSW11	7601	7602	7603	X672	X6F2	X772	X7F2	X872	X8F2	X972
PSW12	7611	7612	7613	X673	X6F3	X773	X7F3	X873	X8F3	X973
PSW13	7621	7622	7623	X674	X6F4	X774	X7F4	X874	X8F4	X974
PSW14	7631	7632	7633	X675	X6F5	X775	X7F5	X875	X8F5	X975
PSW15	7641	7642	7643	X676	X6F6	X776	X7F6	X876	X8F6	X976
PSW16	7651	7652	7653	X677	X6F7	X777	X7F7	X877	X8F7	X977

Instead of the dog switch provided on the machine axis, the coordinate values indicating imaginary dog positions (dog1 and dog2) on the coordinate axis of the axis name preset with axis are set with the position switches (PSW1 – PSW16). When the machine reaches the position, the signal is output to the device corresponding to the PLC interface.

Example of settings of dog1 and dog2 and operation





Setting of dog1 and dog2	Operation	Description
dog1 < dog2		A signal is output between dog1 and dog2.
dog1 > dog2		A signal is output between dog1 and dog2.
dog1 = dog2		If dog1 equals dog2, the dog1 position triggers a signal.



12. Position Switch

12.2 Canceling the Position Switch

Rotary axis

Setting of dog1 and dog2	Operation	Description
dog1 < dog2	 <p style="text-align: right;">(Example) dog1 = 30.000 dog2 = 330.000</p>	A signal is output between dog1 and dog2.
	 <p style="text-align: right;">(Example) dog1 = -30.000 dog2 = 30.000</p>	A signal is also output when dog1 is negative.
dog1 > dog2	 <p style="text-align: right;">(Example) dog1 = 330.000 dog2 = 30.000</p>	A signal is output between dog2 and dog1.
$ \text{dog1} - \text{dog2} \geq 360$	 <p style="text-align: right;">(Example) dog1 = 30.000 dog2 = 390.000</p>	A signal is kept output when the difference between dog1 and dog2 exceeds 360 degrees.

12.2 Canceling the Position Switch

To cancel the position switch, enter the number (#75*1) of the position switch to be canceled in # () of the setting area, enter a slash "/" in DATA (), then press the key. This deletes the axis name for the specified position switch, thus invalidating the position switch. The data specified for <dog1> and <dog2> are still stored in memory. To validate the position switch again, therefore, it is enough to specify the axis name only.

13. Indexing Axis Parameters

13. Indexing Axis Parameters

(Note) These parameters are used only with the G64T.

#	Item	Details	Setting range (unit)	
26251	METHOD	Select the index command method. 0: Matrix command 1: Single command 2: BCD command (without parity) 3: BCD command (with parity)	0/1/2/3	
26252	AUX	bit0	Select the rotary axis' control method. 0: Non-endless method Positioning is carried out without extending over 0.000°. Thus, the rotation direction is automatically determined according to the command. 1: Endless method Positioning is carried out with the designated rotation direction or a short cut.	0 to F Set as a HEX value.
		bit1	Validates addition/subtraction with the index position command input. 0: Addition/subtraction invalid 1: Addition/subtraction valid	
		bit2	Select the valid width of external data input/output function's IN data. 0: 16 bits (IN0 to IN15) 1: 24 bits (IN0 to IN23)	
		bit3	When the "request fixed" signal is ON, the parity of the IN data equivalent to the valid width set in #26252 bit2 is checked. 0: Does not check parity 1: Checks parity	
		bit4	Select the external positioning stop mode. 0: Retraction stop mode After decelerating to a stop, the axis is retracted to the position where the signal was input (point where deceleration started). Then the index position compensation amount is calculated and set. 1: Deceleration stop mode After decelerating to a stop, the index position compensation amount is calculated and set at that point.	
26253	JOG CLAMP SPEED 1	Set JOG speed 1 or indexing speed clamp 1.	1 to 1000000 mm/min, °/min)	
26254	JOG CLAMP SPEED 2	Set JOG speed 2 or indexing speed clamp 2.		
26255	JOG CLAMP SPEED 3	Set JOG speed 3 or indexing speed clamp 3.		

13. Indexing Axis Parameters

#	Item	Details	Setting range (unit)
26256	CURRENT LIMIT	Set current limit value when current limit value command signal is ON.	0 to 100 (%)
26257	OFFSET	Set the indexing position compensation amount.	-999.999 to 999.999 (mm)
26258	OFFSET LIMIT	If the indexing position compensation amount exceeds this value, the "index position offset MAX reached" signal (M:Y18E, L:Y100) will be output.	0 to 999.999 (mm)
26259	DETECTION WIDTH	Set the tolerable width for outputting the in-position signal when indexing is completed.	0 to 999.999 (mm)
26260	CURRENT LIMIT 2	Set current limit value when current limit value command 2 signal is ON.	0 to 100 (%)
26261	CURRENT LIMIT 3	Set current limit value when current limit value command 3 signal is ON.	0 to 100 (%)

14. Indexing Axis Position Switch
14.1 Outline of Function

14. Indexing Axis Position Switch

14.1 Outline of Function

(Note) These parameters are used only with the G64T.

The position switch (PSW) is used as an imaginary dog switch by assigning an axis name and coordinate values that indicate the imaginary dog position to be used instead of the dog switch on the machine axis. When the machine reaches the imaginary dog position, a signal is output to the PLC interface. This imaginary dog switch is called the position switch (PSW).

The position switch for the indexing axis is set on this screen.

No.	Item	Details	Setting range (unit)
27701	<dog1> Imaginary dog position 1	The PLC position output signal turns ON when the machine reaches the range between the imaginary dog position 1 and imaginary dog position 2.	-99999.999 to 99999.999 (0.001mm)
27702	<dog2> Imaginary dog position 2		
:	:		
27731	<dog1> Imaginary dog position 1		
27732	<dog2> Imaginary dog position 2		

Position switch numbers of PSW1 to PSW16 and signal devices

	<dog1>	<dog2>	1st axis device	2nd axis device	3rd axis device	4th axis device
PSW1	27701	27702	R3561/bit0	R3566/bit0	R3571/bit0	R3576/bit0
PSW2	27703	27704	R3561/bit1	R3566/bit1	R3571/bit1	R3576/bit1
PSW3	27705	27706	R3561/bit2	R3566/bit2	R3571/bit2	R3576/bit2
PSW4	27707	27708	R3561/bit3	R3566/bit3	R3571/bit3	R3576/bit3
PSW5	27709	27710	R3561/bit4	R3566/bit4	R3571/bit4	R3576/bit4
PSW6	27711	27712	R3561/bit5	R3566/bit5	R3571/bit5	R3576/bit5
PSW7	27713	27714	R3561/bit6	R3566/bit6	R3571/bit6	R3576/bit6
PSW8	27715	27716	R3561/bit7	R3566/bit7	R3571/bit7	R3576/bit7
PSW9	27717	27718	R3561/bit8	R3566/bit8	R3571/bit8	R3576/bit8
PSW10	27719	27720	R3561/bit9	R3566/bit9	R3571/bit9	R3576/bit9
PSW11	27721	27722	R3561/bitA	R3566/bitA	R3571/bitA	R3576/bitA
PSW12	27723	27724	R3561/bitB	R3566/bitB	R3571/bitB	R3576/bitB
PSW13	27725	27726	R3561/bitC	R3566/bitC	R3571/bitC	R3576/bitC
PSW14	27727	27728	R3561/bitD	R3566/bitD	R3571/bitD	R3576/bitD
PSW15	27729	27730	R3561/bitE	R3566/bitE	R3571/bitE	R3576/bitE
PSW16	27731	27732	R3561/bitF	R3566/bitF	R3571/bitF	R3576/bitF

(Note) If the imaginary dog positions 1 and 2 are both set to "0", the signal will not be output to the PLC interface.

15. Indexing Axis Commands

(Note) These parameters are used only with the G64T.

Item	Details	Setting range (unit)
POSITION	Command the indexing position.	-99999.999 to 99999.999 (0.001mm/0.001°, 0.0001mm/0.0001°)
SPEED	Set the indexing speed.	0 to 999999 (mm/min, °/min)
INPOS	Set the in-position width, which indicates the output range of the in-position signal output when positioning is completed.	0 to 99999.999 (0.001mm/0.001°, 0.0001mm/0.0001°)
FLAG	0: Normal indexing position command 1: Position command valid for external positioning 2: Indexing command compensation valid	0/1/2

100 sets can be set for each axis.

When changing the axis, set the axis No. after "X" in the first setting area, such as # (X2), and then press INPUT. Axis No. "1" corresponds to the 1st peripheral axis.

(Example 1) To change to 2nd peripheral axis # (X2)

(Example 2) To change to 4th peripheral axis # (X4)

16. Auxiliary Axis Parameters

16. Auxiliary Axis Parameters

Turn the NC power OFF after setting parameters indicated with a (PR) in the table. The setting will be validated after the power is turned ON again.

No.	Name		Details	Setting range	Default value																						
1 (PR)	MSR	Motor series	Set the motor series. This is automatically judged by the system when the default value (0000) is set.	0000 to FFFF (hexadecimal)	0000																						
2 (PR)	RTY	Regeneration option type	Set the regenerative resistor type. Do not set values without a description. <div style="text-align: center;"> <table border="1" style="display: inline-table; margin-bottom: 5px;"> <tr> <td style="padding: 2px 5px;">0</td> <td style="padding: 2px 5px;">0</td> <td style="padding: 2px 5px;">0</td> <td style="padding: 2px 5px;">0</td> </tr> </table> (Default value) </div> <table border="1" style="margin-left: auto; margin-right: auto; border-collapse: collapse;"> <thead> <tr> <th style="padding: 2px 5px;">Setting value</th> <th style="padding: 2px 5px;">Details</th> </tr> </thead> <tbody> <tr> <td style="text-align: center; padding: 2px 5px;">0</td> <td style="padding: 2px 5px;">Amplifier standard built-in resistor (10CT has no built-in resistor)</td> </tr> <tr> <td style="text-align: center; padding: 2px 5px;">1</td> <td style="padding: 2px 5px;">Setting prohibited</td> </tr> <tr> <td style="text-align: center; padding: 2px 5px;">2</td> <td style="padding: 2px 5px;">MR-RB032 (30W)</td> </tr> <tr> <td style="text-align: center; padding: 2px 5px;">3</td> <td style="padding: 2px 5px;">MR-RB12 (100W)</td> </tr> <tr> <td style="text-align: center; padding: 2px 5px;">4</td> <td style="padding: 2px 5px;">MR-RB32 (300W)</td> </tr> <tr> <td style="text-align: center; padding: 2px 5px;">5</td> <td style="padding: 2px 5px;">MR-RB30 (300W)</td> </tr> <tr> <td style="text-align: center; padding: 2px 5px;">6</td> <td style="padding: 2px 5px;">MR-RB50 (500W)</td> </tr> <tr> <td style="text-align: center; padding: 2px 5px;">7~F</td> <td style="padding: 2px 5px;"></td> </tr> </tbody> </table>	0	0	0	0	Setting value	Details	0	Amplifier standard built-in resistor (10CT has no built-in resistor)	1	Setting prohibited	2	MR-RB032 (30W)	3	MR-RB12 (100W)	4	MR-RB32 (300W)	5	MR-RB30 (300W)	6	MR-RB50 (500W)	7~F			
0	0	0	0																								
Setting value	Details																										
0	Amplifier standard built-in resistor (10CT has no built-in resistor)																										
1	Setting prohibited																										
2	MR-RB032 (30W)																										
3	MR-RB12 (100W)																										
4	MR-RB32 (300W)																										
5	MR-RB30 (300W)																										
6	MR-RB50 (500W)																										
7~F																											
3 (PR)	PC1	Motor side gear ratio (machine rotation ratio)	Set the No. of gear teeth on the motor side and the No. of gear teeth on the machine side as an integer reduced to its lowest terms.	1 to 32767	1																						
4 (PR)	PC2	Machine side gear ratio (motor rotation ratio)	Set the total gear ratio if there are multiple gear levels. For rotation axes, set the No. of motor rotation speed per machine rotation.	1 to 32767	1																						
5 (PR)	PIT	Feed pitch	Set 360 (default value) for rotation axes. Set the feed lead for linear axes.	1 to 32767 (° or mm)	360																						
6	INP	In-position detection width	In-position is detected when the position droop becomes this setting value or less.	1 to 32767 (1/1000° or μm)	50																						

16. Auxiliary Axis Parameters

No.	Name	Details	Setting range	Default value																														
7	ATU	Auto-tuning	Set the adjustment of the auto-tuning. Do not set values without a description.																															
<div style="display: flex; align-items: center; justify-content: center;"> <table border="1" style="border-collapse: collapse; margin-right: 10px;"> <tr> <td style="padding: 2px 5px;">0</td> <td style="padding: 2px 5px;">1</td> <td style="padding: 2px 5px;">0</td> <td style="padding: 2px 5px;">2</td> </tr> </table> (Default setting value) </div> <div style="display: flex; align-items: center; justify-content: center;"> <table border="1" style="border-collapse: collapse; margin-right: 10px;"> <thead> <tr> <th style="text-align: center;">Setting value</th> <th style="text-align: center;">Details</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">1</td> <td>Low response (low-rigidity loads, loads which easily vibrate)</td> </tr> <tr> <td style="text-align: center;">2</td> <td>Standard setting value</td> </tr> <tr> <td style="text-align: center;">3</td> <td>Standard setting value</td> </tr> <tr> <td style="text-align: center;">4</td> <td>Standard setting value</td> </tr> <tr> <td style="text-align: center;">5</td> <td>High response (high-rigidity loads, loads which do not easily vibrate)</td> </tr> </tbody> </table> <table border="1" style="border-collapse: collapse; margin-right: 10px;"> <thead> <tr> <th style="text-align: center;">Setting value</th> <th style="text-align: center;">Details</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">0</td> <td>Standard</td> </tr> <tr> <td style="text-align: center;">2</td> <td>Large friction amount (set the position loop gain slightly lower)</td> </tr> </tbody> </table> <table border="1" style="border-collapse: collapse;"> <thead> <tr> <th style="text-align: center;">Setting value</th> <th style="text-align: center;">Details</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">0</td> <td>Only auto-tuning PG2, VG2, VIC, and GD2.</td> </tr> <tr> <td style="text-align: center;">1</td> <td>Auto-tuning PG1, PG2, VG1, VG2, VIC, and GD2 (total gain). (Standard setting)</td> </tr> <tr> <td style="text-align: center;">2</td> <td>No auto-tuning.</td> </tr> </tbody> </table> </div>					0	1	0	2	Setting value	Details	1	Low response (low-rigidity loads, loads which easily vibrate)	2	Standard setting value	3	Standard setting value	4	Standard setting value	5	High response (high-rigidity loads, loads which do not easily vibrate)	Setting value	Details	0	Standard	2	Large friction amount (set the position loop gain slightly lower)	Setting value	Details	0	Only auto-tuning PG2, VG2, VIC, and GD2.	1	Auto-tuning PG1, PG2, VG1, VG2, VIC, and GD2 (total gain). (Standard setting)	2	No auto-tuning.
0	1	0	2																															
Setting value	Details																																	
1	Low response (low-rigidity loads, loads which easily vibrate)																																	
2	Standard setting value																																	
3	Standard setting value																																	
4	Standard setting value																																	
5	High response (high-rigidity loads, loads which do not easily vibrate)																																	
Setting value	Details																																	
0	Standard																																	
2	Large friction amount (set the position loop gain slightly lower)																																	
Setting value	Details																																	
0	Only auto-tuning PG2, VG2, VIC, and GD2.																																	
1	Auto-tuning PG1, PG2, VG1, VG2, VIC, and GD2 (total gain). (Standard setting)																																	
2	No auto-tuning.																																	
8	PG1	Position loop gain 1	Set the position loop gain for the model loop. Determine the tracking ability regarding the position commands.	4 to 1000 (1/s)	70																													
9			(Not used.)		0																													
10	EMGt	Deceleration control time constant	Set the deceleration time from the clamp speed (Aspeed1). For normal rapid traverse, set the same value as the acceleration/deceleration time constant.	0 to 32768 (ms)	500																													
11			(Not used.)		0																													
12			(Not used.)		0																													
13	MBR	Vertical axis drop prevention time	Input the time the servo OFF is delayed during servo OFF command. Increase the setting by 100ms at a time and set the minimum value where the axis does not drop.	0 to 1000 (ms)	100																													

16. Auxiliary Axis Parameters

No.	Name	Details	Setting range	Default value																		
14	NCH	Notch filter No.	Set the frequency of the machine resonance suppression filter. Do not set values without a description.																			
		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center;">Setting value</td> <td style="text-align: center;">0</td> <td style="text-align: center;">1</td> <td style="text-align: center;">2</td> <td style="text-align: center;">3</td> <td style="text-align: center;">4</td> <td style="text-align: center;">5</td> <td style="text-align: center;">6</td> <td style="text-align: center;">7</td> </tr> <tr> <td style="text-align: center;">Frequency (Hz)</td> <td style="text-align: center;">No start</td> <td style="text-align: center;">1125</td> <td style="text-align: center;">563</td> <td style="text-align: center;">375</td> <td style="text-align: center;">282</td> <td style="text-align: center;">225</td> <td style="text-align: center;">188</td> <td style="text-align: center;">161</td> </tr> </table>	Setting value	0	1	2	3	4	5	6	7	Frequency (Hz)	No start	1125	563	375	282	225	188	161		
Setting value	0	1	2	3	4	5	6	7														
Frequency (Hz)	No start	1125	563	375	282	225	188	161														
15			(Not used.)	0																		
16	JIT	Jitter compensation	Set the No. of ignored jitter compensation pulses. Do not set values without a description.																			
		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center;">Setting value</td> <td style="text-align: center;">0</td> <td style="text-align: center;">1</td> <td style="text-align: center;">2</td> <td style="text-align: center;">3</td> </tr> <tr> <td style="text-align: center;">Number of ignore pulses</td> <td style="text-align: center;">No start</td> <td style="text-align: center;">1</td> <td style="text-align: center;">2</td> <td style="text-align: center;">3</td> </tr> </table>	Setting value	0	1	2	3	Number of ignore pulses	No start	1	2	3										
Setting value	0	1	2	3																		
Number of ignore pulses	No start	1	2	3																		
17			(Not used.)	0																		
18			(Not used.)	0																		
19	PG2	Position loop gain 2	Set the position loop gain of the actual loop. Determine the position responsiveness for external disturbance.	1 to 500 (1/s)	25																	
20	VG1	Speed loop gain 1	Set the speed loop gain of the model loop. Determine the tracking ability regarding the speed commands.	20 to 5000 (1/s)	1200																	
21	VG2	Speed loop gain 2	Set the speed loop gain of the actual loop. Determine the speed responsiveness for external disturbance.	20 to 8000 (1/s)	600																	
22	VIC	Speed integral compensation	Determine the characteristics of the speed low-frequency region.	1 to 1000 (ms)	20																	
23	VDC	Speed differential compensation	PI control normally results from a default value of 1000. Adjust the overshoot amount by lowering in increments of 20.	0 to 1000	1000																	
24	DG2	Load inertia ratio	Set the load inertia ratio for the motor inertia.	0.0 to 50.0 (fold)	2.0																	
25			(Not used.)	0																		
30 (PR)	MTY	Motor type	Set the motor type. This is automatically judged by the system when the default value (0000) is set.	0000 to FFFF (hexadecimal)	0000																	

16. Auxiliary Axis Parameters

No.	Name	Details	Setting range	Default value
50	MD1	D/A output channel 1 data No.	Set the Nos. of the data to be output on D/A output channel 1. <div style="border: 1px solid black; display: inline-block; padding: 2px;">0 0 0 0</div> (Default setting value)	
			Setting value	Magnification
			0	Speed feedback (with sign) Maximum rotation speed = 8V
			1	Current feedback (with sign) Maximum current (torque) = 8V
			2	Speed feedback (without sign) Maximum rotation speed = 8V
			3	Current feedback (without sign) Maximum current (torque) = 8V
			4	Current command Maximum current (torque) = 8V
			5	Command FΔT 100000 [degrees/min] = 10V
			6	Position droop 1 (1/1) 2048 [pulse] = 10V
			7	Position droop 2 (1/4) 8192 [pulse] = 10V
			8	Position droop 3 (1/16) 32768 [pulse] = 10V
			9	Position droop 4 (1/32) 65536 [pulse] = 10V
			A	Position droop 5 (1/64) 131072 [pulse] = 10V
51	MO1	D/A output channel 1 output offset	-999 to 999 (mV)	0
52		(Not used.)		0
53	MD2	D/A output channel 2 data No.	0000 to FFFF (hexadecimal)	0000
54	MO2	D/A output channel 2 output offset	-999 to 999 (mV)	0
55		(Not used.)		0
100 (PR)	station	No. of indexing stations	2 to 360	2

16. Auxiliary Axis Parameters

No.	Name	Details	Setting range	Default value																																																		
101 (PR)	Cont1 Control parameter 1	This is a HEX setting parameter. Set bits without a description to their default values.																																																				
		<table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <tr> <td style="width: 5%;">bit</td> <td style="width: 5%;">F</td> <td style="width: 5%;">E</td> <td style="width: 5%;">D</td> <td style="width: 5%;">C</td> <td style="width: 5%;">B</td> <td style="width: 5%;">A</td> <td style="width: 5%;">9</td> <td style="width: 5%;">8</td> <td style="width: 5%;">7</td> <td style="width: 5%;">6</td> <td style="width: 5%;">5</td> <td style="width: 5%;">4</td> <td style="width: 5%;">3</td> <td style="width: 5%;">2</td> <td style="width: 5%;">1</td> <td style="width: 5%;">0</td> </tr> <tr> <td>Default value</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>1</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> </tr> </table>				bit	F	E	D	C	B	A	9	8	7	6	5	4	3	2	1	0	Default value	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0															
		bit	F	E	D	C	B	A	9	8	7	6	5	4	3	2	1	0																																				
Default value	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0																																						
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 5%;">bit</th> <th style="width: 45%;">Meaning when "0" is set</th> <th style="width: 50%;">Meaning when "1" is set</th> </tr> </thead> <tbody> <tr> <td>0</td> <td></td> <td></td> </tr> <tr> <td>1</td> <td>High-speed zero point return after establishment of zero point.</td> <td>Dog-type return for each zero point return operation.</td> </tr> <tr> <td>2</td> <td></td> <td></td> </tr> <tr> <td>3</td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> </tr> <tr> <td>6</td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> </tr> <tr> <td>8</td> <td>Reference point return direction (+)</td> <td>Reference point return direction (-)</td> </tr> <tr> <td>9</td> <td>Rotation direction determined by operation control signal (DIR)</td> <td>Rotation direction in the shortcut direction</td> </tr> <tr> <td>A</td> <td>Machine basic position becomes the origin point</td> <td>Electrical zero point becomes the origin point</td> </tr> <tr> <td>B</td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> </tr> <tr> <td>D</td> <td>Coordinate zero point creation valid</td> <td>Zero point established at power supply ON position</td> </tr> <tr> <td>E</td> <td>Rotation direction in operation control signal (DIR) or in the shortcut direction</td> <td>Rotation direction in the random position command sign direction</td> </tr> <tr> <td>F</td> <td>Stopper direction is positioning direction</td> <td>Stopper direction is in the sign direction of the stopper amount</td> </tr> </tbody> </table>				bit	Meaning when "0" is set	Meaning when "1" is set	0			1	High-speed zero point return after establishment of zero point.	Dog-type return for each zero point return operation.	2			3			4			5			6			7			8	Reference point return direction (+)	Reference point return direction (-)	9	Rotation direction determined by operation control signal (DIR)	Rotation direction in the shortcut direction	A	Machine basic position becomes the origin point	Electrical zero point becomes the origin point	B			C			D	Coordinate zero point creation valid	Zero point established at power supply ON position	E	Rotation direction in operation control signal (DIR) or in the shortcut direction	Rotation direction in the random position command sign direction	F	Stopper direction is positioning direction	Stopper direction is in the sign direction of the stopper amount
bit	Meaning when "0" is set	Meaning when "1" is set																																																				
0																																																						
1	High-speed zero point return after establishment of zero point.	Dog-type return for each zero point return operation.																																																				
2																																																						
3																																																						
4																																																						
5																																																						
6																																																						
7																																																						
8	Reference point return direction (+)	Reference point return direction (-)																																																				
9	Rotation direction determined by operation control signal (DIR)	Rotation direction in the shortcut direction																																																				
A	Machine basic position becomes the origin point	Electrical zero point becomes the origin point																																																				
B																																																						
C																																																						
D	Coordinate zero point creation valid	Zero point established at power supply ON position																																																				
E	Rotation direction in operation control signal (DIR) or in the shortcut direction	Rotation direction in the random position command sign direction																																																				
F	Stopper direction is positioning direction	Stopper direction is in the sign direction of the stopper amount																																																				

16. Auxiliary Axis Parameters

No.	Name	Details	Setting range	Default value																																																		
102 (PR)	Cont2 Control parameter 2	This is a HEX setting parameter. Set bits without a description to their default values.																																																				
		<table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <tr> <th style="width: 5%;">bit</th> <th style="width: 3%;">F</th> <th style="width: 3%;">E</th> <th style="width: 3%;">D</th> <th style="width: 3%;">C</th> <th style="width: 3%;">B</th> <th style="width: 3%;">A</th> <th style="width: 3%;">9</th> <th style="width: 3%;">8</th> <th style="width: 3%;">7</th> <th style="width: 3%;">6</th> <th style="width: 3%;">5</th> <th style="width: 3%;">4</th> <th style="width: 3%;">3</th> <th style="width: 3%;">2</th> <th style="width: 3%;">1</th> <th style="width: 3%;">0</th> </tr> <tr> <td>Default value</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>1</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>1</td> <td>1</td> <td>0</td> </tr> </table>				bit	F	E	D	C	B	A	9	8	7	6	5	4	3	2	1	0	Default value	0	0	0	0	0	0	0	0	1	0	0	0	0	1	1	0															
		bit	F	E	D	C	B	A	9	8	7	6	5	4	3	2	1	0																																				
Default value	0	0	0	0	0	0	0	0	1	0	0	0	0	1	1	0																																						
<table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <thead> <tr> <th style="width: 5%;">bit</th> <th style="width: 45%;">Meaning when "0" is set</th> <th style="width: 50%;">Meaning when "1" is set</th> </tr> </thead> <tbody> <tr><td>0</td><td></td><td></td></tr> <tr><td>1</td><td>Error not corrected at servo OFF</td><td>Error corrected at servo OFF</td></tr> <tr><td>2</td><td>Linear axis</td><td>Rotation axis</td></tr> <tr><td>3</td><td>Station assignment direction CW</td><td>Station assignment direction CCW</td></tr> <tr><td>4</td><td>Uniform index</td><td>Non-uniform index</td></tr> <tr><td>5</td><td>DO channel standard assignment</td><td>DO channel reverse assignment</td></tr> <tr><td>6</td><td>2-wire detector communication</td><td>4-wire detector communication</td></tr> <tr><td>7</td><td>Incremental detection</td><td>Absolute position detection</td></tr> <tr><td>8</td><td></td><td></td></tr> <tr><td>9</td><td></td><td></td></tr> <tr><td>A</td><td></td><td></td></tr> <tr><td>B</td><td></td><td></td></tr> <tr><td>C</td><td></td><td></td></tr> <tr><td>D</td><td></td><td></td></tr> <tr><td>E</td><td></td><td></td></tr> <tr><td>F</td><td></td><td></td></tr> </tbody> </table>				bit	Meaning when "0" is set	Meaning when "1" is set	0			1	Error not corrected at servo OFF	Error corrected at servo OFF	2	Linear axis	Rotation axis	3	Station assignment direction CW	Station assignment direction CCW	4	Uniform index	Non-uniform index	5	DO channel standard assignment	DO channel reverse assignment	6	2-wire detector communication	4-wire detector communication	7	Incremental detection	Absolute position detection	8			9			A			B			C			D			E			F		
bit	Meaning when "0" is set	Meaning when "1" is set																																																				
0																																																						
1	Error not corrected at servo OFF	Error corrected at servo OFF																																																				
2	Linear axis	Rotation axis																																																				
3	Station assignment direction CW	Station assignment direction CCW																																																				
4	Uniform index	Non-uniform index																																																				
5	DO channel standard assignment	DO channel reverse assignment																																																				
6	2-wire detector communication	4-wire detector communication																																																				
7	Incremental detection	Absolute position detection																																																				
8																																																						
9																																																						
A																																																						
B																																																						
C																																																						
D																																																						
E																																																						
F																																																						
103 (PR)	EmgCont Emergency stop control	This is a HEX setting parameter. Set bits without a description to their default values.																																																				
		<table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <tr> <th style="width: 5%;">bit</th> <th style="width: 3%;">F</th> <th style="width: 3%;">E</th> <th style="width: 3%;">D</th> <th style="width: 3%;">C</th> <th style="width: 3%;">B</th> <th style="width: 3%;">A</th> <th style="width: 3%;">9</th> <th style="width: 3%;">8</th> <th style="width: 3%;">7</th> <th style="width: 3%;">6</th> <th style="width: 3%;">5</th> <th style="width: 3%;">4</th> <th style="width: 3%;">3</th> <th style="width: 3%;">2</th> <th style="width: 3%;">1</th> <th style="width: 3%;">0</th> </tr> <tr> <td>Default value</td> <td>0</td> <td>1</td> </tr> </table>				bit	F	E	D	C	B	A	9	8	7	6	5	4	3	2	1	0	Default value	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1															
		bit	F	E	D	C	B	A	9	8	7	6	5	4	3	2	1	0																																				
Default value	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1																																						
<table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <thead> <tr> <th style="width: 5%;">bit</th> <th style="width: 45%;">Meaning when "0" is set</th> <th style="width: 50%;">Meaning when "1" is set</th> </tr> </thead> <tbody> <tr><td>0</td><td>External emergency stop valid</td><td>External emergency stop invalid (default value)</td></tr> <tr><td>1</td><td>Dynamic brake stop at emergency stop</td><td>Deceleration control stop at emergency stop</td></tr> <tr><td>2</td><td>NC bus emergency stop input valid</td><td>NC bus emergency stop input invalid</td></tr> <tr><td>3</td><td>NC bus emergency stop output valid</td><td>NC bus emergency stop output invalid</td></tr> <tr><td>4</td><td></td><td></td></tr> <tr><td>5</td><td></td><td></td></tr> <tr><td>6</td><td></td><td></td></tr> <tr><td>7</td><td></td><td></td></tr> <tr><td>8</td><td></td><td></td></tr> <tr><td>9</td><td></td><td></td></tr> <tr><td>A</td><td></td><td></td></tr> <tr><td>B</td><td></td><td></td></tr> <tr><td>C</td><td></td><td></td></tr> <tr><td>D</td><td></td><td></td></tr> <tr><td>E</td><td></td><td></td></tr> <tr><td>F</td><td></td><td></td></tr> </tbody> </table>				bit	Meaning when "0" is set	Meaning when "1" is set	0	External emergency stop valid	External emergency stop invalid (default value)	1	Dynamic brake stop at emergency stop	Deceleration control stop at emergency stop	2	NC bus emergency stop input valid	NC bus emergency stop input invalid	3	NC bus emergency stop output valid	NC bus emergency stop output invalid	4			5			6			7			8			9			A			B			C			D			E			F		
bit	Meaning when "0" is set	Meaning when "1" is set																																																				
0	External emergency stop valid	External emergency stop invalid (default value)																																																				
1	Dynamic brake stop at emergency stop	Deceleration control stop at emergency stop																																																				
2	NC bus emergency stop input valid	NC bus emergency stop input invalid																																																				
3	NC bus emergency stop output valid	NC bus emergency stop output invalid																																																				
4																																																						
5																																																						
6																																																						
7																																																						
8																																																						
9																																																						
A																																																						
B																																																						
C																																																						
D																																																						
E																																																						
F																																																						

16. Auxiliary Axis Parameters

No.	Name		Details	Setting range	Default value
104 (PR)	tleng	Linear axis stroke length	Set the movement stroke length for linear axes. This is meaningless when setting non-uniform assignments or commanding random positions.	0.001 to 99999.999 (mm)	100.000
110	ZRNspeed	Reference point return speed	Set the clamp value of the feedrate when a reference point return is carried out. The feedrate becomes the manual operation speed of the parameter group selected at that time, but it is clamped by this parameter setting value.	1 to 100000 (°/min or mm/min)	1000
111	ZRNcreep	Reference point return creep speed	Set the approach speed to the reference point after dog detection during a reference point return.	1 to 65535 (°/min or mm/min)	200
112	grid mask	Grid mask	Set the amount that the dog is artificially extended. Set 1/2 the grid spacing as a standard.	0 to 65536 (1/1000° or μm)	0
113 (PR)	grspc	Grid spacing	Divide the grid spacing that is the conventional motor rotation movement amount into 2, 4, 8, or 16 divisions.	0 to 4 (1/2 ⁿ division)	0
114	ZRNshift	Reference point shift amount	Set the shift amount in a dog-type reference point return from the electric zero point determined on the grid to the reference point.	0 to 65536 (1/1000° or μm)	0
115	ST. ofset	Station offset	Set the distance (offset) from the reference point to station 1.	-99999.999 to 99999.999 (° or mm)	0.000
116 (PR)	ABS base	Absolute position zero point	When movement of the machine coordinate zero point from the origin point is required during absolute position initializing, set that movement amount.	-99999.999 to 99999.999 (° or mm)	0.000
117	Limit (+)	Soft limit (+)	Commands in the plus direction that exceed this setting value are not possible. If the machine is in a position exceeding the setting value, commands in the minus direction are possible. The soft limit function will not operate if Limit (+) and Limit (-) are set to the same value.	-99999.999 to 99999.999 (mm)	1.000
118	Limit (-)	Soft limit (-)	Commands in the minus direction that exceed this value are not possible. If the machine is in a position exceeding the setting value, commands in the plus direction are possible.	-99999.999 to 99999.999 (mm)	1.000

16. Auxiliary Axis Parameters

No.	Name	Details	Setting range	Default value																																																																																					
120	ABS Type	<p>Absolute position detection parameter</p> <p>This parameter is set as a hexadecimal. Set the default value for bits that have no description.</p> <table border="1" style="width: 100%; border-collapse: collapse; margin-bottom: 10px;"> <thead> <tr> <th style="width: 5%;">bit</th> <th style="width: 5%;">F</th> <th style="width: 5%;">E</th> <th style="width: 5%;">D</th> <th style="width: 5%;">C</th> <th style="width: 5%;">B</th> <th style="width: 5%;">A</th> <th style="width: 5%;">9</th> <th style="width: 5%;">8</th> <th style="width: 5%;">7</th> <th style="width: 5%;">6</th> <th style="width: 5%;">5</th> <th style="width: 5%;">4</th> <th style="width: 5%;">3</th> <th style="width: 5%;">2</th> <th style="width: 5%;">1</th> <th style="width: 5%;">0</th> </tr> </thead> <tbody> <tr> <td>Default value</td> <td>0</td> <td>1</td> <td>0</td> <td>0</td> </tr> </tbody> </table> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 5%;">bit</th> <th style="width: 40%;">Meaning when "0" is set</th> <th style="width: 40%;">Meaning when "1" is set</th> </tr> </thead> <tbody> <tr><td>0</td><td></td><td></td></tr> <tr><td>1</td><td>Dogless-type method initializing</td><td>Dog-type method initializing</td></tr> <tr><td>2</td><td>Mechanical stopper method initializing</td><td>Origin point alignment method initializing</td></tr> <tr><td>3</td><td>Electrical zero point direction (+)</td><td>Electrical zero point direction (-)</td></tr> <tr><td>4</td><td></td><td></td></tr> <tr><td>5</td><td></td><td></td></tr> <tr><td>6</td><td></td><td></td></tr> <tr><td>7</td><td></td><td></td></tr> <tr><td>8</td><td></td><td></td></tr> <tr><td>9</td><td></td><td></td></tr> <tr><td>A</td><td></td><td></td></tr> <tr><td>B</td><td></td><td></td></tr> <tr><td>C</td><td></td><td></td></tr> <tr><td>D</td><td></td><td></td></tr> <tr><td>E</td><td></td><td></td></tr> <tr><td>F</td><td></td><td></td></tr> </tbody> </table>	bit	F	E	D	C	B	A	9	8	7	6	5	4	3	2	1	0	Default value	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	bit	Meaning when "0" is set	Meaning when "1" is set	0			1	Dogless-type method initializing	Dog-type method initializing	2	Mechanical stopper method initializing	Origin point alignment method initializing	3	Electrical zero point direction (+)	Electrical zero point direction (-)	4			5			6			7			8			9			A			B			C			D			E			F				
bit	F	E	D	C	B	A	9	8	7	6	5	4	3	2	1	0																																																																									
Default value	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0																																																																									
bit	Meaning when "0" is set	Meaning when "1" is set																																																																																							
0																																																																																									
1	Dogless-type method initializing	Dog-type method initializing																																																																																							
2	Mechanical stopper method initializing	Origin point alignment method initializing																																																																																							
3	Electrical zero point direction (+)	Electrical zero point direction (-)																																																																																							
4																																																																																									
5																																																																																									
6																																																																																									
7																																																																																									
8																																																																																									
9																																																																																									
A																																																																																									
B																																																																																									
C																																																																																									
D																																																																																									
E																																																																																									
F																																																																																									
123	ABS check	<p>Absolute position power OFF tolerable movement value</p> <p>Set the value for the tolerable amount of movement for a machine that moved during power OFF in an absolute position detection system. The "Absolute position power OFF movement exceeded (ABS)" signal will turn ON if the machine moves more than this setting value during power OFF. The movement amount is not checked when this parameter is set to 0.000.</p>	0.000 to 99999.999 (° or mm)	0.000																																																																																					
130	backlash	<p>Backlash compensation amount</p> <p>Set the backlash compensation amount.</p>	0 to 9999 (1/1000° or μm)	0																																																																																					
132		(Not used.)		0																																																																																					
133		(Not used.)		0																																																																																					
134		(Not used.)		0																																																																																					
135		(Not used.)		0																																																																																					

16. Auxiliary Axis Parameters

< Operation parameter group 1 >

No.	Name	Details	Setting range	Default value
150	Aspeed1 Operation parameter group 1 Automatic operation speed	Set the feedrate during automatic operation when operation parameter group 1 is selected. This parameter is regarded as the clamp value for the automatic operation speeds and manual operation speeds of all operation groups. A speed exceeding Aspeed1 cannot be commanded, even if set in the parameters.	1 to 100000 (°/min or mm/min)	5000
151	Mspeed1 Operation parameter group 1 Manual operation speed	Set the feedrate during manual operation or JOG operation when operation parameter group 1 is selected.	1 to 100000 (°/min or mm/min)	2000
152	time1.1 Operation parameter group 1 Acceleration/deceleration time constant 1	Set the linear acceleration/deceleration time for Aspeed 1 (the operation parameter group 1 automatic operation speed (clamp speed)) when operation parameter group 1 is selected. When operating at speeds less than the clamp speed, the axis will linearly accelerate/decelerate at the inclination determined above. When this is set together with acceleration/deceleration time constant 2, S-shape acceleration/deceleration is carried out. In this case, set the acceleration/deceleration time of the linear part in this parameter.	1 to 9999 (ms)	100
153	time1.2 Operation parameter group 1 Acceleration/deceleration time constant 2	Set this parameter when carrying out S-shape acceleration/deceleration. When S-shape acceleration/deceleration is carried out, set the total time of the non-linear parts. When "1" is set in this parameter, linear acceleration/deceleration is carried out. In the handle feed operation mode, this set value is regarded as the time constant for the linear acceleration/deceleration.	1 to 999 (ms)	1

16. Auxiliary Axis Parameters

No.	Name	Details	Setting range	Default value
154	TL1 Operation parameter group 1 Torque limit value	Set the motor output torque limit value when operation parameter group 1 is selected. At the default value, the torque is limited at the maximum torque of the motor specifications. Set the default value when torque limit is not especially required. In the stopper positioning operation mode, this becomes the torque limit value when positioning to the stopper starting coordinates.	1 to 500 (%)	500
155	OD1 Operation parameter group 1 Excessive error detection width	Set the excessive error detection width when operation parameter group 1 is selected. An alarm of excessive error (S03 0052) is detected when the position droop becomes larger than this setting value. In the stopper positioning operation mode, this becomes the excessive error detection width when positioning to the stopper starting coordinates.	0 to 32767 (° or mm)	100
156	just1 Operation parameter group 1 Set position output width	The signal indicating that the machine position is at any one of the stations is the set position reached (JST) signal. During automatic operation, the automatic set position reached (JSTA) signal is also output under the same conditions. Set the tolerable values at which these signals are output when operation parameter group 1 is selected. These signals turn OFF when the machine position is separated from the station by more than this value.	0.000 to 99999.999 (° or mm)	0.500
157	near1 Operation parameter group 1 Near set position output width	The signal indicating that the machine position is near any one of the station positions is the near set position (NEAR) signal. Set the tolerable value at which this signal is output when operation parameter group 1 is selected. This value is generally set wider than the set position output width. During operations, this is related to special commands when the station selection is "0".	0.000 to 99999.999 (° or mm)	1.000

16. Auxiliary Axis Parameters

< Operation parameter group 2 >

No.	Name	Details	Setting range	Default value
158	Aspeed2 Operation parameter group 2 Automatic operation speed	Set the feedrate during automatic operation when operation parameter group 2 is selected.	1 to 100000 (°/min or mm/min)	5000
159	Mspeed2 Operation parameter group 2 Manual operation speed	Set the feedrate during manual operation or JOG operation when operation parameter group 2 is selected.	1 to 100000 (°/min or mm/min)	2000
160	time2.1 Operation parameter group 2 Acceleration/deceleration time constant 1	Set the linear acceleration/deceleration time for the operation parameter group 1 automatic operation speed (clamp speed) when operation parameter group 2 is selected. When operating at speeds less than the clamp speed, the axis will linearly accelerate/decelerate at the inclination determined above. When this is set together with acceleration/deceleration time constant 2, S-shape acceleration/deceleration is carried out. In this case, set the acceleration/deceleration time of the linear part in this parameter.	1 to 9999 (ms)	100
161	time2.2 Operation parameter group 2 Acceleration/deceleration time constant 2	Set this parameter when carrying out S-shape acceleration/deceleration. When S-shape acceleration/deceleration is carried out, set the total time of the non-linear parts. When 1 is set in this parameter, linear acceleration/deceleration is carried out. In the handle feed operation mode, this set value is regarded as the time constant for the linear acceleration/deceleration.	1 to 9999 (ms)	1

16. Auxiliary Axis Parameters

No.	Name	Details	Setting range	Default value
162	TL2	Operation parameter group 2 Torque limit value	Set the motor output torque limit value when operation parameter group 2 is selected. At the default value, the torque is limited at the maximum torque of the motor specifications. Set the default value when torque limit is not especially required. In the stopper positioning operation mode, this becomes the torque limit value during stopper operation.	1 to 500 (%) 500
163	OD2	Operation parameter group 2 Excessive error detection width	Set the excessive error detection width when operation parameter group 2 is selected. An excessive error alarm (S03 0052) is detected when the position droop becomes larger than this setting value. In the stopper positioning operation mode, this becomes the excessive error detection width during stopper operation.	0 to 32767 (° or mm) 100
164	just2	Operation parameter group 2 Set position output width	The signal indicating that the machine position is at any one of the stations is the set position reached (JST) signal. During automatic operation, the automatic set position reached (JSTA) signal is also output under the same conditions. Set the tolerable values at which these signals are output when operation parameter group 2 is selected. These signals turn OFF when the machine position is separated from the station by more than this value.	0.000 to 99999.999 (° or mm) 0.500
165	near2	Operation parameter group 2 Near set position output width	The signal indicating that the machine position is near any one of the station positions is the near set position (NEAR) signal. Set the tolerable values at which these signals are output when operation parameter group 2 is selected. These values are generally set wider than the set position output width. During operations, this is related to special commands when the station selection is "0".	0.000 to 99999.999 (° or mm) 1.000

16. Auxiliary Axis Parameters

< Operation parameter group 3 >

No.	Name	Details	Setting range	Default value
166	Aspeed3 Operation parameter group 3 Automatic operation speed	Set the feedrate during automatic operation when operation parameter group 3 is selected.	1 to 100000 (°/min or mm/min)	5000
167	Mspeed3 Operation parameter group 3 Manual operation speed	Set the feedrate during manual operation or JOG operation when operation parameter group 3 is selected.	1 to 100000 (°/min or mm/min)	2000
168	time3.1 Operation parameter group 3 Acceleration/deceleration time constant 1	Set the linear acceleration/deceleration time for the operation parameter group 1 automatic operation speed (clamp speed) when operation parameter group 3 is selected. When operating at speeds less than the clamp speed, the axis will linearly accelerate/decelerate at the inclination determined above. When this is set together with acceleration/deceleration time constant 2, S-shape acceleration/deceleration is carried out. In this case, set the acceleration/deceleration time of the linear part in this parameter.	1 to 9999 (ms)	100
169	time3.2 Operation parameter group 3 Acceleration/deceleration time constant 2	Set this parameter when carrying out S-shape acceleration/deceleration. When S-shape acceleration/deceleration is carried out, set the total time of the non-linear parts. When 1 is set in this parameter, linear acceleration/deceleration is carried out. In the handle feed operation mode, this set value is regarded as the time constant for the linear acceleration/deceleration	1 to 9999 (ms)	1

16. Auxiliary Axis Parameters

No.	Name	Details	Setting range	Default value
170	TL3 Operation parameter group 3 Torque limit value	Set the motor output torque limit value when operation parameter group 3 is selected. At the default value, the torque is limited at the maximum torque of the motor specifications. Set the default value when torque limit is not especially required. In the stopper positioning operation mode, this becomes the pressing torque limit value after completion of the positioning.	1 to 500 (%)	500
171	OD3 Operation parameter group 3 Excessive error detection width	Set the excessive error detection width when operation parameter group 3 is selected. An excessive error alarm (S03 0052) is detected when the position droop becomes larger than this setting value. In the stopper positioning operation mode, this becomes the excessive error detection width during pressing after completion of the positioning.	0 to 32767 (° or mm)	100
172	just3 Operation parameter group 3 Set position output width	The signal indicating that the machine position is at any one of the stations is the set position reached (JST) signal. During automatic operation, the automatic set position reached (JSTA) signal is also output under the same conditions. Set the tolerable values at which these signals are output when operation parameter group 3 is selected. These signals turn OFF when the machine position is separated from the station by more than this value.	0.000 to 99999.999 (° or mm)	0.500
173	near3 Operation parameter group 3 Near set position output width	The signal indicating that the machine position is near any one of the station positions is the near set position (NEAR) signal. Set the tolerable values at which these signals are output when operation parameter group 3 is selected. These values are generally set wider than the set position output width. During operations, this is related to special commands when the station selection is "0".	0.000 to 99999.999 (° or mm)	1.000

16. Auxiliary Axis Parameters

< Operation parameter group 4 >

No.	Name	Details	Setting range	Default value
174	Aspeed4 Operation parameter group 4 Automatic operation speed	Set the feedrate during automatic operation when operation parameter group 4 is selected.	1 to 100000 (°/min or mm/min)	5000
175	Mspeed4 Operation parameter group 4 Manual operation speed	Set the feedrate during manual operation or JOG operation when operation parameter group 4 is selected.	1 to 100000 (°/min or mm/min)	2000
176	time4.1 Operation parameter group 4 Acceleration/deceleration time constant 1	Set the linear acceleration/deceleration time for the operation parameter group 1 automatic operation speed (clamp speed) when operation parameter group 4 is selected. When operating at speeds less than the clamp speed, the axis will linearly accelerate/decelerate at the inclination determined above. When this is set together with acceleration/deceleration time constant 2, S-shape acceleration/deceleration is carried out. In this case, set the acceleration/deceleration time of the linear part in this parameter.	1 to 9999 (ms)	100
177	time4.2 Operation parameter group 4 Acceleration/deceleration time constant 2	Set this parameter when carrying out S-shape acceleration/deceleration. When S-shape acceleration/deceleration is carried out, set the total time of the non-linear parts. When 1 is set in this parameter, linear acceleration/deceleration is carried out. In the handle feed operation mode, this set value is regarded as the time constant for the linear acceleration/deceleration.	1 to 9999 (ms)	1

16. Auxiliary Axis Parameters

No.	Name	Details	Setting range	Default value	
178	TL4	<p>Operation parameter group 4 Torque limit value</p>	<p>Set the motor output torque limit value when operation parameter group 4 is selected. At the default value, the torque is limited at the maximum torque of the motor specifications. Set the default value when torque limit is not especially required.</p> <p>In the stopper method initializing mode in absolute position detection systems, this becomes the torque limit value during stopper operation.</p>	1 to 500 (%)	500
179	OD4	<p>Operation parameter group 4 Excessive error detection width</p>	<p>Set the excessive error detection width when operation parameter group 4 is selected. An excessive error alarm (S03 0052) is detected when the position droop becomes larger than this setting value.</p> <p>In the stopper method initializing mode in absolute position detection systems, this becomes the excessive error detection width during stopper operation.</p>	0 to 32767 (° or mm)	100
180	just4	<p>Operation parameter group 4 Set position output width</p>	<p>The signal indicating that the machine position is at any one of the stations is the set position reached (JST) signal. During automatic operation, the automatic set position reached (JSTA) signal is also output under the same conditions.</p> <p>Set the tolerable values at which these signals are output when operation parameter group 4 is selected. These signals turn OFF when the machine position is separated from the station by more than this value.</p>	0.000 to 99999.999 (° or mm)	0.500
181	near4	<p>Operation parameter group 4 Near set position output width</p>	<p>The signal indicating that the machine position is near any one of the station positions is the near set position (NEAR) signal. Set the tolerable values at which these signals are output when operation parameter group 4 is selected. These values are generally set wider than the set position output width.</p> <p>During operations, this is related to special commands when the station selection is "0".</p>	0.000 to 99999.999 (° or mm)	1.000

16. Auxiliary Axis Parameters

No.	Name	Details	Setting range	Default value																																																																																								
190	stpos2	Station 2 coordinate value	Set the coordinate value of each station when non-uniform assignment is selected. The station 1 coordinate value is fixed at 0.000 (machine coordinate zero point). –99999.999 to 99999.999 (° or mm)	0.000																																																																																								
191	stpos3	Station 3 coordinate value																																																																																										
192	stpos4	Station 4 coordinate value																																																																																										
193	stpos5	Station 5 coordinate value																																																																																										
194	stpos6	Station 6 coordinate value																																																																																										
195	stpos7	Station 7 coordinate value																																																																																										
196	stpos8	Station 8 coordinate value																																																																																										
197	stpos9	Station 9 coordinate value																																																																																										
200	PSWcheck	PSW detection method			<p>This is a HEX setting parameter. Set bits without a description to their default values.</p> <table border="1" style="width: 100%; border-collapse: collapse; margin-bottom: 10px;"> <thead> <tr> <th style="text-align: center;">bit</th> <th style="text-align: center;">F</th> <th style="text-align: center;">E</th> <th style="text-align: center;">D</th> <th style="text-align: center;">C</th> <th style="text-align: center;">B</th> <th style="text-align: center;">A</th> <th style="text-align: center;">9</th> <th style="text-align: center;">8</th> <th style="text-align: center;">7</th> <th style="text-align: center;">6</th> <th style="text-align: center;">5</th> <th style="text-align: center;">4</th> <th style="text-align: center;">3</th> <th style="text-align: center;">2</th> <th style="text-align: center;">1</th> <th style="text-align: center;">0</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">Default value</td> <td style="text-align: center;">0</td> </tr> </tbody> </table> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: center;">bit</th> <th style="text-align: center;">Position switch</th> <th style="text-align: center;">Meaning when "0" is set</th> <th style="text-align: center;">Meaning when "1" is set</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">0</td> <td style="text-align: center;">PSW1</td> <td rowspan="8" style="vertical-align: top;">The position switch output is judged by the machine position of the command system.</td> <td rowspan="8" style="vertical-align: top;">The position switch output is judged by the machine FB position (actual position).</td> </tr> <tr> <td style="text-align: center;">1</td> <td style="text-align: center;">PSW2</td> </tr> <tr> <td style="text-align: center;">2</td> <td style="text-align: center;">PSW3</td> </tr> <tr> <td style="text-align: center;">3</td> <td style="text-align: center;">PSW4</td> </tr> <tr> <td style="text-align: center;">4</td> <td style="text-align: center;">PSW5</td> </tr> <tr> <td style="text-align: center;">5</td> <td style="text-align: center;">PSW6</td> </tr> <tr> <td style="text-align: center;">6</td> <td style="text-align: center;">PSW7</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">PSW8</td> </tr> <tr> <td style="text-align: center;">8</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">9</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">A</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">B</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">C</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">D</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">E</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">F</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>		bit	F	E	D	C	B	A	9	8	7	6	5	4	3	2	1	0	Default value	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	bit	Position switch	Meaning when "0" is set	Meaning when "1" is set	0	PSW1	The position switch output is judged by the machine position of the command system.	The position switch output is judged by the machine FB position (actual position).	1	PSW2	2	PSW3	3	PSW4	4	PSW5	5	PSW6	6	PSW7	7	PSW8	8				9				A				B				C				D				E				F	
bit	F	E	D	C	B	A	9	8	7	6	5	4	3	2	1	0																																																																												
Default value	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0																																																																												
bit	Position switch	Meaning when "0" is set	Meaning when "1" is set																																																																																									
0	PSW1	The position switch output is judged by the machine position of the command system.	The position switch output is judged by the machine FB position (actual position).																																																																																									
1	PSW2																																																																																											
2	PSW3																																																																																											
3	PSW4																																																																																											
4	PSW5																																																																																											
5	PSW6																																																																																											
6	PSW7																																																																																											
7	PSW8																																																																																											
8																																																																																												
9																																																																																												
A																																																																																												
B																																																																																												
C																																																																																												
D																																																																																												
E																																																																																												
F																																																																																												

16. Auxiliary Axis Parameters

No.	Name	Details	Setting range	Default value	
201 202	PSW1dog1 PSW1dog2	PSW1 area setting 1 PSW1 area setting 2	When the machine position is in the region between region settings 1 and 2, the position switch of each No. will turn ON. Whether the value of setting 1 is larger than setting 2 (vice versa) does not affect the position switch operation. For rotation axes, the output turns ON at the region without including 0.000 degree.	-99999.999 to 99999.999 (° or mm)	
203 204	PSW2dog1 PSW2dog2	PSW2 area setting 1 PSW2 area setting 2			
205 206	PSW3dog1 PSW3dog2	PSW3 area setting 1 PSW3 area setting 2			
207 208	PSW4dog1 PSW4dog2	PSW4 area setting 1 PSW4 area setting 2			
209 210	PSW5dog1 PSW5dog2	PSW5 area setting 1 PSW5 area setting 2			
211 212	PSW6dog1 PSW6dog2	PSW6 area setting 1 PSW6 area setting 2			
213 214	PSW7dog1 PSW7dog2	PSW7 area setting 1 PSW7 area setting 2			
215 216	PSW8dog1 PSW8dog2	PSW8 area setting 1 PSW8 area setting 2			
220	push	Stopper amount	Set the command stroke of the stopper operation during stopper positioning operations.	0.000 to 359.999 (° or mm)	0.000
221	pusht1	Stopper standby time	Set the standby time from the stopper starting coordinate positioning to the stopper operation start during stopper positioning operations.	0 to 9999 (ms)	0
222	pusht2	Stopper torque release time	Set the time from the completion of the stopper operation to the changeover of the stopper torque during stopper positioning operations.	0 to 9999 (ms)	0
223	pusht3	Set position signal output delay time	Set the time from the completion of the stopper operation to the output of the automatic set position reached (JSTA), set position reached (JST), and near set position (NEAR) signals during stopper positioning operations.	0 to 9999 (ms)	0

Revision History

Date of revision	Manual No.	Revision details																												
Dec. 2000	BNP-B2267*	First edition created.																												
Sep. 2003	BNP-B2267A	<ul style="list-style-type: none"> • The cover (front, spine, back covers) design was changed. • "Type", "Independent Product Code" and "Reference No." were added to the back cover. • The following parameters were added. <ul style="list-style-type: none"> (1) 5. Basic specification parameters <table border="1" style="margin-left: 40px; width: 100%;"> <tbody> <tr> <td data-bbox="667 524 762 562">#1926</td> <td data-bbox="767 524 1007 562">IP address</td> <td data-bbox="1054 524 1150 562">#21025</td> <td data-bbox="1155 524 1378 562">SmpDelay</td> </tr> <tr> <td data-bbox="667 568 762 607">#1927</td> <td data-bbox="767 568 1007 607">Subnet mask</td> <td data-bbox="1054 568 1150 607">#21028</td> <td data-bbox="1155 568 1378 607">ed_mess</td> </tr> <tr> <td data-bbox="667 613 762 651">#1928</td> <td data-bbox="767 613 1007 651">Gateway address</td> <td data-bbox="1054 613 1150 651">#21029</td> <td data-bbox="1155 613 1378 651">NCname</td> </tr> <tr> <td data-bbox="667 658 762 696">#1929</td> <td data-bbox="767 658 1007 696">Port number</td> <td data-bbox="1054 658 1150 696">#21030</td> <td data-bbox="1155 658 1378 696">AlmHold</td> </tr> <tr> <td></td> <td></td> <td data-bbox="1054 703 1150 741">#21031</td> <td data-bbox="1155 703 1378 741">UnitMax</td> </tr> <tr> <td></td> <td></td> <td data-bbox="1054 748 1150 786">#21032</td> <td data-bbox="1155 748 1378 786">UnitNum</td> </tr> <tr> <td></td> <td></td> <td data-bbox="1054 792 1150 831">#21049</td> <td data-bbox="1155 792 1378 831">SPname</td> </tr> </tbody> </table> (2) 16. Indexing axis parameters (#26251 ~) (3) 17. Indexing axis position switch (#27701 ~) (4) 18 Indexing axis commands • Mistakes, etc. were corrected. 	#1926	IP address	#21025	SmpDelay	#1927	Subnet mask	#21028	ed_mess	#1928	Gateway address	#21029	NCname	#1929	Port number	#21030	AlmHold			#21031	UnitMax			#21032	UnitNum			#21049	SPname
#1926	IP address	#21025	SmpDelay																											
#1927	Subnet mask	#21028	ed_mess																											
#1928	Gateway address	#21029	NCname																											
#1929	Port number	#21030	AlmHold																											
		#21031	UnitMax																											
		#21032	UnitNum																											
		#21049	SPname																											
Mar.2004	BNP-B2267C	<ul style="list-style-type: none"> • The contents revised following to the software Ver.C and Ver.D. • Sections of servo parameters (section 7 to 9) were revised all over, and reconstructed to "7. Servo Parameters". • Sections of spindle parameters (section 10 and 11) were revised all over, and reconstructed to "8. Spindle Parameters". • "19 Auxiliary Axis Parameters" was revised all over and its section number became "16". • Mistakes, etc. were corrected. 																												

Notice

Every effort has been made to keep up with software and hardware revisions in the contents described in this manual. However, please understand that in some unavoidable cases simultaneous revision is not possible.

Please contact your Mitsubishi Electric dealer with any questions or comments regarding the use of this product.

Duplication Prohibited

This instruction manual may not be reproduced in any form, in part or in whole, without written permission from Mitsubishi Electric Corporation.

© 2000-2004 MITSUBISHI ELECTRIC CORPORATION
ALL RIGHTS RESERVED



MODEL	MC6/C64/C64T
MODEL CODE	008-046
Manual No.	BNP-B2267C(ENG)

Specifications subject to change without notice.
Printed in Japan on recycled paper.